

PAR Automotive Consultancy

Regn No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0513-18-TCA

27 August 2018

ACCIDENT VEHICLE SURVEY REPORT

Lau Kok Seng
11 Anchorvale Crescent #10-02
Singapore 544649

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLC1994S	<i>Odometer:</i>	135714km
<i>Make & Model:</i>	Toyota Lexus RX450H	<i>Colour:</i>	Black
<i>Chassis number:</i>	JTBC11A402015860	<i>Date of accident:</i>	25/01/2018
<i>Year of Regn.:</i>	20/11/2009	<i>Date inspected:</i>	29/01/2018
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	05/02/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.















































