

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

24-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6974 P

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
1 pc	Rear bumper n/s reflector @ \$46.00	\$	46.00
			<hr/>
			\$ 1,907.00
			Less 10%
			<hr/>
			\$ 1,716.30

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00 200
1 pc	Rear bumper top protector	\$	80.00 50
	Sundry	\$	50.00 x
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 x
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair reshape and adjust of the end panel, etc	\$	650.00 200
	To putty and spray painting on rear bumper, end panel	\$	400.00 180
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 x
			<hr/>
			\$ 3,644.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is subject to confirmation
- No illegal modification(s) is allowed
- Any repair (emiss) must be resurveyed and approved by the Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

1 call 11004
24/9/18 1605h.
2 Pjs
P/P
Before Paint photo