

ASS. REC. BY:

REF:

CS/FCI18017446/Kqd312

Special Instruction:

Surveyor:

Kenneth

CWS

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time:

25/9/18 @ 12:14pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 5956R

Insured:

SHA 9181B

at Workshop in/s

Cheng Hoe Motor

Tel:

6755 6142

of

Blk 1019, Yishun Ind. Park A # 01-374

Policy No:

Claim No:

D18006978MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/09/18

CA / REV / REP. / REV 24 HRS

(DS)

Insp: 38 Woodlands Ind. Park E1 #05-04

H.O.D. Endorsement:

Date/Time:

12:41pm @ 25/9/18

Person Contacted:

Wei Ling

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJS 5956R - X

SHA 9181B - NA / MSG / 8008538 / r3

D.O.A: 10/5/18

28/9/18 @ 7:48pm revised to Sithara by email.

15/11/18 8:515d Calman Tune (Ref \$1681.20, 25%)

ASS. REC. BY:

REF:

PCZ/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STJ5956R

Yr Regn:

08, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda City

c.c.

1.8P7

Colour:

M-Black

A/C:

Insured / Std / NI / NA

Sp. Reading

184350

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR14GM26509P020302

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

24/9/18

D.O.I.

25/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19 File pass to Catherine

MV : \$ 17K - LTA : 9.578 = Net value : \$ 7.422

RECEIVED 15 NOV 2018

16/11/2018

Date/Time, File Pass to?

11/11/18

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Lump Sum / L.B.I. (\$

7P

5150

145

50

50+50

34

329



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017446/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9181B	Veh. Inspected	SJS 5956R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006978MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	25/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/09/2018	Inspection Date	25/09/2018	
Survey held at	38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 SINGAPOR			
Repairer	CHENG HOE MOTOR PL			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006978MFSH

Date: 28 September 2018

Our Ref: CS/FCI18017446/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJS 5956R .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/09/2018 at the premises of M/s CHENG HOE MOTOR . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,831.20</u> .
Revised Estimate Amount	: S\$ <u>5,365.90</u> .
"Check" Items Amount	: S\$ <u>830.72</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	24-09-2018	Our Ref No. D18006978MFSH
Accident Date	24-09-2018	Claim Type. Third Party
Insured Vehicle	SHA9181B	Third Party Vehicle. SJS5956R
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 28 September 2018 2:48 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006978MFSH/1
Attachments: CSFCI18017446Kqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SJS 5956R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 25 September 2018 12:45 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006978MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 25 September 2018 12:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006978MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4870G
Vehicle Details	
Vehicle No.:	SJS5956R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5L I-VTEC AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	L15A71804702
Chassis No.:	MRHGM26509P020302
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,873.00
Original Registration Date:	25 Aug 2009
First Registration Date:	25 Aug 2009
Transfer Count:	1
Actual ARF Paid:	\$16,655.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Aug 2019
PARF Rebate Amount:	\$8,327.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$4,591.00
COE Rebate Amount:	\$1,251.00
Total Rebate Amount:	\$9,578.00

The information contained herein is correct as at 24 Sep 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/WL

Claim Type: Third Party

Accident Date: 24/09/2018

TP Veh Reg No: SHA9181B

Estimate No: ES1891093/WL

Date: 25 Sep 2018

Policy No: DMPCSN3033191802

Veh Reg No: SJS5956R

Make/Model: HONDA CITY 1.5L I-VTEC AUTO

Chassis No: MRHGM26509P020302

Engine No: L15A71804702

Reg. Date: 25/08/2009

Estimate Repair Cost to Vehicle No :SJS5956R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	463.70	1 PC	463.70	—
2 REAR BUMPER SIDE RETAINERS	14.80	2 PCS	29.60	—
3 REAR BUMPER CLIPS	3.70	6 PCS	22.20	—
4 TAILLAMPS	205.70	2 PCS	411.40	—
5 REAR CENTRE PANEL	399.70	1 PC	399.70	—
6 REAR CENTRE PANEL INNER TOP GARNISH	66.40	1 PC	66.40	—
7 REAR BOOT	503.90	1 PC	503.90	—
8 REAR BOOT INNER LOCK	43.50	1 PC	43.50	—
9 REAR BOOT INNER RUBBER	74.40	1 PC	74.40	50.00
10 REAR BOOT LOGO	17.80	1 PC	17.80	—
11 REAR BOOT EMBLEM (CITY)	16.40	1 PC	16.40	—
12 REAR BOOT EMBLEM (I-VTEC)	22.40	1 PC	22.40	—
13 REAR BOOT INNER SPONGE CLIPS	4.20	3 PCS	12.60	—
14 REAR SPARE TYRE COMPARTMENT	580.70	1 PC	580.70	—
15 REAR SPARE TYRE TOP BOARD	70.40	1 PC	70.40	—
16 REAR RH FENDER	766.90	1 PC	766.90	—
17 REAR WINDSCREEN GLASS MOULDING	141.80	1 PC	141.80	—
18 REAR EXHAUST PIPE	457.70	1 PC	457.70	—
			4,101.50	
		Less 20%	820.30	3,281.20
Special Net				
19 REVERSE SENSOR	200.00	1 SET	200.00	—
20 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	—
21 REAR FENDER GLASS GUM	20.00	1 PC	20.00	—
			260.00	260.00
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/WL

Claim Type: Third Party

Accident Date: 24/09/2018

TP Veh Reg No: SHA9181B

Estimate No: ES1891093/WL

Date: 25 Sep 2018

Policy No: DMPCSN3033191802

Veh Reg No: SJS5956R

Make/Model: HONDA CITY 1.5L I-VTEC AUTO

Chassis No: MRHGM26509P020302

Engine No: L15A71804702

Reg. Date: 25/08/2009

Estimate Repair Cost to Vehicle No :SJS5956R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
23 REMOVE & REFIX REAR BUMPER ASSY, TAIL LAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR SPARE TYRE COMPARTMENT, REAR PANEL, REAR RH FENDER, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	1,700.00	1 LA	1,700.00	1600
24 REMOVE & REFIX REAR SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC	120.00	1 LA	120.00	100
25 PUTTY & RESPRAY ON REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR RH FENDER, BOOT, REAR BUMPER & REAR AFFECTED AREAS	1,200.00	1 LA	1,200.00	1100
26 REMOVE AND REFIX REAR EXHAUST AND CHECK LEAKING	60.00	1 LA	60.00	✓
27 RUSTPROOFING	90.00	1 LA	90.00	✓
			3,290.00	3,290.00
Total				SS 6,831.20
Add GST @ 7%				478.18
Total Amount Payable				SS 7,309.38

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017446/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9181B	Veh. Inspected	SJS 5956R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006978MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	25/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MRHGM26509P020302	Colour	METALLIC BLACK	
Odometer	184354	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	MICHELIN	7 mm	
L/H Front Tyre	185/60 R15	MICHELIN	7 mm	
R/H Rear Tyre	185/60 R15	MICHELIN	7 mm	
L/H Rear Tyre	185/60 R15	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/09/2018	Inspection Date	25/09/2018	
Survey held at	38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05			
Repairer	CHENG HOE MOTOR PL			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 5956R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT	463.70	463.70
2	REAR BUMPER SIDE RETAINERS @\$14.80	DISTORTED	29.60	29.60
6	REAR BUMPER CLIPS @\$3.70	NECESSARY	22.20	22.20
2	TAILLAMPS @\$205.70	CRACKED	411.40	411.40
1	REAR CENTRE PANEL	BENT	399.70	399.70
1	REAR CENTRE PANEL INNER TOP GARNISH	DENTED	66.40	66.40
1	REAR BOOR	BENT	503.90	503.90
1	REAR BOOR INNER LOCK	DENTED	43.50	43.50
1	REAR BOOT LOGO	NECESSARY	17.80	17.80
1	REAR BOOT EMBLEM (CITY)	NECESSARY	16.40	16.40
1	REAR BOOT EMBLEM (I-VTEC)	NECESSARY	22.40	22.40
3	REAR BOOT INNER SPONGE CLIPS @\$4.20	NECESSARY	12.60	12.60
1	REAR SPARE TYRE COMPARTMENT	BUCKLED	580.70	580.70
1	REAR SPARE TYRE TOP BOARD	CRACKED	70.40	70.40
1	REAR RH FENDER	BUCKLED	766.90	766.90
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	141.80	141.80
1	REAR EXHAUST PIPE	BENT	457.70	457.70
	LESS 20% DISCOUNT		-805.42	-805.42
			3,221.68	3,221.68
1	REAR BOOR INNER RUBBER (50%)(SN)	DISTORTED	74.40	37.20
	LESS 20% DISCOUNT		-14.88	-
			59.52	37.20
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	DENTED	200.00	200.00
1	REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	REAR FENDER GLASS GUM (SN)	NECESSARY	20.00	20.00
			260.00	260.00

Report Ref No. CS/FCI18017446/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	REMOVE & REFIX REAR BUMPER ASSY, TAIL LAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR SPARE TYRE COMPARTMENT, REAR PANEL, REAR RH FENDER, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME.		1,700.00	1,600.00
	REMOVE & REFIX REAR SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC.		120.00	100.00
	PUTTY & RESPRAY ON REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR RH FENDER, BOOT, REAR BUMPER & REAR AFFECTED AREAS.		1,200.00	1,100.00
	REMOVE AND REFIX REAR EXHAUST AND CHECK LEAKING.		60.00	60.00
	RUSTPROOFING.		90.00	90.00
			3,290.00	3,070.00
	GRAND TOTAL		6,831.20	6,588.88

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,150.00
---	--	--	-----------------

Report Ref No. CS/FCI18017446/Kqd3n2

MARKET VALUE: \$17,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,578.00=NETT VALUE: \$7,422.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.