



**ESTEEM  
PERFORMANCE**

**ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

**Repair Estimates**

SLS 8798 L

<b>Parts</b>	(a) Cost / List Price Items	\$	<b>9,738.50</b>
	Plus/Less 25%	\$	<b>2,434.63</b>
	<b>Total of Cost / List</b>	\$	<b>7,303.88</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) <b>Special Nett Items</b>	\$	<b>300.00</b>
<b>Total Parts Cost</b>		\$	<b>7,603.88</b>
<b>Labour</b>		\$	<b>3,800.00</b>
<b>Total</b>		\$	<b>11,403.88</b>

The above total will be subjected to 7% G.S.T.

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLS 8798 L**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU603571828**

Submit By : **Carmen Lim**  
Year Manufacture : **2017**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	
2	Rear bumper	1	\$497.50		
3	Rear bumper clip	10	\$40.00		
4	Rear bumper side retainer LH	1	\$112.70		
5	Rear bumper side retainer RH	1	\$112.70		
6	Rear bumper reinforcement	1	\$398.90		
7	Rear bumper lower garnish centre	1	\$582.60		
8	Rear bumper lower garnish RH	1	\$149.70		
9	Rear bumper tow cover	1	\$31.70		
10	Rear bumper under cover	1	\$355.20		
11	Rear bumper under cover LH	1	\$187.60		
12	Rear bumper under cover RH	1	\$187.60		
13	Rear bumper under cover clip	4	\$14.00		
14	Tail door	1	\$1,122.50		
15	Tail door lock	1	\$487.70		
16	Tail door emblem	1	\$61.70		
17	Wording "PRIUS"	1	\$51.90		
18	Wording "HYBRID"	1	\$55.47		
19	Tail door plate garnish	1	\$782.50		
20	Tail door inner trim	1	\$278.90		
21	Tail door inner trim clip	10	\$28.00		
22	Tail end panel	1	\$596.60		
23	Tail end panel garnish	1	\$151.60		

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*

**Spare Parts**

Vehicle No. : **SLS 8798 L**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU603571828**

Submit By : **Carmen Lim**

Year Manufacture : **2017**

Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip	10	\$35.00		
25	Boot weatherstrip	1	\$353.10		
26	Spare tyre well panel	1	\$793.15		
27	Spare tyre board	1	\$566.79		
28	Spare tyre compartment sponge LH	1	\$297.67		
29	Spare tyre compartment sponge RH	1	\$297.67		
30	Tail lamp RH - UPPER	1	\$498.75		
31	Tail lamp RH - LOWER	1	\$511.60		
32	Taildoor glass sealant	1	\$50.00	S.N	
33	Rear windscreen moulding	1	\$97.70		
34	Rear windscreen sealant	1	\$50.00	S.N	
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*



**ESTEEM  
PERFORMANCE**

**ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

**Labour**

Vehicle No. : **SLS 8798 L** Submit By : **Carmen Lim**  
 Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER)	\$1,400.00	
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER)	\$1,400.00	
3	To check wiring	\$50.00	
4	To remove & refit reverse sensor	\$120.00	
5	To tuff coat	\$200.00	
6	To remove & refit rear windscreen.	\$120.00	
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	
8	To transfer boot mechanism to new boot	\$120.00	
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	
10	To remove & refit Taildoor glass to assit work load	\$120.00	

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/09/2018 20:40
Date Of Accident	21/09/2018 18:40
Exact Location Of Accident	ECP TOWARDS CHANGI LAMPOST 79
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS8798L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

### Driver

Name of Driver	WEE TECK HUAT
NRIC No	S1469882E
Date Of Birth	31/03/1961
Occupation	OUTDOOR
Date Of Driving Pass	04/06/2012
Driving Experience	6 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90625098
Fax Number	
Contact Number	
Email Address	KNNYWEE@YAHOO.COM.SG

Address HDB BUKIT BATOK, 342 BUKIT BATOK STREET 34 650342  
Postcode

Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -  
-

Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1  
NAME: : P1  
GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
POLICE STATION NAME [OTHER] BUKIT BATOK N.P.C  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT NO: T/20180922/2028 (BUKIT BATOK N.P.C) ON THE 21/09/2018 AT ABOUT 1830HRS, I WAS DRIVING MY GRAB CAR VEHICLE1 SLS8798L, WITH ONE PASSENGER ON BOARD AND WAS TRAVELING ALONG EAST COAST EXPRESSWAY AND WAS HEADING TOWARDS THE DIRECTION OF CHANGI AIRPORT (NEAR LAMP POST 79). AT THAT POINT IN TIME THE ROAD WAS WET AS IT WAS AFTER RAIN. THE TRAFFIC WAS ALSO VERY CONGESTED AND THE VEHICLE AHEAD OF ME WERE TRAVELING SLOWLY. AS I WAS DRIVING, SUDDENLY I FELT A HUGE IMPACT COMING FROM THE REAR OF VEHICLE 1. SHORTLY AFTER THE IMPACT, I STOPPED VEHICLE 1 AND ALIGHTED TO MAKE A CHECK WHEN I DISCOVERED THAT ANOTHER CAR VEHICLE 2 SLS8258M HAS COLLIDED INTO THE REAR OF VEHICLE 1. THE IMPACT OF THE COLLISION HAD CAUSED SERIOUS DAMAGES TO VEHICLE 1 REAR BUMPER. I THEN ALSO MADE A CHECK WITH MY PASSENGER (MALE CAUCASIAN) IF HE WAS INJURED BUT HE TOLD ME HE WAS NOT INJURED. I THEN PROCEEDED TO EXCHANGED PARTICULARS WITH THE DRIVER OF VEHICLE 2. AS THERE WERE NO INJURIES REPORTED AT THE TIME OF ACCIDENT, NO POLICE OR AMBULANCE WAS SUMMONED TO SCENE. AFTER EXCHANGING OUR PARTICULARS, WE THEN LEFT THE ACCIDENT LOCATION AND I CONTINUED DRIVING MY PASSENGER TO HIS DESTINATION. AFTER MY PASSENGER ALIGHTED, I THEN PROCEEDED TO CHAI CHEE NPC TO LODGED A REPORT. HOWEVER WHILE I WAS IN THE POLICE STATION, I WAS FEELING DIZZY AND THUS WAS ADVISED BY THE POLICE OFFICER TO SEEK MEDICAL ATTENTION FIRST. I THEN PROCEEDED TO CHANGI GENERAL HOSPITAL FOR MEDICAL ATTENTION. I WAS TREATED FOR SUSPECTED CERVICAL SPINE INJURY AND ALSO LEFT OCCULT RIB FRACTURE. I WAS GIVEN 08 DAYS OF MEDICAL LEAVE FROM 21/08/2018 TO 28/08/2018. I AM ALSO REQUIRED TO COME BACK TO THE HOSPITAL FOR FOLLOW-UP FOR MY INJURIES. I WISH TO STATE THAT VEHICLE 1 IS EQUIPPED WITH AN IN-BUILT VEHICLE CAMERA HOWEVER THE CAMERA IS ONLY FRONT FACING.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: YES-RETRIEVING  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLC8258M
Vehicle Make/Model/Colour	NISSAN / QASHQAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN DRIVER
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

**DETAILS OF INJURED PERSON 1**

Name	WEE TECK HUAT
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLS8798L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any false misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.
8. Consent under the Personal Data Protection Act (PDPA)

- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or accessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"); the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
  - (b) as insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Md Sharil

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan





## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20160922/2028

1 of 4

Police Station Of Origin:  
Bukit Batok N.P.C.  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6859999

Report No: T/20160922/2028

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/09/2018 09:31	Video Report No.:	Station Diary No. 38
--	-------------------	-------------------------

## Informant's Particulars

Name of Informant: WEE TECK HUAT		Address: APT BLK 342 BUKIT BATOK STREET 34 #04-80 SINGAPORE 650342	
ID Type / ID No. NRIC NO / S1469882E		Contact No.:	Mobile: 90625098
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 57	Date of Birth: 31/03/1961	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3	Date of Expiry:

## General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 21/09/2018 18:40	Type of Location: Straight Road
Location: Along Road 1 EAST COAST EXPRESSWAY				
Along East Coast Expressway (ECP) towards Changi Airport (lamp-post 79)				
Weather: After Rain		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLC8258M	Car	NISSAN	QASHQAI	White		0
SLS8798L	Car	TOYOTA	PRIUS	White	Seriously Damaged	1

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



1/20180922/2028

2 of 4

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

Report No. 1/20180922/2028

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	KOW JUAN HIAN IAN	ID No.	S9534625A
Related Vehicle	SLC8258M (Car)	Contact No.	90031126
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	WEE TECK HUAT	ID No.	S1469882E
Related Vehicle	SLS8798L (Car)	Contact No.	90625098
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	21/09/2018	Date Discharge	21/09/2018
No. of Days granted Medical Leave	08	Degree of Injury	Slight

**Brief Details.**

On 21/09/2018 at about 1840hrs, I was driving my GRAB car V1) SLS8798L, with one passenger on board and was travelling along East Coast Expressway and was heading towards the direction of Changi Airport (near lamp post 79). At that point in time the road was wet as it was after rain. The traffic was also very congested and the vehicles ahead of me were traveling slowly. As I was driving, suddenly I felt a huge impact coming from the rear of V1. Shortly after the impact, I stopped V1 and alighted to make a check when I discovered that another car V2) SLS8258M had collided into the rear of V1. The impact of the collision had caused serious damages to V1 rear bumper. I then also made a check with my passenger (Male Caucasian) if he was injured but he told me that he was not injured. I then proceeded to exchanged particulars with the driver of V2. As there were no injuries reported at the time of accident, no police or ambulance was summoned to scene. After exchanging our particulars, we then left the incident location and I continued driving my passenger to his destination.

After my passenger alighted, I then proceeded to Chai Chee NPC to lodge a report. However while I was in the police station, I was feeling dizzy and thus was advice by the police officer to seek medical attention first. I then proceeded to Changi General Hospital for medical attention. I was treated for suspected cervical spine injury and also left occult rib fracture. I was given 08 days of medical leave from 21/08/2018 to 28/08/2018. I am also required to come back to the hospital for follow-up for my injuries.

I wish to state that V1 is equipped with an in-built vehicle camera however the camera is only front facing.

POLICE REPORT



SINGAPORE  
POLICE FORCE



T/20180922/2028

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6859999

2 of 4

Report No. T/20180922/2028

CONTINUATION OF REPORT