

Ang-LKK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLS 8798 L

Not Authorized
1-B-1
Resurvey By paint

Parts	(a) Cost / List Price Items	\$	9,738.50
	Plus/Less 25%	\$	2,434.63
	Total of Cost / List	\$	7,303.88
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	300.00
Total Parts Cost		\$	7,603.88
Labour		\$	3,800.00
Total		\$	11,403.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 25/9/18 at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-6 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Lc

Date: 25/9/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLS 8798 L**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU603571828**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Del</i>	1	\$200.00	S.N	✓
2	Rear bumper <i>Bj</i>	1	\$497.50		✓
3	Rear bumper clip <i>Am</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>Sm</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Di</i>	1	\$112.70		✓
6	Rear bumper reinforcement <i>Bj</i>	1	\$398.90		✓
7	Rear bumper lower garnish centre <i>Cm</i>	1	\$582.60		✓
8	Rear bumper lower garnish RH <i>Am</i>	1	\$149.70		✓
9	Rear bumper tow cover <i>Del</i>	1	\$31.70		✓
10	Rear bumper under cover	1	\$355.20		?
11	Rear bumper under cover LH <i>Sm</i>	1	\$187.60		X
12	Rear bumper under cover RH	1	\$187.60		?
13	Rear bumper under cover clip	4	\$14.00		?
14	Tail door <i>R</i>	1	\$1,122.50		X
15	Tail door lock <i>R</i>	1	\$487.70		X
16	Tail door emblem <i>Am</i>	1	\$61.70		✓
17	Wording "PRIUS" <i>Am</i>	1	\$51.90		✓
18	Wording "HYBRID" <i>Am</i>	1	\$55.47		✓
19	Tail door plate garnish	1	\$782.50		?
20	Tail door inner trim <i>Sm</i>	1	\$278.90		X
21	Tail door inner trim clip <i>Am</i>	10	\$28.00		X
22	Tail end panel	1	\$596.60		?
23	Tail end panel garnish	1	\$151.60		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLS 8798 L**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU603571828**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip	10	\$35.00		?
25	Boot weatherstrip <i>Sn</i>	1	\$353.10		X
26	Spare tyre well panel <i>R</i>	1	\$793.15		X
27	Spare tyre board <i>Sn</i>	1	\$566.79		X
28	Spare tyre compartment sponge LH <i>Sn</i>	1	\$297.67		X
29	Spare tyre compartment sponge RH <i>Sn</i>	1	\$297.67		X
30	Tail lamp RH - UPPER <i>CM</i>	1	\$498.75		✓
31	Tail lamp RH - LOWER	1	\$511.60		?
32	Taildoor glass sealant <i>Ag Sn</i>	1	\$50.00	S.N	X
33	Rear windscreen moulding <i>Sn</i>	1	\$97.70		X
34	Rear windscreen sealant <i>Sn</i>	1	\$50.00	S.N	X
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLS 8798 L** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER)	\$1,400.00	?
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER)	\$1,400.00	700
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat	\$200.00	?
6	To remove & refit rear windscreen. <i>nn</i>	\$120.00	X
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
8	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
9	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
10	To remove & refit Taildoor glass to assist work load <i>nn</i>	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.