



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259; 569538.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

pair Estimates

SLS 8798 L

Finalised

Cost / List Price Items	\$3763.42	9,738.50
Plus/Less 25%	\$815.86	2,434.63
Total of Cost / List	\$2447.56	7,303.88
Nett Price Items		
Less		
Total of Nett Item		
Special Nett Items	\$ 200.00	300.00
Cost	\$2647.56	7,603.88
	\$ 1690	3,800.00
	\$4337.56	11,403.88

Not authorized
1.2.1
Resony B&Palm

83977.56 ✓ Ok

total will be subjected to 7% G.S.T.

f Surveyor

ly

conducted on

s By Surveyor

repair of this vehicle is authorized / is not authorized until further notice.

commended Days of Repair : 4-6 4 day(s)

survey : Required / Not Required

ess

nature of surveyor

Le

Date:

25/9/18



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Car Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLS 8798 L

TOYOTA PRIUS

JTDKB3FU603571828

Submit By :

Carmen Lim

Year Manufacture :

2017

Engine No. :

Cost / List

No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	✓ S.N	✓
2	Rear bumper	1	\$497.50	✓	✓
3	Rear bumper clip	10	\$40.00	✓	✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70	✓	✓
6	Rear bumper reinforcement	1	\$398.90	✓	✓
7	Rear bumper lower garnish centre	1	\$582.60	✓	✓
8	Rear bumper lower garnish RH	1	\$149.70	✓	✓
9	Rear bumper tow cover	1	\$31.70	✓	✓
10	Rear bumper under cover	1	\$355.20		X
11	Rear bumper under cover LH	1	\$187.60		X
12	Rear bumper under cover RH	1	\$187.60		X
13	Rear bumper under cover clip	4	\$14.00		X
14	Tail door	1	\$1,122.50		X
15	Tail door lock	1	\$487.70		X
16	Tail door emblem	1	\$61.70	✓	✓
17	Wording "PRIUS"	1	\$51.90	✓	✓
18	Wording "HYBRID"	1	\$55.47	✓	✓
19	Tail door plate garnish	1	\$782.50	✓	✓
20	Tail door inner trim	1	\$278.90		X
21	Tail door inner trim clip	10	\$28.00		X
22	Tail end panel	1	\$596.60		X
23	Tail end panel garnish	1	\$151.60		X

If any of the quoted parts are recommended to be repaired, then an additional labour charge

is charged accordingly under supplementary.

5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829

SN 200.00

Company Reg No. 200005485N / GST No. 20-0005485-N

2764.67
200(S.N)

Spare Parts

Vehicle No. :

SLS 8798 L

Submit By :

Carmen Lim

Make & Model :

TOYOTA PRIUS

Year Manufacture :

2017

Chassis No. :

JTDKB3FU603571828

Engine No. :

Cost / List

No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip <i>nn</i>	10	\$35.00		<i>X</i>
25	Boot weatherstrip <i>sn</i>	1	\$353.10		<i>X</i>
26	Spare tyre well panel <i>n</i>	1	\$793.15		<i>X</i>
27	Spare tyre board <i>sn</i>	1	\$566.79		<i>X</i>
28	Spare tyre compartment sponge LH <i>sn</i>	1	\$297.67		<i>X</i>
29	Spare tyre compartment sponge RH <i>sn</i>	1	\$297.67		<i>X</i>
30	Tail lamp RH - UPPER <i>cm</i>	1	\$498.75	<i>✓</i>	<i>✓</i>
31	Tail lamp RH - LOWER <i>sn</i>	1	\$511.60		<i>X</i>
32	Taildoor glass sealant <i>Reg Un</i>	1	\$50.00	S.N	<i>X</i>
33	Rear windscreen moulding <i>un</i>	1	\$97.70		<i>X</i>
34	Rear windscreen sealant <i>un</i>	1	\$50.00	S.N	<i>X</i>
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

498.75



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLS 8798 L** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER)	\$1,400.00	9500 8000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER)	\$1,400.00	700
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat	\$200.00	X
6	To remove & refit rear windscreen. ~ ~	\$120.00	X
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
8	To transfer boot mechanism to new boot ~ ~	\$120.00	X
9	To conduct water leakage tests to ensure proper air and sealing ~ ~	\$120.00	X
10	To remove & refit Taildoor glass to assist work load ~ ~	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.