

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05851

Vehicle Insured : YM 8764L

Accident Date : 19-Sep-2018

Date : 21-Sep-2018

Our Ref : 218156 (AXA) / CHAN

PAGE : 1

SINGAPORE ENGINEERING SERVICES PTE LTD  
32 ANG MO KIO IND. PARK 2  
#05-03, SING INDUSTRIAL COMPLEX  
Singapore 569510

*Not Authorised*  
*11 Sep 87*  
*3 days*

## ESTIMATED COST OF REPAIR FOR ISUZU NNR85UH4A YN286Y

1 pc	Front o/s door	1,760.00	✓
1 pc	Front o/s door rubber	275.00	✓
1 pc	Front o/s door inner lock	245.00	✓
1 pc	Front o/s door outer handle	155.00	✓
1 pc	Front o/s door glass regulator gear	340.00	✓
1 pc	Front o/s door outer moulding	127.00	✓
1 pc	Front o/s door lower garnish	182.00	✓
2 pcs	Front o/s door hinge	376.00	✓
1 pc	Front o/s door checker	122.00	✓
1 pc	Front o/s door protector	95.00	✓
		3,677.00	
		Less 15% :	551.55

1 pc Front o/s door company logo

3,125.45 *1200*  
180.00 *sn*

To putty and spray replaced parts

500.00 *3200*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

400.00 *2500*

Total : S\$ 4,205.45

Singapore Dollars Four Thousand Two Hundred and  
Five and Cents Forty Five Only

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: