

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05851

Vehicle Insured : YM 8764L
Accident Date : 19-Sep-2018

Date : 21-Sep-2018

Our Ref : 218156 (AXA) / CHAN

PAGE : 1

SINGAPORE ENGINEERING SERVICES PTE LTD
32 ANG MO KIO IND. PARK 2
#05-03, SING INDUSTRIAL COMPLEX
Singapore 569510

Not Authorised
1/10/18
3 days

ESTIMATED COST OF REPAIR FOR ISUZU NNR85UH4A YN286Y

1 pc Front o/s door
1 pc Front o/s door rubber
1 pc Front o/s door inner lock
1 pc Front o/s door outer handle
1 pc Front o/s door glass regulator gear
1 pc Front o/s door outer moulding
1 pc Front o/s door lower garnish
2 pcs Front o/s door hinge
1 pc Front o/s door checker
1 pc Front o/s door protector

Bu	1,760.00	✓
au	275.00	X
n	245.00	X
pi	155.00	✓
PTS	340.00	✓
Sn	127.00	X
Bu	182.00	✓
B1	376.00	✓
Sn	122.00	X
na	95.00	✓
	3,677.00	
Less 15% :	551.55	

1 pc Front o/s door company logo

3,125.45
120.00

To putty and spray replaced parts

500.00
32.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00
25.00

Total : S\$ 4,205.45

Singapore Dollars Four Thousand Two Hundred and
Five and Cents Forty Five Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: