



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLG9700AMake & Model : HONDA SHUTTLE HYB 1.5AYear of Manufacture : 2016Chassis No. : GP71043757Ins Company : AIG / AXA

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 20/09/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ 4,774.00Plus/Less 20% \$ 954.80Total of Cost / List \$ 3,819.20(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 390.00Total Parts Cost (Appendix A) \$ 4,209.20Labour (Appendix B) \$ 3,760.00Total Repair Cost \$ 7,969.20

Contact No

Frt Counter Operation

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

braddell_operation@sparkcarcare.com

*Not Authorized
I.B.I
Resurvey By repair*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : CLK
 Survey conducted on : 24/9/18 at _____

Remarks By Surveyor(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 07 day(s)(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 24/9/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLG9700A Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB 1.0 Year Manufacture : 2016

Chassis No : GP71043757 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	RH rear door	1	<i>B1</i>	\$ 2,304.00			✓
2	RH rear door weatherstrip upper	1		\$ 112.50			?
3	RH rear door weatherstrip side	1					
4	RH rear door weatherstrip lower	1					
5	RH rear door hinge upper	1	<i>R</i>	\$ 42.20			X
6	RH rear door hinge lower	1	<i>R</i>	\$ 42.20			X
7	RH rear door window frame black sticker	1	<i>M</i>	\$ 32.10			✓
8	RH rear door lock	1	<i>R</i>	\$ 211.50			X
9	RH rocker panel garnish	1	<i>Od/O11</i>	\$ 393.50			✓
10	RH rear fender	1	<i>B1</i>	\$ 920.10			✓
11	RH rear fender glass moulding upper	1	<i>M</i>	\$ 30.10			✓
12	RH rear fender glass moulding lower	1	<i>M</i>	\$ 55.00			✓
13	RH rear fender glass moulding LH	1	<i>M</i>	\$ 45.80			✓
14	RH rear fender glass sealant	1			<i>M</i> \$ 40.00		✓
15	RH rear fender glass inner seal	1			<i>M</i> \$ 30.00		✓
16	RH rear rim cover	1	<i>Od</i>	\$ 195.00			✓
17	RH rear rim	1		\$ 390.00			?
18	RH rear tyre (PIRELLI CINTURATO P1)	1				\$ 320.00	?
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.