



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2006362  
INV Date 15/09/2020  
Reference CC4/EQI18017456/Gga3s2  
Code EQI



#### PROFESSIONAL SERVICE FEE

Vehicle No. FBD 8962B  
Insured Veh. SGW 5285H  
Claim No. DM18HO01437  
Policy No. DMPPHQ17-003567  
Accident Date 06/06/2018  
Inspection Date 25/09/2018

Description	Total
Survey Inspection	160.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

Your Ref : DM18HO01437

Date: 15<sup>th</sup> September 2020

Our Ref : CC4/EQI18017456/Gga3s2

**M/s EQ Insurance Company Ltd**5 Maxwell Road  
#17-00 Tower Block  
MND Complex  
Singapore 069110

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBD 8962B  
INSURED VEHICLE SGW 5285H ACCIDENT ON 06/06/2018**

Instruction was received to inspect the vehicle Reg. No. FBD 8962B. The inspection was conducted on 25/09/2018 at the premises of M/s Pan Euro Bikes Pte Ltd, 21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462.

The following vehicle information was recorded:

Registration Number : FBD 8962B  
Make/Model : Yamaha YBR125  
Year of Registration : 2008  
Body Colour : Grey  
Chassis Number : LBPKE128090035545  
Engine Capacity : 124 cc  
Speedometer Reading : 97656 km

The following are our comments:-

- (a) The vehicle sustained damages at the front and rear portion and o/s body. The chassis frame affected due to collision. (Details see photographs enclosed)
- (b) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989**, that:  
*no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle.*  
and we therefore recommend it to be written off as **“Total Loss”**



Market Value	S\$ 1,610.00
Less: LTA Reimbursement Value (RV)	(S\$ 110.00)
Nett Liability	<u>S\$ 1,500.00</u> =====

Vehicle Inspected By:

**XING GUO QIANG**  
*M.MATAI, AMSAE-A*  
*Automotive Assessor*

**K.K.LAU**  
*MSc(Eng M), B Eng(Hons), Peng(UK),*  
*MASME(USA), B Bus(Aust),MBA(UK),*  
*IEng(UK), MIIE(mech), MinstAEA, MFIEA,*  
*MIRTE, MIMI,MSAE,MCIAd, AM,NIIAAR(USA),*  
*AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),*  
*Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBD 8962B

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

