

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 9806S

Mudy
AAD1809-172

*Not Not raised
 21 Sep @ 1200h*

Vehicle No.:	SHD 9806S
Chassis No.:	VF1ABL15AUC277371
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	18.9.2018
Third Party Insurer :	AIG

PART	LIST
1 BUMPER COVER FRT	\$ R 1,259.42
1 BUMPER SPOILER FRT	\$ S 181.75
1 BUMPER ABSORBER FRT	\$ S 394.68
1 BUMPER RETAINER FRT LH	\$ S 151.41
1 BUMPER SUPPORT FRT	\$ S 123.88
1 BUMPER RETAINER FRT RH	\$ S 150.77
1 BUMPER SUPPORT FRT	\$ S 123.88
1 BUMPER UNDERTRAY FRT	\$ S 472.83
1 BUMPER GRILLE LOWER FRT	\$ S 266.80
1 BUMPER FOG LAMP GRILLE LH	\$ S 207.21
1 BUMPER BEAM FRT	\$ R 914.08
1 HEADLAMP LH	\$ S 1,184.43
1 HEADLAMP PANEL FRT LH	\$ R 152.15
1 FENDER PANEL FRT LH	\$ R 783.83
1 WHEELARCH FRT LH	\$ S 278.84
1 FENDER BRACKET LOWER LH	\$ S 15.79
1 FENDER INSULATOR LH	\$ S 130.84
1 DOOR PANEL FRT LH	\$ R 2,844.66
1 RADIATOR GRILLE	\$ S 1,707.78
1 RADIATOR GRILLE BADGE 'RENAULT'	\$ S 225.36
1 RADIATOR GRILLE FRAME	\$ S 1,353.75
1 RADIATOR FAN COWLING	\$ S 820.54
1 RADIATOR FAN MOTOR LH	\$ S 967.36
1 RADIATOR FAN MOTOR RH	\$ S 1,479.46
1 RADIATOR GRILLE FRAME	\$ S 1,353.75
1 FRAME FULL SUPPORT PANEL	\$ S 615.90
1 FRAME FULL SUPPORT BRACKET	\$ R 89.79
1 AIR CLEANER BOX	\$ S 464.20
1 AIR CLEANER HOSE	\$ S 175.85

X

X

Trans-cab Auto Services Pte Ltd

AAD1809-172

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9806S

1	LOWER ARM LH L70Y	\$	<i>Sh</i> 685.76 X
1	KUNCKLE ARM LH L70Y	\$	<i>Sh</i> 846.98 X
1	ABSORBER FRT LH L70Y	\$	<i>Sh</i> 360.54 X

TOTAL	\$	20,784.28
10%	\$	2,078.43
	\$	18,705.85

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>na</i> 66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i> 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i> 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i> 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i> 30.00	
1SET	WHEELARCH CLIP FRT RH	\$	<i>na</i> 30.50	
1	FRONT LEFT TYRE	\$	<i>Sh</i> 300.00	
1	FRONT LEFT TYRE RIM	\$	<i>Sh</i> 380.00	
		\$	988.00	

TOTAL PARTS	\$	19,693.85
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00 <i>3000</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>4400</i>
To rust-proofing of the affected areas.	\$	170.00 <i>300</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1809-172

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 98065

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>15/</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00	X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
TOTAL	\$	9,090.00	
Over All Total	\$	28,783.85	

LUMP SUM (REPAIR DAY)*10 DAYS**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: