

ASS. REC. BY:

REF

CS/ASM/8017460/71qdz<sup>52</sup>

Special Instruction:

Surveyor

Tau Jitah

ASSIGNMENT (Office)

From (Person):

Lynn Khong

of

ASM (AXA)

Date/Time:

25/09/2018

Estimated Cost:

Bill to:

① / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDV 88864

Insured:

at Workshop in/

cycle &amp; Carriage Ind.

Tel:

8332 0062

of

188 Pandan Loop.

Policy No:

Claim No:

88M000WMP

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 22/09/18

② / REV / REP. / REV 24 HRS

26/9/18 @ Morning

H.O.D. Endorsement:

Date/Time:

4.40pm @ 25/9/18

Person Contacted:

Vincent

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SDV 88864 - X

12/9/18 @

5.28pm revised to Lynn Khong via Smart Claim.

14/12/18 @

11.42am and revised to Lynn Khong via Smart Claim. (Supplementary)

17/1/19 @

4.36pm Lynn Khong informed can proceed Supplementary via Smart Claim. She also have mentioned that informed wksp to submit their supplementary listing during re-inspection for marking. Although taking photos do not conclude anything on quantum. They may consider not to

Tanpin

REF:

ASM (AXA)

ASSIGNMENT

From:

Date:

26/1/18

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

SDV 88864

at Workshop m/s

of

Cycle & Carriage Ind.  
188 Pandan Loop

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

\$500.00

(Client's Record)

Moring

Make of Veh:

Vincent @ 833 20062

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$108K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT  
Vincent

Veh No

SDV 88864

Yr Regn

2015 Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz C180 AMG

1595

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD208402R028594

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50 R17

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

26/1/18 @ 1345

Survey held at

C&C Pandan Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No Batching

pay for the supplementary

Marked: \$66,207

since not approved in advance. Do not take this as future precedent.

12/1/19 @ 5.33pm confirmed with Vincent final fig \$22575.40, 8 days.

Used \$9773.58, 30/1/19

RECEIVED 21 FEB 2019

Date/Time, File Pass to?

☐

: Preli. Report

12/1/2 for m/s

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

1

Survey Fee:

300

Transportation:

\$ + RS. SI

Photos:

Others:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

Smart Claims

Lump Sum / I.B.I. (\$

22575.40

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18017460/T1qd3

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 25-09-2018



Code : ASM

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SDV 8886U
Policy No.	Coverage (\$)	0.00
Claim No. S8M00WMP	Excess (\$)	500.00
Assign From SMARTCLAIM (LYNN KHONG)	Assign Date	25/09/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date 22/09/2018	Inspection Date
Survey held at CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)	

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

## ◀ Service Request Details

Claim

S8M00WMP

Reference

None ✎

Loss Date

September 22, 2018

Request Date

September 25, 2018

Due Date

October 2, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SDV8886U

Make

MERCEDES

Model

C180 BLUE EFFICIENCY

Service Address

...

Primary Contact/Insured

ONG GEOK LAN LANDY

16 ANG MO KIO CENTRAL 3, #12-25 GRANDEUR 8, 567748, Singapore

96818886

LANDY.PANCAKE@GMAIL.COM

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Additional Instructions

C&amp;C (Pandan) OD EXCESS \$500 (unnamed)

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

## KUMAR Shailendra

---

**From:** Vincent Seah Yong Kuan <vincent.seah@cyclecarriage.com.sg>  
**Sent:** Monday, September 24, 2018 6:57 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** SDV8886U- OD CLAIM - SURVEY  
**Attachments:** img-924185234-0001.pdf, SAS2476984.PDF

**Categories:** Shailendra

Hi

Kindly arrange survey tomorrow

Vehicle in our premises

OD CLAIM

Tks

Vincent Seah  
Cycle & Carriage Ind. Pte Limited  
Body Care & Repair - Pandan Loop Service Center  
188 Pandan Loop Singapore 128378  
Tel : 83320062 ( H/P ) DID: 6771 4401  
Fax.: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 17 January 2019 5:33 PM  
**To:** 'Vincent Seah'  
**Cc:** Cheong Chin Leong; 'Yik Chan Hoe'  
**Subject:** RE: KINDLY ASSIST TO FINALISE OF VEHICLES

Dear Vincent,

WITHOUT PREJUDICE

Confirm final fig \$22,575.40 before excess \$500.00 & GST and 8 repair days.

Kindly send the relevant documents to AXA Insurance company.

**Please take note from insurance comment/instruction: "Please submit supplementary list during re-inspection for marking, although have taking photos do not conclude anything on quantum. We may consider not to pay for the supplementary since not approved in advance. Do not take this as future precedent."**

Best Regards,

**Shiau Chan (Ms) | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Vincent Seah <[vincent.seah@cyclecarriage.com.sg](mailto:vincent.seah@cyclecarriage.com.sg)>  
**Sent:** Friday, 30 November 2018 6:05 PM  
**To:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Subject:** RE: KINDLY ASSIST TO FINALISE OF VEHICLES

Evening Shiau

Finalize

Vincent Seah  
Cycle & Carriage Ind. Pte Limited  
Body Care & Repair - Pandan Loop Service Center  
188 Pandan Loop Singapore 128378  
Tel : 83320062 ( H/P ) DID: 6771 4401  
Fax.: 6872 1272

---

**From:** Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]  
**Sent:** Friday, 30 November 2018 3:52 PM  
**To:** Vincent Seah <[vincent.seah@cyclecarriage.com.sg](mailto:vincent.seah@cyclecarriage.com.sg)>; Yik Chan Hoe <[chanhoe.yik@cyclecarriage.com.sg](mailto:chanhoe.yik@cyclecarriage.com.sg)>  
**Subject:** KINDLY ASSIST TO FINALISE OF VEHICLES

Dear Sir,

Kindly advise the status of below vehicles.



## 2ND IA OF VEHICLE SDV 8886U UPLOADED | Noted to proceed

Type

Question

Message

Hi Shiau Chan, Kindly inform C&C to submit their supplementary listing during re-inspection for marking. Taking photos do not conclude anything on quantum. We may consider not to pay for the supplementary since not approved in advance. Do not take this as future precedent. Thanks

Reply





## RE: Re:2ND IA OF VEHICLE SDV 8886U UPLOADED

Type

🔔 Question

Message

Dear Lynn, the supplementary was put up attached together with the final bill which was received on 30th November 2018. The surveyor had inspected the damaged items before they put supplementary. - Shiau Chan

Reply



## Re:2ND IA OF VEHICLE SDV 8886U UPLOADED

Type

❏ Question

Message

Hi Shiau Chan, for this supplementary, was it put up only recently and has workshop informed our surveyor to inspect before any repair / replacement. Thanks

*was*

*Workshop did inform our surveyor to remove the car for the supplementary items*

Reply

*attached*

*The supplementary was put up together with the final bill which was received ~~recently~~ on 30th Nov 2018.*

*The surveyor had inspected the damaged ~~supplementary~~ items before they put the supplementary*



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/12/18

### Survey Details:

Date of loss	22-Sep-18
Date of appointment	25-Sep-18
Date of survey	26-Sep-18
Location of survey	CYCLE & CARRIAGE (PANDAN LOOP)

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SDV 8886U
Make and Model	MERCEDES C180 AVANTGARDE
Date of registration	11/2/2015
Excess	\$ 500.00
Market Value	\$ 108,000.00
Parf Rebate	\$ 66,188.00
Nett Loss	\$ 41,812.00

### Repair details:

Initial Estimate	\$ 32,348.98	(ESTIMATE \$30,232.18 + SUPP \$2,116.80)
------------------	--------------	---

### Proposed/Revised repair cost:

Parts	\$ 15,625.40
Check items (estimate)	\$ -
Labour	\$ 6,950.00
<b>Total</b>	<b>\$ 22,575.40</b>
Lump Sum(if applicable)	-

Number of days for repair	<u>8</u>
---------------------------	----------



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.  
KINDLY APPROVE ON SUPPLEMENTARY.

**Mandate:**

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



## IA OF VEHICLE SDV 8886U UPLOADED

Type

🔗 Question

Message

Dear Lynn, please be informed that IA of vehicle SDV 8886U uploaded. Damages consistent. Repair cost economical. We have authorise repair. - Shiau Chan

Reply



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 27/09/18

### Survey Details:

Date of loss	22-Sep-18
Date of appointment	25-Sep-18
Date of survey	26-Sep-18
Location of survey	CYCLE & CARRIAGE (PANDAN LOOP)

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SDV 8886U
Make and Model	MERCEDES C180 AVANTGARDE
Date of registration	11/2/2015
Excess	\$ 500.00
Market Value	\$ 108,000.00
Parf Rebate	\$ 66,188.00
Nett Loss	\$ 41,812.00

### Repair details:

Initial Estimate	\$ 30,232.18
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 11,571.70
Check items (estimate)	\$ 8,266.57
Labour	\$ 6,950.00
<b>Total</b>	<b>\$ 26,788.27</b>
Lump Sum(if applicable)	-

Number of days for repair	<u>8</u>
---------------------------	----------



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE  
HAVE AUTHORISE REPAIR.

**Mandate:**

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
<b>Proposed Total</b>	<b>#VALUE!</b>	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/09/2018 15:05
Date Of Accident	22/09/2018 18:55
Exact Location Of Accident	JCT OF TELOK BLANGAH RD TWDS BT. CHERMIN RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDV8886U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG GEOK LAN LANDY
NRIC No	S1754553A
Email Address	LANDY.PANCAKE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96818886
Alternative Phone No	OFFICE-96818886

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA056815/1
Cover Note Number	

### Driver

Name of Driver	LIM CHIN TONG
NRIC No	S1651980D
Date Of Birth	23/11/1964
Occupation	INDOOR
Date Of Driving Pass	29/12/1983
Driving Experience	34 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96818866
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	16 ANG MO KIO CENTRAL 3 #12-25
Postcode	567748
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ONG GEOK LAN, LANDY GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ACCIDENT HAPPENED ON 22 SEP 2018 AT APPROXIMATELY 6.55PM ALONG TELOK BLANGAH ROAD AT THE YELLOW BOX WHILE WE WERE TURNING RIGHT INTO BT CHERMIN ROAD. IT IS A 4 LANE RD AND FRONT 3 LANES STOPPED TO LET US TURN RIGHT BUT THE TAXI ON THE FOURTH LANE WENT STRAIGHT AHEAD THUS WE KNOCKED ONTO THE RIGHT SIDE OF HIS CAR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC5316X
Vehicle Make/Model/Colour	TRANSCAB RED
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	MOHD KEMARUDIN BINWAHID
NRIC/Passport Number	S2020506G
Contact Number	
Address	
Postcode	
Insurance Company Name	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time 24.09.18 14:00PM

Driver's Signature

(If driver is not the policyholder)

Date & Time 24.09.18 14:00PM

Reporting Centre


Name:

NRIC/FIN No.:

Vincent Seah  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 671 4401 HP: 8332 0022 Fax: 6872 1272  
Email: vincent.seah@cyclecarriage.com

SKETCH PLAN

A: SDV 88864  
B: SAC 5316X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Accident happened on 22/9/18 at approx. 6.55pm along Telok Blangah road at the <sup>yellow</sup> box while we were turning right into Bt Chermin ~~road~~ road. It is a 4 lane road and first 3 lanes stopped to let us turn right but the taxi on the fourth lane went straight ahead thus we knocked onto the right side of his vehicle.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

  
Policyholder's Signature  
Date & Time 24.09.18 14:00PM

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time 24.09.18 14:00PM

  
Reporting Centre Person  
Name:  
NRIC/FIN No.:  
DID: 6771 4401  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
HP: 8332 0062 Fax: 682 1272  
Email: vincent.seah@cyclcarriage.com.sg

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4553A
Vehicle Details	
Vehicle No.:	SDV8886U
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Sep 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	27491030318343
Chassis No.:	WDD2050402R038594
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$32,861.00
Original Registration Date:	11 Feb 2015
First Registration Date:	11 Feb 2015
Transfer Count:	1
Actual ARF Paid:	\$28,006.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Feb 2025
PARF Rebate Amount:	\$21,004.00
Intended COE Rebate Details	
COE Expiry Date:	10 Feb 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$45,184.00
<b>Total Rebate Amount:</b>	<b>\$66,188.00</b>

The information contained herein is correct as at 27 Sep 2018

OK



redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)

(65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

account number

04570

## Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)  
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

### Policy details

Policyholder name	ONG GEOK LAN LANDY	Certificate number	GA056815 / 1
Cover	Comprehensive	Chassis number	WDD2050402R038594
Plan name	Flexi+	Engine number	27491030318343
NCD applicable	50%		
Vehicle registration number	SDV8886U		
Period of Insurance	from 11/02/2018 to 10/02/2019 (both dates inclusive)		
Finance loan company	Nil		

### Persons or classes of persons entitled to drive\*

- (a) The Policyholder
- (b) Any Named Driver as stated in the Policy:
  - 1. LIM LIANG CHIN
- (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

\* Limitations rendered inoperative by Section B of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

#### EXCESS

Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

### Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

### Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).  
The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.



4137858



NRIC No. S1754553A

Date of issue  
29-11-2007Address  
16 ANG MO KIO CENTRAL 3  
#12-25  
SINGAPORE 567748

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars &lt;= 3000kg with &lt;= 7 passengers, &lt;= 2 of the driver; and other motor vehicles, &lt;= 25

29-12-1983

NP 428A



Licence No: S1651980D

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1754553A



Name

ONG GEOK LAN, LANDY

王 玉 兰

Race

CHINESE

Date of birth

04-07-1966

Sex

F

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S1651980D

Name

LIM CHIN TONG

Birth Date 23 Nov 1964

Issue Date 06 May 2010



001853011J





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SDV8886U

Ms Ong Geok Lan, Landy

16 Ang Mo Kio Central 3  
#12-25  
Singapore 567748

Mobile: 96818886

## Vehicle &amp; Document Information

WIP No 27087  
Reg No/Reg Date SDV8886U / 11/02/2015  
Date In/Mileage / 0  
Chassis No WDD2050402R038594  
Engine No 27491030318343  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 028 890 Cavansit Bl/ 041 115 Pebble

Account No	Terms	Date/Time Printed	CSE	Operator				
CSI00001	Cash	24/09/2018/ 18:43	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : GA056815/1 // 22.09.18 TOW IN/EXCESS : 23.09.18 // DATE IN/DATE SURVEY: 23.09.18 BY/AUTHORIZED ON :								150.00
S BPNTOW ACCIDENT TOWING FROM 16 ANG MO KIO CENTRAL 3 TO PLSC USING KING DOLLEY WO: 153757								380.00
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT					0.10			120.00
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT								600.00
A BPILAB REMOVE AND REPLACE RADIATOR COOLING SYSTEM , CONDENSER WITH VACUUM AND RECHARGE REFRIGERANT. NETT								60.00
S BPNSUB SUPPLY 1PCS NUMBER PLATE WITH HOUSING. NETT								1000.00
A BPILAB PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT					0.07			540.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT								1920.00
A BPILAB REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE								4800.00
A BPILAB DISASSEMBLE AND REPLACE ON FRONT BUMPER, BONNET, RH/LHF FENDER , FRONT SUPPORT PANEL								3000.00
A BPIRES RESPRAY ON FRONT BUMPER, RH/LH FRONT FENDER , BONNET								881.86
M LEFT FRONT FENDER					1.00	881.86	00.00	881.86

Confirmed &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SDV8886U

Ms Ong Geok Lan, Landy

16 Ang Mo Kio Central 3  
#12-25  
Singapore 567748

Mobile: 96818886

## Vehicle &amp; Document Information

WIP No 27087  
Reg No/Reg Date SDV8886U / 11/02/2015  
Date In/Mileage / 0  
Chassis No WDD2050402R038594  
Engine No 27491030318343  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 028 890 Cavansit B1/ 041 115 Pebble

Account No	Terms	Date/Time Printed	CSE	Operator	
CSI00001	Cash	24/09/2018/ 18:43	VS	356 / Vincent Seah	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M RIGHT FRONT FENDER		1.00	881.86	00.00	881.86
M RHF FENDER OUTER LINEAR		1.00	120.19	00.00	120.19
M FRONT BUMPER		1.00	1506.37	00.00	1506.37
M FRONT BUMPER CENTRE CHROME MOULDING		1.00	172.64	00.00	172.64
M FRONT BUMPER LOWER GRILLE		1.00	120.86	00.00	120.86
M LICENSE PLATE MOLDING		1.00	120.86	00.00	120.86
M LHF INNER FOGLAMP COVER		1.00	75.40	00.00	75.40
M LHF FOGLAMP COVER		1.00	75.40	00.00	75.40
M LEFT FOGLAMP BOTTOM ORNAMENTAL MOLDING		1.00	54.36	00.00	54.36
M TOP LEFT FOGLAMP ORNAMENTAL MOLDING		1.00	65.23	00.00	65.23
M LEFT BASIC MOUNTING FOR BUMPER		1.00	68.53	00.00	68.53
M RIGHT BASIC MOUNTING FOR BUMPER		1.00	68.53	00.00	68.53
M BOTTOM BASIC MOUNTING FOR BUMPER		1.00	102.80	00.00	102.80
M LHF MOUNTING RAIL		1.00	11.22	00.00	11.22
M RHF MOUNTING RAIL		1.00	11.22	00.00	11.22
M TOP BASIC MOUNTING FOR BUMPER		1.00	63.42	00.00	63.42
M IMPACT ABSORBER		1.00	149.56	00.00	149.56
M PRESSURE SENSOR		1.00	182.62	00.00	182.62
M IMPACT ABSORBER		1.00	149.56	00.00	149.56
M SEALING FRONT END		1.00	23.59	00.00	23.59
M HOOD		1.00	1999.27	00.00	1999.27
M COMPANY SIGN		1.00	78.83	00.00	78.83
M BONNET CATCH		2.00	32.77	00.00	65.54
M SPRING ELEMENT		2.00	29.91	00.00	59.82
M RETAINING HOOK		1.00	64.63	00.00	64.63
M AIR DUCT		1.00	125.66	00.00	125.66
M RAD. PROTECTIVE GRILLE		1.00	130.01	00.00	130.01
M RADIATOR GRILLE BEAM		1.00	205.32	00.00	205.32
M TOP LEFT ORNAMENTAL MOLDING		1.00	60.43	00.00	60.43
M BOTTOM LEFT ORNAMENTAL MOLDING		1.00	74.70	00.00	74.70
M TOP RIGHT ORNAMENTAL MOLDING		1.00	60.43	00.00	60.43
M BOTTOM RIGHT ORNAMENTAL MOLDING		1.00	74.70	00.00	74.70
M STAR BEAM		1.00	72.06	00.00	72.06

Confirmed &amp; accepted by

7095.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SDV8886U

Ms Ong Geok Lan, Landy

16 Ang Mo Kio Central 3  
#12-25  
Singapore 567748

Mobile: 96818886

WIP No  
Reg No/Reg Date  
Date In/Mileage  
Chassis No  
Engine No  
Make/Model  
Colour/Trim

## Vehicle & Document Information

27087  
SDV8886U / 11/02/2015  
/ 0  
WDD2050402R038594  
27491030318343  
MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
028 890 Cavansit B1/ 041 115 Pebble

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	24/09/2018/ 18:43	VS	356 / Vincent Seah
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount
M MERCEDES STAR	1.00	130.65	00.00	130.65
M CROSS MEMBER	1.00	407.90	00.00	407.90
M FRONT SUPPORT CONSOLE	1.00	202.17	00.00	202.17
M LEFT BRACKET	1.00	67.58	00.00	67.58
M RIGHT BRACKET	1.00	65.64	00.00	65.64
M U-SHAPED STRIKER	1.00	74.16	00.00	74.16
M LEFT HEADLAMP UNIT	1.00	3126.25	00.00	3126.25
M RIGHT HEADLAMP UNIT	1.00	3126.25	00.00	3126.25
M LEFT HEADLIGHT CONTROL UNIT	1.00	571.36	00.00	571.36
M FRONT SUPPORT PANEL	1.00	691.68	00.00	691.68
M RADIATOR	1.00	948.39	00.00	948.39
M BOTTOM AIR DUCT SEGMENT	1.00	167.52	00.00	167.52
M AIR DUCT FOR RADIATOR	1.00	64.59	00.00	64.59
M TOP COLD AIR INDUCTION	1.00	40.56	00.00	40.56

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taylor 97495749  
26/9/18 R 1345  
Authorised  
Ex \$500  
surellkauto.com  
\*Resurvey for supplementary items  
for Insurance approval  
Soleys

Confirmed & accepted by

Authorized signatory and company stamp

7% GST on 30232.18  
Nett 30,232.18  
2116.25

Total Payable 32,348.43

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SDV8886U

Ms Ong Geok Lan, Landy

16 Ang Mo Kio Central 3  
#12-25  
Singapore 567748

### Vehicle & Document Information

WIP No 27087  
Reg No/Reg Date SDV8886U / 11/02/2015  
Date In/Mileage 26/09/2018/ 52719  
Chassis No WDD2050402R038594  
Engine No 27491030318343  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 028 890 Cavansit B1/ 041 115 Pebble

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	30/11/2018/ 17:59		356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M. BPNSUN

POLICY NO/ACC DATE : GA056815/1 // 22.09.18  
TOW IN/EXCESS : 23.09.18 // \$500  
DATE IN/DATE SURVEY: 23.09.18// 26.09.18 TAUFIKH=LKK 14:00PM  
BY/AUTHORIZED ON : TAUFIKH=LKK // 26.09.18

- X ELECTRICAL WIRING HARNESS
- X DISTANCE SENSOR
- X SPACER RING
- X COVER F ENGINE COMP. BM
- X DISTANCE SENSOR
- X [STR] REFRIGERANT CONDENSER
- X FIXTURE

1.00	128.55	00.00	cut	128.55
1.00	172.07	00.00	dog	172.07
2.00	6.42	00.00	ole	12.84
1.00	181.26	00.00	Ch	181.26
1.00	172.07	00.00	pel	172.07
1.00	1428.90	00.00	bt	1428.90
1.00	21.11	00.00	re	21.11

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 2,116.80**  
2116.80 **148.18**

**Total Payable 2,264.98**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz, the registered trademark of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg