



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: MS TAN MAY YENG JENNY ADDRESS: 2B JALAN BINCHANG SINGAPORE 574031 TEL: 97857805		WIP: 22312 EXCESS: DATE: 24-Sep-18	
VEH NO:	SLE5663K	DATE IN:		CONTACT PERSON:	JOB THOMAS 6331 0682
CHASSIS NO:	WMWXS720402C51817	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MINI COOPER F55	DATE REG.:	27-Jul-16	POLICY NO.:	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	TRIM RING LH	1	M51.13.7.300.631	net ✓	\$ 68.38
2	TRIM RING RH	1	M51.13.7.300.632	net ✓	\$ 68.38
3	MINI EMBLEM	1	M51.14.7.316.703	net ✓	\$ 73.88
4	BONNET AIR SCOOP	1	M51.13.7.376.052	net ✓	\$ 134.00
5	FRONT BUMPER LOWER SPOILER LH	1	M51.11.7.337.813	cut ✓	\$ 86.19
6	SPORT RIM	1	M36.11.6.855.111	cut ✓	\$ 1,025.81
7	SPORT RIM CAP	1	M36.13.6.857.149	X	\$ 31.94
8	FRONT WHEEL ARCH LH	1	M51.77.7.300.819	cut ✓	\$ 170.56
	TOTAL PARTS				\$ 1,659.14
					\$ -
	TOTAL PARTS COST				\$ 1,659.14
	Labour Description				
1	TO REPLACE THE FRONT BUMPER AND BONNET. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			840 / 1680.	\$ 1,900.00
2	TO RESPRAY THE FRONT BUMPER AND BONNET.			800 / 1600.	\$ 1,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			150.	\$ 250.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.			NETT ✓	\$ 120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			NETT ✓	\$ 560.00
6	TO INSTALL THE FRONT STICKER.			NETT ✓	\$ 350.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150.	\$ 250.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			250	\$ 350.00
9	SUNDRIES.			NETT 50	\$ 100.00

TOTAL LABOUR	\$ -	\$ 5,680.00
TOTAL PARTS	\$ -	\$ 1,659.14
TOTAL	\$ -	\$ 7,339.14
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Tanfuin 97445749
 up
 26/9/18 @ 11pm
 Resurvey after repair
 06 days
 Sur@lkkauto.com

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: