

ASS. REC. BY:

REF: CS/CT1180174621 ASD3 172

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Elaine cheong

of CT1

Date/Time: 25/9/18 @ 3:18pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KM 5875E

Insured: GU 3205M

at Workshop m/s

United SG automobile

Tel: 9007 7556

of

53 ubi Ave 1 # 01-56

Policy No:

DMCVSN3079491700

Claim No:

SNM18D04579C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/09/18

CA / REV / REP. / REV 24 HRS

lup

26/9/18

H.O.D. Endorsement:

Date/Time:

5:20pm @ 25/9/18

Person Contacted:

chms

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

8KM 5875E-x

GU 3205M-NA/TM118017227/h4

DOA: 20/9/18

08/03/19

Confirmed HS \$ 1,850/- @ 3 days with Adrian
C \$ 7,192.52 Rev - 30%

REF: CT1

ASSIGNMENT

From:

Date:

26/9/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

SKM 5875E
United SG Automobile

at Workshop m/s

of 53 Ubi Ave 1 # 61-56

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKNS875E.

Yr Regn: 2014 Jne.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

C.C. 1496.

Colour:

Red.

A/C: Insured / Std / NI / NA

Sp. Reading

135892

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BM42A8E0126377.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16.

R:

205/60R16

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

26/09/18

Survey held at

United SG.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Chien.

RECEIVED 08 MAR 2019

Date/Time, File Pass to?

08/03/19
Typist

1)

Date/Time, File Return to?

2)

☐

Preli. Report

☒

Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$) 1,850/- 45)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18017462/Asd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-09-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GU 3205M	Veh. Inspected	SKM 5875E
Policy No.	DMCVSN3079491700	Coverage (\$)	0.00
Claim No.	SNM18D04579C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	25/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/09/2018	Inspection Date	26/09/2018
Survey held at	UNITED SG AUTOMOBILE PTE LTD 53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2018		25 Sep 2018 15:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIENTA ENGINEERING & SANITARY WORKS, Co. Reg. No.: 44992900X		
Main Claimant:	URBAN TREKKER		
Vehicle Reg. No.:	SKM5875E	Date of Loss:	20/09/2018 17:00 - :59
Claim Type:	TP / SNM18D04579C02	Policy/Cover Note No.:	DMCVSN3079491700 (Third Party Only)
Vehicle Reg. No. (Insured):	GU3205M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4538K
Vehicle Details	
Vehicle No.:	SKN5875E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	P520216134
Chassis No.:	JM6BM42A8E0126377
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,020.00
Original Registration Date:	27 Jun 2014
First Registration Date:	27 Jun 2014
Transfer Count:	2
Actual ARF Paid:	\$9,020.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2024
PARF Rebate Amount:	\$6,765.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,335.00
COE Rebate Amount:	\$37,748.00
Total Rebate Amount:	\$44,513.00

The information contained herein is correct as at 11 Mar 2019

OK

United SG Automobile Pte Ltd

"We are always in your journey"....

53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg

UEN No. 201729521C | GST Registered No: 2017259521C

Jm6Bm42A8E0126377

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

ATTN: MOTOR CLAIMS DEPARTMENT

Shirley

VEHICLE NO : SKN5875E

MAKE MODEL : MAZDA 3

REFERENCE : USG-201809-09

DOA : 20-Sep-18

CLAIM TYPE : TP CLAIM

PAGE 1 OF 1

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER Distorted	1	\$ 1,305.00	1074.80
REAR BUMPER TOW HOOK COVER Dehd	1	\$ 104.00	16.20
REAR BUMPER REFLECTOR LH und	1	\$ 89.00	50.40
REAR BUMPER REINFORCEMENT BAR Best	1	\$ 725.00	537
REAR END PANEL Rejs	1	\$ 680.00	X
REAR END PANEL INNER TRIM Garage	1	\$ 208.00	X
REAR END PANEL INSULATION SEAL	1	\$ 190.00	X
REAR BOOTLID WEATHERSTRIP xpm	1	\$ 150.00	T
REAR BUMPER INNER BRACKET LH New	1	\$ 75.00	36.10
REAR TAILLAMP xpm	1	\$ 1,025.30	X
REAR TAILLAMP BRACKET LH xpm	1	\$ 389.40	X

1714.50
1371.60

\$ 4,940.70
LESS 20% \$ 988.14
SUBTOTAL \$ 3,952.56
BALANCE C/F \$ 3,952.56

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 3,952.56	
REAR BUMPER CLIPS Re	1	\$ 80.00	30
REAR NUMBER PLATE New	1	\$ 100.00	X
REVERSE SENSOR Danyd	4	\$ 800.00	200
HEADLAMP CLIPS New	1	\$ 80.00	X

SUBTOTAL \$ 1,060.00
BALANCE C/F \$ 5,012.56

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 5,012.56	
CHECK WIRING AND LIGHTING SYSTEM	1	\$ 80.00	30
REMOVE AND REFIT REAR BUMPER	2	\$ 800.00	X
PANEL BEATING ON AFFECTED AREA	3	\$ 1,500.00	300
SPRAY PAINTING ON AFFECTED AREA	4	\$ 1,500.00	400
APPLY ANTI-RUST ON AFFECTED AREA	5	\$ 150.00	X

SUBTOTAL \$ 4,030.00
GRAND TOTAL \$ 9,042.56

total 2331.60
4/5: 1850 ✓
03 days

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18017462/ASD3N2

Date: 11/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3079491700
Claimant Vehicle No :	SKN5875E	Insured Vehicle No :	GU3205M
Date of Loss:	20/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04579C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN5875E	Engine No:	P520216134
Make & Model:	MAZDA 3, 1.6 (A)	Chassis No:	JM6BM42A8E0126377
Reg. Date:	27/06/2014 (Man. Year: 2014)	Odometer:	135892 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,012.56	1,601.60	3,410.96	68.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	730.00	3,300.00	81.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,042.56	2,331.60	6,710.96	74.22
Approved Total (Overridden) (\$\$)		1,850.00		
(\$\$)	9,042.56	1,850.00	7,192.56	79.54
+ GST 7.00/7.00% (\$\$)	632.98	129.50	503.48	79.54
Nett Amount (\$\$)	9,675.54	1,979.50	7,696.04	79.54

INSPECTION

Date of Assignment:	25/09/2018	
Date Inspected:	26/09/2018 Inspected At:	United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2019)
Parts: 144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKN5875E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,305.00 FL	*1,074.80 FL
2	1		*REAR BUMPER TOW HOOK COVER	Deformed	104.00 FL	*16.20 FL
3	1		*REAR BUMPER REFLECTOR LH	Cracked	89.00 FL	*50.40 FL
4	1		*REAR BUMPER REINFORCEMENT BAR	Bent	725.00 FL	*537.00 FL
5	1		*REAR END PANEL	Repair	680.00 FL	*- FL
6	1		*REAR END PANEL INNER TRIM	Not Necessary	208.00 FL	*- FL
7	1		*REAR END PANEL INSULATION SEAL	Not Necessary	190.00 FL	*- FL
8	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	150.00 FL	*- FL
9	1		*REAR BUMPER INNER BRACKET LH	Necessary	75.00 FL	*36.10 FL
10	1		*REAR TAILLAMP	Not Necessary	1,025.30 FL	*- FL
11	1		*REAR TAILLAMP BRACKET LH	Not Necessary	389.40 FL	*- FL
12	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
13	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
14	4		*REVERSE SENSOR	Damaged	800.00 FS	*200.00 FS
15	1		*HEADLAMP CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,000.70	1,944.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	988.14	342.90
Total Parts (\$\$)	5,012.56	1,601.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	REMOVE AND REFIT REAR BUMPER	New	800.00	0.00
3	PANEL BEATING ON AFFECTED AREA	New	1,500.00	300.00
4	SPRAY PAINTING ON AFFECTED AREA	New	1,500.00	400.00
5	APPLY ANTI-RUST ON AFFECTED AREA	New	150.00	0.00
Gross Labour Cost (\$\$)			4,030.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >