

ASS. REC. BY:

REF:

CS/FCI18017467/RHd3

n2

Special Instructions:

Surveyor:

CWS

Rasul

ASSIGNMENT (Office)

From (Person):

Juarne Yong

of

FCI

Date/Time:

25/9/18 @ 4:41pm

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGH 3111T

Insured:

SHC 8207H

at Workshop m/s

Tan Chong Motor

Tel:

64694091 / 67038916

of

913 Bkt Jimah

Policy No:

Claim No:

D18006300 MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/08/18

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

4:56pm @ 25/9/18

Person Contacted:

Zuhni

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGH 3111T-X

SHC 8207H-CS/DAI13022171/4m3k3

DOA: 22/11/13

26/11/18-

(Zuhni nt in tdy, xox to ansf.)

Part by Part \$1542.80 (Red. 2162; 58%)

(02/11/18)

Surveyor

Rosa

REF:

44116

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGH 3111T

at Workshop m/s TAN CHONG

of 911, BURIT TIMPAH RD

Insured: FCI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

I am
ZuhriRemark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGH 3111T Yr Regn: 2015 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN QASHQAI 1.2 c.c 1197

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 81668 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SJN FGA31141460941

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/60R17

R: 215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/08/18 D.O.I. 04/10/18

Survey held at TAN CHONG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 JAN 2019

Date/Time, File Pass to?

1) P11 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others:

TOTAL

130

50

38

218

Report Format: TP

Lump Sum / (B.I.): (\$ 1542.80)

MOTOR SURVEY ASSIGNMENT

Date	23-08-2018	Our Ref No. D18006300MFSH
Accident Date	20-08-2018	Claim Type. Third Party
Insured Vehicle	SHC8207H	Third Party Vehicle. SGH3111T
Survey Location	913 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE	
Contact Person.	ZUHRI	
Contact No.	64694091/ 67038916	Fax No. 64697472
Survey Type	DIRECT SETTLEMENT: EST. COR - \$3,711.80	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN CHONG MOTOR SALES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S85305061**

Name: **HON JIA KAI, JUSTIN**
(HAN JIAKAI, JUSTIN)

Birth Date: **10 Sep 1985**

Issue Date: **29 Apr 2016**

002562522B

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S85305061**

Name: **HON JIA KAI, JUSTIN**
(HAN JIAKAI, JUSTIN)
韓家凱

Race: **CHINESE**

Date of birth: **10-09-1985**

Sex: **M**

Country/Place of birth: **SINGAPORE**

S85305061

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S2564411E**

Name: **CHONG SIEW HAR**

Race: **CHINESE**

Date of Birth: **16-11-1959**

Sex: **F**

Country of Birth: **JOHORE**

S2564411E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$

EFFECTIVE DATE
18 May 2005

NP 428A

Licence No: S85305061

5630058

NRIC No: S85305061

Date of issue: **01-08-2016**

Address: **APT BLK 574 CHOA CHU KANG STREET 52**
#12-292
SINGAPORE 680574

0132139

NRIC No: S2564411E

Blood Group: **A+**

Date of issue: **19-10-1991**

Address: **APT BLK 584 ANG MO KIO AVENUE 3 #02-3111**
SINGAPORE 560584

NRIC No: S2564411E

Date: **20-06-2000**

No: **3762406**



CERTIFICATE OF INSURANCE

NISSAN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHONG SIEW HAR
Period of Insurance : 30 Jun 2018 To 29 Jun 2019
Engine No. : HRA2147214A
Chassis No. : SJNFEAJ11U1400941

Vehicle No. : SGH3111T
Policy No. : 2100419949-03
Endorsement No. :
Issued Date : 19 Jun 2018

ABOUT THE COVER

Make/Model : NISSAN QASHQAI 1.2 DIG-TURBO
Engine Capacity/Tonnage : 1,197.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2015
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$0 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHONG SIEW HAR

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. TC AutoClinic Add: No. 1, Sixth Lok Yang Road Singapore 628099 62622212
2. Autolion Industrial Add: 19 Ubi Road 4 Singapore 408623 64909666
3. TC AutoClinic Add: 25 Leng Kee Road Singapore 159097 67038511 67038512 67038513
4. Tan Chong Motor Sales Add: 913 Bukit Timah Road Singapore 589623 64694091 64694092 64694093
5. Tan Chong Motor Sales Add: 17 Lorong 8 Toa Payoh Singapore 319254 63570753 63570754

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500610479

TAN CHONG CREDIT PTE LTD - GYZ
911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE
SINGAPORE 589622 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSPDAC

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/2HR/0382/2018
DATE : 21-SEP-2018

FIRST CAPITAL INSURANCE LTD REFER MS FIRST

36 ROBINSON ROAD

#16-01 CITY HOUSE

S(068877)

TEL : 65073848 / 68543466

FAX : 65073849

ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : CHONG SIEW HAR
ADDRESS : BLK 584 ANG MO KIO AVE 3
#02-3111
S(560584)
TELEPHONE NO : 96499163

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHC8207H
VEHICLE NO : SGH3111T
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2147214A
CHASSIS NO : SJNFEAJ11U1400941
MILEAGE : 1 KM
DATE IN : 21/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 20/08/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

21/9/2018

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGH3111T

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X + 22
2 RSI	RENEW OR REPLACE REVERSE SENSOR NECESSARY ADJSTMNT FUNCTION TEST	110.00	✓
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X + 22
4 ZZ/001	REPAIR REAR TAILGATE, REAR END PANEL & RENEW REAR BUMPER COVER	975.00	390 ✓
5 ZZ/002	S/PAINT REAR BUMPER COVER(2 TONE), REAR END PANEL REAR TAILGATE & REAR FENDER RH	1000.00	350 ✓
6 ZZ/003	RENEW OR R/INSTAL R/LAMP VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	X ✓
TOTAL LABOUR CHARGES		2353.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGH3111T

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			180.00 ?/8u
2 SUNDRIES	NPN			50.00 20 ✓
3 COMB LAMP	26550-4EA5E	306.30	X X	} 8u
4 LAMP COMB RR,RH	26550-4EA0A	323.70	X X	
5 FINISHER-REAR B	85071-4EA0A	16.80	SA ✓	
6 CLIP(10X1.2)	01553-05933	12.00	rec ✓	
7 CANOE RIVET(2X6.5)	76882-0M000	13.00	re ✓	
8 CLIP(3X7.4)	85284-JD00A	22.20	re ✓	
9 FASCIA-RR BUMP	85022-HV00H	717.00	cut ✓	
SUB TOTAL		1411.00	0.00	230.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		282.20	0.00	0.00
GRAND TOTAL		1128.80	0.00	230.00
OVERALL TOTAL		1358.80		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGH3111T

TOTAL LABOUR CHARGES	2353.00
TOTAL SPARE PARTS CHARGES	1358.80
GRAND TOTAL	3711.80 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul
SURVEYED DATE	:	04/10/18 @ 11.00
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 3 days
LIABILITY	:	0.00
REMARKS	:	

Reg 6 & part

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0382/2018
DATE : 21-SEP-2018

PS => Rasu 1

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

ZHR

OWNER'S NAME : CHONG SIEW HAR
ADDRESS : BLK 584 ANG MO KIO AVE 3
#02-3111
S(560584)
TELEPHONE NO : 96499163

(3 Days)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHC8207H
VEHICLE NO : SGH3111T
MODEL CODE : FRLARBEJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2147214A
CHASSIS NO : SJNFEAJ11U1400941
MILEAGE : 1 KM
DATE IN : 21/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 20/08/2018

Lau = \$90 x 3
= \$270

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TINAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGH3111T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00
2	RSI	RENEW OR REPLACE REVERSE SENSOR NECESSARY ADJSTMNT FUNCTION TEST	110.00	110.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
4	22/001	REPAIR REAR TAILGATE, REAR END PANEL & RENEW REAR BUMPER COVER	975.00	390.00
5	22/002	S/PAINT REAR BUMPER COVER(2 TONE), REAR END PANEL REAR TAILGATE & REAR FENDER RH	1000.00	350.00
6	22/003	RENEW OR R/INSTAL R/LAMP VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
TOTAL LABOUR CHARGES			2353.00	898.00

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGH3111T

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			180.00	X
2 COMB LAMP	26550-4EASE	306.30			X
3 LAMP COMB RR,RH	26550-4EA0A	323.70			X
4 SUNDRIES	NPN			20.00	OK
5 FINISHER-REAR B	85071-4EA0A	16.80			OK
6 CLIP(10X1.2)	01553-05933	12.00			OK
7 CANOE RIVET(2X6.5)	76882-0M000	13.00			OK
8 CLIP(3X7.4)	85284-JD00A	22.20			OK
9 FASCIA-RR BUMP	85022-HV00H	717.00			OK
SUB TOTAL		781.00	0.00	20.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		156.20	0.00	0.00	
GRAND TOTAL		624.80	0.00	20.00	
OVERALL TOTAL		644.80			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGH3111T

NETT ITEM	781.00
LESS 20.00%	-156.20
NETT AMOUNT	624.80
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	20.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	20.00
TOTAL LABOUR CHARGES	898.00
TOTAL SPARE PARTS CHARGES	644.80
TOTAL CHARGES	1542.80
ADD 7 % GST	108.00
GRAND TOTAL	1650.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017467/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8207H	Veh. Inspected	SGH 3111T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006300MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	25/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI 1.2	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1400941	Colour	BROWN	
Odometer	81668	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2018	Inspection Date	04/10/2018	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 913 BUKIT TIMAH ROAD SINGAPORE 589623			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 3111T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COMB LAMP (N)	SERVICEABLE	306.30	-
1	LAMP COMB RR,RH (N)	SERVICEABLE	323.70	-
1	FINISHER-REAR B (N)	SCRATCHED	16.80	16.80
10	CLIP @\$1.20 (N)	NECESSARY	12.00	12.00
2	CANOE RIVET @\$6.50 (N)	NECESSARY	13.00	13.00
3	CLIP @\$7.40 (N)	NECESSARY	22.20	22.20
1	FASCIA-RR BUMP (N)	CUT	717.00	717.00
	LESS 20% DISCOUNT		-282.20	-156.20
			1,128.80	624.80
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (J11 & T32)(SN)	SERVICEABLE	180.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			230.00	20.00
LABOUR				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	120.00	-
	RENEW OR REPLACE REVERSE SENSOR NECESSARY ADJSTMNT FUNCTION TEST.		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	-
	REPAIR REAR TAILGATE,REAR END PANEL & RENEW REAR BUMPER COVER.		975.00	390.00
	S/PAINT REAR BUMPER COVER (2 TONE),REAR END PANEL REAR TAILGATE & REAR FENDER RH.		1,000.00	350.00
	RENEW OR R/INSTALL R/LAMP VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.		48.00	48.00
	-		-	-
	-		-	-
	-		-	-
			2,353.00	898.00
GRAND TOTAL			3,711.80	1,542.80

Report Ref No. CS/FCI18017467/R1td3n2



RECOMMENDED COST OF REPAIRS			1,542.80
-----------------------------	--	--	----------

Report Ref No. CS/FCI18017467/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.