

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1320/2018/PH
Date	:	29-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr.Yap Tze Mei
Address	:	1 Robin Road Singapore 258176
Telephone	:	HP +65 96777880
Type of Claim	:	Third Party Claims
Policy No.	:	2100452818-02
Vehicle No	:	SLA 2117 L
Model Code	:	Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year	:	Feb-16
Engine No	:	CVN 001236
Chassis No	:	WAUZZZF47GA012708
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	24-Sep-18
Place of Accident	:	DRAYCOTT PARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLA 2177 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear kick sensor. Check function.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. Re-organize rear crash components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray rear bumper.	\$ 800.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLA 2117 L .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Rehurd</i>	\$ 1,907.00	✓
2	FIXING PARTS FOR REAR BUMPER <i>new</i>	\$ 63.00	X
3	SECURING PLATE <i>2 new</i>	4 \$ 56.00	X
4	SECURING STRIP	\$ 191.00	X
5	REAR BUMPER SPOILER <i>new</i>	\$ 216.00	X
6	REAR BUMPER REFLECTOR LIGHT-LH/RH <i>new</i>	2 \$ 70.00	X
7	REAR BUMPER CARRIER <i>new</i>	\$ 786.00	X
8	SEAL <i>2</i>	2 \$ 24.00	✓
9	GUIDE SECTION - LH <i>new</i>	\$ 37.00	✓
10	GUIDE SECTION - RH <i>new</i>	\$ 38.00	✓
11	GUIDE SECTION - LH/RH	2 \$ 38.00	X
12	REVERSE SENSOR - REAR INNER/OUTER <i>new</i>	2 \$ 421.00	X
13	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 4,147.00	
TOTAL LABOUR CHARGES		\$ 2,252.00	
GRAND TOTAL		\$ 6,399.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 12/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant