

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

21-Sep-18

Our ref : TP/4576/18

Kerk Kim Chew

TPA167
Vic

RE : estimate cost for vehicle no : SLQ 5362R

1 pc	frt lh door <i>Dented.</i>		\$	1,395.00	✓
1 pc	frt lh door outer handle <i>Not new</i>			395.00	X
1 pc	rear lh door <i>Distorted.</i>			1435.00	✓
1 pc	rear lh door protector <i>missing</i>			268.80	✓
1 pc	rear lh door outer handle <i>Not new</i>			110.00	X
1 pc	rear lh door lock <i>Not new</i>			660.00	X
1 pc	rear lh door w/strip w/sensor <i>Not new</i>			1060.00	X
1 pc	rear lh door regulator gear <i>Damaged</i>			365.00	✓
1 pc	rear lh door regulator motor <i>crushed</i>			845.00	✓
1 pc	rear lh door channel <i>Bent</i>			186.45	✓
1 pc	rear lh door trimboard <i>crushed</i>			840.20	✓
1 pc	rear lh door centre lock motor <i>Not new</i>			450.30	X
1 pc	rear lh door outer moulding <i>Not new</i>			150.80	X
1 pc	rear lh door railing centre <i>Not new</i>			417.00	X
1 pc	rear lh door hinge <i>Bent</i>	6784.55		145.00	✓
1 pc	rear lh fender <i>Distorted</i>			1,150.00	✓
1 pc	rear lh fender inner trim <i>Not new</i>	5388.41		765.00	X
1 pc	rear lh fender protector <i>missing</i>			154.10	✓
1 pc	rear lh door pillar <i>Repair</i>	SN 80		532.60	X
1 pc	rear lh door railing lower			196.30	X
1 pc	rear lh door railing top			175.80	X
1 pc	rear lh door railing lock			253.60	X
1 pc	rear lh door railing lock lower			162.20	X
1 pc	rear lh fender inner panel <i>Repair</i>			985.20	X
1 pc	rear bumper <i>Repair</i>			685.00	X
1 pc	rear lh rim <i>Not new</i>			2200.00	X
1 pc	rear lh hup cap <i>Not</i>			240.00	X
1 pc	rocker panel <i>Repair</i>			650.30	X
1 pc	rocker panel rubber <i>Not new</i>			230.60	X
				17104.25	
				4276.06	
				12828.19	
				50.00	snett ✓
				300.00	X
				13178.19	

less 25%

1 pc rear fender gum *Not new*
1 pc rear lh tyre *Not new*

50

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SLQ 5362R

Bal brought forward:	\$	13,178.19
Panel beating.		1500.00 1000
Spray painting.		1500.00 800
Transfer 2 door parts.	2100	160.00
Upholstery.		120.00 80
Remove & refit rear quarter glass.		120.00 60
		16,578.19
	Plus 7% GST	1,160.47
		<u>17,738.66</u>

SD : Seventeen thousand seven hundred thirty-eight & cents sixty-six only.

Supplementary : 1829.92

total 9148.33

L/S : 7.31K ✓

09 Days

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

24-Sep-18

Our ref : TP/4576/18

Kerk Kim Chew

RE : Supplementary cost for vehicle no : SLQ 5362R

1 pc	door oillar rubber w/sensor	<i>new</i>	\$	1,060.00 X
1 pc	auto motor	<i>new</i>		2118.90
1 pc	door inner rubber	<i>new</i>		321.00 ✓
				3499.90
		less 25%		874.97
				2,624.93
		Plus 7% GST		183.75
				2,808.68

SD : Two thousand eight hundred & eight & cents sixty-eight only.

Adrian Lim -
R.S.

24/09/18 .

Supplementary : 2438.5
1825.52