



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address   | Owner Name & Vehicle Info |                                      |
|--|---------------------------|--------------------------------------|
| MR REN ZHENG<br><br>2E HONG SAN WALK<br>#10-04 PALM GARDENS<br>SINGAPORE 689051<br><br>Contact No Mobile: 97514862 | Cust No/Name              | /MR REN ZHENG                        |
|  | Reg No/Reg Date           | SLK2242E / 10/01/201                 |
|  | Date In/Mileage           | / 0                                  |
|  | Chassis No                | KNAFX411MH5668560                    |
|  | Engine No                 | G4FGGH658499                         |
|  | Make/Model                | KIA/FORTE K3 1.6 A EX BRQ            |
|  | Colour/Trim               | SWP SNOW WHITE PEAR/ WK SATURN BLACK |

| Account No  | Terms | Date/Time Printed | CSE | Operator          | WIP No     |       |              |
|---|-------|-------------------|-----|-------------------|------------|-------|--------------|
| CSM00081  | Cash  | 25/09/2018/ 12:03 | QUE | 261 / Edwin Caina | 36067      |       |              |
| Description of Goods / Services                       |       |                   |     | Qty               | Unit Price | Disc% | Amount       |
| E PNT88000  |       |                   |     |                   |            |       | 1375 2750.00 |
| RENEW & RE-ALIGN RR DAMAGED PORTION:                  |       |                   |     |                   |            |       |              |
| RENEW RR BUMPER , BOOTLID & RR END PNL                |       |                   |     |                   |            |       | 1260         |
| REPAIR RHR FENDER                                     |       |                   |     |                   |            |       | 1700.00      |
| E PNT98000  |       |                   |     |                   |            |       | 250 275.00   |
| RESPRAY RR BUMPER , RR END PNL , BOOTLID & RHR FENDER |       |                   |     |                   |            |       | 150 275.00   |
| E PNT88000  |       |                   |     |                   |            |       | 30 50.00     |
| REMOVE & REFIT BOOTLID COMPONENT                      |       |                   |     |                   |            |       |              |
| E PNT88000  |       |                   |     |                   |            |       | 150 275.00   |
| REMOVE & REFIT RR FLR BOARD,TRIM & CARPET             |       |                   |     |                   |            |       | 30 50.00     |
| A 54900099  |       |                   |     |                   |            |       | ✓ 200.00     |
| CHECK WIRING & ELECTRICAL SYSTEM                      |       |                   |     |                   |            |       |              |
| A 10028901  |       |                   |     |                   |            |       | 80 120.00    |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST  |       |                   |     |                   |            |       | X 80.00      |
| USING HI-SCAN PRO TEST                                |       |                   |     |                   |            |       | 60 100.00    |
| M SUNDRY  |       |                   |     |                   |            |       | nw ✓ 220.00  |
| APPLY ANTI CORROSION ON AFFECTED AREAS                |       |                   |     |                   |            |       | 20 50.00     |
| M SUNDRY  |       |                   |     |                   |            |       | nw ✓ 50.00   |
| SUPPLY RR NUMBER PLATE WITH CASING                    |       |                   |     |                   |            |       | de 688.00    |
| E PNT88000  |       |                   |     |                   |            |       | de 347.00    |
| TO RENEW REVERSE SENSOR                               |       |                   |     |                   |            |       | 1 318.00     |
| M SUNDRY  |       |                   |     |                   |            |       | 1 120.00     |
| TO SUPPLY REVERSE SENSOR                              |       |                   |     |                   |            |       | 1 120.00     |
| M SUNDRY  |       |                   |     |                   |            |       | 1 120.00     |
| Sundries  |       |                   |     |                   |            |       | 1 17.00      |
| M SUNDRY  |       |                   |     |                   |            |       |              |
| TO SUPPLY C&C BADGE                                   |       |                   |     | 1.00              | 688.00     | 00.00 |              |
| M COVER-RR BUMPER                                     |       |                   |     | 1.00              | 347.00     | 00.00 |              |
| M COVER-RR BUMPER,CTR                                 |       |                   |     | 1.00              | 318.00     | 00.00 |              |
| M BEAM-RR BUMPER                                      |       |                   |     | 1.00              | 120.00     | 00.00 |              |
| M STAY-RR BUMPER LH                                   |       |                   |     | 1.00              | 120.00     | 00.00 |              |
| M STAY-RR BUMPER RH                                   |       |                   |     | 1.00              | 120.00     | 00.00 |              |
| M GUARD-BUMPER REAR,RH                                |       |                   |     | 1.00              | 17.00      | 00.00 |              |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address      | Owner Name & Vehicle Info                        |
|-----------------------------|--|
| MR REN ZHENG                | Cust No/Name /MR REN ZHENG                       |
| 2E HONG SAN WALK            | Reg No/Reg Date SLK2242E / 10/01/201             |
| #10-04 PALM GARDENS         | Date In/Mileage / 0                              |
| SINGAPORE 689051            | Chassis No KNAFX411MH5668560                     |
| Contact No Mobile: 97514862 | Engine No G4FGGH658499                           |
|                             | Make/Model KIA/FORTE K3 1.6 A EX BRQ             |
|                             | Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK |

| Account No                      | Terms | Date/Time Printed | CSE        | Operator          | WIP No  |
|---------------------------------|-------|-------------------|------------|-------------------|---------|
| CSM00081                        | Cash  | 25/09/2018/ 12:03 | QUE        | 261 / Edwin Caina | 36067   |
| Description of Goods / Services |       | Qty               | Unit Price | Disc%             | Amount  |
| M BRACKET-RR BUMPER SIDE MTG,LH |       | 1.00              | 29.00      | 00.00             | 29.00   |
| M BRACKET-RR BUMPER SIDE MTG,RH |       | 1.00              | 29.00      | 00.00             | 29.00   |
| M PANEL ASSY-TRUNK LID          |       | 1.00              | 1491.00    | 00.00             | 1491.00 |
| M W/STRIP-TRUNK LID OPNG        |       | 1.00              | 100.00     | 00.00             | 100.00  |
| M LATCH ASSY-TRUNK LID          |       | 1.00              | 112.00     | 00.00             | 112.00  |
| M LOGO ASSY-KIA SUB             |       | 1.00              | 37.00      | 00.00             | 37.00   |
| M EMBLEM-CERATO                 |       | 1.00              | 35.00      | 00.00             | 35.00   |
| M EMBLEM FORTE                  |       | 1.00              | 20.00      | 00.00             | 20.00   |
| M EMBLEM K3                     |       | 1.00              | 15.00      | 00.00             | 15.00   |
| M PANEL ASSY-BACK               |       | 1.00              | 274.00     | 00.00             | 274.00  |
| M TRIM-TRANSVERSE RR            |       | 1.00              | 58.00      | 00.00             | 58.00   |
| M LAMP ASSY-REAR COMBINATION,RH |       | 1.00              | 788.00     | 00.00             | 788.00  |

SURVEYOR NAME: Tanpin 97495749SURVEYOR SIGNATURE: [Signature]DATE: 19/11/18 3:30 pm WPREMARKS: Resurvey before paint.surellauto.com5 days**LKK Auto Consultants hence notify****the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final price from insurance company

**Confirm & accepted by**

Acknowledged by Repairer

Signature:

Date:

7% GST on      **Nett**      **10,468.00**  
                          **10468.00**      **732.76**

**Total Payable      11,200.76****Authorized signatory and company stamp**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.