

ASS. REC. BY:

REF:

CS/MSH 18017484/Tivbe

Special Instruction:

Surveyor

Tavala

ASSIGNMENT (Office)

merimen

From (Person):

Eliza Hu

of

MSH

Date/Time:

26/02/18 9:35am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SK 39J

Insured:

at Workshop w/s

Performance Motor

Tel:

81214600

of

303 Alexandra Rd

Policy No:

2759299MTR

Claim No:

Sum Insured:

Excess:

\$1500.00

Make of Veh:

D.O.A.

24092018

(Client's Record)

CA / REP / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

26/02/18 9:51am

Person Contacted:

Inthiran

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SK 39J - X

27/9/18

Revert via merimen

27/9/18

Rece approved from ming shao by merimen

27/9/18

Informed Inthiran c/A ex \$1500 by email

28/11/18

Final fig \$16,319.85 confirmed by email (Reel 18,693.60, 537)

Signature: Tanfer

REF:

MSIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: \$1500
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$260K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: Merimen

Vehicle: IN / OUT

Veh No: SCK 329J Yr Regn: 2016 Aug
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 740Li CC: 2998
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 49811 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA7E220506.651542
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/40R20
 R: 1 1
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 26/9/18
 Survey held at: PML
 Des. of Damages: ☒ Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

RECEIVED 29 NOV 2018

Date/Time, File Pass to?

☐
☐

: Preli. Report
 : Final Report

1)

Date/Time, File Return to?

2)

28/11 - typist

Report Format: Merimen

Lump Sum / I.B.I: (\$) 16,319.85

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

(S + RS) (\$)

Photos

Others

TOTAL

250

10

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2018 17:28		26 Sep 2018 09:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	PERFORMANCE MOTORS LTD , Co. Reg. No.: 197401559W			[Created by insurer]					
Vehicle Reg. No.:	SCK329J	Date of Loss:	24/09/2018 15:00 - :59 [25 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD	Policy/Cover Note No.:	27392999MTR (Comprehensive) Coverage: 01/10/2017 - 30/09/2018						
		Excess:	S\$1,500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/09/2018]								
Driver/Custodian:	WONG KIT SIONG (27 / Male), NRIC: G2078798N, Tel: +6597523311								
Adj Asg. Remarks:	Car in, pls survey and revert								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case. View All Compose Case Mail									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

View Received Message

This mail is associated with :

***SCK329J (571640)**

OD

Sep 24 2018 3:00PM

[PERFORMANCE MOTORS LTD]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 28/11/2018 16:25 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$16319.85) - SCK329J - Claim Handler: Eliza Ho Teng Boon

Approved:16319.85:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 23 Nov 2018

Preliminary Advice

Vehicle No	: SCK329J	Accident Date	: 24/09/2018
Make	: BMW 735Li	Policy No.	: 27392999MTR
Assignment Date	: 26/09/2018	Excess	: S\$1,500.00
Date of Inspection	: 26/09/2018	Est. Duration of Repair	: 9.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,013.45	(incl.supplementary \$931.65)
Revised Amount	:S\$	16,319.85	(incl.supplementary \$931.65)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	16,319.85	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	260,000.00
COE / PARF Rebate	:S\$	136,795.00
Salvage Value	:S\$	
Margin for Repair	:S\$	123,205.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 27 September 2018 5:21 PM
To: 'Inthiran Thurasamy'
Cc: SUR; 'PBSP'
Subject: SCK 329J-DOA: 24/9/2018 (MSIG OD)

Dear Inthiran,

As instructed by our client, please proceed to repair the insured vehicle **SCK 329J (Excess S1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SCK329J**

OD

Sep 24 2018 3:00PM

[PERFORMANCE MOTORS LTD]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 27/09/2018 17:16 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12011.35) - SCK329J - Claim Handler: Eliza Ho Teng Boon

Approved:12011.35:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 27 Sep 2018

Preliminary Advice

Vehicle No	: SCK329J	Accident Date	: 24/09/2018
Make	: BMW 735Li	Policy No.	: 27392999MTR
Assignment Date	: 26/09/2018	Excess	: S\$1,500.00
Date of Inspection	: 26/09/2018	Est. Duration of Repair	: 9.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,081.80
Revised Amount	:S\$	12,011.35
Check Items (Estimated)	:S\$	20,918.45
Total	:S\$	32,929.80

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	260,000.00
COE / PARF Rebate	:S\$	136,795.00
Salvage Value	:S\$	
Margin for Repair	:S\$	123,205.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0301R
Vehicle Details	
Vehicle No.:	SCK329J
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	740LI SR LED NAV HUD
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	25919622B58B30A
Chassis No.:	WBA7E22050G651542
Maximum Power Output:	240.0 kW (321 bhp)
Open Market Value:	\$84,262.00
Original Registration Date:	02 Aug 2016
First Registration Date:	02 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$123,672.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Aug 2026
PARF Rebate Amount:	\$92,754.00
Intended COE Rebate Details	
COE Expiry Date:	01 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,089.00
COE Rebate Amount:	\$44,041.00
Total Rebate Amount:	\$136,795.00

The information contained herein is correct as at 25 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2018 08:26
Date Of Accident	24/09/2018 15:15
Exact Location Of Accident	SDPC@LEVEL 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCK329J
Insured/Policyholder	
Name Of Registered Owner	PERFORMANCE MOTORS LTD
Co Reg No	197401559W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63190100

Vehicle Particulars

Manufacturer	BMW
Model	740
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	UNAVAILABLE
Cover Note Number	

Driver

Name of Driver	WONG KIT SIONG
NRIC No	G2078798N
Date Of Birth	19/05/1991
Occupation	INDOOR
Date Of Driving Pass	09/12/2013
Driving Experience	4 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97523311
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	303 ALEXANDRA ROAD
Postcode	159941
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX6051X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


PERFORMANCE MOTORS LIMITED

UEN No. 197401559W
303 Aljunied Road
Singapore 400201
Date & Time: 1800-2255-389

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
PERFORMANCE MOTORS LIMITED
303 Aljunied Road
Singapore 400201
Tel: 6315 0100 (Sales)
6315 0111 (Admin)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

UPON collecting car for repair @ level 1, upon turning out from car park LOT 51, there is a car park at the rhs which I am not able to do a rhs turn. So I decided to make a lhs turn instead; Then to exit. upon arriving at the exit there is another car came from the lhs and he would like to make a rhs turn also. Unfortunately When I saw the car I do hard braking but the car slipped and hit on to another car. I am driving SCK39J.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Reporting Center Person's Signature
Name:
NRIC/FIN No.:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 137401559W GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48550
Date Estimated : 25/09/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Tiong Seng Contractors Private Limi
21 Fan Yoong Road

Singapore 629796

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCK329J	G651542	02/08/2016	740Li	0

DESCRIPTION

To replace front bumper, air duct, support, bonnet and attachments.

Painting front bumper and bonnet.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To replace both left and right headlights.
If replace 1 side @\$481

To supply front emboss number plate.

To replace radiator assembly, fan housing with fan including to conduct pressure test, bleed bleed cooling system and check for leak. (For all models except 7 series).

To replace auxiliary radiator assembly including pressure test, bleed cooling system and check for leak.

To remove and install front view cameras including program and conduct checks for proper function.

To carry out body cavity preservation.
(Per panel).

Sundries.

Support panel - 4250 ✓
~~2550~~ 5,100.00

✓ 1950 2,167.00

✓ 150 177.00

m x 711? 837.00

✓ 86 83.00

✓ 702. ? 826.00

m x 651 ? 767.00

✓ 226 266.00

✓ 100 118.00

✓ 7 150.00

Total Labour 1: 10,491.00

DESCRIPTION

RADIATOR
COVER TOP
COVERING LOWER
RADIATOR

QTY	PRIC	VALUE
1	974.25	974.25
1	70.60	70.60
1	70.60	70.60
1	1,082.50	1,082.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190112 (AfterSales)
Fax. 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48550
Date Estimated : 25/09/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCK329J	G651542	02/08/2016	740Li	0

DESCRIPTION	QTY	PRIC	VALUE
Rock guard	1	91.75	91.75
HOSE RADIATOR TRANSMISSION OIL COOL	1	100.10	100.10
ALUMINIUM BONNET	1	2,882.55	2,882.55
SET MOUNTS PDC SENSOR FRT	1	69.00	69.00
FRT BUMPER BOTTOM CARRIER	1	441.55	441.55
GUIDE LH BOTTOM	1	14.55	14.55
GUIDE RH BOTTOM	1	14.55	14.55
GUIDE TOP LH	1	30.35	30.35
GUIDE TOP RH	1	30.35	30.35
LH SUPPORT FOG LAMP	1	61.90	61.90
RH SUPPORT FOG LAMP	1	61.90	61.90
IMPACT ABSORBER TOP	1	83.20	83.20
FRT BOTTOM IMPACT ABSORBER	1	67.40	67.40
FRT BUMPER CARRIER	1	802.80	802.80
LH PROTECTIVE STRIP BOTTOM	1	50.95	50.95
RH PROTECTIVE STRIP BOTTOM	1	50.95	50.95
PROTECTIVE STRIP TOP LH	1	82.65	82.65
PROTECTIVE STRIP TOP RH	1	82.65	82.65
BUMPER GUARD CENTRE	1	77.50	77.50
BUMPER GUARD CENTRE	1	77.50	77.50
DAMPER KERB DESCENT	1	5.10	5.10
FRT BUMPER PANEL PRIMED (PDC/PMA)	1	1,503.60	1,503.60
FRT BUMPER TOWING LUG COVER PRIMED	1	55.70	55.70
LICENCE PLATE BASE	1	68.95	68.95
GRILLE AIR INLET MIDDLE (PURE EXCEL	1	76.35	76.35
GRILLE AIR INLET LH (PURE EXCELLENC	1	71.80	71.80
GRILLE AIR INLET RH (PURE EXCELLENC	1	71.80	71.80
RH INSULATED	1	51.50	51.50
TRIM GRILLE I-CAM	1	20.35	20.35
FRT LH GRILLE (BASIS)	1	174.95	174.95
FRT RH GRILLE (BASIS)	1	174.95	174.95
Holder	1	9.75	9.75
AIR FLAPS TOP	1	316.25	316.25
EMBLEM GROMMET	2	0.80	1.60
BMW EMBLEM	1	69.50	69.50
CONNECTION FRT TOP	1	252.05	252.05
FRT PANEL SUPPORT	1	82.55	82.55
AIR DUCT BOTTOM	1	36.95	36.95
LH HEADLIGHT MOUNTING	1	134.30	134.30
COVERING CROSS MEMBER (ECE)	1	33.50	33.50
AIR DUCT RADIATOR TOP	1	56.65	56.65
AIR DUCT RADIATOR BOTTOM	1	56.65	56.65
LH HEADLIGHT LED AHL HIGH (ICON LIG	1	5,847.60	5,847.60
RH HEADLIGHT LED AHL HIGH (ICON LIG	1	5,847.60	5,847.60
ULTRASONIC SENSOR BLACK	2	248.70	497.40
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
SURROUND VIEW CAMERA	1	681.10	681.10

Total Parts : 23,590.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747775

299, Tampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64736601 (AfterSales)
64736624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48550
Date Estimated : 25/09/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCK329J	G651542	02/08/2016	740Li	0

Claimed QD / 3rd Party / Uninsured Motorist / Direct Settlement

Regn No: _____ Claim No: _____

Date & Time: 26/9/18 Excess \$: 1500

Surveyor's Name: Tanylin Sign: _____

Surveyor's Tel: 97485749 Authorised: Yes ☒

Authorised Date: Revert Time: _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes ☒ No ☐ PUL Yes ☐ No ☐

Surveyor's E-mail: tanylin@lkk-auto.com

No. of Working Days Recommended: 9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

35,013.45

Labour 1	:	10,491.00
Parts	:	23,590.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,385.73
Grand Total	:	36,467.53

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the S&P Group
Co. Reg. No. 197401509W. GST Reg. No. M2-0020061-X



FINAL REPORT

Estimate No. : b1 48550
Date Estimated : 25/09/2018
Prepared By : Inthiran A/L Thurassamy

Page No. :

REPAIR FOR -
Tiong Seng Contractors Private Limi
21 Fan Yoong Road

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 629796

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SCK329J	G651542	02/08/2016	740Li	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, bonnet, top air flap, front crosslink, front top connection air duct bottom, Y strut, front engine compartment shielding include knocking out dents caused by the accident	4250.00		4,250.00	
To spray paint front bumper and bonnet	1950.00		1,950.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
To supply front emboss number plate.	83.00		83.00	
* To replace radiator assembly, fan housing with fan include pressure tests, bleed cooling system and conducting checks for leak	702.00		702.00	
To remove and install front view cameras include programming and conducting checks for proper function	226.00		226.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.75	2.00		3.50
# EXPANDING NUT L=19.9MM *	1.40	10.00		14.00
RADIATOR	974.25	1.00		974.25
ALUMINIUM BONNET	2,882.55	1.00		2,882.55
SET MOUNTS PDC SENSOR FRT	69.00	1.00		69.00
FRT BUMPER BOTTOM CARRIER	441.55	1.00		441.55
IMPACT ABSORBER TOP	83.20	1.00		83.20
FRT BOTTOM IMPACT ABSORBER	67.40	1.00		67.40
FRT BUMPER CARRIER	802.80	1.00		802.80
BUMPER GUARD CENTRE	77.50	1.00		77.50
FRT BUMPER PANEL PRIMED (PDC/PPA)	1,503.60	1.00		1,503.60
LICENCE PLATE BASE	68.95	1.00		68.95

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 191401509W, GST Reg. No. M2-0020081-X



FINAL REPORT

GRILLE AIR INLET MIDDLE (PURE EXCEL	76.35	1.00	76.35
# FRT LH GRILLE (PURE EXCELLENCE) *	209.90	1.00	209.90
# FRT RH GRILLE (PURE EXCELLENCE) *	262.40	1.00	262.40
AIR FLAPS TOP	316.25	1.00	316.25
EMBLEM GROMMET	0.80	2.00	1.60
BMW EMBLEM	69.50	1.00	69.50
# FRT CROSSLINK *	157.10	1.00	157.10
CONNECTION FRT TOP	252.05	1.00	252.05
AIR DUCT BOTTOM	36.95	1.00	36.95
# Y STRUT *	26.75	1.00	26.75
COVERING CROSS MEMBER (ECE)	33.50	1.00	33.50
# ENGINE COMPARTMENT SHIELDING FRT *	171.95	1.00	171.95
# COVER STEERING GEAR *	46.55	1.00	46.55
DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00	20.20
# ANTI-FREEZE 1.5 LITRES *	19.75	2.00	39.50

SUPPLEMENTARY ITEMS

Total Labour :	7,611.00
Total Parts :	8,708.85
Total Labour & Parts :	16,319.85
Deduction for Excess :	1,500.00
Total Repair Costs less Excess:	14,819.85
GST @7%:	1,037.39
Grand Total :	15,857.24

Performance Motors Limited

A member of the Sival Dairy Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. b1 48550
Date Estimated 25/09/2018
Prepared By Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tiong Seng Contractors Private Limi
21 Fan Yoong Road

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 629796

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SCK329J	G651542	02/08/2016	740Li	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.75	2.00		3.50 <i>ml ✓</i>
# EXPANDING NUT L=19.9MM *	1.40	10.00		14.00 <i>ml ✓</i>
# FRT LH GRILLE (PURE EXCELLENCE) *	209.90	1.00		209.90 <i>ml ✓</i>
# FRT RH GRILLE (PURE EXCELLENCE) *	262.40	1.00		262.40 <i>ml ✓</i>
# FRT CROSSLINK *	157.10	1.00		157.10 <i>ml ✓</i>
# Y STRUT *	26.75	1.00		26.75 <i>ml ✓</i>
# ENGINE COMPARTMENT SHIELDING FRT *	171.95	1.00		171.95 <i>ml ✓</i>
# COVER STEERING GEAR *	46.55	1.00		46.55 <i>ml ✓</i>
# ANTI-FREEZE 1.5 LITRES *	19.75	2.00		39.50 <i>ml ✓</i>

Total Labour :	
Total Parts :	931.65
Total Labour & Parts :	931.65

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 28 November 2018 5:08 PM
To: 'Keith Leo Chi Yung'; PBSP
Cc: SUR
Subject: RE: FINAL REPORT / SCK329J

Dear Caroline,

Confirmed amount \$16,319.85 before excess \$1500 and GST @ 9 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>
Sent: Friday, 23 November 2018 12:35 PM
To: PBSP <pml-pbsp@sime-darby.com.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: FINAL REPORT / SCK329J

Warm Regards

Keith Leo
Body & Paint
DDI: 6319 0172
FAX: 6479 4601

UNLOCK A WORLD OF JOY
WITH 0% INTEREST RATES*.

*T & Cs apply.

Book a Test Drive

WORLD OF JOY

The advertisement features a row of seven car keys, each with a different colored fob, set against a dark background. The text is in white and yellow, with the 'WORLD OF JOY' logo in the bottom right corner.

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: PBSP
Sent: Monday, 19 November, 2018 5:35 PM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: Re: FINAL REPORT / SCK329J

Dear Keith

Gentle reminder

Thanks

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Monday, 12 November 2018 10:59:46 AM
To: Keith Leo Chi Yung
Cc: PBSP; SUR
Subject: FW: FINAL REPORT / SCK329J

Dear Keith,

Re-forward.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 8 November 2018 10:07 AM
To: Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>; PBSP <pml-pbsp@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: FW: FINAL REPORT / SCK329J

Dear Keith,

Kindly provides us check items photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

• **From:** PBSP <pml-pbsp@simedarby.com.sg>
Sent: Wednesday, 7 November 2018 2:54 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SCK329J

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 7,611.00
Total Parts : 8,708.85
Total Labour & Parts : 16,319.85

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2018		26 Sep 2018 09:35 Edit Adj Rpt	\$516,319.85 Edit Estimates	\$516,319.85 View Rpt		Pending for Survey Report Cancel Case

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=dsp...> 30/11/2018

Claim Documents

*SCK329J (571640)
OD
Sep 24 2018 3:00PM
[PERFORMANCE MOTORS LTD]
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print			
1	25/09/18 10:30	Accident Statement		 Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	27/09/18 14:44	Adjuster Immediate Advice		 Load HTM				
2	23/11/18 16:02	Adjuster Immediate Advice		 Load HTM				
Photos/Images							3 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print			
1	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
2	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
3	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
4	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
5	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
6	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
7	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
8	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
9	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
10	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
11	25/09/18 10:28	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	27/09/18 12:07	General View		 Load JPG	☒			
2	27/09/18 12:07	General View		 Load JPG	☒			
3	27/09/18 12:07	General View		 Load JPG	☒			
4	27/09/18 12:07	General View		 Load JPG	☒			
5	27/09/18 12:07	General View		 Load JPG	☒			
6	27/09/18 12:07	General View		 Load JPG	☒			
7	27/09/18 12:07	General View		 Load JPG	☒			
8	27/09/18 12:07	General View		 Load JPG	☒			
9	27/09/18 12:07	General View		 Load JPG	☒			
10	27/09/18 12:07	General View		 Load JPG	☒			
11	27/09/18 12:07	General View		 Load JPG	☒			
12	27/09/18 12:07	General View		 Load JPG	☒			
13	27/09/18 12:07	General View		 Load JPG	☒			
14	27/09/18 12:07	General View		 Load JPG	☒			
15	27/09/18 12:07	General View		Load JPG	☒			
16	27/09/18 12:07	General View		Load JPG	☒			
17	27/09/18 12:07	General View		Load JPG	☒			

Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
18	27/09/18 12:07	General View		☒
19	27/09/18 12:07	General View		☒
20	27/09/18 12:07	General View		☒
21	27/09/18 12:07	General View		☒
22	27/09/18 12:07	General View		☒
23	27/09/18 12:07	General View		☒
24	27/09/18 12:07	General View		☒
25	27/09/18 12:07	General View		☒
26	27/09/18 12:07	General View		☒
27	27/09/18 12:07	General View		☒
28	27/09/18 12:07	General View		☒
29	27/09/18 12:07	General View		☒
30	27/09/18 12:07	General View		☒
31	27/09/18 12:07	General View		☒
32	27/09/18 12:07	General View		☒
33	27/09/18 12:07	General View		☒
34	27/09/18 12:07	General View		☒
35	27/09/18 12:07	General View		☒
36	27/09/18 12:07	General View		☒
37	23/11/18 15:41	Reinspection Photo		☒
38	23/11/18 15:41	Reinspection Photo		☒
39	23/11/18 15:41	Reinspection Photo		☒
40	23/11/18 15:41	Reinspection Photo		☒
41	23/11/18 15:41	Reinspection Photo		☒
42	23/11/18 15:41	Reinspection Photo		☒
43	23/11/18 15:41	Reinspection Photo		☒
44	23/11/18 15:41	Reinspection Photo		☒
45	23/11/18 15:41	Reinspection Photo		☒
46	23/11/18 15:41	Reinspection Photo		☒
47	23/11/18 15:41	Reinspection Photo		☒
48	23/11/18 15:42	Reinspection Photo		☒
49	23/11/18 15:42	Reinspection Photo		☒
50	23/11/18 15:42	Reinspection Photo		☒
51	23/11/18 15:42	Reinspection Photo		☒
52	23/11/18 15:42	Reinspection Photo		☒
53	23/11/18 15:42	Reinspection Photo		☒
54	23/11/18 15:42	Reinspection Photo		☒
55	23/11/18 15:42	Reinspection Photo		☒
56	23/11/18 15:42	Reinspection Photo		☒
57	23/11/18 15:42	Reinspection Photo		☒
58	23/11/18 15:42	Reinspection Photo		☒
59	23/11/18 15:42	Reinspection Photo		☒
60	23/11/18 15:42	Reinspection Photo		☒
61	23/11/18 15:42	Reinspection Photo		☒
62	23/11/18 15:42	Reinspection Photo		☒
63	23/11/18 15:42	Reinspection Photo		☒
64	23/11/18 15:42	Reinspection Photo		☒
65	23/11/18 15:42	Reinspection Photo		☒
66	23/11/18 15:42	Reinspection Photo		☒
67	23/11/18 15:43	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
68	23/11/18 15:43	Reinspection Photo		☒
69	23/11/18 15:43	Reinspection Photo		☒
70	23/11/18 15:43	Reinspection Photo		☒
71	23/11/18 15:43	Reinspection Photo		☒
72	23/11/18 15:43	Reinspection Photo		☒
73	23/11/18 15:43	Reinspection Photo		☒
74	23/11/18 15:43	Reinspection Photo		☒
75	23/11/18 15:43	Reinspection Photo		☒
76	23/11/18 15:43	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/09/18 17:29	COE/PARF		☐
2	25/09/18 17:30	ESTIMATE + DRIVING LICENCE		☐
3	25/09/18 17:30	REQUEST SURVEY		☐
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/09/18 08:44	Sketch Plan [Linked Accident Report Documents]		☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 12:06	MARK ESTIMATE		☐
2	23/11/18 15:46	1ST MARK ESTIMATE		☐
3	23/11/18 15:47	SUPPLEMENTARY		☐

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/09/18 10:30	Accident Statement		☐
Photos/Images			3 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/09/18 10:28	Accident Photo		☒
2	25/09/18 10:28	Accident Photo		☒
3	25/09/18 10:28	Accident Photo		☒
4	25/09/18 10:28	Accident Photo		☒
5	25/09/18 10:28	Accident Photo		☒
6	25/09/18 10:28	Accident Photo		☒
7	25/09/18 10:28	Accident Photo		☒
8	25/09/18 10:28	Accident Photo		☒
9	25/09/18 10:28	Accident Photo		☒
10	25/09/18 10:28	Accident Photo		☒
11	25/09/18 10:28	Accident Photo		☒
Documentation			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/09/18 08:44	Sketch Plan		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Sheraton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18017484/T1VBE2

Date: 30/11/2018

REFERENCE

Insured/Claimant: PERFORMANCE MOTORS LTD

Policy No: 27392999MTR

Date of Loss: 24/09/2018

Nature of Claim: OD

Claim No: 571640

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCK329J

Make & Model: BMW 735Li, 3.6 (A)

Engine No: 25919622B58B30A

Reg. Date: 02/08/2016 (Man. Year: 2016)

Chassis No: WBA7E22050G651542

Colour: Black

Odometer: 49811 km

Engine Capacity: 2998 cc

Market Value/New Car Price: S\$260,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R20

Rear Tyre Size: 245/40 R20

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,755.45	8,941.85	15,813.60	63.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,258.00	7,378.00	2,880.00	28.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,013.45	16,319.85	18,693.60	53.39
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	33,513.45	14,819.85	18,693.60	55.78
+ GST 7.00/7.00% (S\$)	2,345.94	1,037.39	1,308.55	55.78
Nett Amount (S\$)	35,859.39	15,857.24	20,002.15	55.78

INSPECTION

Date of Assignment: 26/09/2018

Date Inspected: 26/09/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2018)
Parts: 143	BMW 735LI 3.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCK329J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*RADIATOR	Bent	974.25 FS	*974.25 FS
4	1		*COVER TOP	Not Necessary	70.60 FS	*- FS
5	1		*COVERING LOWER	Not Necessary	70.60 FS	*- FS
6	1		*RADIATOR	Not Necessary	1,082.50 FS	*- FS
7	1		*ROCK GUARD	Not Necessary	91.75 FS	*- FS
8	1		*HOSE RADIATOR TRANSMISSION OIL COOL	Not Necessary	100.10 FS	*- FS
9	1		*ALUMINIUM BONNET	Bent	2,882.55 FS	*2,882.55 FS
10	1		*SET MOUNTS PDC SENSOR FRT	Necessary	69.00 FS	*69.00 FS
11	1		*FRT BUMPER BOTTOM CARRIER	Bent	441.55 FS	*441.55 FS
12	1		*GUIDE LH BOTTOM	Not Necessary	14.55 FS	*- FS
13	1		*GUIDE RH BOTTOM	Not Necessary	14.55 FS	*- FS
14	1		*GUIDE TOP LH	Not Necessary	30.35 FS	*- FS
15	1		*GUIDE TOP RH	Not Necessary	30.35 FS	*- FS
16	1		*LH SUPPORT FOG LAMP	Not Necessary	61.90 FS	*- FS
17	1		*RH SUPPORT FOG LAMP	Not Necessary	61.90 FS	*- FS
18	1		*IMPACT ABSORBER TOP	Deformed	83.20 FS	*83.20 FS
19	1		*FRT BOTTOM IMPACT ABSORBER	Deformed	67.40 FS	*67.40 FS
20	1		*FRT BUMPER CARRIER	Cracked	802.80 FS	*802.80 FS
21	1		*LH PROTECTIVE STRIP BOTTOM	Not Necessary	50.95 FS	*- FS
22	1		*RH PROTECTIVE STRIP BOTTOM	Not Necessary	50.95 FS	*- FS
23	1		*PROTECTIVE STRIP TOP LH	Not Necessary	82.65 FS	*- FS
24	1		*PROTECTIVE STRIP TOP RH	Not Necessary	82.65 FS	*- FS
25	1		*BUMPER GUARD CENTRE	Deformed	77.50 FS	*77.50 FS
26	1		*BUMPER GUARD CENTRE	Not Necessary	77.50 FS	*- FS
27	1		*DAMPER KERB DESCENT	Not Necessary	5.10 FS	*- FS
28	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,503.60 FS	*1,503.60 FS
29	1		*FRT BUMPER TOWING LUG COVER PRIMED	Not Necessary	55.70 FS	*- FS
30	1		*LICENCE PLATE BASE	Deformed	68.95 FS	*68.95 FS
31	1		*GRILLE AIR INLET MIDDLE (PURE EXCEL	Cracked	76.35 FS	*76.35 FS
32	1		*GRILLE AIR INLET LH (PURE EXCELLENC	Not Necessary	71.80 FS	*- FS
33	1		*GRILLE AIR INLET RH (PURE EXCELLENC	Not Necessary	71.80 FS	*- FS
34	1		*RH INSULATED	Not Necessary	51.50 FS	*- FS
35	1		*TRIM GRILLE I-CAM	Not Necessary	20.35 FS	*- FS
36	1		*FRT LH GRILLE (BASIS)	Not Necessary	174.95 FS	*- FS
37	1		*FRT RH GRILLE (BASIS)	Not Necessary	174.95 FS	*- FS
38	1		*HOLDER	Not Necessary	9.75 FS	*- FS
39	1		*AIR FLAPS TOP	Deformed	316.25 FS	*316.25 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
41	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
42	1		*CONNECTION FRT TOP	Deformed	252.05 FS	*252.05 FS
43	1		*FRT PANEL SUPPORT	Not Necessary	82.55 FS	*- FS
44	1		*AIR DUCT BOTTOM	Deformed	36.95 FS	*36.95 FS
45	1		*LH HEADLIGHT MOUNTING	Not Necessary	134.30 FS	*- FS
46	1		*COVERING CROSS MEMBER (ECE)	Deformed	33.50 FS	*33.50 FS
47	1		*AIR DUCT RADIATOR TOP	Not Necessary	56.65 FS	*- FS
48	1		*AIR DUCT RADIATOR BOTTOM	Not Necessary	56.65 FS	*- FS
49	1		*LH HEADLIGHT LED AHL HIGH (ICON LIG	Not Necessary	5,847.60 FS	*- FS
50	1		*RH HEADLIGHT LED AHL HIGH (ICON LIG	Not Necessary	5,847.60 FS	*- FS
51	2		*ULTRASONIC SENSOR BLACK	Not Necessary	497.40 FS	*- FS
52	4		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
53	1		*SURROUND VIEW CAMERA	Not Necessary	681.10 FS	*- FS
54	2		*BLIND RIVET	Necessary	3.50 FS	*3.50 FS
55	10		*EXPANDING NUT L=19.9MM	Necessary	14.00 FS	*14.00 FS
56	1		*FRT LH GRILLE (PURE EXCELLENCE)	Cracked	209.90 FS	*209.90 FS
57	1		*FRT RH GRILLE (PURE EXCELLENCE)	Cracked	262.40 FS	*262.40 FS
58	1		*FRT CROSSLINK	Bent	157.10 FS	*157.10 FS
59	1		*Y STRUT	Bent	26.75 FS	*26.75 FS
60	1		*ENGINE COMPARTMENT SHIELDING FRT	Deformed	171.95 FS	*171.95 FS
61	1		*COVER STEERING GEAR	Deformed	46.55 FS	*46.55 FS
62	2		*ANTI-FREEZE 1.5 LITRES	Necessary	39.50 FS	*39.50 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	24,755.45	8,941.85
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER, AIR DUCT, SUPPORT, BONNET AND ATTACHMENTS	New	5,100.00	4,250.00
2	PAINTING FRONT BUMPER AND BONNET	New	2,167.00	1,950.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS. IF REPLACE 1 SIDE @\$481	New	837.00	0.00
5	TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING TO CONDUCT PRESSURE TEST, BLEED COOLING SYSTEM AND CHECK FOR LEAK (FOR ALL MODELS EXCEPT 7 SERIES)	New	826.00	702.00
6	TO REPLACE AUXILIARY RADIATOR ASSEMBLY INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM AND CHECK FOR LEAK	New	767.00	0.00
7	TO REMOVE AND INSTALL FRONT VIEW CAMERAS INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	266.00	226.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			10,258.00	7,378.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >