## BH AUTO SERVICES PTE LTD

Blk 1, Sector C , Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636 Tel: 6559 8944 / Fax: 6269 2404

ATTN: MOTOR CLAIMS DEPARTMENT AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120

TEL: 6419 3000

ACCIDENT REPAIR ON: SKN4860D

MODEL: NISSAN 200SX(M) POLICY NO: GA233885/1

CHASSIS NO : JN1GBAS15A0031575 YEAR OF MANUFACTURE : 2001

DATE / TIME OF ACCIDENT: 20/09/2018@11:00HRS

LOCATION : ALONG SOO CHOW DRIVE THIRD PARTY VEHICLE NO : SKS4410T

DATE: 16/11/2018 PAGE: 1 OF 1

> Nor Norhanne Rehmy Ather Pains

REPLACEMENT OF PARTS	QUANTITY	UNIT PRICE	1	AMOUNT
1 REAR BUMPER	1	n	\$	1,368.20
	LES	S 30%	\$	(410.46)
	PARTS	STOTAL	\$	957.74

SPECIAL NETT ITEMS	QUANTITY	UNIT PRICE	AMOUNT
1 REAR BUMPER CLIPS	10		\$~~ 50.00
	PARTS	STOTAL	\$ 50.00

LABOUR CHARGES FOR REAR PORTION		AMOUNT	
1 PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$	300.00	
2 PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		300.00	
LABOUR TOTAL	\$	600.00	

TOTAL PARTS & LABOUR	\$	1,607,74
GST 7%	\$	112.54
GRAND TOTAL	\$	1,720.28
ESTIMATE REPAIR DURATION	3 DAYS	

YOURS SINCERELY

ESTIMATOR: KIT TEL: 8405 4058 FAX: 6269 2404

EMAIL: karkit.ngai@bhauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: