

27/03/2002

ASS. REC. BY:

REF:

CS/MSG18017487/Tthber

Special Instruction:

Survivor

laufidh

ASSIGNMENT (Office)

From (Person):

Nara Milah

of

MSLH

Date/Time:

26/9/2018 9:37am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 6051 X

Insured:

at Workshop m/s

Performance Motor

Tel:

8121 4600

of

303 Alexander Rd

Policy No:

27392999MTR

Claim No:

571253

Sum Insured:

Excess:

\$ 1500.00

Make of Veh:

(Client's Record)

D.O.A.

24/9/2018

CA / REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

26/9/2018 9:51am

Person Contacted:

Inthiran

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLS 6051X - X

27/9-

Revert via menimen.

28/9@

8.07am - authorize by Ng Chew How

28/9@

9:50am email to Inthiran authorize excess \$1500 -

Part by Part \$15245.20 (Red: 3065.6', 16%)

Taufiq

REF: MS19

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 91500
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9190K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT
Luhman

Veh No: SLS 6057X Yr Regn: 2017 Sep
Type: M / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: BMW 530I c.c. 1998
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 7914 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBAJA520706885636
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: _____ R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 26/2/18
Survey held at PMC
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Frt o/s
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 3 5 DEC 2018	
	<u>[Signature]</u> 5/12/2018

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 512 Typist
 Date/Time, File Return to?
 2) _____

Report Format: OD
 Lump Sum / I.B.I.: (\$ 15245.20)

Days Of Repair: 7
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))

Survey Fee: 200
 Transportation _____)
 S + RS. Sl _____)
 Photos _____)
 Others 10)
 TOTAL 210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2018		26 Sep 2018 09:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	PERFORMANCE MOTORS LTD , Co. Reg. No.: 197401559W								
Vehicle Reg. No.:	SLS6051X	Date of Loss:	24/09/2018 15:00 - :59 [11 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 571253	Policy/Cover Note No.:	27392999MTR (Comprehensive) Coverage: 01/10/2017 - 30/09/2018						
		Excess:	S\$1,500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Miah Yeo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/09/2018]								
Driver/Custodian:	SEAH JOO BENG KIRBY (30 / Male), NRIC: S8802821Z, Tel: +6596559812								
Adj Asg. Remarks:	Car In. Please revert. Thanks.								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS									
			View All	Search Tasks	Create New Task	Complete			
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SLS6051X (571253)**
OD
Sep 24 2018 3:00PM
[PERFORMANCE MOTORS LTD]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 28/09/2018 08:07 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14906.20) - SLS6051X - Claim Handler: Clara Milah Yeo

Approved:14906.20.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 28 September 2018 9:50 AM
To: Inthiran Thurasamy
Cc: SUR
Subject: SLS 6051X / MSIG / OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLS 6051X (Excess \$1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1559W
Vehicle Details	
Vehicle No.:	SLS6051X
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	530I LED NAV
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	14919932B48B20B
Chassis No.:	WBAJA52070G885636
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$50,933.00
Original Registration Date:	28 Sep 2017
First Registration Date:	28 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$63,680.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2027
PARF Rebate Amount:	\$47,760.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$45,000.00
Total Rebate Amount:	\$92,760.00

The information contained herein is correct as at 27 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2018 08:47
Date Of Accident	24/09/2018 15:15
Exact Location Of Accident	PML'S ROOF TOP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS6051X
Insured/Policyholder	
Name Of Registered Owner	PERFORMANCE MOTORS LTD
Co Reg No	197401559W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96559812

Vehicle Particulars

Manufacturer	BMW
Model	530
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	SEAH JOO BENG KIRBY
NRIC No	S8802821Z
Date Of Birth	27/01/1988
Occupation	INDOOR
Date Of Driving Pass	02/10/2007
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96559812
Fax Number	
Contact Number	
EEmail Address	KIRBY.SEAH.JOOBENG@SIMEDARBY.COM.SG

Address	666B PUNGGOL DRIVE #08-558
Postcode	822666
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCK329J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

 24/11
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: General Insurance Association of Singapore
 NRIC/FIN No: S9041

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


At about 1515 hrs on 24/09, 2018. Completed car wash for SLS 6051X. Driving the said car out of washing bay and met into a collision with SCK329J at the junction as he was going against the flow of traffic.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

x 
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 24/09


 Reporting Centre Personnel's Signature
 Name: Singapore 15504
 NRIC/FIN No.:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48555	Page No. : 1 of 5
Date Estimated : 25/09/2018	
Prepared By : Inthiran A/L Thurasamy	

<p>- ESTIMATE REPAIR FOR - Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941</p>	<p>- ACCOUNT - 66 MSIG Insurance (S) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807</p>
----------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS6051X	G885636	28/09/2017	530i	0

DESCRIPTION	VALUE
To replace front bumper, support right, fender right, attachments and repair right door.	2550 4,250.00
Painting front bumper, fender right and front right door.	2527 2,808.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To replace right headlight.	408 481.00
To carry out body cavity preservation. (Per panel).	100 118.00
To replace tyre and wheel rim including balancing. (1x).	80 94.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	451 531.00
Sundries.	150.00
Total Labour 1:	8,609.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM FERRICGREY 9JX19 SPK 663	1	1,541.65	1,541.65
FRT SIDE PANEL BRACKET 3	1	53.55	53.55
FRT RH SIDE PANEL BRACKET 1	1	53.55	53.55
FRT RH SIDE PANEL ALUMINIUM	1	906.50	906.50
FRT RH SIDE PANEL BRACKET 2	1	53.55	53.55
RH GUIDE TOP	1	34.55	34.55
RH BUMPER GUIDE	1	16.15	16.15
FRT BUMPER PANEL PRIMED (PMA/PDC)	1	1,290.35	1,290.35
SET MOUNTING PDC/PMA SENSOR FRT	1	77.60	77.60
RH HEADLIGHT MOUNTING	1	136.80	136.80
RH HEADLIGHT LED AHL HIGH (ICON LIG	1	4,855.25	4,855.25
DECOUPLING RING PDC TORQUE CONVERTER	6	5.05	30.30



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48555	Page No. : 2 of 5
Date Estimated : 25/09/2018	
Prepared By : Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS6051X	G885636	28/09/2017	530i	0

DESCRIPTION	QTY	PRIC	VALUE
Ultrasonic s	1	380.65	380.65
Total Parts :			9,430.45

(Faint background form)

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No _____ Claim No _____

Date&Time 26/9/18 Excess S\$ 1500

Surveyor's Name Tanjith Sign [Signature]

Surveyor's Tel 97495749 Authorised Yes / No _____

Auth used Date Report Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjith@ulianto.com

Days Recommend 07 days

Handwritten signature and date: 27/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

1831020

Labour 1	:	8,609.00
Parts	:	9,430.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,262.76
Grand Total	:	19,302.21

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

Performance Motors Limited

A member of the Sime Darby Group
Co, Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 48555
Date Estimated : 25/09/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLS6051X	G885636	28/09/2017	530i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET *	3.15	2.00		6.30
# RH FOG LAMP SUPPORT *	77.95	1.00		77.95
# LETTERING (LUXURY LINE) *	45.20	1.00		45.20
# COVER BULB REPLACEMENT *	9.85	1.00		9.85
# FRT RH WHEEL ARCH FRT SECTION COVER *	132.05	1.00		132.05

Total Labour:	
Total Parts:	271.35
Total Labour & Parts:	271.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 48555
Date Estimated : 25/09/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLS6051X	G885636	28/09/2017	530i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, front RH fender and attachments, RH foglamp support include making good the front RH door and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint front bumper, front RH fender and front RH door	2527.00		2,527.00	
To check electrical wiring systems at the front section for proper function	150.00		150.00	
To replace RH LED AHL headlight include programming and conducting tests for proper function	408.00		408.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To replace wheel rim include balancing (1x)	80.00		80.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET *	3.15	2.00		6.30
ALLOY RIM FERRICGREY 8JX19 SPK 663	1,401.50	1.00		1,401.50
FRT RH SIDE PANEL BRACKET 1	53.55	1.00		53.55
FRT RH SIDE PANEL ALUMINIUM	906.50	1.00		906.50
# RH FOG LAMP SUPPORT *	77.95	1.00		77.95
RH GUIDE TOP	34.55	1.00		34.55
RH BUMPER GUIDE	16.15	1.00		16.15
FRT BUMPER PANEL PRIMED (PMA/PDC)	1,290.35	1.00		1,290.35
# LETTERING (LUXURY LINE) *	45.20	1.00		45.20
# COVER BULB REPLACEMENT *	9.85	1.00		9.85
# FRT RH WHEEL ARCH FRT SECTION COVER *	132.05	1.00		132.05
RH HEADLIGHT LED AHL HIGH (ICON LIG	4,855.25	1.00		4,855.25

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

SUPPLEMENTARY ITEMS

Total Labour :	6,416.00
Total Parts :	8,829.20
Total Labour & Parts :	15,245.20
Deduction for Excess :	1,500.00
Total Repair Costs less Excess:	13,745.20
GST @7%:	962.16
Grand Total :	<u>14,707.36</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2018		26 Sep 2018 09:37 Edit Adj Rpt	S\$15,245.20 Edit Estimates	S\$15,245.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	PERFORMANCE MOTORS LTD , Co. Reg. No.: 197401559W								
Vehicle Reg. No.:	SLS6051X	Date of Loss:	24/09/2018 15:00 - :59 [11 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 571253	Policy/Cover Note No.:	27392999MTR (Comprehensive) Coverage: 01/10/2017 - 30/09/2018						
		Excess:	S\$1,500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/10/2018]								
Driver/Custodian:	SEAH JOO BENG KIRBY (30 / Male), NRIC: S8802821Z, Tel: +6596559812								
Adj Asg. Remarks:	Car in. Please revert. Thanks.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> MSIG_SG (04/12/2018): Alert - Adj Mandate Approved (S\$15245.20) - SLS6051X - Claim Handler: Clara Mila... MSIG_SG (28/09/2018): Alert - Adj Mandate Approved (S\$14906.20) - SLS6051X - Claim Handler: Clara Mila... 									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS6051X (571253)
OD
Sep 24 2018 3:00PM
[PERFORMANCE MOTORS LTD]
Performance Motors Limited

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>
Assessment Reports				1 per page <input type="button" value=""/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/09/18 10:36	Accident Statement	Load HTM	<input type="checkbox"/>
No		LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 13:46	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
2	27/11/18 15:46	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="button" value=""/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
3	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
4	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
5	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
6	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
7	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
8	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
9	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
10	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
11	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
12	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
13	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
14	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
15	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
16	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
17	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
18	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
19	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
20	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
21	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
22	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
23	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
24	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
25	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
26	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
27	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
28	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
29	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
30	27/09/18 13:50	General View	Load JPG	<input checked="" type="checkbox"/>
31	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	27/11/18 15:36	Reinspection Photo	Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
				<input checked="" type="checkbox"/>
34	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	27/11/18 15:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/09/18 16:44	TP SCK329J GIA report	Load PDF	
2	25/09/18 16:44	Repair Estimate + IC & DL + Staff Pass + Policy Schedule	Load PDF	
3	25/09/18 16:48	Email from w/shop to request for survey	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 13:50	ESTIMATE	Load PDF	
2	27/11/18 15:37	ESTIMATE 2	Load PDF	
3	27/11/18 15:37	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/09/18 10:36	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
7	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	25/09/18 10:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/09/18 08:51	Sketch Plan	Load TIF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18017487/T1TB2E
Date: 10/12/2018

REFERENCE

Insured/Claimant:	PERFORMANCE MOTORS LTD	Policy No:	27392999MTR
Date of Loss:	24/09/2018	Nature of Claim:	OD
		Claim No:	571253

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6051X	Engine No:	14919932B48B20B
Make & Model:	BMW 530I, 2.0 LED NAV (A)	Chassis No:	WBAJA52070G885636
Reg. Date:	28/09/2017 (Man. Year: 2017)	Odometer:	7914 km
Colour:	Beige		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$190,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,851.80	8,979.20	872.60	8.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,459.00	6,266.00	2,193.00	25.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,310.80	15,245.20	3,065.60	16.74
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
	(S\$)	16,810.80	13,745.20	3,065.60
+ GST 7.00/7.00% (S\$)	1,176.76	962.16	214.60	18.24
Nett Amount (S\$)	17,987.56	14,707.36	3,280.20	18.24

INSPECTION

Date of Assignment:	26/09/2018	
Date Inspected:	26/09/2018	Inspected At:
		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2018)
Parts: 143	BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLS6051X)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*ALLOY RIM FERRICGREY 9JX19 SPF 663	Cut	1,541.65 FS	*1,401.50 FS
3	1		*FRT SIDE PANEL BRACKET 3	Not Necessary	53.55 FS	*- FS
4	1		*FRT RH SIDE PANEL BRACKET 1	Bent	53.55 FS	*53.55 FS
5	1		*FRT RH SIDE PANEL ALUMINIUM	Bent	906.50 FS	*906.50 FS
6	1		*FRT RH SIDE PANEL BRACKET 2	Not Necessary	53.55 FS	*- FS
7	1		*RH GUIDE TOP	Deformed	34.55 FS	*34.55 FS
8	1		*RH BUMPER GUIDE	Necessary	16.15 FS	*16.15 FS
9	1		*FRT BUMPER PANEL PRIMED (PMA/PDC)	Deformed	1,290.35 FS	*1,290.35 FS
10	1		*SET MOUNTING PDC/PMA SENSOR FRT	Not Necessary	77.60 FS	*- FS
11	1		*RH HEADLIGHT MOUNTING	Not Necessary	136.80 FS	*- FS
12	1		*RH HEADLIGHT LED AHL HIGH (ICON LIG	Cracked	4,855.25 FS	*4,855.25 FS
13	6		*DECOUPLING RING PDC TORQUE CONVERTER	Not Necessary	30.30 FS	*- FS
14	1		*ULTRASONIC S	Not Necessary	380.65 FS	*- FS
15	2		*ADJUSTABLE BLIND RIVET	Necessary	6.30 FS	*6.30 FS
16	1		*LETTERING (LUXURY LINE)	Necessary	45.20 FS	*45.20 FS
17	1		*COVER BULB REPLACEMENT	Deformed	9.85 FS	*9.85 FS
18	1		*FRT RH WHEEL ARCH FRT SECTION COVER	Deformed	132.05 FS	*132.05 FS
19	1		*RH FOG LAMP SUPPORT	Deformed	77.95 FS	*77.95 FS
Total Parts (\$\$)					9,851.80	8,979.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER, SUPPORT RIGHT, FENDER RIGHT, ATTACHMENTS AND REPAIR RIGHT DOOR	New	4,250.00	2,550.00
2	PAINTING FRONT BUMPER, FENDER RIGHT AND FRONT RIGHT DOOR	New	2,808.00	2,527.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO REPLACE RIGHT HEADLIGHT	New	481.00	408.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X)	New	94.00	80.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	451.00
Gross Labour Cost (\$\$)			8,459.00	6,266.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >