

Surveyor:

PASUL

DOI:

ASSIGNMENT

25/09/18

Date of tr:

21/9/18

Registered to Mariner:

Pre-assign / CCU / FTE

YN1038R



Insured Vehicle No. :

Claim No. : 17488/18/VC10/020937

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II : \$5

D.O.A. : 19/09/18

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (VL: YES / NO)

Insured Liability : % Final ? Yes / No

YP 27920



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sin Ming



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler: Typist:

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

27/9

Sent By:

h

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 46

\$5 1,800.00 (3 days) Reduction: 40 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

19/08/19

Confirm with:

Pai SIN

Email ☒ Call ☐

Final Liability:

%

50

(Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost: 21,926.00

\$5

963.00

Loss of Rental (LOR):

\$5

-

(days)

Loss of Use (LOU):

\$5

600.00

\$120 x 5 days)

Loss of Income (LOI):

\$5

-

(\$ x days)

LOR only ☐ LOU only ☒

\$5

LOR + LOU ☐ LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5

2.00

Medical:

\$5

-

Disbursement:

\$5

-

Legal Cost:

\$5

-

(e.g. Tow/Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4460.00

Total: 42,528.00

\$5

1,265.00

Global Sum \$5: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$5

1,265.00

Name 1:

SIN SHING ENGINEERING SERVICES

Payee 2: (Strike if N.A.)

\$5

-

Name 2:

Payee 3: (Strike if N.A.)

\$5

-

Name 3:


Superior *Parme*

REF:

4962

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **YP 27920**
 at Workshop m/s: **Sin Seng**
 of _____
 Insured: **LPC / up**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: **YP 27920** Yr Regn: **2016 / Jun**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **mitsubishi Canter Feb 71** c.c. **2498**
 Colour: **Red** A/C: Insured / Std / NI / NA
 Sp. Reading: **72438** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 Cr/No: **FEB 71 EA 20217**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: NP / S/Rim / STD A/Rim or
 Tyre Size: F: **215/75 R17.5**
 R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **D/O**
 Front: _____ Rear: _____
 R/Bal: **7** mm R/Bal: **7/7** mm
 L/Bal: **7** mm L/Bal: **7/7** mm
 D.O.A: **19/09/18** D.O.I: **25/09/18**
 Survey held at: **Sin Seng**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	US \$1,800.00
	CRP: \$1,221.00 (40%)

Date/Time. File Pass to? ☐ : Preli. Report
☐ : Final Report
 1) _____
 Date/Time. File Return to? _____
 2) _____

Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 1) Photos _____
 1) Others _____
 TOTAL: _____



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VC10/020937
Our ref: CC4/LPC18017488/R1fa3

Date: 27.09.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

YP 2792D

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25.09.2018 at the premises of M/s Sin Sheng Engineering Services have the following to report:-

Workshop Estimate Amount	: S\$	3,021.00
Revised Estimate Amount	: S\$	2,266.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,266.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1196N

Vehicle Details

Vehicle No.:	YP2792D
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB71ER4SDEC (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C25779
Chassis No.:	FEB71EA20217
Maximum Power Output:	-
Open Market Value:	\$35,237.00
Original Registration Date:	06 Jun 2016
First Registration Date:	06 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$1,762.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	05 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$44,213.00
COE Rebate Amount:	\$32,852.00
Total Rebate Amount:	\$32,852.00

The information contained herein is correct as at 24 Sep 2018

OK

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002611

Date : 24/09/2018

Vehicle Num. : YP2792D

Make/Model : MITSUBISHI FEB 21

Chassis/Eng# : FEB21EA20217

Accident Date : 19/09/2018

Claim No. :

Reference : YN1038R

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.	2	FRONT DOOR, LHS (R&M)		
3.	1	DOOR HINGE		
		CONTAINER LOCK		

Nett Total S\$:

10.00% Discount S\$:

LABOUR :

TO REPAIR REAR BODY

TO DISMANTLE/REPLACE REAR DOOR

SPRAY PAINTING

TO APPLY NEW LOGO

LOSS OF USE : 5 DAYS @ \$ 120/DAY

Labour Total S\$:

Rasul

Hp 90010068

3 days

43

25/09/18 @ 1710

Resum after repair

1,500.00
240.00
450.00

2,190.00
219.00

1,971.00

300 450.00

300 400.00

100 200.00

1,050.00

Total S\$: 3,021.00

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 25 September, 2018 9:40 AM
To: assignments
Subject: FW: Accident Involving YP2792D with YN1038R on 19/09/2018

12.40 pm @ 25/9/18

Susan vhin

Rasul

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 25 September 2018 9:36 AM
To: Admin A <admin-a@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; sinsheng engineerservices <sinsheng1981@gmail.com>
Subject: FW: Accident Involving YP2792D with YN1038R on 19/09/2018

Our Ref : 17/18/18/VC10/020937

Dear Catherine/Nivitha,

Kindly proceed with the survey accordingly.

For your information, our insured has yet to lodge a report and we are making enquiries.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: sinsheng engineerservices [<mailto:sinsheng1981@gmail.com>]

Sent: Tuesday, 25 September, 2018 9:25 AM

To: GERALD POH WEE BIN

Cc: MT_Claim_SG

Subject: Re: Accident Involving YP2792D with YN1038R on 19/09/2018

Hi Mr Gerald,

We are selected Mr Rasul.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On 24 September 2018 at 17:49, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

Without Prejudice

Our Ref : To be advised

Dear Susan,

We attached the list of 10 surveyors from LKK Auto Consultants Pte Ltd
for your attention.

Please let us hear from you.

In addition, for future pre-repair survey, please email to mt_claim@lonpac.com

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: sinsheng engineeringservices [mailto:sinsheng1981@gmail.com]
Sent: Monday, 24 September, 2018 10:38 AM
To: GERALD POH WEE BIN
Subject: Accident Involving YP2792D with YN1038R on 19/09/2018

Dear Officer In charge,

We are repairer of motor vehicle YP2792D. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert us with the liability issue if direct settlement is in order.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 8 October, 2018 4:43 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Accident Involving YP2792D with YN1038R on 19/09/2018
Attachments: INSD REPORT.pdf

Categories: HMK

Dear Mei Kwan,

Attached copy of insured's report

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 27 September, 2018 11:34 AM
To: ONG LI LI
Cc: MT_Claim_SG; Poh Kin (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Accident Involving YP2792D with YN1038R on 19/09/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 17/18/18/VC10/020937
LKK REF: CC4/LPC18017488/R1fa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: YP 2792D

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- TP GIA report

Kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On 24 September 2018 at 17:49, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

Without Prejudice

Our Ref : To be advised

Dear Susan,

We attached the list of 10 surveyors from LKK Auto Consultants Pte Ltd
for your attention.

Please let us hear from you.

In addition, for future pre-repair survey, please email to mt_claim@lonpac.com

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555



新盛机械工程服务

SIN SHENG ENGINEERING SERVICES

REGISTRATION NO : 312029/00D

No 8 Tuas Ave 18 (Level 3), Singapore 638892

Tel : 6863 9595 Fax : 6863 6477 Email : sinsheng1981@gmail.com

Date : 17/08/2019

TO WHOM IT MAY CONCERN

Dear Sir / Mdm,

RE : CHANGED OF COMPANY CORRESPONDENCE ADDRESS

Refer to the above matter.

I would like to inform you that my company correspondence address will change immediately as below and please update accordingly.

8 Tuas Avenue 18
Singapore 638892

Your kind attention for this matter shall be highly appreciated.

Your faithfully,

CHUA GEOK TOH
SOLE PROPRIETOR



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18017488/R1ha3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 03-09-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 1038R	Veh. Inspected	YP 2792D
	Policy No.	Z/18/VC10/102151-001	Coverage (\$)	0.00
	Claim No.	17/18/18/VC10/020937	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	25/09/2018
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI CANTER FEB71	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	FEB71EA20217	Colour	RED
	Odometer	72438	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/75 R17.5	BRIDGESTONE	7 mm
	L/H Front Tyre	215/75 R17.5	BRIDGESTONE	7 mm
	R/H Rear Tyre	215/75 R17.5 (D)	BRIDGESTONE	7/7 mm
	L/H Rear Tyre	215/75 R17.5 (D)	BRIDGESTONE	7/7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	19/09/2018	Inspection Date	25/09/2018
	Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2792D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR ,LHS (N)	TORN	1,500.00	1,500.00
2	DOOR HINGE @\$120.00 (N)	BENT	240.00	240.00
1	CONTAINER LOCK (N)	NOT NECESSARY	450.00	-
	LESS 10% DISCOUNT		-219.00	-174.00
			1,971.00	1,566.00
LABOUR				
	TO REPAIR REAR BODY,TO DISMANTLE /REPLACE REAR DOOR.		450.00	300.00
	SPRAY PAINTING .		400.00	300.00
	TO APPLY NEW LOGO .		200.00	100.00
			1,050.00	700.00
GRAND TOTAL			3,021.00	2,266.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITE PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CC4/LPC18017488/R1ha3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.