

ASS. REC BY: Tauhich REF: CS3/SMO18013355/T1sd37

ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 23/07/18 @ 2:18pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8JZ 725L Insured: SJN 2107X

at Workshop with: Million Auto Tel: 6264 9091

of: No. 4 penjuru place # 01-12

Policy No: _____ Claim No: CMTD1803144 / THE

Sum Insured: _____ Excess: _____

Make of Veh: _____ (Client's Record)

CA / REV / REP. / REV 24 HRS ^{1up} D.O.A. 20/07/2018

Date/Time: 2:58pm @ 23/07/18 Person Contacted: Ms. Chaney H.O.D. Endorsement: _____

Vehicle: IN OUT

Date/Time	Action/Instruction (X) Estimate
	<u>8JZ 725L - X</u>
	<u>SJN 2107X - 4541 AXA 16014 727 / Aurb 52 DUA 3/5/16</u>
<u>12/10/18</u>	<u>Confirmed Hs \$2,000/- @ 3 days with Tauhich</u>
	<u>(\$ 3,239.90 Red - 62%)</u>
	<u>Est. Average 2 Rep. in Day</u>


12/10/2018

RECEIVED 22 NOV 2018

ASSIGNMENT

From: _____ Date: 24/7/18
 Estimated Cost: _____
 ON (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLZ 725 L
 at Workshop m/s Million Auto
 of No. 4 Penjuru Place # 01-12
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt. Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS (up)
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJZ 725L Yr Regn: 2010, out
 Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Kia Auto cc 1571
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 206520 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAPW 4114A . 527 3915
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / (S)Rim / STD A/Rim or
 Tyre Size: F: 215/43R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 24/7/18 @ 12:10 pm
 Survey held at Million Auto
 Des. of Damages: Frt / (R)ear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1/8</u>	<u>Estimated repair range \$4,500 - \$5,000</u>
<u>1/8</u>	<u>Submit PRS report.</u>
	<u>(Signature)</u>
	<u>11/8/18</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 6
 Resurvey No. of Trip: -

Report Format: PRS
 Lump Sum / I.B.I.: (\$ _____)

Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))

Survey Fee: _____
 Transportation: _____
 S + RS: \$ _____
 Photos: _____
 Others: _____
 TOTAL: _____

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 22 November 2018 1:52 PM
To: 'Ms Chong'
Cc: 'Taufikh (LKKAuto)'
Subject: RE: SJZ725L estimate

Hi Ms Chong,

Final invoice and all supporting documents sent over to Sampo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ms Chong [mailto:mschong@millionauto.com]
Sent: Thursday, 22 November 2018 1:36 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>
Subject: RE: SJZ725L estimate

Dear Shirley Hiew,

We confirmed acceptance your offer lump sum \$2000 + 3 days + GST.

Thanks !

Best Regards,
Ms Chong
Million Auto Service
No.4 Penjuru Place #01-12,
Singapore 608782
62649091/82285020

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, November 22, 2018 9:50 AM
To: 'Ms Chong' <mschong@millionauto.com>
Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: SJZ725L estimate

Hi Ms Chong,

Please re-confirm final fig of \$2,000.00 (lump sum) @ 3 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ms Chong [<mailto:mschong@millionauto.com>]

Sent: Monday, 19 November 2018 2:05 PM

To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>

Cc: Taufikh@lkkauto.com

Subject: ref: SJZ725L estimate

Dear Shirley Hiew,

We disagree with your lump sum cost \$17,00.00, please adjust lump sum cost to \$2,200.00.

We look forward on your favorable reply.

Thanks !

Best Regards,

Ms Chong

Million Auto Service

No.4 Penjuru Place #01-12,

Singapore 608782

62649091/82285020

From: Ms Chong [<mailto:mschong@millionauto.com>]

Sent: Friday, November 16, 2018 12:47 PM

To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>

Cc: 'Taufikh@lkkauto.com' <Taufikh@lkkauto.com>

Subject: RE: ref: SJZ725L estimate

Dear Shirley Hiew,

We disagree with your lump sum cost \$17,00.00, please adjust lump sum cost.

We look forward on your favorable reply.

Thanks !

Best Regards,

Ms Chong

Million Auto Service

No.4 Penjuru Place #01-12,

Singapore 608782

62649091/82285020

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Monday, October 15, 2018 2:26 PM

To: 'Ms Chong' <mschong@millionauto.com>; SUR <sur@lkkauto.com>
Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: ref: SJZ725L estimate

RE-SEND

Hi Ms Chong,

Please Confirm final fig of \$1,700.00 (lump sum) @ 3 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ms Chong [<mailto:mschong@millionauto.com>]

Sent: Saturday, 13 October 2018 9:32 AM

To: sur@lkkauto.com

Cc: Taufikh@lkkauto.com

Subject: FW: ref: SJZ725L estimate

Dear ,

Please refer to the attachment for SJZ725L after paint photos.

Thanks !

Best Regards,

Ms Chong

Million Auto Service

No.4 Penjuru Place #01-12,

Singapore 608782

62649091/82285020

From: Ms Chong [<mailto:mschong@millionauto.com>]

Sent: Tuesday, September 25, 2018 1:48 PM

To: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>

Cc: 'sur@lkkauto.com' <sur@lkkauto.com>

Subject: ref: SJZ725L estimate

Dear Taufikh,

Please refer to the attachment for SJZ725L estimate cost.

Thanks !

Best Regards,

Ms Chong

Million Auto Service

No.4 Penjuru Place #01-12,
Singapore 608782
62649091/82285020

萬 汽 車 服 務

MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782
 Website: <http://www.millionauto.com> Email: wendy@millionauto.com
 Tel: 6567 0817, 6264 9091 Fax: 6791 4716
 Reg No: 317413/00-K GST Reg No: M90363176A

Sompo Insurance Singapore Pte. Ltd.
 50 Raffles Place, #05-01/06
 Singapore Land Tower,
 Singapore 048623

Without Prejudice

Attention: Motor Claim Department

ESTIMATE COST FOR REPAIR SJZ725L KIA CERATO

	2 pcs Rear bumper cup <i>clip</i>	9.60 <i>new</i>
	Rear bumper	601.00 <i>del</i>
	Rear bumper lower spoiler	304.00 <i>del</i>
	Rear bumper and foam	144.50 <i>del</i>
	2 pcs Rear retainer R/L	108.00 <i>new</i>
	Rear lid	747.00 <i>Rx</i>
	Rear lid rubber	99.00 <i>xun</i>
	Rear lid lock	113.00 <i>xun</i>
	Rear lamp	194.00 <i>new</i>
	Rear lamp panel	282.30 <i>Rx</i>
	Reverse sensor	167.50 <i>new</i>
	To cut & weld rear panel & floor panel, dismantle & replace rear lamp, lid, bumper, reinforcement, lock & knock (repair damaged & affected parts.)	1,500.00 <i>500</i>
	To spray paint rear panel, floor panel, rear lid, bumper & affected parts	850.00 <i>500</i>
	To check & repair wiring	120.00 <i>30</i>
	Sub total :	5,239.90
	GST 7% :	366.79
	Total: \$	5,606.69

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1528.60
 10% - 1575.74
 Labour - 1130
2505.74
 45 @ 2000 #
 3 days
 gaw



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO18013355/T1sd3s2-1

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 26-11-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 2107X	Veh. Inspected	SJZ 725L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803144/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/07/2018

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFW411MA5273915	Colour	WHITE
Odometer	206520	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45R17	MICHELIN	6 mm
L/H Front Tyre	215/45R17	MICHELIN	6 mm
R/H Rear Tyre	215/45R17	MICHELIN	6 mm
L/H Rear Tyre	215/45R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/07/2018	Inspection Date	24/07/2018
Survey held at	MILLION AUTO SERVICE 4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 725L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	REAR BUMPER CLIP	NECESSARY	9.60	9.60
1	REAR BUMPER	DEFORMED	601.00	601.00
1	REAR BUMPER LOWER SPOILER	DEFORMED	304.00	304.00
1	REAR BUMPER FOAM	DEFORMED	144.50	144.50
2	REAR RETAINER R/L	NECESSARY	108.00	108.00
1	REAR LID	TO REPAIR SEE LABOUR	747.00	-
1	REAR LID RUBBER	NOT NECESSARY	99.00	-
1	REAR LID LOCK	NOT NECESSARY	113.00	-
1	REAR LAMP	CRACKED	194.00	194.00
1	REAR LAMP PANEL	TO REPAIR SEE LABOUR	282.30	-
1	REVERSE SENSOR	NOT WORKING	167.50	167.50
	LESS 10% DISCOUNT		-	-152.86
			2,769.90	1,375.74
LABOUR				
	TO CUT & WELD REAR PANEL & FLOOR PANEL, DISMANTLE & REPLACE REAR LAMP, LID, BUMPER, REINFORCEMENT, LOCK & KNOCK (REPAIR DAMAGED & AFFECTED PARTS.) INCLUSIVE OF THE REPAIR OF REAR LID AND REAR LAMP PANEL.		1,500.00	500.00
	TO SPRAY PAINT REAR PANEL, FLOOR PANEL, REAR LID, BUMPER & AFFECTED PARTS.		850.00	600.00
	TO CHECK & REPAIR WIRING.		120.00	30.00
			2,470.00	1,130.00
GRAND TOTAL			5,239.90	2,505.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS3/SMO18013355/T1sd3s2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.