

## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 21/09/2018

User ID : kimmingchin

### Section A - Accident Details

Registration Number	SHF446X
Case Reference Number	TAX/09/18/2087
Registration Date	12/27/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHIA SENG HOCK
Type of Accident	Head To Side
Accident Date and Time	9/19/2018 12:05 PM
Accident Reported Date and Time	9/19/2018 1:20 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24097996
Special Instruction to ARC, if any	
Prepared Date and Time	9/20/2018 4:34 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates


Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$1,314.00	\$0.00
Total Spare Part Cost	\$3,825.95	\$0.00
Total Other Cost	\$916.88	\$0.00
<b>TOTAL COST</b>	<b>\$6,901.83</b>	<b>\$0.00</b>
Lump Sum Total	\$6,900.00	\$0.00
Number of Repair Days	5.0	3
Prepared / Adjusted By	Tuck Foo Kok	Naz
ARC / Surveyor Sign Off Date	21/09/2018 9:29 AM	
Signature		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

### Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	
<b>Total Labour</b>	<b>\$845.00</b>	





## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/09/2018

User ID : kimmingchin

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	200
TO RESPRAY FRONT FENDER RH	\$378.00	200
TO RESPRAY RIM	\$180.00	80
TO RESPRAY FRONT DOOR RH	\$378.00	200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,314.00</b>	

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	20
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$296.88	1K1
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	50
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$120.00	40
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	30
TO WASH AND VACUUM	\$60.00	x 10
TO TRANSFER DOOR MECHANISM	\$120.00	x 10
<b>Total Other Costs</b>	<b>\$916.88</b>	

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	DEF
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	?
		81511-47050	LENS & BODY, FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	SCR
		81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	SCR
		53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	DD
		53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.77	Replace	TN
		53851-47040	FENDER LINER PAD, FR WHEEL, RH	1.00	\$49.30	25.00	\$36.97	Replace	?
		42611-47140	WHEEL DISC, FRONT	1.00	\$1,484.20	25.00	\$1,113.15	Replace	XR
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.92	Replace	1K1
		85315-47140	WIPER WASHER JAR	1.00	\$180.10	25.00	\$135.07	Replace	?
		53827-47030	FENDER PROTECTOR FRT/RH SIDE	1.00	\$113.90	25.00	\$85.43	Replace	?
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	XR
		68730-12120	HINGE LOWER RHF, DOOR	1.00	\$90.10	25.00	\$67.57	Replace	?
		68710-12151	HINGE UPPER RHF, DOOR	1.00	\$80.50	25.00	\$60.38	Replace	?
		68610-47021	CHECK ASSY, FR DOOR,	1.00	\$150.30	25.00	\$112.73	Replace	?
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	1K1
<b>Total</b>					<b>\$6,065.20</b>		<b>\$4,782.44</b>		

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NA2 LKK  
21/9/18 1730  
LIS  
3 DAYS  
APPROX REPAIR PHOTO