

ASS. REC. BY:

REF: CS/CT18017492/Ktbn2 Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time: 26092018 1058am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 8991P

Insured:

QJD 4591U

at Workshop m/s

BH Auto

Tel:

6551 8944

of

Blk 1 Sin Ming Ind Est # 01-115

Policy No:

DMP(CN3023141800

Claim No:

SNM1800459800.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

26092018 11:04am

Person Contacted:

Jacelyn

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 8991P - X

QJD 4591U - NA / RS103020642 / p1

DCA: 06092008

13/12

1 / Lny 8440d Confirm
(Red: 9285.26, 6796)

REF: CT2

ASSIGNMENT

From:

Date: 28/09/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.:

SLA 2991P

at Workshop m/s:

BH Auto

of:

Blk 1 Simming Ind Est #D1-115

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:


(Client's Record)

Make of Veh.:

10am - 11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$641c

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.:

SLA 2991

Yr Regn.:

03 16

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

N/S Slaphy

c.c.

1598

Colour:

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading:

54244

T/Radio: Insured / Std / NI / NA

Eng/No.:

C/No.:

MN+8BAB1770026883

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

22/9/18

D.O.I.

28/9/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

2 B1

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18 File pass to Carhome

RECEIVED 13 DEC 2018.

Date/Time: File Pass to?



Preli. Report

1) B/R Typst



Final Report

Date/Time: File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ - RS \$

) Photos:

) Others:

Report Format:

TP

Lump Sum / I.B.I. (\$

4400

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2018		26 Sep 2018 10:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LEONG MENG WAI(LIANG MINGWEI), ID: S7409164D								
Main Claimant:	YEO THENG KWEE, ID: S1761678A								
Vehicle Reg. No.:	SLA8991P	Date of Loss:	22/09/2018 08:00 - :59						
Claim Type:	TP / SNM18D04598C02	Policy/Cover Note No.:	DMPCSN3023141800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJD4591U	Policy No. (Claimant):	2100457387-02						
		Excess:	S\$0.00						
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2018]								
Driver/Custodian (Insured):	LEONG MENG WAI(LIANG MINGWEI) (44 / Male), NRIC: S7409164D								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Honda Freed 1.5i AT 32600



Well Maintained! Cheapest In
Market
Grande Car Gallery 11th Fl



Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

12 vehicles

Nissan Sylphy

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Sylphy		Any	Any	2016	Any	Any	Any	Available
	Nissan Sylphy 1.6A		\$65,000	\$7,550 /yr	24-Mar-2016	1,598 cc	58,000 km	Sedan	Available
1.99% Loan Interest Rate Available! Well Maintained By The Previous Owner. Factory Fitted Interior. Accident Free. No Repairs Needed. Best Deal In Town. 2 Years Warranty With Tan Chong. Fully Serviced...									
Carro									
Posted: 25-Sep-2018 Tags: 2016 Nissan Sylphy, 2016 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									
	Nissan Sylphy 1.6A Premium		\$65,000	\$7,740 /yr	27-Jan-2016	1,598 cc	80,000 km	Sedan	Available
Down Payment \$6,500 Only! From \$940/Month. Guaranteed Non-Private Hire Unit. Fully Serviced By Agent, Valid Agent Warranty Till 2019! New Tyres, Original Paint Work, Diligently Maintained! Outstanding...									
Audax Auto Pte Ltd									
Posted: 24-Sep-2018 Tags: 2016 Nissan Sylphy, 2016 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									
	Nissan Sylphy 1.6A Premium		\$69,888	\$7,880 /yr	13-Jul-2016	1,598 cc	25,800 km	Sedan	Available
No Admin Fees! 1 Owner, Low Mileage Done! Fully Agent Maintained! Road Tax Renewed Until July 2019! Superb Condition Like New, Smells New! 100% Accident Free! Most Luxurious Mid-Sized Sedan With Ample...									
Posted: 24-Sep-2018 Tags: 2016 Nissan Sylphy, 2016 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									
	Nissan Sylphy 1.6A Premium		\$70,800	\$8,080 /yr	16-Jun-2016	1,598 cc	40,000 km	Sedan	Available
Fully Serviced And Warranty By Tan Chong! Promo Interest 2.28%! 100% Loan Available For High Trade, In House Financing Plans. 100% Accident Free,\$2000 Deposit Require. Call Us Now Before It Is Gone. \$...									
Hua Yang Credit Pte Ltd									
Posted: 24-Sep-2018 Tags: 2016 Nissan Sylphy, 2016 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									
Car Buying	Car Selling		Car Ownership			Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation			
Car Aftermarket	On The Move		Lifestyle						
	Nissan Sylphy 1.8A Premium		\$72,800	\$8,820 /yr	04-Jan-2016	1,798 cc	21,000 km	Sedan	Available
1.99% RATES, Cheapest In Market,Pearly Black, Higher Bhp Than 1.6L, Just Serviced By Nissan Service Centre, Agent Warranty Till 2019, Low Mileage, Immaculate Condition. Led, Navi, Auto Head Lamps, Sid...									
Posted: 08-Sep-2018 Tags: 2016 Nissan Sylphy, 2016 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									
	Nissan Sylphy 1.6A Premium		\$66,800	\$7,990 /yr	25-Jan-2016	1,598 cc	73,000 km	Sedan	Available
Lowest Depreciation Of \$7900 Only, For A Luxury & Spacious Sedan, 1 Owner, Still Under Warranty, Recently Serviced At Tan Chong In July 2018, Original Paintwork, High Perf \$8141, Flexible Loan Up To 9...									
Posted: 06-Sep-2018 Tags: 2016 Nissan Sylphy, 2016 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									
	Nissan Sylphy 1.6A Premium		\$66,800	\$7,930 /yr	16-Feb-2016	1,598 cc	48,318 km	Sedan	Available
1 Owner, Fully Maintained By Tan Chong Agent, 1 Year Extended Warranty Cover Engine And Gear Box, Original Condition, Comfortable Drive, And Luxury. Comfortable Leg Room Space, Big Trunk Size, Low Mal...									
Accendore Autolution Pte Ltd									
Posted: 06-Sep-2018 Tags: 2016 Nissan Sylphy, 2016 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									

Compare

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1678A

Vehicle Details

Vehicle No.: SLA8991P
Vehicle to be Exported: No
Intended Deregistration Date: 25 Sep 2018
Vehicle Make: NISSAN
Vehicle Model: SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour: Red
Manufacturing Year: 2016
Engine No.: HR16986192B
Chassis No.: MNTBBAB17Z0026883
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$16,807.00
Original Registration Date: 21 Mar 2016
First Registration Date: 21 Mar 2016
Transfer Count: 0
Actual ARF Paid: \$16,807.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 Mar 2026
PARF Rebate Amount: \$12,605.00

Intended COE Rebate Details

COE Expiry Date: 20 Mar 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$45,000.00
COE Rebate Amount: \$33,657.00
Total Rebate Amount: \$46,262.00

The information contained herein is correct as at 25 Sep 2018

OK

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL : 6389 6111 FAX : -

DATE : 26/09/2018

PAGE : 1 OF 4

*Not withain
1.B.I
Running Bypain*

ACCIDENT REPAIR ON : SLA8991P
MODEL : NISSAN SYLPHY 1.6 CVT
POLICY NO : 2100457387-02
CHASSIS NO : MNTBBAB17Z0026883
YEAR OF MANUFACTURE : 2016
DATE / TIME OF ACCIDENT : 22/09/2018@08:35HRS
LOCATION : ALONG CTE TOWARDS CITY
THIRD PARTY VEHICLE NO : SJD4591U

REPLACEMENT OF PARTS	QUANTITY	UNIT PRICE	AMOUNT
1 FRONT HEADLAMP LH	1	\$	521.70
2 FRONT HEADLAMP RH	1	\$	521.70
3 FRONT HEADLAMP LOWER BRACKET LH	1	\$	32.00
4 FRONT HEADLAMP LOWER BRACKET RH	1	\$	32.00
5 FRONT GRILLE	1	\$	700.70
6 FRONT GRILLE "LOGO" EMBLEM	1	\$	59.70
7 FRONT GRILLE INNER BRACKET LH	1	\$	35.00
8 FRONT GRILLE INNER BRACKET RH	1	\$	35.00
9 FRONT BUMPER	1	\$	476.50
10 FRONT BUMPER SIDE RETAINER LH	1	\$	24.00
11 FRONT BUMPER SIDE RETAINER RH	1	\$	24.00
12 FRONT BUMPER NUMBER PLATE GARNISH	1	\$	127.80
13 FRONT BUMPER LOWER GRILLE	1	\$	255.30
14 FRONT BUMPER FOG LAMP COVER LH	1	\$	112.20
15 FRONT BUMPER FOG LAMP COVER RH	1	\$	112.20
16 FRONT BUMPER TOW HOOK COVER	1	\$	26.70
17 FRONT BUMPER UNDER COVER	1	\$	75.80
18 FRONT BUMPER INNER SPONGE	1	\$	206.30
19 FRONT BUMPER REINFORCEMENT	1	\$	212.40
20 FRONT FENDER INNER SHIELD LH	1	\$	87.60
21 FRONT FENDER INNER SHIELD RH	1	\$	87.60
22 REAR BOOTLID	1	\$	1,163.80
23 REAR BOOTLID "LOGO" EMBLEM	1	\$	46.90
24 REAR BOOTLID "SYLPHY" EMBLEM	1	\$	88.60
25 REAR BOOTLID "PURE DRIVE" EMBLEM	1	\$	59.70
26 REAR BOOTLID OUTER CHROME MOULDING TOP	1	\$	185.70
27 REAR BOOTLID NUMBER PLATE LAMP LH	1	\$	78.40
28 REAR BOOTLID NUMBER PLATE LAMP RH	1	\$	78.40
29 REAR BOOTLID OUTER SWITCH LOCK	1	\$	95.20
30 REAR BOOTLID REVERSE CAMERA	1	\$	850.00
31 REAR BOOTLID OUTER KEY LOCK	1	\$	110.70
32 REAR BOOTLID OUTER CHROME MOULDING LOWER	1	\$	123.50
33 REAR BOOTLID REFLECTOR LAMP LH	1	\$	141.60
34 REAR BOOTLID REFLECTOR LAMP RH	1	\$	141.60
35 REAR BOOTLID MECHANISM LOCK	1	\$	83.90
TOTAL CARRY DOWN			\$ 7,014.20

DATE : 26/09/2018
PAGE : 2 OF 4

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
		TOTAL BRING DOWN		\$ 7,014.20
36	REAR BOOTLID RUBBER GUIDE STOPPER LH	1	\$n	\$ 10.00
37	REAR BOOTLID RUBBER GUIDE STOPPER RH	1	\$n	\$ 10.00
38	REAR BOOTLID INNER TRIM BOARD	1	\$n	\$ 159.40
39	REAR BOOTLID HINGE LH	1	R	\$ 87.60
40	REAR BOOTLID HINGE RH	1	R	\$ 87.60
41	REAR BOOTLID WEATHERSTRIP	1	Od/Dr	\$ 101.50
42	REAR TAILLAMP LH	1	\$n	\$ 365.00
43	REAR TAILLAMP RH	1	CM	\$ 365.00
44	REAR TAILLAMP LOWER BRACKET LH	1	\$R	\$ 36.00
45	REAR TAILLAMP LOWER BRACKET RH	1	Dr	\$ 36.00
46	REAR BUMPER	1	\$Ry	\$ 607.00
47	REAR BUMPER SIDE RETAINER LH	1	Dr	\$ 36.00
48	REAR BUMPER SIDE RETAINER RH	1	CM	\$ 36.00
49	REAR BUMPER REVERSE SENSOR LH	1	\$n	\$ 224.00
50	REAR BUMPER REVERSE SENSOR RH	1	\$n	\$ 224.00
51	REAR BUMPER REFLECTOR LH	1	Mr	\$ 55.00
52	REAR BUMPER REFLECTOR RH	1	\$n	\$ 55.00
53	REAR BUMPER INNER SHIELD LH	1	\$n	\$ 36.00
54	REAR BUMPER INNER SHIELD RH	1	\$n	\$ 36.00
55	REAR BUMPER INNER SPONGE CENTER	1	\$n	\$ 43.10
56	REAR BUMPER INNER SPONGE LH	1	CRM	\$ 85.10
57	REAR BUMPER INNER SPONGE RH	1	CRM	\$ 85.10
58	REAR BUMPER IMPACT BRACKET LH	1	R	\$ 49.80
59	REAR BUMPER IMPACT BRACKET RH	1	R	\$ 49.80
60	REAR END PANEL	1	Ry	\$ 428.40
61	REAR END PANEL INNER LOCK STRIKER	1	\$R	\$ 57.90
62	REAR END PANEL INNER TOP GARNISH	1	Dr	\$ 109.70
63	REAR FENDER INNER TRIM BOARD LH	1	\$n	\$ 417.80
64	REAR FENDER INNER TRIM BOARD RH	1	\$n	\$ 417.80
		SUB TOTAL		\$ 11,325.80
		LESS 30%		\$ (3,397.74)
		PARTS TOTAL		\$ 7,928.06

ACCIDENT REPAIR ON : SLA8991P
MODEL : NISSAN SYLPHY 1.6 CVT
POLICY NO : 2100457387-02
CHASSIS NO : MNTBBAB17Z0026883
YEAR OF MANUFACTURE : 2016
DATE / TIME OF ACCIDENT : 22/09/2018@08:35HRS
LOCATION : ALONG CTE TOWARDS CITY
THIRD PARTY VEHICLE NO : SJD4591U

DATE : 26/09/2018
PAGE : 3 OF 4

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT BONNET INSULATOR MAT CLIPS	6	\$ 4.10	\$ 24.60
2	FRONT HEADLAMP CLIPS LH	3	\$ 4.10	\$ 12.30
3	FRONT HEADLAMP CLIPS RH	3	\$ 4.10	\$ 12.30
4	FRONT GRILLE CLIPS	4	\$ 4.10	\$ 16.40
5	FRONT BUMPER CLIPS	10	\$ 4.10	\$ 41.00
6	FRONT BUMPER NUMBER PLATE WITH HOLDER	1		\$ 65.00
7	FRONT BUMPER UNDER COVER CLIPS	4	\$ 4.10	\$ 16.40
8	FRONT FENDER INNER SHIELD CLIPS LH	4	\$ 4.10	\$ 16.40
9	FRONT FENDER INNER SHIELD CLIPS RH	4	\$ 4.10	\$ 16.40
10	REAR BOOTLID OUTER CHROME MOULDING TOP CLIPS	4	\$ 4.10	\$ 16.40
11	REAR BOOTLID NUMBER PLATE WITH HOLDER	1		\$ 65.00
12	REAR BOOTLID REFLECTOR LAMP CLIPS LH	3	\$ 4.10	\$ 12.30
13	REAR BOOTLID REFLECTOR LAMP CLIPS RH	3	\$ 4.10	\$ 12.30
14	REAR BOOTLID INNER TRIM BOARD CLIPS	6	\$ 4.10	\$ 24.60
15	REAR TAILLAMP CLIPS LH	3	\$ 4.10	\$ 12.30
16	REAR TAILLAMP CLIPS RH	3	\$ 4.10	\$ 12.30
17	REAR BUMPER CLIPS	10	\$ 4.10	\$ 41.00
18	REAR BUMPER INNER SHIELD CLIPS LH	3	\$ 4.10	\$ 12.30
19	REAR BUMPER INNER SHIELD CLIPS RH	3	\$ 4.10	\$ 12.30
20	REAR END PANEL INNER TOP GARNISH CLIPS	4	\$ 4.10	\$ 16.40
21	REAR FENDER INNER TRIM BOARD CLIPS LH	6	\$ 4.10	\$ 24.60
22	REAR FENDER INNER TRIM BOARD CLIPS RH	6	\$ 4.10	\$ 24.60
PARTS TOTAL				\$ 507.20

LABOUR CHARGES FOR FRONT AND REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 2,200.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 2,000.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 50.00
4	REMOVE AND REPLACE REAR BOOTLID LINING TO FACILITATE REPAIRS.	\$ 80.00
5	REMOVE AND REPLACE REAR END PANEL LINING TO FACILITATE REPAIRS.	\$ 80.00
6	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS.	\$ 120.00
7	MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH AND RESET CHASSIS ALIGNMENT TO RECOMMENDED SPECIFICATION.	\$ 300.00
8	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 120.00
9	PROVIDE SKILL LABOUR AND WATER PROOF SEALANT FOR ALL REPLACE AND REPAIR PARTS.	\$ 100.00
10	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 200.00
LABOUR TOTAL		\$ 5,250.00

TOTAL PARTS & LABOUR	\$ 13,685.26
GST 7%	\$ 957.97
GRAND TOTAL	\$ 14,643.23
ESTIMATE REPAIR DURATION	14 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7 days

ACCIDENT REPAIR ON : SLA8991P
MODEL : NISSAN SYLPHY 1.6 CVT
POLICY NO : 2100457387-02
CHASSIS NO : MNTBBAB17Z0026883
YEAR OF MANUFACTURE : 2016
DATE / TIME OF ACCIDENT : 22/09/2018@08:35HRS
LOCATION : ALONG CTE TOWARDS CITY
THIRD PARTY VEHICLE NO : SJD4591U

DATE : 26/09/2018
PAGE : 4 OF 4

YOURS SINCERELY,



ESTIMATOR : KIT
TEL : 8405 4058
FAX : 6269 2404
EMAIL : karkit.ngai@bhauto.com.sg

SURVEY ATTENDED BY :

NAME	Kenner
COMPANY	L/C/L
DATE	28/9/18
TIME	
TEL	98910663
EMAIL	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118017492/KTBN2

Date: 13/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3023141800
Claimant Vehicle No :	SLA8991P	Insured Vehicle No :	SJD4591U
Date of Loss:	22/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04598C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA8991P	Engine No:	HR16986192B
Make & Model:	NISSAN SYLPHY, 1.6 (A)	Chassis No:	MNTBBAB17Z0026883
Reg. Date:	21/03/2016 (Man. Year: 2016)	Odometer:	54244 km
Colour:	Metallic Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R16	Rear Tyre Size:	195/60R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,435.26	3,417.96	5,017.30	59.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	2,150.00	3,100.00	59.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,685.26	5,567.96	8,117.30	59.31
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	13,685.26	4,400.00	9,285.26	67.85
+ GST 7.00/7.00% (S\$)	957.97	308.00	649.97	67.85
Nett Amount (S\$)	14,643.23	4,708.00	9,935.23	67.85

INSPECTION

Date of Assignment: 26/09/2018

Date Inspected: 28/09/2018 Inspected At:

 BH Auto Services Pte Ltd (Sin Ming)
 Blk 1 Sin Ming Industrial Estate Sector
 C, #01/111/113/115/117
 Singapore 575636

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2018)
Parts: 143	NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLA8991P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Serviceable	521.70 FL	*- FL
2	1		*FRONT HEADLAMP RH	Serviceable	521.70 FL	*- FL
3	1		*FRONT HEADLAMP LOWER BRACKET LH	Repair	32.00 FL	*- FL
4	1		*FRONT HEADLAMP LOWER BRACKET RH	Repair	32.00 FL	*- FL
5	1		*FRONT GRILLE	Mtg Cracked	700.70 FL	*700.70 FL
6	1		*FRONT GRILLE LOGO EMBLEM	Necessary	59.70 FL	*59.70 FL
7	1		*FRONT GRILLE INNER BRACKET LH	Serviceable	35.00 FL	*- FL
8	1		*FRONT GRILLE INNER BRACKET RH	Serviceable	35.00 FL	*- FL
9	1		*FRONT BUMPER	Repair	476.50 FL	*- FL
10	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	24.00 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	24.00 FL	*- FL
12	1		*FRONT BUMPER NUMBER PLATE GARNISH	Dented	127.80 FL	*127.80 FL
13	1		*FRONT BUMPER LOWER GRILLE	Serviceable	255.30 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP COVER LH	Serviceable	112.20 FL	*- FL
15	1		*FRONT BUMPER FOG LAMP COVER RH	Serviceable	112.20 FL	*- FL
16	1		*FRONT BUMPER TOW HOOK COVER	Serviceable	26.70 FL	*- FL
17	1		*FRONT BUMPER UNDER COVER	Serviceable	75.80 FL	*- FL
18	1		*FRONT BUMPER INNER SPONGE	Serviceable	206.30 FL	*- FL
19	1		*FRONT BUMPER REINFORCEMENT	Repair	212.40 FL	*- FL
20	1		*FRONT FENDER INNER SHIELD LH	Serviceable	87.60 FL	*- FL
21	1		*FRONT FENDER INNER SHIELD RH	Serviceable	87.60 FL	*- FL
22	1		*REAR BOOTLID	Bent	1,163.80 FL	*1,163.80 FL
23	1		*REAR BOOTLID LOGO EMBLEM	Necessary	46.90 FL	*46.90 FL
24	1		*REAR BOOTLID SYLPHY EMBLEM	Necessary	88.60 FL	*88.60 FL
25	1		*REAR BOOTLID PURE DRIVE EMBLEM	Necessary	59.70 FL	*59.70 FL
26	1		*REAR BOOTLID OUTER CHROME MOULDING TOP	Dented	185.70 FL	*185.70 FL
27	1		*REAR BOOTLID NUMBER PLATE LAMP LH	Serviceable	78.40 FL	*- FL
28	1		*REAR BOOTLID NUMBER PLATE LAMP RH	Serviceable	78.40 FL	*- FL
29	1		*REAR BOOTLID OUTER SWITCH LOCK	Repair	95.20 FL	*- FL
30	1		*REAR BOOTLID REVERSE CAMERA	Serviceable	850.00 FL	*- FL
31	1		*REAR BOOTLID OUTER KEY LOCK	Serviceable	110.70 FL	*- FL
32	1		*REAR BOOTLID OUTER CHROME MOULDING LOWER	Dented	123.50 FL	*123.50 FL
33	1		*REAR BOOTLID REFLECTOR LAMP LH	Missing	141.60 FL	*141.60 FL
34	1		*REAR BOOTLID REFLECTOR LAMP RH	Serviceable	141.60 FL	*- FL
35	1		*REAR BOOTLID MECHANISM LOCK	Repair	83.90 FL	*- FL
36	1		*REAR BOOTLID RUBBER GUIDE STOPPER LH	Serviceable	10.00 FL	*- FL
37	1		*REAR BOOTLID RUBBER GUIDE STOPPER RH	Serviceable	10.00 FL	*- FL
38	1		*REAR BOOTLID INNER TRIM BOARD	Serviceable	159.40 FL	*- FL
39	1		*REAR BOOTLID HINGE LH	Repair	87.60 FL	*- FL
40	1		*REAR BOOTLID HINGE RH	Repair	87.60 FL	*- FL
41	1		*REAR BOOTLID WEATHERSTRIP	Dented/Distorted	101.50 FL	*101.50 FL
42	1		*REAR TAILLAMP LH	Serviceable	365.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR TAILLAMP RH	Cracked	365.00 FL	*365.00 FL
44	1		*REAR TAILLAMP LOWER BRACKET LH	Repair	36.00 FL	*- FL
45	1		*REAR TAILLAMP LOWER BRACKET RH	Distorted	36.00 FL	*36.00 FL
46	1		*REAR BUMPER	Bent	607.00 FL	*607.00 FL
47	1		*REAR BUMPER SIDE RETAINER LH	Distorted	36.00 FL	*36.00 FL
48	1		*REAR BUMPER SIDE RETAINER RH	Cracked	36.00 FL	*36.00 FL
49	1		*REAR BUMPER REVERSE SENSOR LH	Serviceable	224.00 FL	*- FL
50	1		*REAR BUMPER REVERSE SENSOR RH	Serviceable	224.00 FL	*- FL
51	1		*REAR BUMPER REFLECTOR LH	Missing	55.00 FL	*55.00 FL
52	1		*REAR BUMPER REFLECTOR RH	Serviceable	55.00 FL	*- FL
53	1		*REAR BUMPER INNER SHIELD LH	Serviceable	36.00 FL	*- FL
54	1		*REAR BUMPER INNER SHIELD RH	Serviceable	36.00 FL	*- FL
55	1		*REAR BUMPER INNER SPONGE CENTER	Serviceable	43.10 FL	*- FL
56	1		*REAR BUMPER INNER SPONGE LH	Cracked	85.10 FL	*85.10 FL
57	1		*REAR BUMPER INNER SPONGE RH	Cracked	85.10 FL	*85.10 FL
58	1		*REAR BUMPER IMPACT BRACKET LH	Repair	49.80 FL	*- FL
59	1		*REAR BUMPER IMPACT BRACKET RH	Repair	49.80 FL	*- FL
60	1		*REAR END PANEL	Bent	428.40 FL	*428.40 FL
61	1		*REAR END PANEL INNER LOCK STRIKER	Repair	57.90 FL	*- FL
62	1		*REAR END PANEL INNER TOP GARNISH	Distorted	109.70 FL	*109.70 FL
63	1		*REAR FENDER INNER TRIM BOARD LH	Serviceable	417.80 FL	*- FL
64	1		*REAR FENDER INNER TRIM BOARD RH	Serviceable	417.80 FL	*- FL
65	6		*FRONT BONNET INSULATOR MAT CLIPS	Necessary	24.60 FS	*24.60 FS
66	3		*FRONT HEADLAMP CLIPS LH	Not Necessary	12.30 FS	*- FS
67	3		*FRONT HEADLAMP CLIPS RH	Not Necessary	12.30 FS	*- FS
68	4		*FRONT GRILLE CLIPS	Necessary	16.40 FS	*16.40 FS
69	10		*FRONT BUMPER CLIPS	Not Necessary	41.00 FS	*- FS
70	1		*FRONT BUMPER NUMBER PLATE WITH HOLDER	Dented	65.00 FS	*45.00 FS
71	4		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	16.40 FS	*- FS
72	4		*FRONT FENDER INNER SHIELD CLIPS LH	Not Necessary	16.40 FS	*- FS
73	4		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	16.40 FS	*- FS
74	4		*REAR BOOTLID OUTER CHROME MOULDING TOP CLIPS	Not Necessary	16.40 FS	*- FS
75	1		*REAR BOOTLID NUMBER PLATE WITH HOLDER	Serviceable	65.00 FS	*- FS
76	3		*REAR BOOTLID REFLECTOR LAMP CLIPS LH	Not Necessary	12.30 FS	*- FS
77	3		*REAR BOOTLID REFLECTOR LAMP CLIPS RH	Not Necessary	12.30 FS	*- FS
78	6		*REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	24.60 FS	*- FS
79	3		*REAR TAILLAMP CLIPS LH	Necessary	12.30 FS	*12.30 FS
80	3		*REAR TAILLAMP CLIPS RH	Necessary	12.30 FS	*12.30 FS
81	10		*REAR BUMPER CLIPS	Necessary	41.00 FS	*41.00 FS
82	3		*REAR BUMPER INNER SHIELD CLIPS LH	Not Necessary	12.30 FS	*- FS
83	3		*REAR BUMPER INNER SHIELD CLIPS RH	Not Necessary	12.30 FS	*- FS
84	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	16.40 FS	*16.40 FS
85	6		*REAR FENDER INNER TRIM BOARD CLIPS LH	Not Necessary	24.60 FS	*- FS
86	6		*REAR FENDER INNER TRIM BOARD CLIPS RH	Not Necessary	24.60 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,833.00	4,810.80
- List Item Discount on L Items 30.00/30.00% (\$\$)	3,397.74	1,392.84
Total Parts (\$\$)	8,435.26	3,417.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	2,200.00	800.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	2,000.00	1,100.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	50.00	50.00
4	REMOVE AND REPLACE REAR BOOTLID LINING TO FACILITATE REPAIRS	New	80.00	50.00
5	REMOVE AND REPLACE REAR END PANEL LINING TO FACILITATE REPAIRS	New	80.00	60.00
6	REMOVE AND REPLACE REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS	New	120.00	-
7	MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH AND RESET CHASSIS ALIGNMENT TO RECOMMENDED SPECIFICATION	New	300.00	-
8	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS	New	120.00	60.00
9	PROVIDE SKILL LABOUR AND WATER PROOF SEALANT FOR ALL REPLACE AND REPAIR PARTS	New	100.00	30.00
10	DISCONNECT,CHECK,RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING,HARNESS,WIRE SOCKETS AND ETC.REMOVE AND REINSTALL DAMAGED PARTS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	200.00	-
Gross Labour Cost (\$\$)			5,250.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >