



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 25.09.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2086Z TOYOTA VELLFIRE (2014)

To Supply

1)	1pc	Rear bumper	\$	1,785.00	DE ✓
2)	1set	Rear bumper clip	\$	30.00	na ✓
3)	1pc	Rear bumper right bracket	\$	145.00	? ✓
4)	1pc	Rear bumper left bracket	\$	145.00	? ✓
5)	1pc	Rear right bumper tow hook cover	\$	59.80	int ✓
6)	1pc	Rear bumper center right parking sensor (Genuine)	\$	290.00	na ✓
7)	1pc	Rear bumper center left parking sensor (Genuine)	\$	290.00	- ✓
8)	1pc	Rear bumper center right parking sensor cover (Genuine)	\$	25.00	na ✓
9)	1pc	Rear bumper center left parking sensor cover (Genuine)	\$	25.00	na ✓

Sub total parts	\$	2,794.80
Less: 25% discount	\$	698.70
	\$	2,096.10

L/charges

1)	To remove & refit center reverse sensor & sensor cover, reset reverse sensor light. Check wiring.	\$	60.00	✓
2)	To knock rear end panel. Remove & replace rear bumper. Align & adjust rear bumper and tail gate.	\$	400.00	300 ✓
3)	To putty, respray painting rear bumper, end panel, & reverse sensor cover in pearl white. To polish	\$	400.00	300 ✓

Rasul

Hp 9006068

3 days

4/8

25/09/18 @ 1010

Resurvey after repair

Sub total L/charges	\$	860.00
Estimated Grand total	\$	2,956.10