

22/03/2002

ASS. REC. BY:

REF: CS/CT1180/7494/ R1td302

Special Instruction:

Surveyor  
menmen

## ASSIGNMENT (Office)

From (Person):

Rasul  
Catherine Fria

of

CT1

Date/Time: 26/9/18 @ 11:59 am

Estimated Cost:

Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 3280A

Insured:

SKB 8752U

at Workshop m/s

Kah Motor

Tel:

8288 6309

of

No. 255 Alexandra Road

Policy No:

DMPCSN 3015511806

Claim No:

3NM18D 04624C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12:07pm @ 26/9/18

Person Contacted:

Jack

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SLD 3280A-X

SKB 8752U-X


Confirm \$10739.58, 14 days (Red: 3011.51; 21%)

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLD 3280A  
 at Workshop m/s KAH MOTOR  
 of \_\_\_\_\_  
 Insured: CT  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLD 3280A Yr Regn: 2016 / Jun  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Honda City 1.5 Svt c.c 1497  
 Colour: Maroon A/C: Insured / Std / NI / NA  
 Sp. Reading: 032712 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: MRHGM666 OH P0000 Y1

Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S Rim / STD A/Rim or

Tyre Size: F: 185/55R16  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front		Rear	
R/Bal.	<u>S</u> mm	R/Bal.	<u>S</u> mm
L/Bal.	<u>S</u> mm	L/Bal.	<u>S</u> mm
D.O.A.	<u>24/09/18</u>	D.O.I.	<u>02/10/18</u>

Survey held at KAH MOTORDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 05 NOV 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 14

1) 511 Typist  
 Date/Time, File Return to?

☒ : Final ReportResurvey No. of Trip: 1

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

) S + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 10739.58)220220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2018		26 Sep 2018 11:59 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YEO SUNG YI ,BENJAMIN, ID: S8028737B		
Main Claimant:	YEO HUS YIN		
Vehicle Reg. No.:	SLD3280A	Date of Loss:	24/09/2018 19:00 - :59
Claim Type:	TP / SNM18D04624C02	Policy/Cover Note No.:	DMPCSN3015511806 (Comprehensive)
Vehicle Reg. No. (Insured):	SKB8752U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2018]		
Adj Asg. Remarks:	EST \$10,878.41 , CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 5 November 2018 12:02 PM  
**To:** 'Jack Ng'  
**Subject:** RE: FINALIZATION FOR SLD 3280 A

Dear Jack,

Confirm amount \$10,739.58, 14days

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jack Ng <[jackng@honda.com.sg](mailto:jackng@honda.com.sg)>  
**Sent:** Monday, 5 November 2018 11:59 AM  
**To:** Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Subject:** Re: FINALIZATION FOR SLD 3280 A

Dear Denise,

Called 14 days

Jack

Get [Outlook for iOS](#)

---

**From:** Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Sent:** Monday, November 5, 2018 11:56  
**To:** Jack Ng  
**Subject:** RE: FINALIZATION FOR SLD 3280 A

Dear Jack,

Check with Rasul, he said 14days. He say if anything call him directly 90010068

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/09/2018 16:40
Date Of Accident	24/09/2018 19:20
Exact Location Of Accident	PAYA LEBAR FLYOVER
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD3280A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEO HUS YIN
NRIC No	S7246849Z
Email Address	MYTHICSG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97392480
Alternative Phone No	OFFICE-97392480

### Vehicle Particulars

Manufacturer	HONDA
Model	CITY 1.5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	YEO HUS YIN
NRIC No	S7246849Z
Date Of Birth	17/12/1972
Occupation	INDOOR
Date Of Driving Pass	09/10/2004
Driving Experience	13 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97392480
Fax Number	
Contact Number	OFFICE-97392480
EMail Address	MYTHICSG@HOTMAIL.COM

Address	202 LOYANG RISE
Postcode	507399
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TO LARGE
Was there any audio recorded?	NO

Vehicle No SLD3280ASKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorised Driver.
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


25/9/2018  
 Policyholder's Signature / Date & Time

\_\_\_\_\_  
 Driver's Signature (If driver is not the policyholder) / Date & Time

\_\_\_\_\_  
 Witnessed by Reporting Centre Personnel

Sketch Plan

Paya Lebar Flyover.





A = SLD 32 80A

B = SKB 8752U

Please continue to Annex E

Sketch Plan Pg. 2

Vehicle No <u>SLD3280A</u>	Annex E	
Describe Circumstances of the Accident		
<div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;">I was travelling along Paya Lebar Flyover towards Changi when a red Jaguar slammed into my car from the back.</div>		
<div style="border: 1px solid black; padding: 5px; width: fit-content;">You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a <u>Fourteen (14) days clause</u> whereby the claim must be made within the stipulated timeframe from the day of occurrence.</div>		
Declaration		
We declare the foregoing particulars are true in every respect.		
<u>Yusuf - 25/9/18</u> Policyholder's Signature / Date & Time	<div style="text-align: center;"> Driver's Signature (If driver is not the policyholder) / Date &amp; Time</div>	<div style="text-align: center;"> Witnessed by Reporting Centre Personnel</div>





**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT18004055	<b>Page</b>	1
<b>Registration No</b>	: SLD3280A	<b>Date</b>	: 25. Sep 2018		
<b>Chassis No</b>	: MRHGM6660HP000041	<b>Customer No.</b>	: WZC008		
<b>Model</b>	: CITY 1.5SV CVT 2017	<b>Svc Advisor</b>	:		
<b>Owner's Name</b>	: YEO HSUYIN	<b>Engine No</b>	: L15Z14102231		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 25. Sep 2018 4:57:02 PM		
<b>Date of Accident</b>	: 24/9/2018	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: YEO HSUYIN OWNER INSURER: LIBERTY INSURANCE ACC DATE: 24/09/2018 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: SKB 8752 U						
71501-T9A-T00ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
33505-T9A-T01	REFLECTOR ASSYR.RR.	1	14.80	25	11.10	0.78	11.88
33555-T9A-K01	REFLECTOR ASSY, L. RR.	1	14.80	25	11.10	0.78	11.88
91505-TM8-003	CLIPBUMPER	4	2.00	25	6.00	0.42	6.42
66100-T9A-T50ZZ	PANEL COMPRR.	1	323.90	25	242.92	17.00	259.92
04655-T9A-T00ZZ	PANEL SETRR.FLOOR	1	408.80	25	306.60	21.46	328.06
68500-T9A-T30ZZ	LID COMPTRUNK	1	444.50	25	333.37	23.34	356.71
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1	71.60	25	53.70	3.76	57.46
74890-T9A-T11	GARNISH ASSYRR.LICENSE	1	62.00	25	46.50	3.26	49.76
74829-TA0-A00	STOPPERTRUNK LID LOWER	1	7.30	25	5.47	0.38	5.85
74851-T2A-003	LOCK ASSYTRUNK	1	89.90	25	67.42	4.72	72.14
74862-T2A-003	STRIKERTRUNK LID	1	9.50	25	7.12	0.50	7.62
NMRS-4P	4 PCS REAR SENSOR	1	149.20	10	134.28	9.40	143.68
74940-SZW-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22
75701-T9A-000	EMBLEM H	1	11.00	25	8.25	0.58	8.83
75722-T9A-T00	EMBLEMRR.CITY	1	11.30	25	8.47	0.59	9.06
75725-T9A-T00	EMBLEMRR.I-VTEC	1	11.90	25	8.92	0.62	9.54
91512-SR3-004	CLIP TUBULAR	2	2.30	25	3.45	0.24	3.69
Sum Item					1664.75	116.52	1,781.27

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

Registration No : SLD3280A

Chassis No : MRHGM6660HP000041

Model : CITY 1.5SV CVT 2017

Owner's Name : YEO HSUYIN

Ins Policy No. :

Date of Accident : 24/9/2018

Document No. : SQT18004055 Page 2

Date : 25. Sep 2018

Customer No. : WZC008

Svc Advisor :

Engine No : L15Z14102231

Date | Time : 25. Sep 2018 4:57:02 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	100.00	80	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	180	280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	19.60	299.60
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1	280.00		280.00	19.60	299.60
BOMISC1	RESET & CALLIBRATE SMART SYSTEM (N)	1	380.00		380.00	26.60	406.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TRUCK	1	800.00	560	800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	6000.00	5040	6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00	2250	3500.00	245.00	3745.00
Sum Labor					11920.00	834.40	12,754.40

Survey By

Date &amp; Time

Excess

Status

Signature

Total Amount 13,584.75 950.92 14,535.67

Total (Inclusive of GST) 14,535.67

Reg by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/9/2018 7:02:19 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** WZC008 / CHINA TAIPING  
**Chassis No:** MRHGM6660HP000041  
**License No:** SLD3280A  
**Mileage:** 32713  
**Engine No:** L15Z14102231

**Document No:** SVO18058081  
**Printed By:** JACKNG  
**Order Date:** 2. October 2018  
**Order Time:** 4:56:09 PM  
**Service Advisor:** JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	
						Amount	GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: YEO HSUYIN OWNER INSURER: LIBERTY INSURANCE ACC DATE: 24/09/2018 SURVEYED BY: DATE: REF NO: SNM18D04624 (CATHERERINE THIA) TP INSURER: CHINA TAIPING TP VEH: SKB 8752 U ADDITIONAL PART						
71501-T9A-T00ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	4	2.00	25	6.00	0.42	6.42
66100-T9A-T50ZZ	PANEL COMPRR.	1	323.90	25	242.92	17.00	259.92
04655-T9A-T00ZZ	PANEL SETRR.FLOOR	1	408.80	25	306.60	21.46	328.06
68500-T9A-T30ZZ	LID COMPTRUNK	1	444.50	25	333.37	23.34	356.71
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1	71.60	25	53.70	3.76	57.46
75701-T9A-000	EMBLEM H	1	11.00	25	8.25	0.58	8.83
75722-T9A-T00	EMBLEMRR.CITY	1	11.30	25	8.47	0.59	9.06
75725-T9A-T00	EMBLEMRR.I-VTEC	1	11.90	25	8.92	0.62	9.54
38387-TZ5-A01	ANTENNA ASSYL.F. S	1	59.30	25	44.47	3.11	47.58
65513-T9A-T00ZZ	STIFFENERRR.JACK UP S	1	95.90	25	71.92	5.03	76.95
84640-T9A-T01ZA	LINING ASSYRR.PANEL S	1	66.60	25	49.95	3.50	53.45
	<b>SUM PARTS:</b>				<b>1,499.58</b>	<b>104.95</b>	<b>1,604.53</b>
BOSUN	0669 SUNDRIES	1	30.00		30.00	2.10	32.10
BOJSE	1610 BODY JOINT SEALANT TAILGATE	1	80.00		80.00	5.60	85.60
BOJSE	1610 BODY JOINT SEALANT END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	1610 BODY JOINT SEALANT FLOOR PANEL	1	80.00		80.00	5.60	85.60
BML02I	0669 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BA02R	0669 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	19.60	299.60
BOMISC1	0669 REMOVE & INSTALL REAR VIEW CAMERA (N)	1	280.00		280.00	19.60	299.60
BOMISC1	0669 RESET & CALLIBRATE SMART SYSTEM (N)	1	380.00		380.00	26.60	406.60
BKTG02R	0669 REMOVE & TRANSFER ITEMS TO NEW TRUCK ALIGN TAILGATE.(N)	1	560.00		560.00	39.20	599.20



## SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** WZC008 / CHINA TAIPING  
**Chassis No:** MRHGM6660HP000041  
**License No:** SLD3280A  
**Mileage:** 32713  
**Engine No:** L15Z14102231

**Document No:** SVO18058081  
**Printed By:** JACKNG  
**Order Date:** 2. October 2018  
**Order Time:** 4:56:09 PM  
**Service Advisor:** JACK NG

BKRP02M	0669 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	5,040.00	5,040.00	352.80	5,392.80
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,250.00	2,250.00	157.50	2,407.50
			<b>SUM LABOUR:</b>	<b>9,240.00</b>	<b>646.80</b>	<b>9,886.80</b>
			<b>TOTAL SGD</b>	<b>10,739.58</b>	<b>751.75</b>	<b>11,491.33</b>

**Total Payable (SGD)**

**11,491.33**

GST Amount is calculated from individual line(s)



## SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** S7246849Z / YEO HSUYIN  
**Chassis No:** MRHGM6660HP000041  
**License No:** SLD3280A  
**Mileage:** 32713  
**Engine No:** L15Z14102231

**Document No:** SVO18058081  
**Printed By:** JACKNG  
**Order Date:** 2. October 2018  
**Order Time:** 4:56:09 PM  
**Service Advisor:** JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Incd	
						Amount	GST
38387-TZ5-A01	ANTENNA ASSYL.F. <i>OK</i>	1	59.30	25	44.47	3.11	47.58
65513-T9A-T00ZZ	STIFFENERRR.JACK UP <i>OK</i>	1	95.90	25	71.92	5.03	76.95
84640-T9A-T01ZA	LINING ASSYRR.PANEL <i>OK</i>	1	66.60	25	49.95	3.50	53.45
SUM PARTS:					166.34	11.64	177.98
TOTAL SGD					166.34	11.64	177.98

Total Payable (SGD)

177.98

GST Amount is calculated from Individual line(s)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2018		26 Sep 2018 11:59 <a href="#">Edit Adj Rpt</a>	<b>S\$10,739.58</b> <a href="#">Edit Estimates</a>	<b>S\$10,739.58</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>YEO SUNG YI ,BENJAMIN</b> , ID: S8028737B									
Main Claimant: <b>YEO HUS YIN</b>									
Vehicle Reg. No.: <b>SLD3280A</b>		Date of Loss: 24/09/2018 19:00 - :59 [27 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM18D04624C02</b>		Policy/Cover Note No.: DMPCSN3015511806 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SKB8752U</b>		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: <b>Kah Motor Co Sdn Bhd (ALEXANDRA)</b> 255 ALEXANDRA ROAD, - Alexandra - Tel:									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Catherine Thia</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 05/10/2018]									
Adj Asg. Remarks: EST \$10,878.41 , CASE WITH SJE.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLD3280A (SNM18D04624C02)  
[SKB8752U]  
TP  
YEO HUS YIN  
Sep 24 2018 7:00PM  
[YEO SUNG YI ,BENJAMIN]  
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print					
1	25/09/18 17:16	Video - Accident [Linked Accident Report Documents]		Load MP4						
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print					
1	25/09/18 17:21	Accident Statement		Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print					
1	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
11	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
12	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
13	25/09/18 17:05	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
14	25/09/18 17:05	SCENE PHOTO [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
2	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
3	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
4	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
5	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
6	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
7	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
8	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
9	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					
10	05/11/18 14:21	General View		Load JPG	<input checked="" type="checkbox"/>					


Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
11	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>



Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
61	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	05/11/18 14:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 11:58	REPAIR EST	 Load PDF	
2	26/09/18 11:58	PRS	 Load PDF	
3	26/09/18 11:58	TP GIA	 Load PDF	
4	26/09/18 11:58	OI GIA	 Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 17:03	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 17:03	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 17:04	IDENTIFICATION CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	25/09/18 17:04	DRIVING LICENCE [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/18 09:43	Supplementary	 Load PDF	


## Linked Accident Report Documents

View [View In Browser](#)

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 17:16	Video - Accident	 Load MP4	<input checked="" type="checkbox"/>















Assessment Reports

1 per page☒

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 17:21	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>





Photos/Images

3 per page☒

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	25/09/18 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	25/09/18 17:05	SCENE PHOTO	 Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page☒

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 17:03	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 17:03	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 17:04	IDENTIFICATION CAR	 Load JPG	<input checked="" type="checkbox"/>
4	25/09/18 17:04	DRIVING LICENCE	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18017494/R1TD3E2

Date: 13/11/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3015511806

Claimant Vehicle  
No: SLD3280AInsured Vehicle  
No: SKB8752U

Date of Loss: 24/09/2018

Nature of Claim: TP

Claim  
No: SNM18D04624C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLD3280A

Make &amp; Model: HONDA CITY, 1.5 (A)

Engine No: L15Z14102231

Reg. Date: 14/06/2016 (Man. Year: 2016)

Chassis No: MRHGM6660HP000041

Colour: Maroon

Odometer: 32712 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size: 185/55 R16

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,931.09	1,529.58	401.51	20.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,820.00	9,210.00	2,610.00	22.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,751.09</b>	<b>10,739.58</b>	<b>3,011.51</b>	<b>21.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>962.58</b>	<b>751.77</b>	<b>210.81</b>	<b>21.90</b>
<b>Nett Amount (S\$)</b>	<b>14,713.67</b>	<b>11,491.35</b>	<b>3,222.32</b>	<b>21.90</b>

## INSPECTION

Date of Assignment: 26/09/2018

Date Inspected: 02/10/2018 Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)  
NO. 255 ALEXANDRA ROAD  
SINGAPORE 159937

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2018)
<b>Parts:</b> 143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLD3280A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACERR.BUMPER	Deformed	347.77 FS	*347.77 FS
2	1		*SPACER R.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
3	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
4	1		*REFLECTOR ASSYR.RR.	Serviceable	11.10 FS	*- FS
5	1		*REFLECTOR ASSY, L. RR.	Serviceable	11.10 FS	*- FS
6	4		*CLIPBUMPER	Necessary	6.00 FS	*6.00 FS
7	1		*PANEL COMPRR.	Buckled	242.92 FS	*242.92 FS
8	1		*PANEL SETRR.FLOOR	Buckled	306.60 FS	*306.60 FS
9	1		*LID COMPTRUNK	Bent	333.37 FS	*333.37 FS
10	1		*WEATHERSTRIPTRUNK LID	Necessary	53.70 FS	*53.70 FS
11	1		*GARNISH ASSYRR.LICENSE	Serviceable	46.50 FS	*- FS
12	1		*STOPPERTRUNK LID LOWER	Serviceable	5.47 FS	*- FS
13	1		*LOCK ASSYTRUNK	Serviceable	67.42 FS	*- FS
14	1		*STRIKERTRUNK LID	Serviceable	7.12 FS	*- FS
15	4		*REAR SENSOR	Serviceable	134.28 FS	*- FS
16	1		*BUZZER ASSYSMART	Serviceable	45.07 FS	*- FS
17	1		*EMBLEMRR.CITY	Necessary	8.47 FS	*8.47 FS
18	1		*EMBLEMRR.I-VTEC	Necessary	8.92 FS	*8.92 FS
19	2		*CLIP TUBULAR	Not Necessary	3.45 FS	*- FS
20	1		*EMBLEM H	Necessary	8.25 FS	*8.25 FS
21	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
22	1		*ANTENNA ASSYL.F	Cracked	44.47 FS	*44.47 FS
23	1		*STIFFENERRR.JACK UP	Deformed	71.92 FS	*71.92 FS
24	1		*LINING ASSYRR.PANEL	Necessary	49.95 FS	*49.95 FS
Total Parts (S\$)					1,931.09	1,529.58

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	BODY JOINT SEALANT TAILGATE	New	100.00	80.00
2	BODY JOINT SEALANT END PANEL	New	100.00	80.00
3	BODY JOINT SEALANT FLOOR PANEL	New	100.00	80.00
4	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	280.00	180.00
5	REMOVE & RENEW REVERSE SENSORS - 4 PCS	New	280.00	280.00
6	REMOVE & INSTALL REAR VIEW CAMERA	New	280.00	280.00
7	RESET & CALIBRATE SMART SYSTEM	New	380.00	380.00
8	REMOVE & TRANSFER ITEMS TO NEW TRUCK	New	800.00	560.00
9	CUT OFF & RENEW RR PANEL. STRAIGHTEN	New	6,000.00	5,040.00
10	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,500.00	2,250.00
Gross Labour Cost (\$\$)			<b>11,820.00</b>	<b>9,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >