

ASS. REC. BY:

REF: CS/SMO/8017495/719d3

Special Instruction:

Surveyor: Taufik h
menmen

ASSIGNMENT (Office)

From (Person): Chan Shu Hui Agnes

SMO

Date/Time: 26/9/18 @ 11:42am

Estimated Cost:

Bill to:

OD / ~~FD~~ WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SLN 3326A

Insured:

SLC 4595R

at Workshop m/s

Mova Automotive

Tel:

6272 3892

of

No. 22 Jalan Kilang #07-01

Policy No:

D18MTPV01006929

Claim No:

CMTD1804123

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/09/18

Insp: 15 Fan Yong Road

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

12:01pm @ 26/9/18

Person Contacted:

Nitha

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 3326A - X

SLC 4595R - X

1/10-

Revert via menmen preli advise

12/10/18 @

3.25pm confirmed with Billy is \$3800, 5 days.

CRed \$1736.64, 31%.

Surveyor *Tan Jie*

REF:

Songpo

ASSIGNMENT

CoE 2027 Nov

2027 Dec

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *\$53K*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *5* days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SLN 332 6A* Yr Regn: *2027*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda Civic* C.C. *1799*

Colour: *Black* A/C: Insured / Std / NI / NA

Sp. Reading: *118041* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *RT 11205952*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *235/50R18*

R: *2 -*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. *6* mm

L/Bal. *6* mm

D.O.A.

Rear

R/Bal. *6* mm

L/Bal. *6* mm

D.O.I. *27/9/18 R45*

Survey held at *Mova Fm Jang*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 12 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + RS \$

) Photos

) Others

TOTAL

250
10

260

Report Format: *TP*

Lump Sum / I.B.I. (\$) *3800*

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 01 Oct 2018

Preliminary Advice

Insured Vehicle No	: SLC4595R	Accident Date	: 22/09/2018
TP Vehicle No	: SLN3326A	Assignment Date	: 26/09/2018
Make	: HONDA CROSSROAD	Est. Duration of Repair	: 5.00
Date of Inspection	: 27/09/2018		
Inspection At	: MOVA AUTOMOTIVE PTE LTD (HQ) NO. 22 JALAN KILANG, #07-01, MOVA BUILDING SINGAPORE 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,312.56
Revised Amount	:S\$	4,538.80
Check Items (Estimated)	:S\$	120.75
Total	:S\$	4,659.55

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2018		26 Sep 2018 11:42 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	EUNICE CHONG MIAO EN , ID: S8107945E, Tel: +6597366863, Email: chong.eunice@gmail.com		
Main Claimant:	SAMUEL KWAN , ID: S7621937J		
Vehicle Reg. No.:	SLN3326A	Date of Loss:	22/09/2018 13:00 - :59
Claim Type:	TP / CMTD1804123	Policy/Cover Note No.:	D18MTPV01006929 (Comprehensive)
Vehicle Reg. No. (Insured):	SLC4595R	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (HQ) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2018]		
Driver/Custodian (Insured):	EUNICE CHONG MIAO EN (37 / Female), NRIC: S8107945E, Tel: +6597366863		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 12 October 2018 3:25 PM
To: Billy; Taufikh (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: Re:SLN3326A

Dear Billy,

WITHOUT PREJUDICE

Confirm Lump Sum \$3,800.00 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Billy <billy@moval.com.sg>
Sent: Friday, 12 October 2018 11:48 AM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: FW: Re:SLN3326A

Hi Sir,

Attach with Finalization Report, Please advice. Thank You.

Best Regard's

Billy Liaw

MOVA Automotive Pte Ltd

Tel: +65 6272 3892

Fax: +65 6270 8314

From: Billy [<mailto:billy@moval.com.sg>]
Sent: 04 October 2018 13:31
To: 'Taufikh (LKK Auto)'
Cc: 'sur@lkkauto.com'; 'cs-a@lkkauto.com'
Subject: Re:SLN3326A

Hi Sir,

Attach with Finalization Report, Please advice. Thank You.

Best Regard's

Billy Liaw

MOVA Automotive Pte Ltd

Tel: +65 6272 3892

Fax: +65 6270 8314

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/09/2018 14:12
Date Of Accident	22/09/2018 13:25
Exact Location Of Accident	HOLLAND ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN3326A
Insured/Policyholder	
Name Of Registered Owner	SAMUEL KWAN TZUN SING (SAMUEL GUAN ZHENSHENG)
NRIC No	S7621937J
Email Address	SAMUELKWAN0719@YAHOO.COM.TW
Mobile Phone No	(LOCAL) +65-94574665
Alternative Phone No	OFFICE-94574665

Vehicle Particulars

Manufacturer	HONDA
Model	CROSSROAD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095490542
Cover Note Number	

Driver

Name of Driver	SAMUEL KWAN TZUN SING (SAMUEL GUAN ZHENSHENG)
NRIC No	S7621937J
Date Of Birth	19/07/1976
Occupation	INDOOR
Date Of Driving Pass	19/02/2004
Driving Experience	14 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94574665
Fax Number	
Contact Number	OFFICE-94574665
Email Address	SAMUELKWAN0719@YAHOO.COM.TW

Address BLK 90 #02-326 TANGLIN HALT ROAD
 Postcode 141090
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : ANNA NEO (WIFE) 98583569
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: CANNOT BE UPLOADED
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLC4595R
 Vehicle Make/Model/Colour HONDA VEZEL / BLACK
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver EUNICE CHONG MIAO EN
 NRIC/Passport Number S8107945E
 Contact Number 97366663
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

22/9/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:


22/9/18



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NG WING KIN JAMES
S7927881E

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car A Hyundai Getz stopped as bus was exiting from bus stop, I followed and slow down. However Honda Vezel SLN 4595R did not stop and crash into the back of the Honda Crossroad SLN 3326A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

22/9/18
1400hr

Driver's Signature
(If driver is not the policyholder)
Date & Time:

22/9/18
1400hr

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



NG WING KIN JAMES
S7927881E

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

25/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SLN3326A

Veh Model :- HONDA CROSSROAD

Estimate# :- CK418029

Claim # :-

ACC. Date :- 22/09/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	TAILGATE	1 PC	1,247.00	1,247.00 <i>at</i>
2.	TAILGATE GLASS MOULDING	1 SET	85.00	85.00 <i>at</i>
3.	TAILGATE "H" LOGO	1 PC	35.50	35.50 <i>at</i>
4.	TAILGATE EMBLEM - CROSSROAD	1 PC	58.00	58.00 <i>at</i>
5.	TAILGATE EMBLEM - CHECK	1 PC		<i>nn</i>
6.	TAILGATE GARNISH	1 PC	601.00	601.00 <i>at</i>
7.	TAILGATE LOCK	1 PC	115.00	115.00 <i>at</i>
8.	TAILGATE WEATHERSTRIP	1 PC	185.00	185.00 <i>at</i>
9.	TAILGATE INNER TRIM - CHECK	1 PC		<i>280.10</i>
10.	REAR END PANEL	1 PC	510.70	510.70 <i>Rp</i>
11.	REAR END PANEL TOP GARNISH - CHECK	1 PC		<i>nn</i>
12.	REAR BUMPER	1 PC	1,050.00	1,050.00 <i>de</i>
13.	REAR BUMPER BRACKET RH & LH	2 PC	25.00	50.00 <i>? x } X</i>
14.	REAR BUMPER RETAINER RH & LH	2 PC	27.50	55.00 <i>? x } nn</i>
15.	REAR BUMPER BEAM	2 PC	28.00	56.00 <i>? x } X</i>
16.	REAR BUMPER REFLECTOR RH & LH	2 PC	58.00	116.00 <i>RH-LH</i>
17.	REAR BUMPER CLIPS	10 PC	3.90	39.00 <i>at</i>
18.	REAR TOW COVER	1 PC	25.00	25.00 <i>at</i>
19.	REAR BUMPER PLATE LAMP - CHECK	1 PC		<i>nn</i>
20.	REVERSE CAMERA - CHECK	1 PC		<i>nn</i>
LIST TOTAL S\$				4,228.20
20% DISCOUNT S\$				-845.64
				3,382.56
SPECIAL NET ITEMS :				
1.	TAILGATE GLAS SEALANT	1 PC	40.00	40.00 <i>at</i>
2.	REVERSE SENSOR	1 PC	200.00	200.00 <i>at</i>
3.	REAR NUMBER PLATE	1 PC	40.00	40.00 <i>at</i>
SPECIAL NET TOTAL S\$				280.00
LABOUR :				
TO CUT/WELD REAR END PANEL, KNOCK AND STRAIGHTEN REAR BODY MEMBER. REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION				600 - 700.00
SPRAY PAINT TAILGATE, TAILGATE GARNISH, REAR END PANEL, REAR BUMPER, REAR BODY MEMBER				600 - 650.00
REMOVE & REPLACE TAILGATE GLASS AND CHECK WATER LEAKAGE				120.00 ✓
REMOVE & REPLACE TAILGATE MECHANISM AND CHECK LOCKING SYSTEM				40 - 60.00
REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, COVERING, GARNISH				40 - 60.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

25/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 132687

Veh # :- SLN3326A

Veh Model :- HONDA CROSSROAD

Estimate# :- CK418029

Claim # :-

ACC. Date :- 22/09/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION			✓ 30.00 ✓
	RUST PROOF AFFECTED AREAS			✓ 30.00 ✓
	LABOUR TOTAL S\$			1,650.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,312.56

GST @ 7 % 371.88

AMOUNT DUE S\$ 5,684.44

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanglin 97495749

WP' 27/9/18 @ 1145

Resurvey after repair

5 days

Sur @ lkkauto.com

5536.64

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/05/06/07
Singapore 159722

Tel: (65) 6272 3692
Fax: (65) 6270 8314
Co. Reg. 196904033G
GST Reg. M2-008864-2

Estimate

25/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SLN3326A

Veh Model :- HONDA CROSSROAD

Estimate# :- CK418029

Claim # :-

ACC. Date :- 22/09/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	TAILGATE	1 PC	1,247.00	1,247.00 <i>ht</i>
2.	TAILGATE GLASS MOULDING	1 SET	85.00	85.00 <i>ht</i>
3.	TAILGATE "H" LOGO	1 PC	35.50	35.50 <i>ht</i>
4.	TAILGATE EMBLEM - CROSSROAD	1 PC	58.00	58.00 <i>ht</i>
5.	TAILGATE EMBLEM - CHECK	1 PC		
6.	TAILGATE GARNISH	1 PC	601.00	601.00 <i>ht</i>
7.	TAILGATE LOCK	1 PC	115.00	115.00 <i>ht</i>
8.	TAILGATE WEATHERSTRIP	1 PC	185.00	185.00 <i>ht</i>
9.	TAILGATE INNER TRIM - CHECK - <i>280.10</i>	1 PC		
10.	REAR END PANEL	1 PC	510.70	510.70 <i>Rx</i>
11.	REAR END PANEL TOP GARNISH - CHECK <i>280.10</i>	1 PC		
12.	REAR BUMPER	1 PC	1,050.00	1,050.00 <i>ht</i>
13.	REAR BUMPER BRACKET RH & LH	2 PC	25.00	50.00 <i>X</i>
14.	REAR BUMPER RETAINER RH & LH	2 PC	27.50	55.00 <i>X</i>
15.	REAR BUMPER BEAM	2 PC	28.00	56.00 <i>X</i>
16.	REAR BUMPER REFLECTOR RH & LH	2 PC	58.00	116.00 <i>RH-LH</i>
17.	REAR BUMPER CLIPS	10 PC	3.90	39.00 <i>ht</i>
18.	REAR TOW COVER	1 PC	25.00	25.00 <i>ht</i>
19.	REAR BUMPER PLATE LAMP - CHECK <i>220.00</i>	1 PC		
20.	REVERSE CAMERA - CHECK - <i>320.00</i>	1 PC		
LIST TOTAL S\$				<i>3778.60</i> 4,228.20
20% DISCOUNT S\$				<i>755.72</i> -845.64
				<i>1) 3022.88</i> 3,382.56
SPECIAL NET ITEMS :				
1.	TAILGATE GLAS SEALANT	1 PC	40.00	40.00 <i>ht</i>
2.	REVERSE SENSOR	1 PC	200.00	200.00 <i>ht</i>
3.	REAR NUMBER PLATE	1 PC	40.00	40.00 <i>ht</i>
SPECIAL NET TOTAL S\$				<i>280.00</i>
LABOUR :				
TO CUT/WELD REAR END PANEL, KNOCK AND STRAIGHTEN REAR BODY MEMBER. REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION				600
				700.00
SPRAY PAINT TAILGATE, TAILGATE GARNISH, REAR END PANEL, REAR BUMPER, REAR BODY MEMBER				600
				650.00
REMOVE & REPLACE TAILGATE GLASS AND CHECK WATER LEAKAGE				120.00
REMOVE & REPLACE TAILGATE MECHANISM AND CHECK LOCKING SYSTEM				40
				60.00
REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, COVERING, GARNISH				40
				60.00



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

25/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 132687

Veh # :- SLN3326A

Veh Model :- HONDA CROSSROAD

Estimate# :- CK418029

Claim # :-

ACC. Date :- 22/09/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION			✓ 30.00
	RUST PROOF AFFECTED AREAS			✓ 30.00
	LABOUR TOTAL S\$			2) 1460.00 1,650.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,312.56

GST @ 7 % 371.88

AMOUNT DUE S\$ 5,684.44

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

1) PARTS 3022.88
2) SINE T 280.00
3) LABOUR 1460.00
4762.88
- 952.58 less 20%
3810.30

Lump Sum \$3800.00

Please advice.
Thank You
Beny LAW.

Tanjin 974915749

27/9/18 1145

Revisy after repair

5 days

sur @ lkuanto.com



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

SUPPLEMENTARY

SOMPO INSURANCE (S) PTE LTD
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623.

Page : 1
Veh No : SLN3326A
Model : HONDA CROSSROAD
DOA : 22-Sep-18
Incharge : BILLY

No	Description	Qty	U.Price	Amt \$
<u>LIST ITEMS:</u>				
<u>PART WITHOUT PRICE DURING ESTIMATE</u>				
1	TAILGATE INNER TRIM	1	\$ 280.10	\$280.10
	LIST TOTAL S\$			\$280.10
	20% DISCOUNT S\$			\$56.02
				<u>\$224.08</u>

NON-TAX AMOUNTS	\$224.08
GST @ 7%	\$15.69
AMOUNT DUE	<u>\$239.77</u>

Customer's Signature/Co.Stamp

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18017495/T1QD3N2
Date: 23/10/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01006929	
Claimant Vehicle No :	SLN3326A	Insured Vehicle No :	SLC4595R	
Date of Loss:	22/09/2018	Nature of Claim:	TP	Claim No: CMTD1804123

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN3326A	Engine No:	R18A3008141
Make & Model:	HONDA CROSSROAD, 1.8 (A)	Chassis No:	RT11005952
Reg. Date:	21/12/2007 (Man. Year: 2007)	Odometer:	118041 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,886.64	3,302.88	583.76	15.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,460.00	190.00	11.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,536.64	4,762.88	773.76	13.98
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	5,536.64	3,800.00	1,736.64	31.37
+ GST 7.00/7.00% (S\$)	387.56	266.00	121.56	31.37
Nett Amount (S\$)	5,924.20	4,066.00	1,858.20	31.37

INSPECTION

Date of Assignment:	26/09/2018
Date Inspected:	27/09/2018 Inspected At:

15 Fan Yong Road
Repairer: Mova Automotive Pte Ltd (HQ)
No. 22 Jalan Kilang, #07-01, Mova Building
Singapore 159419

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2018)
Parts:	M1-SUV	HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3326A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Bent	1,247.00 FL	*1,247.00 FL
2	1	*SET TAILGATE GLASS MOULDING	Necessary	85.00 FL	*85.00 FL
3	1	*TAILGATE H LOGO	Necessary	35.50 FL	*35.50 FL
4	1	*TAILGATE EMBLEM-CROSSROAD	Necessary	58.00 FL	*58.00 FL
5	1	*TAILGATE EMBLEM (NPA)	Not Necessary	0.00 FL	*- FL
6	1	*TAILGATE GARNISH	Cracked	601.00 FL	*601.00 FL
7	1	*TAILGATE LOCK	Dented	115.00 FL	*115.00 FL
8	1	*TAILGATE WEATHERSTRIP	Cut	185.00 FL	*185.00 FL
9	1	*TAILGATE INNER TRIM	Cracked	280.10 FL	*280.10 FL
10	1	*REAR END PANEL	Repair	510.70 FL	*- FL
11	1	*REAR END PANEL TOP GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
12	1	*REAR BUMPER	Deformed	1,050.00 FL	*1,050.00 FL
13	2	*REAR BUMPER BRACKET RH & LH	Not Necessary	50.00 FL	*- FL
14	2	*REAR BUMPER RETAINER RH & LH	Not Necessary	55.00 FL	*- FL
15	2	*REAR BUMPER BEAM	Not Necessary	56.00 FL	*- FL
16	1	*REAR BUMPER REFLECTOR RH & LH	O/s Cut/N/s Not Necessary	116.00 FL	*58.00 FL
17	10	*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
18	1	*REAR TOW COVER	Necessary	25.00 FL	*25.00 FL
19	1	*REAR BUMPER PLATE LAMP (NPA)	Not Necessary	0.00 FL	*- FL
20	1	*REVERSE CAMERA (NPA)	Not Necessary	0.00 FL	*- FL
21	1	*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
22	1	*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
23	1	*REAR NUMBER PLATE	Cracked	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,788.30	4,058.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	901.66	755.72
Total Parts (\$\$)	3,886.64	3,302.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT/WELD REAR END PANEL,KNOCK AND STRAIGHTEN REAR BODY MEMBER,REMOVE & REPLACE ACCIDENT DAMAGED PARTS,REALIGN ALL CONNECTION	New	700.00	600.00
2	SPRAY PAINT TAILGATE,TAILGATE GARNISH,REAR END PANEL,REAR BUMPER,REAR BODY MEMBER	New	650.00	600.00
3	REMOVE & REPLACE TAILGATE GLASS AND CHECK WATER LEAKAGE	New	120.00	120.00
4	REMOVE & REPLACE TAILGATE MECHANISM AND CHECK LOCKING SYSTEM	New	60.00	40.00
5	REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM,COVERING,GARNISH	New	60.00	40.00
6	REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION	New	30.00	30.00
7	RUST PROOF AFFECTED AREAS	New	30.00	30.00
Gross Labour Cost (S\$)			1,650.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >