

ASS. REC. BY:

REF: CS/ASM18017498/Kcd307 Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person): Hitty Teo of ASM (AXA) Date/Time: 26/09/18

Estimated Cost: Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLU 907 G Insured:

at Workshop m/s: Ah Lim Motor Tel: 6483 1244

of 10 AMK Ind. park 2A #01-09

Policy No: Claim No: S8M00WSJ

Sum Insured: Excess: \$1,000.00

Make of Veh: D.O.A. 21/09/18

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRSDate/Time: 9.51am @ 26/9/18 Person Contacted: Zila Vehicle: ☒ IN ☐ OUT

H.O.D. Endorsement:

Date/Time	Action/Instruction (✓) Estimate
	pls Get Audatex from Wksp
	SLU 907 G - X
27/9/18	Revert thru smart claim; Pending market value
28/9/18	Zila revert back their are able to undertake \$4,900.00
1/10/18	Authorise repair; inform Zila to proceed repair within \$4900.

ASS. REC. BY:

REF:

A/A / CS/ASM18017498 / Krd3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / (REV) / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLU 90TG

Yr Regn:

05, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Axio

c.c.

1.4.96

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

14 P811

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NZE141

6714219

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: B.S

195/85R15

R:

BS / DUN / EXNOVA / BY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

2

mm

L/Bal.

4

mm

L/Bal.

2

mm

D.O.A.

21/9/18

D.O.A.

26/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/9

File pass to Catherine

27/9/2018 @ 10:00am informed Zila repair limit not more than \$4900.00 (by Kenneth)
12/12/2019 Confirmed final bill \$4,718.43 and 7 days with Hui Hong (Ref 4357, 74, 482)

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

200

200

Report Format:

OD

Lump Sum / (B): (\$

4,718.43



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18017498/Krd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 26-09-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLU 907G
Policy No.	Coverage (\$)	0.00
Claim No. S8M00WSJ	Excess (\$)	1,000.00
Assign From SMARTCLAIM (KITTY TEO)	Assign Date	26/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/09/2018	Inspection Date	26/09/2018
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



Service Request Details

Claim

S8M00WSJ

Reference

None 

Loss Date

September 21, 2018

Request Date

September 26, 2018

Due Date

October 3, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLU907G

Make

TOYOTA

Model
AXIO 1.5

Service Address

10 Ang Mo Kio Ind. Park 2A, ., 568047

Primary Contact/Insured

LIM HOCK LIM
211B COMPASSVALE LANE, #08-208, 542211, Singapore
90071520
PHILIP.HESED@GMAIL.COM

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS \$1000

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE



SENT 9/26/18 9:18 AM

FROM TEO Kitty

SUBJECT WP SURVEY

BODY Hi Please get audatex from workshop.



Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, October 01, 2018 4:42 PM
To: zila@ahlimmotor.com.sg
Cc: SUR
Subject: SLU 907G AXA OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLU 907G (excess \$1,000/-)**. **Please note that the vehicle repair at repair cost not more than \$4,900.00**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

English (default) ▼

Invalid ▼



SERVICE REQUESTS

MESSAGES

CLAIMS



Re:RE: Re:SLU 907G IA UPLOADED

Type

❗ Question

Message

Please authorise.

[Reply](#)

English (default) ▼

LKK AUTO CONSULTANTS PTE LTD (OD) ▼



SERVICE REQUESTS

MESSAGES

CLAIMS



RE: Re:SLU 907G IA UPLOADED

Type

🔗 Question

Message

Dear Kitty, Please refer to second IA which had uploaded on last Friday. The revised item : \$5,324.65, check item : \$2,789.40 , total revised : \$8,114.05. The repairer had agree to repair the vehicle within \$4,900.00 . Kindly let us have your approval.

[Reply](#)

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (OD) ▾



SERVICE REQUESTS

MESSAGES

CLAIMS



Re:SLU 907G IA UPLOADED

Type

Question

Message

Hi Jannice, Please advise the revised COR.

[Reply](#)

Janice Lee (LKKAuto)

From: zila <zila@ahlimmotor.com.sg>
Sent: Friday, September 28, 2018 11:19 AM
To: Janice Lee (LKKAuto); SUR; ALM MUI HONG
Subject: Re: SLU907G - OD CLAIM

Hi Janice,

We are able to repair within the limit.

Thanks.

Best Regards,

Zila
Ah Lim Motor
Tel: 64831244 Fax: 64836170

On 28/09/2018 11:16 AM, Janice Lee (LKKAuto) wrote:

> Dear Zila,
>
> Kindly advice whether the vehicle can be repair within \$4,900.00 ?
>
> Thank you.
>
> Best Regards,
> Jannice Lee (Ms) | Case Handler
> LKK Auto Consultants Pte Ltd
> Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315 Blk
> S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
>



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62863561 FAX : (065) 62864318

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 27.09.2018

Survey Details:

Date of loss	25.09.2018
Date of appointment	26.09.2018
Date of survey	26.09.2018
Location of survey	AH LIM MOTOR PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLU 907G
Make and Model	MITSUBISHI FE639C6SRDEA
Date of registration	19-Feb-05
Excess	\$1,000.00
Market Value	\$13,000.00
Parf Rebate	\$8,070.00
Nett Loss	\$4,930.00

Repair details:

Initial Estimate	\$9,076.17
------------------	------------

Proposed/Revised repair cost:

Parts	\$3,697.70
Check items (estimate)	\$2,789.40
Labour	\$1,626.95
Total	\$8,114.05
Lump Sum(if applicable)	\$

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Remarks:

Vehicle sustained damages at front portion. Damages consistent. Pending repair cost from repairer.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



AUTO
Consultants
Pte Ltd

51 UBI AVENUE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62863561 FAX : (065) 62864315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 27.09.2018

Survey Details:

Date of loss	25.09.2018
Date of appointment	26.09.2018
Date of survey	26.09.2018
Location of survey	AH LIM MOTOR PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLU 907G
Make and Model	MITSUBISHI FE639C65RDEA
Date of registration	19-Feb-05
Excess	\$1,000.00
Market Value	\$13,000.00
Part Rebate	\$8,070.00
Nett Loss	\$4,930.00

Repair details:

Initial Estimate	\$9,076.17
------------------	------------

Proposed/Revised repair cost:

Parts	\$3,697.70
Check items (estimate)	\$2,789.40
Labour	\$1,626.95
Total	\$8,114.05
Lump Sum(if applicable)	\$

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564312

Remarks:

Vehicle sustained damages at front portion. Damages consistent. Repairer agree to repair the vehicle at repair cost not more than \$4,900.00. Kindly let us have your approval.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$ no. of days	
Loss of rental	\$ no. of days	
Loss of income	\$ no. of days	
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 55798

Vehicle Details

Vehicle No.: SLU907G
Vehicle to be Exported: No
Intended Deregistration Date: 22 Sep 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA AXIO 1.5X A
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: 1N2D369521
Chassis No.: NZE1416114219
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$15,552.00
Original Registration Date: 21 May 2009
First Registration Date: 21 May 2009
Transfer Count: 2
Actual ARF Paid: \$15,552.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 May 2019
PARF Rebate Amount: \$7,776.00

Intended COE Rebate Details

COE Expiry Date: 20 May 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$5,889.00
COE Rebate Amount: \$294.00
Total Rebate Amount: \$8,070.00

The information contained herein is correct as at 22 Sep 2018

OK



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN BLADE
Dept Direct: 6417 8781 / 8740 9028



Dept Direct: 6417 8781

Dept Direct: 6417 8781

Dept Direct: 6417 8781

Dept Direct: 6417 8781

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY

10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL: 64831244 FAX: 64836170

ATTN: SIMON 96205405

TAX INVOICE : AR201810-01166

DATE: 02/10/2018

CUSTOMER ID: AHL008

VEH REG NO: SLU907G

TERMS: 30 days

PO NO:

PAGE NO: Page 1 of 1

CURR: SGD

SO STOCKID	DESCRIPTION	Std Loc	QTY	U/PRICE	AMOUNT
1 T52611-12200	FRT BUMPER SPONGE	U1	1	48.00	48.00
NZE141		SUPPLIER			

page 5

SUB-TOTAL 48.00

ADD GST 7.00 % 3.36

E & O E TOTAL AMOUNT SGD 51.36

[P] 02/10/2018 12:17:04PM

[E] 02/10/2018 12:16:39PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte Ltd

Sales Executive: STEVEN



Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL

美汽車私人有限公司

AE AUTO PTE LTD

3018 UBI ROAD 1 #01-121 SINGAPORE 408710
EL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

M MOTOR COMPANY

NG MO KIO PARKS 2A

09 AMK AUTO POINT

SINGAPORE 568047

TEL: 64831244 FAX: 64836170

ATTN: SIMON 96205405

WIPER BLADES
Dept Direct: 6417 9101 / 6418 9908



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9707

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201810-01275

DATE : 02/10/2018

CUSTOMER ID : AHL008

VEH REG NO : SLU907G

TERMS : 30 days

PO NO :

PAGE NO : Page 1 of 1

CURR : SGD

SO STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. T52116-12400	FRT BUMPER S/RETAINER LH	U1	1	30.00	30.00
NZE141		I-2-F11-A			
2. T53301-12A30 ROC	FRT BONET	U1	1	225.00	225.00
NZE141 AXIO		L1-B10			
3. T88450-02350/12280-YUKI	A/C CONDENSOR (02350)	U1	1	160.00	160.00
ZZE141		I-3-P4			
4. T16410-21180-KOYO	RADIATOR (AUTO) (EG)	U1	1	230.00	230.00
AXIO-NZE141		L3-A4			

SUB-TOTAL : 645.00
ADD GST 7.00% 45.15

TOTAL AMOUNT SGD : 690.15

[P] 02/10/2018 1:50:51PM

[E] 02/10/2018 1:49:17PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAB Auto Pte. Ltd.

Sales Executive: STEVEN



Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL

美汽車私人有限公司

AE AUTO PTE LTD

(3018 UBI ROAD 1 #01-12) SINGAPORE 408710
 TEL: 67453833 FAX: 67454442 67450618 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPER BLADE
 Dept Direct: \$417 \$791 / \$345 \$628



Dept Direct: \$200 \$610

Dept Direct: \$200 \$610

Dept Direct: \$417 \$792



Dept Direct: \$417 \$792

Dept Direct: \$417 \$792

Dept Direct: \$417 \$792

Dept Direct: \$417 \$792

Wiper blade: HWB (Nippon Wiper blade), Siliper (Made in Korea),
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made in Japan)

M MOTOR COMPANY
 G MO KIO PARKS 2A
 9 AMK AUTO POINT

SINGAPORE 568047
 TEL: 64831244 FAX: 64836170
 ITN: SIMON 96205405

TAX INVOICE : AR201810-01161
 DATE : 02/10/2018
 CUSTOMER ID : AHL008
 VEH REG NO : SLU907G
 TERMS : 30 days
 PO NO :
 PAGE NO : Page 1 of 1
 CURR : SGD

SO STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. T16363-22120(J) NZE141	RAD FAN MOTOR (8450)	U1 L1-R27	1	100.00 ✓	100.00
2. T16712-21010 NZE141	RAD COWLING TOP	U1 I.2-A16-I	1	55.00 ✓	55.00
3. T53811-12A30 NZE141	FRT FENDER RH	U1 I.1-D5	1	175.00 ✓	175.00
4. T81170-12C80 AXIO-NZE141	HEAD LAMP LH 09"	U1 I.2-D17	1	205.00 ✓	205.00
5. T53410-12550/02060 NZE141 ZZE141	FRT BONET HINGE RH	U1 I.2-D4-I	1	32.00 ✓	32.00

Handwritten signature

SUB-TOTAL: 567.00 ✓
 ADD GST 7.00% 39.69

E & O E TOTAL AMOUNT SGD: 606.69

[P] 02/10/2018 12:15:53PM

[E] 02/10/2018 12:13:50PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd

Sales Executive: STEVEN



Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 8417 8781 / 8748 8639



Dept Direct: 8385 9610

Dept Direct: 8385 9611

Dept Direct: 8417 8788



Dept Direct: 8417 8788

Dept Direct: 8417 8788

Dept Direct: 8417 8788

Dept Direct: 8417 8788

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL: 64831244 FAX: 64836170
ATTN: SIMON 96205405

TAX INVOICE : AR201810-01159
DATE : 02/10/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SLU907G
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. T53208-12530 NZE141	BRACE PANEL	GC CC12-P-05A1	1	45.00	45.00

Page 2

SUB-TOTAL : 45.00
ADD GST 7.00 % 3.15

E. & O.E TOTAL AMOUNT SGD : 48.15

[P] 02/10/2018 12:16:11PM

[E] 02/10/2018 12:13:25PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.

No signature is required.



* A - B - C - D - E - F - G - H - I - J - K - L - M - N - O - P - Q - R - S - T - U - V - W - X - Y - Z - 0 - 1 - 2 - 3 - 4 - 5 - 6 - 7 - 8 - 9 *

ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERSCREEN BLADE
Dept Direct: 6417 8781 / 6746 8833



Dept Direct: 6305 9616

Dept Direct: 6305 9611

Dept Direct: 6417 8782



Dept Direct: 6417 8784

Dept Direct: 6417 8785

Dept Direct: 6417 8786

Dept Direct: 6417 8788

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL: 64831244 FAX: 64836170
ATTN: SIMON 96205405

TAX INVOICE : AR201810-01151
DATE : 02/10/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SLU907G
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
1	T52119-13957 NZE141	FRT BUMPER	PA PL4-C1-01	1	170.00	170.00
2	T52021-12260/1 NZE141	FRT BUMPER REINFORCEMENT	PA PL2-G1-09B	1	85.00	85.00
3	T53101-12B40/1 AXIO-NZE141	FRT GRILLE ASSY 09"	PA PL2-H1-10A	1	130.00	130.00
4	T53420-02060/12520 TZE141 NZE141	FRT BONET HINGE LH	PA PL2-K1-05T	1	32.00	32.00
5	T53510-12A10 NZE141	FRT BONET LOCK	PA PL2-N1-04A	1	42.00	42.00
6	T81130-12C80 AXIO 09	H/LAMP RH	PA PL2-E1-110	1	205.00	205.00
7	T53812-12A30 NZE141	FRT FENDER LH	PA PL2-B1-07A	1	175.00	175.00

Page 1

CONTINUE NEXT PAGE

[P] 02/10/2018 12:13:34PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[B] 02/10/2018 12:06:21PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 8101 / 6746 9028



Dept Direct: 6417 8104

Dept Direct: 6417 8106

Dept Direct: 6417 8108

Dept Direct: 6417 8109

Wiper blade: NWB (Nippon Wiper blade), Bilper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY

10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL: 64831244 FAX: 64836170

ATTN: SIMON 96205405

TAX INVOICE : AR201810-01151

DATE : 02/10/2018

CUSTOMER ID : AHL008

VEH REG. NO. : SLU907G

TERMS : 30 days

PO NO. :

PAGE NO. : Page 2 of 2

CURR : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
8. T53201-12B20 NZE141	RAD SUPPORT PANEL	PA PL2-A1-12B	1	270.00✓	270.00
9. T16711-21140 NZE141	RAD FAN COWLING	PA PL2-Q1-040	1	75.00✓	75.00
10. T16361-21110 NZE141 NZT260	RAD FAN BLADE	PA PL2-Q1-06A	1	55.00✓	55.00

SUB-TOTAL : 1,239.00
ADD GST 7.00 % 86.73✓

E & O E TOTAL AMOUNT SGD : 1,325.73

[P] 02/10/2018 12:13:34PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 02/10/2018 12:06:21PM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/09/2018 12:18
Date Of Accident	21/09/2018 14:30
Exact Location Of Accident	ALONG BEGONIA RD TWDS SARACA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU907G
Insured/Policyholder	
Name Of Registered Owner	LIM HOCK LIM
NRIC No	S1255579B
Email Address	PHILIP.HESED@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90233474
Alternative Phone No	OTHERS-90233474

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA305697
Cover Note Number	15/12/2017 - 14/12/2018

Driver

Name of Driver	LIM HOCK LIM
NRIC No	S1255579B
Date Of Birth	22/01/1957
Occupation	INDOOR
Date Of Driving Pass	30/08/1978
Driving Experience	40 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90233474
Fax Number	
Contact Number	OTHERS-90233474
Email Address	PHILIP.HESED@GMAIL.COM

Address	BLK 211B COMPASSVALE LANE #08-208
Postcode	542211
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLE
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ1364Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SAW JIN HONG
NRIC/Passport Number	S1301684D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 22/09/13
 11:50 AM


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Company Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 21/09/18 Time: 2:30pm Location: Hong, Begonia Rd towards Saraca Rd
 My Vehicle A: SLU907G Vehicle B: SLJ1364Z Vehicle C: —

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21st September 2018 at 2.30pm I was travelling along Begonia Road heading toward Saraca Road travelling at about 50kmh. There was road work ahead of me where only one lane was allowed for car to pass. When approaching the road work area, the car in front suddenly brake his car when it was clear to move ahead - I then step on my brake but was too late & hit the back bumper of car SLJ1364Z.

Car B - SCV in Hong
 SLJ1364Z.

☐ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address: philip.hesed@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Philip
 Policyholder's Signature

Date & Time: 21/09/18
11:50 hrs

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Philip
 Reporting Officer's Signature

Name:
 NRIC/FIN No.:

AH LIM MOTOR COMPANY



redefining / insurance

AXA Insurance Pte Ltd
 ☎ 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 📠 (ES) 6880 4740
 ✉ customer.care@axa.com.sg
 🌐 www.axa.com.sg

LIM HOCK LIM
 BLK 211B COMPASSVALE LANE
 #08-208
 SINGAPORE 542211

New business

date
 15/12/2017

your servicing distributor
 CAR TIMES INSURANCE AGENCY PTE
 LTD / 03809

your servicing distributor contact
 6841 5111

Policy Schedule

Your SmartDrive Comprehensive Essential

Your policy snapshot

Policyholder name	LIM HOCK LIM	Policy number	VA1 / GA305697
Cover	Comprehensive	FIN / NRIC	S1255579B
Period of Insurance	from 15/12/2017 to 14/12/2018 (both dates inclusive)		

Premium breakdown

Gross Premium after 0% NCD	SGD 2,175.56
Total Discounts	- SGD 109.27
7% GST	SGD 144.64
Final Premium	SGD 2,210.93

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Essential Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability

Add-on Benefits

- Personal accident benefit of up to \$ 50,000.00 for you and your named drivers
- Courtesy car Standard in Singapore up to ten (10) days
- Personal accident benefit of up to \$20,000 per passenger

Vehicle details

Make & Model of Vehicle	TOYOTA AXIO 1.5 X A	Year of manufacture	2009
Vehicle registration number	SLU9070	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1496
Seating capacity (excl driver)	4	Engine number	1N2D369521
Off-Peak car	No	Chassis number	NZE1416114219


Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	OBS BANK LTD

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 1,000.00
Windscreen Excess	SGD 100.00
Third Party Excess	SGD 1,000.00

AXA Insurance Pte Ltd (199903512M)
 B Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

1 of 2



G0233494.
drive/wet
No injur.
No uder.
1 for 1



Sketch Plan Pg. 5



redefining / insurance

Date: 22/09/18

To: Owner of Vehicle Number: BU 9021

The following has been advised to you via your workshop, Ah Lim Motor Company through their staff, Zila Eileen / Mui Hong.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others Claim Own Damage

Signed and acknowledge by:

[Signature]

Name and signature of policyholder/authorised driver

[Signature]

Name and signature of workshop personnel including company stamp



Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: AHLIM001/1
Date Calculated: 25/09/2018 04:03

Full Report - V1
Registration: SLU907G
Printed: 25/09/2018 11:05

car at workshop

Summary Information

Claim

Location: Singapore (SG)
 Printed by: Ahlim ahlim
 Authorisation Status: Interim
 Work Provider: AXA Insurance S'pore Pte Ltd
 Claim Reference: OD CLAIM
 Policy Number:
 Other Reference:
 Third Party:
 Insured Amount:
 Under Warranty:
 Warranty Expired:

Currency: SGD
 Date of Incident:
 Able to Authorise Repairs: TBA
 Repairs Authorised: TBA
 Estimated Repair Time:
 Quote Due Date:
 Actual Repair Days:
 Parts Ordered Date:
 Hire Car Start:
 Hire Car End:
 Vehicle Collected:

LRS Auto Consultants hence notify the Repairer SGD following:
 • To resurvey before/after spray painting
 • To resurvey after part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • If modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Vehicle Details

Vehicle

Manufacturer: TOYOTA
 Model: Corolla
 Sub Model: BASE MODEL
 Model Sheet Number: YAC 01
 Registration: SLU907G
 Registration Month: May
 Registration Year: 2009
 VIN Number: NZE1416114219
 Manufacture Year: 2009
 Odometer: Not Known
 Colour:
 Engine Number: 1NZD369521
 Fuel Level: %

Model Specs

FROM 05/2009
 FOG LAMPS
 4-SPEED AUTOMATIC
 PAINTING OFF VEHICLE

AIR CONDITIONING
 1.6 LTR 91 KW
 TWO COAT METALLIC

18


Not Withheld
1-2-1
Resurvey B&P only
Ex 810000
7 days

Fax: 62564315

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
 Steering:

Severity of Impact:
 Vehicle Status on
 Inspection:

Brakes Pedal Travel:
 Place of Inspection:
 Pre-Accident Damage:

Date of Inspection: 25/09/2018

PLEASE NOTE THAT VEHICLE IS TOYOTA COROLLA AXIO 1.5X AT 2009 YEAR MODEL ,TOYOTA COROLLA SEDAN 2007 YEAR MODEL IS ONLY USED AS A REFERENCE MODEL...

Tyres Condition:

Tread Depth LHF:
 Tread Depth LHR:

Tread Depth RHF:
 Tread Depth RHR:
 Direction of Impact:

Damage Areas:

Ah Lim Motor Company

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: AHLIM001/1
Date Calculated: 25/09/2018 04:03

Full Report - V1
Registration: SLU907G
Printed: 25/09/2018 11:05

**Addresses****Cost Summary**

Total Labour	\$1,908.00
Total Paint/Material	\$318.27
Total Parts	\$6,279.90
Total of Additional Costs	\$570.00
Excess:	TBA
Grand Total Exc GST:	\$9,076.17
7 % GST:	\$635.33
Grand Total Inc GST:	\$9,711.50

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
B040)	ADJUST HEADLAMPS	3.0	13.50
B010)	R + R FRONT BUMPER	5.0	22.50
B020)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	13.0	58.50
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
B040)	RENEW HEADLAMP	1.0	4.50
B140	RENEW FRONT PANEL CPL	9.0	40.50
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.00
B100	R + R LEFT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B100	R + R RIGHT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B110)	RENEW L/F WING (REMOVED)	2.0	9.00

Ah Lim Motor Company

Claim Reference: OD CLAIM

Assessment Number: AH000936

Version: AHLIM001/1

Date Calculated: 25/09/2018 04:03

Full Report - V1

Registration: SLU907G

Printed: 25/09/2018 11:05

B110)	RENEW RIGHT FRONT WING (REMOVED)	2.0	9.00
B060	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50
B070)	RENEW BONNET (REMOVED)	1.0	4.50
B080	R + R BONNET HINGES	1.0	4.50
530121)	RENEW BONNET LOCK RELEASE CABLE	1.0	4.50
851051)	RENEW WISH/WASH SYSTEM PUMP	1.0	4.50
M010)	R + R AIR CONDITIONING CONDENSER	3.0	13.50
NO NUMBER	R + R EVAPORATOR/COMPRESSOR LINE	4.0	18.00
NO NUMBER	R + R CONDENSER/COMPRESSOR PIPE	3.0	13.50
NO NUMBER	R + R EVAPORATOR HOSES	4.0	18.00
002889	REFILL AIR CONDITIONING	7.0	31.50
160021	R + R RADIATOR OVERFLOW TANK	3.0	13.50
M020	R + R RADIATOR	6.0	27.00
	INCLUDES: BLEED COOLING SYSTEM		
160101)	R + R UPPER RADIATOR HOSE	1.0	4.50
160111)	R + R LOWER RADIATOR HOSE	2.0	9.00
M020)	RENEW RADIATOR (RADIATOR REMOVED)	3.0	13.50
210061)	R + R THROTTLE BODY	3.0	13.50
170011)	R + R AIR INTAKE MANIFOLD	3.0	13.50
NN	BRACE PANAL R&R / NEW PARTS	2 4.0*	18.00
NN	FAN MOTOR RESISTER R&R / NEW PARTS	2 3.0*	13.50
NN	AIR CLENNER BOX ASSY R&R / NEW PARTS	2 5.0*	22.50
1117	REPAIR L/F WHEELHOUSE CPL	20.0*	90.00
1118	REPAIR R/F WHEELHOUSE CPL	10 20.0*	90.00
1201	REPAIR L/F SIDE MEMBER CPL	30.0* ?	135.00
1202	REPAIR R/F SIDE MEMBER CPL	30.0* ?	135.00
1481	REPAIR LEFT FRONT DOOR	20.0* X	90.00
1482	REPAIR RIGHT FRONT DOOR	20.0* X	90.00
2227	REPAIR LEFT A-PILLAR	10.0* X	45.00
2228	REPAIR RIGHT A-PILLAR	10.0* X	45.00

LABOUR COST

Total Work Units

268.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Sub Total

26.8HRS

\$1,206.00

Paint Labour

15.6HRS

\$702.00

Total Labour

42.4HRS

\$1,908.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PAINTING OFF VEHICLE		
471	BONNET NEW PART PAINTING	21.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	16.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	16.0	
2227	LEFT A-PILLAR REPAIR PAINTING <50%	8.0	
2228	RIGHT A-PILLAR REPAIR PAINTING <50%	8.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	

Ah Lim Motor Company

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: AHLIM001/1
Date Calculated: 25/09/2018 04:03

Full Report - V1
Registration: SLU907G
Printed: 25/09/2018 11:05

1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT	5.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT	5.0	
LABOUR COST - PAINT			
	TIME(PAINT)	130.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	156.0	
	Total Paintwork Labour	15.6HRS	\$702.00
MATERIAL COST - PAINT			
			Cost Price
	New Part Painting		\$108.37
	New Part Painting - Plastic K1R		\$67.40
	Surface-/Blend Paint		\$50.80
	Repair Painting		\$64.60
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$318.27
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$318.27

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
281	1	FRONT BUMPER	52119 02979		0% CM 170.00* ✓
317	1	L/F BUMPER BRACKET	52116 12390		0% 01 30.00* ✓
318	1	R/F BUMPER BRACKET	52115 02100		0% R 30.00* X
340	1	BUMPER SUPPORT	52021 12240		0% A 85.00* ✓
341	1	FRT BUMPER ABSORBER	52611 12190		0% CM 48.00* ✓
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	~	0% A 24.00* ✓
410	1	GRILLE	53100 02190		0% CM 130.00* ✓
471	1	BONNET	53301 12A20		0% B 225.00* ✓
475	1	L/F HINGE	53420 02110		0% 01 32.00* ✓
476	1	R/F HINGE	53410 02110	Refuse	0% 01 32.00* ✓
481	1	BONNET INSULATION	53341 12260		0% A 150.00* ✓
493	1	BONNET LOCK	53510 02291		0% A 42.00* ✓
500	1	BONNET CABLE	53630 12770		0% JL 32.00* X
561	1	LEFT HEADLAMP ASSY	81170 02560		0% CM 205.00* ✓
562	1	RIGHT HEADLAMP ASSY	81130 02560	WZ 844	0% 205.00* ✓
707	1	L/REPEATER LAMP CPL	81730 02080		0% JL 38.00* X
708	1	R/REPEATER LAMP CPL	81730 02080		0% JL 38.00* X
741	1	L/F WING	53812 12A10		0% B 175.00* ✓
742	1	R/F WING	53811 12A10		0% B 175.00* ✓
747	1	L/DOOR MIRROR TRIM	60118 12030		0% JL 28.00* X
748	1	R/DOOR MIRROR TRIM	60117 12030		0% JL 28.00* X
789	1	L/F WING CLAMP KIT	SEE GUIDE NO. 6001		0% JL 20.00* X
790	1	R/F WING CLAMP KIT	SEE GUIDE NO. 6002		0% JL 20.00* X
841	1	L/WHEELHOUSE SHELL	53876 12480		0% R 65.00* X
842	1	R/WHEELHOUSE SHELL	53875 12520		0% R 65.00* X
1009	1	INNER FRT PANEL CPL	53201 12903		0% A 270.00* ✓
1436	1	WASHER CONTAINER	85315 02270	SVC	0% JL 58.00* ✓
1445	1	L/F WASHER JET	85381 12300		0% JL 32.00* X

Ah Lim Motor Company

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: AHLIM001/1
Date Calculated: 25/09/2018 04:03

Full Report - V1
Registration: SLU907G
Printed: 25/09/2018 11:05

1446	1	R/F WASHER JET	85381 12300
4465	1	CONDENSER CPL	88450 12280
4483	1	EVAPORATOR OUTL PIPE	88710 02870
4484	1	COMPR/CONDENSER HOSE	88703 12830
4488	1	COMPR/EVAP TUBE	88704 1A180
7761	1	RADIATOR CPL	16400 0D450
7767	1	RADIATOR SHROUD	16711 0D220
7768	1	UPP RADIATOR SHROUD	16712 0D040
7773	1	LWR RADIATOR HOSE	16572 0D170
7776	1	UPPER RADIATOR HOSE	16573 37040
7787	1	EXPANSION TANK	16480 22080
7793	1	COOLING FAN	16361 0N050
7797	1	FAN MOTOR	16363 22100
8221	1	INTAKE MANIFOLD	17120 37021
8783	1	FRONT LWR ENGINE CVR	52618 12020
9631	1	BATTERY TRAY	74431 02210
9645	1	HORN	86520 28180
1000	1	F BUMP TOW COVER	Renew
1000	1	ENGINE UNER COVER	Renew
1000	1	FOG LAMP OUT COVR X2	Renew
1000	1	BRACE PANAL	Renew
1000	1	TEMP SENSOR	Renew
1000	1	F BOT INS CLIPS X10	Renew
1000	1	F BOT RUBER CENTRE	Renew
1000	1	F BOT STAND CLIPS	Renew
1000	1	F GRILE CLIPS X8	Renew
1000	1	HEAD LAMP BULB LH	Renew
1000	1	HEAD LAMP CLIPS X4	Renew
1000	1	RADIATOR T BRAT X2	Renew
1000	1	RADIATOR T BUSH X2	Renew
1000	1	FAN MOTOR RESISTER	Renew
1000	1	RESONATOR TANK LH	Renew
1000	1	RESONATOR HOSE OUT	Renew
1000	1	AIR DUCT UPPER LH	Renew
1000	1	FUSE BOX TOP COVER	Renew
1000	1	F BOX LOW COVER	Renew
1000	1	AIR CLENNER BOX ASSY	Renew
1000	1	BATTEY COVER	Renew
1000	1	BATTEY TOP BRACET	Renew

f: OEM Parts
g: Original
h: Secondhand
p: Parallel
x: Exchange

Sub Total
Mark Up From Cost (10 %)
Total Parts

0%	32.00*	X
0%	270.00*	✓
0%	210.00*	X
0%	185.00*	X
0%	165.00*	X
0%	420.00*	✓
0%	75.00*	✓
0%	55.00*	✓
0%	35.00*	X
0%	30.00*	X
0%	55.00*	X
0%	55.00*	X
0%	100.00*	X
0%	205.00*	X
0%	64.00*	X
0%	38.00*	X
0%	90.00*	X
0%	0.00	X
0%	40.00*	X
0%	30.00*	X
0%	45.00*	✓
0%	175.00*	X
0%	20.00*	X
0%	38.00*	X
0%	25.00*	X
0%	16.00*	X
0%	20.00*	X
0%	10.00*	X
0%	70.00*	X
0%	40.00*	X
0%	175.00*	X
0%	0.00	X
0%	28.00*	X
0%	45.00*	X
0%	58.00*	X
0%	45.00*	X
0%	265.00*	X
0%	0.00	X
0%	28.00*	X
\$5,709.00		
\$570.90		
\$6,279.90		

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment
BATTERY ASSY	SPECIALIST 0%
COOLANT	SPECIALIST
F NUMBER PLATE	SPECIALIST 0%
CHECK WIRING	SPECIALIST
REFILL A/C GAS	SPECIALIST 0%

Price
\$210.00
\$35.00
\$35.00
\$40.00
\$50.00

Ah Lim Motor Company

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: AHLIM001/1
Date Calculated: 25/09/2018 04:03

Full Report - V1
Registration: SLU907G
Printed: 25/09/2018 11:05

RESET AL
DIAGNOSTIC

SPECIALIST

~ \$200.00

X

Total Extras

\$570.00

Final Calculation

Total Parts		\$6,279.90
Labour		
Total Panel/Mechanical	\$1,206.00	603.50
Total Paintwork	\$702.00	625.50
Total Labour		\$1,908.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$570.00	335
Total of Additional Costs		\$570.00
Total Paint/Material Costs		\$318.27
Grand Total Excludes GST		\$9,076.17
GST @ 7 %		\$635.33
Grand Total Includes GST		\$9,711.50

Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: LKKAUTOC/3
Date Calculated: 27/09/2018 07:20

Full Report - V1
Registration: SLU907G
Printed: 27/09/2018 14:20

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	OD CLAIM	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla
Sub Model:	BASE MODEL
Model Sheet Number:	YAC 01
Registration:	SLU907G
Registration Month:	May
Registration Year:	2009
VIN Number:	NZE1416114219
Manufacture Year:	2009
Odometer:	Not Known
Colour:	
Engine Number:	1N2D369521
Fuel Level:	%

Model Specs

FROM 05/2009	AIR CONDITIONING
FOG LAMPS	1.6 LTR 91 KW
4-SPEED AUTOMATIC	TWO COAT METALLIC
PAINTING OFF VEHICLE	



Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	25/09/2018
Place of Inspection:		
Pre-Accident Damage:	PLEASE NOTE THAT VEHICLE IS TOYOTA COROLLA AXIO 1.5X AT 2009 YEAR MODEL ,TOYOTA COROLLA SEDAN 2007 YEAR MODEL IS ONLY USED AS A REFERENCE MODEL...	
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore
 Claim Reference: OD CLAIM
 Assessment Number: AH000936
 Version: LKKAUTOC/3
 Date Calculated: 27/09/2018 07:20

Full Report - V1
 Registration: SLU907G
 Printed: 27/09/2018 14:20



Addresses

Cost Summary

Total Labour	\$1,345.50
Total Paint/Material	\$281.45
Total Parts	\$5,952.10
Total of Additional Costs	\$535.00
Excess:	TBA
Grand Total Exc GST:	\$8,114.05
7 % GST:	\$567.98
Grand Total Inc GST:	\$8,682.03

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$45.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
B040)	ADJUST HEADLAMPS	3.0	13.50
B010)	R + R FRONT BUMPER	5.0	22.50
B020)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	13.0	58.50
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
B040)	RENEW HEADLAMP	1.0	4.50
B140	RENEW FRONT PANEL CPL	9.0	40.50
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.00
B100	R + R LEFT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B100	R + R RIGHT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B110)	RENEW L/F WING (REMOVED)	2.0	9.00
B110)	RENEW RIGHT FRONT WING (REMOVED)	2.0	9.00
B060	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50

B070)	RENEW BONNET (REMOVED)	1.0	4.50
B080	R + R BONNET HINGES	1.0	4.50
530121)	RENEW BONNET LOCK RELEASE CABLE	1.0	4.50
851051)	RENEW WISH/WASH SYSTEM PUMP	1.0	4.50
M010)	R + R AIR CONDITIONING CONDENSER	3.0	13.50
NO NUMBER	R + R EVAPORATOR/COMPRESSOR LINE	4.0	18.00
NO NUMBER	R + R CONDENSER/COMPRESSOR PIPE	3.0	13.50
NO NUMBER	R + R EVAPORATOR HOSES	4.0	18.00
002889	REFILL AIR CONDITIONING	7.0	31.50
160021	R + R RADIATOR OVERFLOW TANK	3.0	13.50
M020	R + R RADIATOR	6.0	27.00
	INCLUDES: BLEED COOLING SYSTEM		
160101)	R + R UPPER RADIATOR HOSE	1.0	4.50
160111)	R + R LOWER RADIATOR HOSE	2.0	9.00
M020)	RENEW RADIATOR (RADIATOR REMOVED)	3.0	13.50
210061)	R + R THROTTLE BODY	3.0	13.50
170011)	R + R AIR INTAKE MANIFOLD	3.0	13.50
NN	BRACE PANAL R&R / NEW PARTS	2.0*	9.00
NN	FAN MOTOR RESISTER R&R / NEW PARTS	2.0*	9.00
NN	AIR CLENNER BOX ASSY R&R / NEW PARTS	2.0*	9.00
1117	REPAIR L/F WHEELHOUSE CPL	8.0*	36.00
1118	REPAIR R/F WHEELHOUSE CPL	10.0*	45.00
1201	REPAIR L/F SIDE MEMBER CPL	30.0*	135.00
1202	REPAIR R/F SIDE MEMBER CPL	30.0*	135.00
1482	REPAIR RIGHT FRONT DOOR	5.0*	22.50
LABOUR COST			
	Total Work Units	185.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	18.5HRS	\$832.50
	Paint Labour	11.4HRS	\$513.00
	Total Labour	29.9HRS	\$1,345.50

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PAINTING OFF VEHICLE		
471	BONNET NEW PART PAINTING	21.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	16.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT	5.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT	5.0	
LABOUR COST - PAINT			
	TIME(PAINT)	98.0	
	Preparation Main Work Metal	11.0	
	Preparation Comp. Work Plastic	5.0	

Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	114.0	
Total Paintwork Labour	11.4HRS	\$513.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$108.37
New Part Painting - Plastic K1R		\$67.40
Surface-/Blend Paint		\$50.80
Repair Painting		\$27.78
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$281.45
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$281.45

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281	1	FRONT BUMPER	52119 02979		0%	170.00*
317	1	L/F BUMPER BRACKET	52116 12390		0%	30.00*
318	1	R/F BUMPER BRACKET	52115 02100		0%	30.00*
340	1	BUMPER SUPPORT	52021 12240		0%	85.00*
341	1	FRT BUMPER ABSORBER	52611 12190		0%	48.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	24.00*
410	1	GRILLE	53100 02190		0%	130.00*
471	1	BONNET	53301 12A20		0%	225.00*
475	1	L/F HINGE	53420 02110		0%	32.00*
476	1	R/F HINGE	53410 02110		0%	32.00*
481	1	BONNET INSULATION	53341 12260		0%	150.00*
493	1	BONNET LOCK	53510 02291		0%	42.00*
500	1	BONNET CABLE	53630 12770		0%	32.00*
561	1	LEFT HEADLAMP ASSY	81170 02560		0%	205.00*
562	1	RIGHT HEADLAMP ASSY	81130 02560		0%	205.00*
741	1	L/F WING	53812 12A10		0%	175.00*
742	1	R/F WING	53811 12A10		0%	175.00*
789	1	L/F WING CLAMP KIT	SEE GUIDE NO. 6001		0%	20.00*
790	1	R/F WING CLAMP KIT	SEE GUIDE NO. 6002		0%	20.00*
841	1	L/WHEELHOUSE SHELL	53876 12480		0%	65.00*
842	1	R/WHEELHOUSE SHELL	53875 12520		0%	65.00*
1009	1	INNER FRT PANEL CPL	53201 12903		0%	270.00*
1436	1	WASHER CONTAINER	85315 02270		0%	58.00*
1445	1	L/F WASHER JET	85381 12300		0%	32.00*
4465	1	CONDENSER CPL	88450 12280		0%	270.00*
4483	1	EVAPORATOR OUTL PIPE	88710 02870		0%	210.00*
4484	1	COMPR/CONDENSER HOSE	88703 12830		0%	185.00*
4488	1	COMPR/EVAP TUBE	88704 1A180		0%	165.00*
7761	1	RADIATOR CPL	16400 0D450		0%	420.00*
7767	1	RADIATOR SHROUD	16711 0D220		0%	75.00*
7768	1	UPP RADIATOR SHROUD	16712 0D040		0%	55.00*
7773	1	LWR RADIATOR HOSE	16572 0D170		0%	35.00*
7776	1	UPPER RADIATOR HOSE	16573 37040		0%	30.00*
7787	1	EXPANSION TANK	16480 22080		0%	55.00*

7793	1	COOLING FAN	16361 0N050	0%	55.00*
7797	1	FAN MOTOR	16363 22100	0%	100.00*
8221	1	INTAKE MANIFOLD	17120 37021	0%	205.00*
9631	1	BATTERY TRAY	74431 02210	0%	38.00*
9645	1	HORN	86520 28180	0%	90.00*
1000	1	F BUMP TOW COVER	Renew	0%	0.00
1000	1	BRACE PANAL	Renew	0%	45.00*
1000	1	TEMP SENSOR	Renew	0%	175.00*
1000	1	F BOT INS CLIPS X10	Renew	0%	20.00*
1000	1	F BOT RUBER CENTRE	Renew	0%	38.00*
1000	1	F BOT STAND CLIPS	Renew	0%	25.00*
1000	1	F GRILE CLIPS X8	Renew	0%	16.00*
1000	1	HEAD LAMP BULB LH	Renew	0%	20.00*
1000	1	HEAD LAMP CLIPS X4	Renew	0%	10.00*
1000	1	RADIATOR T BRAT X2	Renew	0%	70.00*
1000	1	RADIATOR T BUSH X2	Renew	0%	40.00*
1000	1	FAN MOTOR RESISTER	Renew	0%	175.00*
1000	1	RESONATOR TANK LH	Renew	0%	0.00
1000	1	RESONATOR HOSE OUT	Renew	0%	28.00*
1000	1	AIR DUCT UPPER LH	Renew	0%	45.00*
1000	1	FUSE BOX TOP COVER	Renew	0%	58.00*
1000	1	F BOX LOW COVER	Renew	0%	45.00*
1000	1	AIR CLENNER BOX ASSY	Renew	0%	265.00*
1000	1	BATTEY TOP BRACET	Renew	0%	28.00*
f: OEM Parts				Sub Total	\$5,411.00
g: Original				Mark Up From Cost (10 %)	\$541.10
h: Secondhand				Total Parts	\$5,952.10
p: Parallel					
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
BATTERY ASSY	SPECIALIST 0%	\$210.00
COOLANT	SPECIALIST	\$20.00
F NUMBER PLATE	SPECIALIST 0%	\$35.00
CHECK WIRING	SPECIALIST	\$20.00
REFILL A/C GAS	SPECIALIST 0%	\$50.00
RESET AL	SPECIALIST	\$200.00
DIAGNOSTIC		
Total Extras		\$535.00

Final Calculation

Total Parts	\$5,952.10
Labour	
Total Panel/Mechanical	\$832.50
Total Paintwork	\$513.00
Total Labour	\$1,345.50
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$535.00
Total of Additional Costs	\$535.00

Total Paint/Material Costs	\$281.45
Grand Total Excludes GST	\$8,114.05
GST @ 7 %	\$567.98
Grand Total Includes GST	\$8,682.03

Assessment Notes

Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: AHLIM001/1
Date Calculated: 05/11/2018 07:08

Full Report - V1
Registration: SLU907G
Printed: 05/11/2018 15:08

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ahlim ahlim	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	OD CLAIM	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla
Sub Model:	BASE MODEL
Model Sheet Number:	YAC 01
Registration:	SLU907G
Registration Month:	May
Registration Year:	2009
VIN Number:	NZE1416114219
Manufacture Year:	2009
Odometer:	Not Known
Colour:	
Engine Number:	1NZD369521
Fuel Level:	%

Model Specs

FROM 05/2009	AIR CONDITIONING
FOG LAMPS	1.6 LTR 91 KW
4-SPEED AUTOMATIC	TWO COAT METALLIC
PAINTING OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	25/09/2018
Place of Inspection:		
Pre-Accident Damage:	PLEASE NOTE THAT VEHICLE IS TOYOTA COROLLA AXIO 1.5X AT 2009 YEAR MODEL ,TOYOTA COROLLA SEDAN 2007 YEAR MODEL IS ONLY USED AS A REFERENCE MODEL...	
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Ah Lim Motor Company

Claim Reference: OD CLAIM

Assessment Number: AH000936



Version: AHLIM001/1

Date Calculated: 05/11/2018 07:08

Full Report - V1

Registration: SLU907G

Printed: 05/11/2018 15:08



Addresses

Cost Summary

Total Labour	\$1,269.00
Total Paint/Material	\$316.03
Total Parts	\$2,798.40
Total of Additional Costs	\$335.00
Excess:	TBA
Grand Total Exc GST:	\$4,718.43
7 % GST:	\$330.29
Grand Total Inc GST:	\$5,048.72

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/Dent = \$45.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
B040)	ADJUST HEADLAMPS	3.0	13.50
B010)	R + R FRONT BUMPER	5.0	22.50
B020)	RENEW FRONT BUMPER (BUMPER REMOVED)	13.0	58.50
	INCLUDES: R + R RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED)	1.0	4.50
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED)	1.0	4.50
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B040)	RENEW HEADLAMP	1.0	4.50
B140	RENEW FRONT PANEL CPL	9.0	40.50
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.00
B100	R + R LEFT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B100	R + R RIGHT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B110)	RENEW L/F WING (REMOVED)	2.0	9.00
B110)	RENEW RIGHT FRONT WING (REMOVED)	2.0	9.00
B060	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50

Ah Lim Motor Company

Claim Reference: OD CLAIM

Assessment Number: AH000936

Version: AHLIM001/1

Date Calculated: 05/11/2018 07:08

Full Report - V1

Registration: SLU907G

Printed: 05/11/2018 15:08

Surface-/Blend Paint	\$79.19
Repair Painting	\$33.97
Material-Const Main Work Metal	\$18.10
Material-Const Comp. Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$316.03
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$316.03

PARTS

Guide No.Qty		Description	Part Number	Supplier	Price Valid: 01/06/2015	
					Bet.	Price (\$)
281	1	FRONT BUMPER	52119 02979		0%	170.00*
317	1	L/F BUMPER BRACKET	52116 12390		0%	30.00*
340	1	BUMPER SUPPORT	52021 12240		0%	85.00*
341	1	FRT BUMPER ABSORBER	52611 12190		0%	48.00*
410	1	GRILLE	53100 02190		0%	130.00*
471	1	BONNET	53301 12A20		0%	225.00*
475	1	L/F HINGE	53420 02110		0%	32.00*
476	1	R/F HINGE	53410 02110		0%	32.00*
493	1	BONNET LOCK	53510 02291		0%	42.00*
561	1	LEFT HEADLAMP ASSY	81170 02560		0%	205.00*
562	1	RIGHT HEADLAMP ASSY	81130 02560		0%	205.00*
741	1	L/F WING	53812 12A10		0%	175.00*
742	1	R/F WING	53811 12A10		0%	175.00*
1009	1	INNER FRT PANEL CPL	53201 12903		0%	270.00*
4465	1	CONDENSER CPL	88450 12280		0%	160.00*
7761	1	RADIATOR CPL	16400 0D450		0%	230.00*
7767	1	RADIATOR SHROUD	16711 0D220		0%	75.00*
7768	1	UPP RADIATOR SHROUD	16712 0D040		0%	55.00*
7793	1	COOLING FAN	16361 0N050		0%	55.00*
7797	1	FAN MOTOR	16363 22100		0%	100.00*
1000	1	BRACE PANAL	Renew		0%	45.00*
f: OEM Parts		Sub Total				\$2,544.00
g: Original		Mark Up From Cost (10 %)				\$254.40
h: Secondhand		Total Parts				\$2,798.40
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
BATTERY ASSY	SPECIALIST 0%	\$210.00
COOLANT	SPECIALIST	\$20.00
F NUMBER PLATE	SPECIALIST 0%	\$35.00
CHECK WIRING	SPECIALIST	\$20.00
REFILL A/C GAS	SPECIALIST 0%	\$50.00
Total Extras		\$335.00

Final Calculation

Total Parts	\$2,798.40
Labour	
Total Panel/Mechanical	\$643.50
Total Paintwork	\$625.50
Total Labour	\$1,269.00
Additional Costs	

Ah Lim Motor Company

Claim Reference: OD CLAIM

Assessment Number: AH000936

Version: AHLIM001/1

Date Calculated: 05/11/2018 07:08

Full Report - V1

Registration: SLU907G

Printed: 05/11/2018 15:08

B070)	RENEW BONNET (REMOVED)	1.0	4.50
B080	R + R BONNET HINGES	1.0	4.50
M010)	R + R AIR CONDITIONING CONDENSER	3.0	13.50
002889	REFILL AIR CONDITIONING	7.0	31.50
160021	R + R RADIATOR OVERFLOW TANK	3.0	13.50
M020	R + R RADIATOR	6.0	27.00
	INCLUDES: BLEED COOLING SYSTEM		
M020)	RENEW RADIATOR (RADIATOR REMOVED)	3.0	13.50
NO NUMBER	R + R L/LOWER ENGINE PROTECTION	2.0	9.00
NO NUMBER	R + R R/LOWER ENGINE PROTECTION	2.0	9.00
NN	BRACE PANAL R&R / NEW PARTS	2.0*	9.00
1117	REPAIR L/F WHEELHOUSE CPL	8.0*	36.00
1118	REPAIR R/F WHEELHOUSE CPL	10.0*	45.00
1201	REPAIR L/F SIDE MEMBER CPL	20.0*	90.00
1202	REPAIR R/F SIDE MEMBER CPL	20.0*	90.00
1482	REPAIR RIGHT FRONT DOOR	5.0*	22.50
LABOUR COST			
	Total Work Units	143.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	14.3HRS	\$643.50
	Paint Labour	13.9HRS	\$625.50
	Total Labour	28.2HRS	\$1,269.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PAINTING OFF VEHICLE		
471	BONNET NEW PART PAINTING	21.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	25.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT	5.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT	5.0	
1481	LEFT FRONT DOOR SURFACE PAINT	8.0	
2227	LEFT A-PILLAR SURFACE PAINT	4.0	
2228	RIGHT A-PILLAR SURFACE PAINT	4.0	
LABOUR COST - PAINT			
	TIME(PAINT)	123.0	
	Preparation Main Work Metal	11.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	139.0	
	Total Paintwork Labour	13.9HRS	\$625.50
MATERIAL COST - PAINT			
	New Part Painting		\$108.37
	New Part Painting - Plastic K1R		\$67.40

Ah Lim Motor Company

Claim Reference: OD CLAIM

Assessment Number: AH000936

Version: AHLIM001/1

Date Calculated: 05/11/2018 07:08

Full Report - V1

Registration: SLU907G

Printed: 05/11/2018 15:08

Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$335.00	
Total of Additional Costs		\$335.00
Total Paint/Material Costs		\$316.03
Grand Total Excludes GST		\$4,718.43
GST @ 7 %		\$330.29
Grand Total Includes GST		\$5,048.72

Assessment Notes



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0913453

Ref No: MF0911459

Date: 05 Nov 2018

Policy No: GA305697

Veh Reg No: SLU907G

Make/Model: TOYOTA COROLLA
AXIO 1.5A

Your Ref No: S8M00WSJ

Claim Type: Own Damage

Accident Date: 21/09/2018

Repair Cost to Vehicle No (For Finalization):SLU907G

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET		1 PC	225.00	
2 FRONT BONNET HINGE		2 PC	64.00	
3 FRONT BONNET LOCK		1 PC	42.00	
4 FRONT GRILLE WITH CHROME ASSY		1 PC	130.00	
5 HEADLAMP		2 PC	410.00	
6 FRONT BUMPER		1 PC	170.00	
7 FRONT BUMPER SIDE RETAINER LH		1 PC	30.00	
8 FRONT BUMPER SPONGE		1 PC	48.00	
9 FRONT BUMPER REINFORCEMENT		1 PC	85.00	
10 FRONT FENDER		2 PC	350.00	
11 RADIATOR SUPPORT PANEL		1 PC	270.00	
12 BRACE PANEL		1 PC	45.00	
13 AIR CON CONDENSER ASSY		1 PC	160.00	
14 RADIATOR ASSY		1 PC	230.00	
15 RADIATOR TOP PLATE CTR		1 PC	55.00	
16 RADIATOR FAN MOTOR		1 PC	100.00	
17 RADIATOR FAN BLADE		1 PC	55.00	
18 RADIATOR FAN COWLING		1 PC	75.00	
			2,544.00	
	Add 10%		254.40	2,798.40
Special Nett				
19 BATTERY		1 PC	210.00	
20 RADIATOR COOLANT		1 PC	20.00	
21 NUMBER PLATE		1 PC	35.00	
				265.00
LABOUR				
22 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
23 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	50.00	

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 FAX: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DPAST FINALIZATION

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0913453
Ref No: MF0911459
Date: 05 Nov 2018
Policy No: GA305697
Veh Reg No: SLU907G
Make/Model: TOYOTA COROLLA
AXIO 1.5A

Your Ref No: S8M00WSJ
Claim Type: Own Damage
Accident Date: 21/09/2018

Repair Cost to Vehicle No (For Finalization):SLU907G

Description	U/Price	Quantity	Cost S\$	Amount S\$
24 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL,BRACE PANEL,FRONT BUMPER REINFORCEMENT & BRACKET.TO KNOCK & REPAIR FRONT DOOR LH & RH,FRONT DOOR PILLAR, FRONT CHASSIS FRAME,FRONT WHEELHOUSE.TO REFIT LISTED PARTS BACK SAME.		1 PC	643.50	
25 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT BUMPER REINFORCEMENT & BRACKET,BRACE PANEL, RADIATOR SUPPORT PANEL,FRONT DOOR LH & RH,FRT DOOR PILLAR,FRT CHASSIS FRAME,FRT WHEELHOUSE.		1 PC	941.53	
				1,655.03

Amount Before Excess	S\$ 4,718.43
Less Excess	S\$ 1,000.00
Amount Before GST	S\$ 3,718.43
Add GST @ 7%	260.29
Total Amount payable	S\$ 3,978.72

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED SEVENTY EIGHT AND CENTS SEVENTY TWO ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 26/09/2018

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
E-MAIL: ahlimmc@singnet.com.sg
AUTHORISED SIGNATURE

Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: AHLIM001/1
Date Calculated: 25/09/2018 04:03

Full Report - V1
Registration: SLU907G
Printed: 25/09/2018 11:05

car at workshop

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ahlim ahlim	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	OD CLAIM	Estimated Repair Time:	
Policy Number:		Quote Due Date:	End of.
Other Reference:		Actual Repair Days:	Resing
Third Party:		Parts Ordered Date:	3:45 pm
Insured Amount:		Hire Car Start:	03/10/18
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	TOYOTA	FROM 05/2009	AIR CONDITIONING
Model:	Corolla	FOG LAMPS	1.6 LTR 91 KW
Sub Model:	BASE MODEL	4-SPEED AUTOMATIC	TWO COAT METALLIC
Model Sheet Number:	YAC 01	PAINTING OFF VEHICLE	
Registration:	SLU907G		
Registration Month:	May		
Registration Year:	2009		
VIN Number:	NZE1416114219		
Manufacture Year:	2009		
Odometer:	Not Known		
Colour:			
Engine Number:	1N2D369521		
Fuel Level:	%		

26/9/18
12:00 pm

Not with a...
1-B1
Resing B6 point
Ex 81000
7 days

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	25/09/2018
Pre-Accident Damage:	PLEASE NOTE THAT VEHICLE IS TOYOTA COROLLA AXIO 1.5X AT 2009 YEAR MODEL ,TOYOTA COROLLA SEDAN 2007 YEAR MODEL IS ONLY USED AS A REFERENCE MODEL...



Tyres Condition:

Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

Ah Lim Motor Company

Claim Reference: OD CLAIM
 Assessment Number: AH000936
 Version: AHLIM001/1
 Date Calculated: 25/09/2018 04:03

Full Report - V1
 Registration: SLU907G
 Printed: 25/09/2018 11:05



Addresses

Cost Summary

Total Labour	\$1,908.00
Total Paint/Material	\$318.27
Total Parts	\$6,279.90
Total of Additional Costs	\$570.00
Excess:	TBA
Grand Total Exc GST:	\$9,076.17
7 % GST:	\$635.33
Grand Total Inc GST:	\$9,711.50

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$45.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
B040)	ADJUST HEADLAMPS	3.0	13.50
B010)	R + R FRONT BUMPER	5.0	22.50
B020)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	13.0	58.50
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
B040)	RENEW HEADLAMP	1.0	4.50
B140	RENEW FRONT PANEL CPL	9.0	40.50
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.00
B100	R + R LEFT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B100	R + R RIGHT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B110)	RENEW L/F WING (REMOVED)	2.0	9.00

Ah Lim Motor Company

Claim Reference: OD CLAIM

Assessment Number: AH000936

Version: AHLIM001/1

Date Calculated: 25/09/2018 04:03

Full Report - V1

Registration: SLU907G

Printed: 25/09/2018 11:05

B110)	RENEW RIGHT FRONT WING (REMOVED)	2.0	9.00
B060	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50
B070)	RENEW BONNET (REMOVED)	1.0	4.50
B080	R + R BONNET HINGES	1.0	4.50
530121)	RENEW BONNET LOCK RELEASE CABLE	1.0	4.50
851051)	RENEW WISH/WASH SYSTEM PUMP	1.0	4.50
M010)	R + R AIR CONDITIONING CONDENSER	3.0	13.50
NO NUMBER	R + R EVAPORATOR/COMPRESSOR LINE	4.0	18.00
NO NUMBER	R + R CONDENSER/COMPRESSOR PIPE	3.0	13.50
NO NUMBER	R + R EVAPORATOR HOSES	4.0	18.00
002889	REFILL AIR CONDITIONING	7.0	31.50
160021	R + R RADIATOR OVERFLOW TANK	3.0	13.50
M020	R + R RADIATOR	6.0	27.00
	INCLUDES: BLEED COOLING SYSTEM		
160101)	R + R UPPER RADIATOR HOSE	1.0	4.50
160111)	R + R LOWER RADIATOR HOSE	2.0	9.00
M020)	RENEW RADIATOR (RADIATOR REMOVED)	3.0	13.50
210061)	R + R THROTTLE BODY	3.0	13.50
170011)	R + R AIR INTAKE MANIFOLD	3.0	13.50
NN	BRACE PANAL R&R / NEW PARTS	2 4.0*	18.00
NN	FAN MOTOR RESISTER R&R / NEW PARTS	2 3.0*	13.50
NN	AIR CLENNER BOX ASSY R&R / NEW PARTS	2 5.0*	22.50
1117	REPAIR L/F WHEELHOUSE CPL	20.0*	90.00
1118	REPAIR R/F WHEELHOUSE CPL	10 20.0*	90.00
1201	REPAIR L/F SIDE MEMBER CPL	30.0* 7	135.00
1202	REPAIR R/F SIDE MEMBER CPL	30.0* 7	135.00
1481	REPAIR LEFT FRONT DOOR	20.0* X	90.00
1482	REPAIR RIGHT FRONT DOOR	20.0* X	90.00
2227	REPAIR LEFT A-PILLAR	10.0* X	45.00
2228	REPAIR RIGHT A-PILLAR	10.0* X	45.00
LABOUR COST			
	Total Work Units	268.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	26.8HRS	\$1,206.00
	Paint Labour	15.6HRS	\$702.00
	Total Labour	42.4HRS	\$1,908.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PAINTING OFF VEHICLE		
471	BONNET NEW PART PAINTING	21.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	16.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	16.0	
2227	LEFT A-PILLAR REPAIR PAINTING <50%	8.0	
2228	RIGHT A-PILLAR REPAIR PAINTING <50%	8.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	

Ah Lim Motor Company

Claim Reference: OD CLAIM

Assessment Number: AH000936

Version: AHLIM001/1

Date Calculated: 25/09/2018 04:03

Full Report - V1

Registration: SLU907G

Printed: 25/09/2018 11:05

1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT	5.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT	5.0	
LABOUR COST - PAINT			
	TIME(PAINT)	130.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	156.0	
	Total Paintwork Labour	15.6HRS	\$702.00
MATERIAL COST - PAINT			
			Cost Price
	New Part Painting		\$108.37
	New Part Painting - Plastic K1R		\$67.40
	Surface-/Blend Paint		\$50.80
	Repair Painting		\$64.60
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$318.27
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$318.27

PARTS

						Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)		
281	1	FRONT BUMPER	52119 02979		0%	CM 170.00*	✓	
317	1	L/F BUMPER BRACKET	52116 12390		0%	30.00*	✓	PhG
318	1	R/F BUMPER BRACKET	52115 02100		0%	30.00*	✓	
340	1	BUMPER SUPPORT	52021 12240		0%	85.00*	✓	
341	1	FRT BUMPER ABSORBER	52611 12190		0%	CM 48.00*	✓	
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	24.00*	✓	
410	1	GRILLE	53100 02190		0%	CM 130.00*	✓	
471	1	BONNET	53301 12A20		0%	Bu 225.00*	✓	
475	1	L/F HINGE	53420 02110		0%	DT 32.00*	✓	
476	1	R/F HINGE	53410 02110		0%	DT 32.00*	✓	
481	1	BONNET INSULATION	53341 12260	Return	0%	150.00*	✓	
493	1	BONNET LOCK	53510 02291		0%	42.00*	✓	
500	1	BONNET CABLE	53630 12770		0%	32.00*	✓	
561	1	LEFT HEADLAMP ASSY	81170 02560		0%	CM 205.00*	✓	
562	1	RIGHT HEADLAMP ASSY	81130 02560	W/L 811	0%	205.00*	✓	
707	1	L/REPEATER LAMP CPL	81730 02080		0%	38.00*	X	
708	1	R/REPEATER LAMP CPL	81730 02080		0%	38.00*	X	
741	1	L/F WING	53812 12A10		0%	Bu 175.00*	✓	
742	1	R/F WING	53811 12A10		0%	Bu 175.00*	✓	
747	1	L/DOOR MIRROR TRIM	60118 12030		0%	28.00*	X	
748	1	R/DOOR MIRROR TRIM	60117 12030		0%	28.00*	X	
789	1	L/F WING CLAMP KIT	SEE GUIDE NO.		0%	20.00*	✓	
			6001					
790	1	R/F WING CLAMP KIT	SEE GUIDE NO.		0%	20.00*	✓	
			6002					
841	1	L/WHEELHOUSE SHELL	53876 12480		0%	65.00*	✓	
842	1	R/WHEELHOUSE SHELL	53875 12520		0%	65.00*	✓	
1009	1	INNER FRT PANEL CPL	53201 12903		0%	270.00*	✓	
1436	1	WASHER CONTAINER	85315 02270		0%	58.00*	✓	
1445	1	L/F WASHER JET	85381 12300		0%	32.00*	✓	

Ah Lim Motor Company

Claim Reference: OD CLAIM
Assessment Number: AH000936

Version: AHLIM001/1

Date Calculated: 25/09/2018 04:03

Full Report - V1
Registration: SLU907G
Printed: 25/09/2018 11:05

1446	1	R/F WASHER-JET	85381-12300	0%	32.00*	X
4465	1	CONDENSER CPL	88450 12280	0%	270.00*	✓
4483	1	EVAPORATOR-OUTL-PIPE	88710-02870	0%	210.00*	?
4484	1	COMPR/CONDENSER-HOSE	88703-12830	0%	185.00*	?
4488	1	COMPR/EVAP-TUBE	88704-1A180	0%	165.00*	?
7761	1	RADIATOR CPL	16400 0D450	0%	420.00*	✓
7767	1	RADIATOR SHROUD	16711 0D220	0%	75.00*	✓
7768	1	UPP RADIATOR SHROUD	16712 0D040	0%	55.00*	✓
7773	1	LWR-RADIATOR-HOSE	16572-0D170	0%	35.00*	?
7776	1	UPPER-RADIATOR-HOSE	16573-37040	0%	30.00*	?
7787	1	EXPANSION TANK	16480-22080	0%	55.00*	✓
7793	1	COOLING FAN	16361 0N050	0%	55.00*	?
7797	1	FAN MOTOR	16363 22100	0%	100.00*	?
8221	1	INTAKE-MANIFOLD	17120-37021	0%	205.00*	?
8783	1	FRONT-LWR-ENGINE-CVR	52618-12020	0%	64.00*	X
9631	1	BATTERY-TRAY	74431-02210	0%	38.00*	?
9645	1	HORN	86520-28180	0%	90.00*	?
1000	1	F-BUMP-TOW-COVER	Renew	0%	0.00	✓
1000	1	ENGINE-UNER-COVER	Renew	0%	40.00*	X
1000	1	FOG LAMP-OUT-COVR-X2	Renew	0%	30.00*	X
1000	1	BRACE PANAL	Renew	0%	45.00*	✓
1000	1	TEMP-SENSOR	Renew	0%	175.00*	?
1000	1	F-BOT-INS-CLIPS-X10	Renew	0%	20.00*	✓
1000	1	F-BOT-RUBER-CENTRE	Renew	0%	38.00*	✓
1000	1	F-BOT-STAND-CLIPS	Renew	0%	25.00*	✓
1000	1	F-GRILE-CLIPS-X8	Renew	0%	16.00*	?
1000	1	HEAD-LAMP-BULB-LH	Renew	0%	20.00*	?
1000	1	HEAD-LAMP-CLIPS-X4	Renew	0%	10.00*	?
1000	1	RADIATOR-T-BRAT-X2	Renew	0%	70.00*	?
1000	1	RADIATOR-T-BUSH-X2	Renew	0%	40.00*	?
1000	1	FAN-MOTOR-RESISTER	Renew	0%	175.00*	?
1000	1	RESONATOR-TANK-LH	Renew	0%	0.00	?
1000	1	RESONATOR-HOSE-OUT	Renew	0%	28.00*	?
1000	1	AIR-DUCT-UPPER-LH	Renew	0%	45.00*	?
1000	1	FUSE-BOX-TOP-COVER	Renew	0%	58.00*	?
1000	1	F-BOX-LOW-COVER	Renew	0%	45.00*	?
1000	1	AIR-CLENNER-BOX-ASSY	Renew	0%	265.00*	?
1000	1	BATTEY-COVER	Renew	0%	0.00	X
1000	1	BATTEY-TOP-BRACET	Renew	0%	28.00*	✓

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

(10 %)

Total Parts

\$5,709.00

\$570.90

\$6,279.90

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
BATTERY ASSY	0%	\$210.00
COOLANT	0%	\$35.00
F NUMBER PLATE	0%	\$35.00
CHECK WIRING	0%	\$40.00
REFILL A/C GAS	0%	\$50.00

Ah Lim Motor Company

Claim Reference: OD CLAIM

Assessment Number: AH000936

Version: AHLIM001/1

Date Calculated: 25/09/2018 04:03

Full Report - V1

Registration: SLU907G

Printed: 25/09/2018 11:05

RESET AL DIAGNOSTIC	SPECIALIST	\$200.00	?
Total Extras		\$570.00	

Final Calculation

Total Parts		\$6,279.90
Labour		
Total Panel/Mechanical	\$1,206.00	
Total Paintwork	\$702.00	
Total Labour		\$1,908.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$570.00	
Total of Additional Costs		\$570.00
Total Paint/Material Costs		\$318.27
Grand Total Excludes GST		\$9,076.17
GST @ 7 %		\$635.33
Grand Total Includes GST		\$9,711.50

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: OD CLAIM
Assessment Number: AH000936
Version: AHLIM001/2
Date Calculated: 10/12/2018 10:23

Full Report - V1
Registration: SLU907G
Printed: 10/12/2018 18:24

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	OD CLAIM	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla
Sub Model:	BASE MODEL
Model Sheet Number:	YAC 01
Registration:	SLU907G
Registration Month:	May
Registration Year:	2009
VIN Number:	NZE1416114219
Manufacture Year:	2009
Odometer:	Not Known
Colour:	
Engine Number:	1NZD369521
Fuel Level:	%



Model Specs

FROM 05/2009	AIR CONDITIONING
FOG LAMPS	1.6 LTR 91 KW
4-SPEED AUTOMATIC	TWO COAT METALLIC
PAINTING OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection: 25/09/2018
Place of Inspection:	
Pre-Accident Damage:	PLEASE NOTE THAT VEHICLE IS TOYOTA COROLLA AXIO 1.5X AT 2009 YEAR MODEL ,TOYOTA COROLLA SEDAN 2007 YEAR MODEL IS ONLY USED AS A REFERENCE MODEL...
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,269.00
Total Paint/Material	\$316.03
Total Parts	\$2,798.40
Total of Additional Costs	\$335.00
Excess:	TBA
Grand Total Exc GST:	\$4,718.43
7 % GST:	\$330.29
Grand Total Inc GST:	\$5,048.72

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
B040)	ADJUST HEADLAMPS	3.0	13.50
B010)	R + R FRONT BUMPER	5.0	22.50
B020)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	13.0	58.50
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
B040)	RENEW HEADLAMP	1.0	4.50
B140	RENEW FRONT PANEL CPL	9.0	40.50
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.00
B100	R + R LEFT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B100	R + R RIGHT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	4.0	18.00
B110)	RENEW L/F WING (REMOVED)	2.0	9.00
B110)	RENEW RIGHT FRONT WING (REMOVED)	2.0	9.00
B060	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50

B070)	RENEW BONNET (REMOVED)	1.0	4.50
B080	R + R BONNET HINGES	1.0	4.50
M010)	R + R AIR CONDITIONING CONDENSER	3.0	13.50
002889	REFILL AIR CONDITIONING	7.0	31.50
160021	R + R RADIATOR OVERFLOW TANK	3.0	13.50
M020	R + R RADIATOR	6.0	27.00
	INCLUDES: BLEED COOLING SYSTEM		
M020)	RENEW RADIATOR (RADIATOR REMOVED)	3.0	13.50
NO NUMBER	R + R L/LOWER ENGINE PROTECTION	2.0	9.00
NO NUMBER	R + R R/LOWER ENGINE PROTECTION	2.0	9.00
NN	BRACE PANAL R&R / NEW PARTS	2.0*	9.00
1117	REPAIR L/F WHEELHOUSE CPL	8.0*	36.00
1118	REPAIR R/F WHEELHOUSE CPL	10.0*	45.00
1201	REPAIR L/F SIDE MEMBER CPL	20.0*	90.00
1202	REPAIR R/F SIDE MEMBER CPL	20.0*	90.00
1482	REPAIR RIGHT FRONT DOOR	5.0*	22.50

LABOUR COST

Total Work Units	143.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	14.3HRS	\$643.50
Paint Labour	13.9HRS	\$625.50
Total Labour	28.2HRS	\$1,269.00

PAINT WORK	Time Basis 10 WU = 1 HR. Price = \$45.00/HR
Guide Number Description	WU Cost Price (\$)

	- TWO COAT METALLIC	
	- PAINTING OFF VEHICLE	
471	BONNET NEW PART PAINTING	21.0
741	L/F WING NEW PART PAINTING	10.0
742	R/F WING NEW PART PAINTING	10.0
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0
281	FRONT BUMPER NEW PART PAINT K1R	13.0
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	25.0
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0
1201	L/F SIDE MEMBER CPL SURFACE PAINT	5.0
1202	R/F SIDE MEMBER CPL SURFACE PAINT	5.0
1481	LEFT FRONT DOOR SURFACE PAINT	8.0
2227	LEFT A-PILLAR SURFACE PAINT	4.0
2228	RIGHT A-PILLAR SURFACE PAINT	4.0

LABOUR COST - PAINT

TIME(PAINT)	123.0	
Preparation Main Work Metal	11.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	139.0	
Total Paintwork Labour	13.9HRS	\$625.50

MATERIAL COST - PAINT

New Part Painting	\$108.37
New Part Painting - Plastic K1R	\$67.40

Surface-/Blend Paint	\$79.19
Repair Painting	\$33.97
Material-Const Main Work Metal	\$18.10
Material-Const Comp. Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$316.03
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$316.03

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
471	1	BONNET	53301 12A20		0% 225.00*
493	1	BONNET LOCK	53510 02291		0% 42.00*
1000	1	BRACE PANAL	Renew		0% 45.00*
340	1	BUMPER SUPPORT	52021 12240		0% 85.00*
4465	1	CONDENSER CPL	88450 12280		0% 160.00*
7793	1	COOLING FAN	16361 0N050		0% 55.00*
7797	1	FAN MOTOR	16363 22100		0% 100.00*
281	1	FRONT BUMPER	52119 02979		0% 170.00*
341	1	FRT BUMPER ABSORBER	52611 12190		0% 48.00*
410	1	GRILLE	53100 02190		0% 130.00*
1009	1	INNER FRT PANEL CPL	53201 12903		0% 270.00*
317	1	L/F BUMPER BRACKET	52116 12390		0% 30.00*
475	1	L/F HINGE	53420 02110		0% 32.00*
741	1	L/F WING	53812 12A10		0% 175.00*
561	1	LEFT HEADLAMP ASSY	81170 02560		0% 205.00*
476	1	R/F HINGE	53410 02110		0% 32.00*
742	1	R/F WING	53811 12A10		0% 175.00*
7761	1	RADIATOR CPL	16400 0D450		0% 230.00*
7767	1	RADIATOR SHROUD	16711 0D220		0% 75.00*
562	1	RIGHT HEADLAMP ASSY	81130 02560		0% 205.00*
7768	1	UPP RADIATOR SHROUD	16712 0D040		0% 55.00*
f: OEM Parts			Sub Total		\$2,544.00
g: Original			Mark Up From Cost	(10 %)	\$254.40
h: Secondhand			Total Parts		\$2,798.40
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
BATTERY ASSY	SPECIALIST	0%	\$210.00
COOLANT	SPECIALIST		\$20.00
F NUMBER PLATE	SPECIALIST	0%	\$35.00
CHECK WIRING	SPECIALIST		\$20.00
REFILL A/C GAS	SPECIALIST	0%	\$50.00
Total Extras			\$335.00

Final Calculation

Total Parts		\$2,798.40
Labour		
Total Panel/Mechanical	\$643.50	
Total Paintwork	\$625.50	
Total Labour		\$1,269.00
Additional Costs		

Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$335.00	
Total of Additional Costs		\$335.00
Total Paint/Material Costs		\$316.03
Grand Total Excludes GST		\$4,718.43
GST @ 7 %		\$330.29
Grand Total Includes GST		\$5,048.72

Assessment Notes



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18017498/Kcd3e2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 20-12-2018



ATTN : KITTY TEO

Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLU 907G
Policy No.	GA305697	Coverage (\$)	0.00
Claim No.	S8M00WSJ	Excess (\$)	1,000.00
Assign From	KITTY TEO	Assign Date	26/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	NZE1416114219	Colour	METALLIC SILVER
Odometer	149811	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	BRIDGESTONE	4 mm
L/H Front Tyre	195/65 R15	BRIDGESTONE	4 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	2 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/09/2018	Inspection Date	26/09/2018
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE MARKET VALUE IS S\$13,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 907G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (WCP) (CONSISTENT)	CRACKED	170.00	170.00
1	L/F BUMPER BRACKET (WCP) (CONSISTENT)	DISTORTED	30.00	30.00
1	R/F BUMPER BRACKET (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	30.00	-
1	BUMPER SUPPORT (WCP) (CONSISTENT)	BENT	85.00	85.00
1	FRT BUMPER ABSORBER (WCP) (CONSISTENT)	CRACKED	48.00	48.00
1	FRT BUMPER CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	24.00	-
1	GRILLE (WCP) (CONSISTENT)	CRACKED	130.00	130.00
1	BONNET (WCP) (CONSISTENT)	BUCKLED	225.00	225.00
1	L/F HINGE (WCP) (CONSISTENT)	DISTORTED	32.00	32.00
1	R/F HINGE (WCP) (CONSISTENT)	DISTORTED	32.00	32.00
1	BONNET INSULATION (WCP) (CONSISTENT)	SERVICEABLE	150.00	-
1	BONNET LOCK (WCP) (CONSISTENT)	BENT	42.00	42.00
1	BONNET CABLE (WCP) (CONSISTENT)	SERVICEABLE	32.00	-
1	LEFT HEADLAMP ASSY (WCP) (CONSISTENT)	CRACKED	205.00	205.00
1	RIGHT HEADLAMP ASSY (WCP) (CONSISTENT)	MTG CRACKED	205.00	205.00
1	L/REPEATER LAMP CPL (WCP) (CONSISTENT)	SERVICEABLE	38.00	-
1	R/REPEATER LAMP CPL (WCP) (CONSISTENT)	SERVICEABLE	38.00	-
1	L/F WING (WCP) (CONSISTENT)	BUCKLED	175.00	175.00
1	R/F WING (WCP) (CONSISTENT)	BUCKLED	175.00	175.00
1	L/DOOR MIRROR TRIM (WCP) (CONSISTENT)	SERVICEABLE	28.00	-
1	R/DOOR MIRROR TRIM (WCP) (CONSISTENT)	SERVICEABLE	28.00	-
1	L/F WING CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
1	R/F WING CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
1	L/WHEELHOUSE SHELL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	R/WHEELHOUSE SHELL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	INNER FRT PANEL CPL (WCP) (CONSISTENT)	BENT	270.00	270.00
1	WASHER CONTAINER (WCP) (CONSISTENT)	SERVICEABLE	58.00	-
1	L/F WASHER JET (WCP) (CONSISTENT)	SERVICEABLE	32.00	-
1	R/F WASHER JET (WCP) (CONSISTENT)	SERVICEABLE	32.00	-

Report Ref No. CS/ASM18017498/Kcd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CONDENSER CPL (WCP) (CONSISTENT)	BENT / PUNCTURE	270.00	160.00
1	EVAPORATOR OUTL PIPE (WCP) (CONSISTENT)	SERVICEABLE	210.00	-
1	COMPR/CONDENSER HOSE (WCP) (CONSISTENT)	SERVICEABLE	185.00	-
1	COMPR/EVAP TUBE (WCP) (CONSISTENT)	SERVICEABLE	165.00	-
1	RADIATOR CPL (WCP) (CONSISTENT)	BENT	420.00	230.00
1	RADIATOR SHROUD (WCP) (CONSISTENT)	CRACKED	75.00	75.00
1	UPP RADIATOR SHROUD (WCP) (CONSISTENT)	CRACKED	55.00	55.00
1	LWR RADIATOR HOSE (WCP) (CONSISTENT)	SERVICEABLE	35.00	-
1	UPPER RADIATOR HOSE (WCP) (CONSISTENT)	SERVICEABLE	30.00	-
1	EXPANSION TANK (WCP) (CONSISTENT)	SERVICEABLE	55.00	-
1	COOLING FAN (WCP) (CONSISTENT)	DISTORTED	55.00	55.00
1	FAN MOTOR (WCP) (CONSISTENT)	JAMMED	100.00	100.00
1	INTAKE MAIFOLD (WCP) (CONSISTENT)	SERVICEABLE	205.00	-
1	FRONT LWR ENGINE CVR (WCP) (CONSISTENT)	SERVICEABLE	64.00	-
1	BATTERY TRAY (WCP) (CONSISTENT)	SERVICEABLE	38.00	-
1	HORN (WCP) (CONSISTENT)	SERVICEABLE	90.00	-
1	F BUMP TOW COVER (WCP) (CONSISTENT) (NPA)	SERVICEABLE	-	-
1	ENGINE UNER COVER (WCP) (CONSISTENT)	SERVICEABLE	40.00	-
2	FOG LAMP OUT COVR (WCP) (CONSISTENT)	SERVICEABLE	30.00	-
1	BRACE PANAL (WCP) (CONSISTENT)	BENT	45.00	45.00
1	TEMP SENSOR (WCP) (CONSISTENT)	SERVICEABLE	175.00	-
10	F BOT INS CLIPS (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
1	F BOT RUBER CENTRE (WCP) (CONSISTENT)	NOT NECESSARY	38.00	-
1	F BOT STAND CLIPS (WCP) (CONSISTENT)	NOT NECESSARY	25.00	-
8	F GRILLE CLIPS (WCP) (CONSISTENT)	SERVICEABLE	16.00	-
1	HEAD LAMP BULB LH (WCP) (CONSISTENT)	SERVICEABLE	20.00	-
4	HEAD LAMP CLIPS (WCP) (CONSISTENT)	SERVICEABLE	10.00	-
2	RADIATOR T BRAT (WCP) (CONSISTENT)	SERVICEABLE	70.00	-
2	RADIATOR T BUSH (WCP) (CONSISTENT)	SERVICEABLE	40.00	-
1	FAN MOTOR RESISTER (WCP) (CONSISTENT)	SERVICEABLE	175.00	-
1	RESONATOR TANK LH (WCP) (CONSISTENT) (NPA)	SERVICEABLE	-	-
1	RESONATOR HOSE OUT (WCP) (CONSISTENT)	SERVICEABLE	28.00	-
1	AIR DUCT UPPER LH (WCP) (CONSISTENT)	SERVICEABLE	45.00	-

Report Ref No. CS/ASM18017498/Kcd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FUSE BOX TOP COVER (WCP) (CONSISTENT)	SERVICEABLE	58.00	-
1	F BOX LOW COVER (WCP) (CONSISTENT)	SERVICEABLE	45.00	-
1	AIR CLEANER BOX ASSY	SERVICEABLE	265.00	-
1	BATTEY COVER (WCP) (CONSISTENT) (NPA)	NO SUCH PARTS	-	-
1	BATTEY TOP BRACET (WCP) (CONSISTENT)	SERVICEABLE	28.00	-
	COST PLUS 10%		570.90	254.40
			6,279.90	2,798.40
	<u>SPECIAL NETT ITEMS</u>			
1	BATTERY ASSY (SN)	DENTED	210.00	210.00
1	COOLANT (SN)	NECESSARY	35.00	20.00
1	F NUMBER PLATE (SN)	MISSING	35.00	35.00
			280.00	265.00
	<u>LABOUR</u>			
	CHECK WIRING.		40.00	20.00
	REFILL A/C GAS.		50.00	50.00
	RESET AL DIAGNOSTIC.	NOT NECESSARY	200.00	-
	TOTAL PANEL / MECHANICAL INCLUSIVE OF THE REPAIR OF R/F BUMPER BRACKET, L/WHEELHOUSE SHELL AND R/WHEELHOUSE SHELL.		1,206.00	643.50
	TOTAL PAINTWORK.		702.00	625.50
	TOTAL PAINT / /MATERIAL COSTS.		318.27	316.03
			2,516.27	1,655.03
	GRAND TOTAL		9,076.17	4,718.43
	RECOMMENDED COST OF REPAIRS			4,718.43
	LESS EXCESS			-1,000.00
	NETT LIABILITY			3,718.43

Report Ref No. CS/ASM18017498/Kcd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.