

INS. CASE OWNER:

Ang Li Li

CC 4, WPC 180 17503, T1fa32

LKK: IDAC:

Surveyor:

MJA

DOI:

26/9/18

Date / Time:

24/09/10

Registered in Jurisdiction:

Pre-assign / CCU / FT&



Insured Vehicle No.:

YN 9146J

Claim No.:

12/18/10 / VC05/020 932

Name of Insured:

PAN OCEAN SA P/L

Policy No.:

218 VC 05 000577

Insured Tel No.:

HP:

Make / Model:

Mit. Conter

Excess Sec II :SS

D.O.A.:

21/9/2018

Place of Accident:

AYE

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

PRAVEEN PRAVIN
21/4/95 (VL: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

666 7302

Insured Liability: %

Final ? Yes / No



INSRS: WSP: Tel: Liability: RMKS:

Singal Automotive



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time		STAGE	DATE / PIC
7/10	666 7302 - X; YN 9146J - X	Non-Reporting ltr (1st):	
CPC		Non-Reporting ltr (2nd):	
4/10/2018	e-mail liability clear to TP workshop	Non-Reporting ltr (Final):	
	pass file to finalize ✓	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler Typist	
	pending LOD ✓	Notification ltr (if non-pickup)	
		After call ltr to OI:	
	pass file for type mandate report ✓	Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	
	After repair photo ✓		

PRELIMINARY ADVICE Date/Time: 27/9/2018 Sent By: HMC

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S\$ 8,750.00 (6 days) Reduction: 62.69 % Email Call

FINAL SETTLEMENT Date/Time: 24/11/2019 Confirm with: Michael Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia: Front to rear

Repair Cost: S\$ 8,750.00 Loss of Rental (LOR): S\$ 600.00 (6 days) x \$100.00 Loss of Use (LOU): S\$ - (\$ x days) Loss of Income (LOI): S\$ - (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: S\$ - Medical: S\$ - Disbursement: S\$ - (e.g. Tow/Independent) Legal Cost: S\$ - Total: S\$ 9,350.00 Global Sum S\$:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: S\$ 9,350.00 Name 1: Singal Automotive Pte Ltd

Payee 2: (Strike if N.A.) S\$ - Name 2: Payee 3: (Strike if N.A.) S\$ - Name 3:

13/02/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VC05/020932
Our ref: CC4/LPC18017503/T1fa3

Date: 27.09.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBG 730R

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.09.2018 at the premises of M/s Sinai Automotive Pte. Ltd. have the following to report:-

Workshop Estimate Amount	: S\$	18,895.18
Revised Estimate Amount	: S\$	11,011.49
"Check" Items Amount	: S\$	466.20
Total (Including Check Items)	: S\$	11,477.69

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

SINAI AUTOMOTIVE PTE.LTD.

ROC NO:201830476Z
 1 SOON LEE STREET #04-44/45
 PIONEER CENTRE, SINGAPORE [627605]
 Tel: 62624438 Fax:69289896

TO INSURANCE CO	: LONPAC INSURANCE BHD	DATE	21-Sep-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	TP CLAIMS
ESTIMATE REPORT	:		
OWNER'S PARTICULAR		VEHICLE DETAILS	
NAME	: FIRETECH SERVICES PTE LTD	VEHICLE NO	: GBG730R
ADDRESS	: 50 BUKIT BATOK STREET 23 #07-03 MIDVIEW BUILDING S(659578)	MODEL	: NISSAN NV200
TEL. NO.	:	CHASSIS NO	: VSKYBAM20Z0140629
OWNER'S INSURANCE	: NTUC Income	REGISTRATION DATE	: 27/5/2017
POLICY NO.	: 5091278335-01	MARKET VALUE	: \$54,800
ACCIDENT DETAILS	:	COE REBATE AMOUNT	: \$26,561
DATE/TIME	: 21/9/2018 / 8:05AM	LIMIT REPAIR	: \$28,239

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR DOOR LH	1	\$ 1,415.00	\$ 1,415.00	bt ✓
2	REAR DOOR RH	1	\$ 1,225.00	\$ 1,225.00	bt ✓
3	REAR DOOR "LOGO"	1	\$ 89.00	\$ 89.00	ner ✓
4	REAR DOOR "NISSAN NV200"	1	\$ 78.00	\$ 78.00	ner ✓
5	REAR DOOR GLASS DEFROSTER WIREHARNES	1	\$ 281.00	\$ 281.00	cut ✓
6	REAR DOOR GLASS LH	1	\$ 720.00	\$ 720.00	cut ✓
7	REAR DOOR GLASS RH	1	\$ 410.00	\$ 410.00	cut ✓
8	REAR DOOR GARNISH LH	1	\$ 189.00	\$ 189.00	cut ✓
9	REAR DOOR GLASS FILM	2	\$ 208.00	\$ 416.00	ner ✓
10	REAR NUMBER PLATE LAMP	2	\$ 98.00	\$ 196.00	xm ✓
11	REAR DOOR INNER TRIM LH	1	\$ 381.00	\$ 381.00	xm ✓
12	REAR DOOR WIPER MOTOR	1	\$ 518.00	\$ 518.00	bt ✓
13	REAR DOOR WIPER ARM	1	\$ 140.00	\$ 140.00	cut ✓
14	REAR DOOR WIPER ARM COVER	1	\$ 60.00	\$ 60.00	lat ✓
15	REAR DOOR HINGE	2	\$ 120.00	\$ 240.00	xm ✓
16	REAR DOOR CHECKER LH	1	\$ 189.70	\$ 189.70	xm ✓
17	REAR DOOR WEATHERSTRIP (INNER)	1	\$ 221.00	\$ 221.00	cut ✓
18	REAR DOOR WEATHERSTRIP (CENTER)	1	\$ 163.00	\$ 163.00	cut ✓
19	REAR DOOR LOWER LOCK	2	\$ 99.90	\$ 199.80	xm ✓
20	REAR DOOR TOP LOCK	2	\$ 128.00	\$ 256.00	LH-X, RH-b ✓
22	REAR BUMPER	1	\$ 480.80	\$ 480.80	de ✓
23	REAR BUMPER REFLECTOR	2	\$ 41.60	\$ 83.20	LH-X, RH ✓
24	REAR BUMPER SIDE RETAINER	2	\$ 35.20	\$ 70.40	ner ✓
25	REAR BUMPER SPONGE	1	\$ 160.00	\$ 160.00	de ✓

27	REAR TOWING HOOK	1	\$ 154.00	\$ 154.00
27	REAR TOWING HOOK COVER	1	\$ 54.00	\$ 54.00
29	TAIL LAMP	2	\$ 630.00	\$ 1,260.00
30	REAR END PANEL (OUTER)	1	\$ 652.00	\$ 652.00
31	REAR END PANEL (INNER)	1	\$ 610.00	\$ 610.00
32	REAR FLOOR PANEL TOP MAT	1	\$ 594.00	\$ 120 594.00
33	REAR END PANEL TOP GARNISH	1	\$ 174.30	\$ 174.30
TOTAL PRICE				\$ 11,680.20
LESS 10%				\$ 1,168.02
SUB TOTAL PRICE				\$ 10,512.18

dd
art
24-nt, R4
bl-
R2
*tn
de
\$8590.11
10%
\$7,731.11

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP SET	1	\$ 65.00	\$ 65.00
2	TAILLAMP CLIP SET	1	\$ 40.00	\$ 40.00
3	REAR DOOR SEALANT	2	\$ 80.00	\$ 160.00
4	REAR DOOR INNER TRIM CLIP SET	1	\$ 60.00	\$ 60.00
5	REAR NUMBER PLATE LAMP GARNISH CLIP SET	1	\$ 26.00	\$ 26.00
6	REAR DOOR GLASS SEALANT	2	\$ 80.00	\$ 160.00
7	REAR DOOR "70KM" STICKER	1	\$ 30.00	\$ 30.00
8	REAR DOOR "Pax" STICKER	1	\$ 30.00	\$ 30.00
9	REAR DOOR GLASS INNER SEAL	2	\$ 60.00	\$ 120.00
10	REAR DOOR COMPANY LOGO (SET)	1	\$ 920.00	\$ 920.00
11	REAR END PANEL (OUTER) SEALANT	1	\$ 120.00	\$ 120.00
12	REAR END PANEL (INNER) SEALANT	1	\$ 120.00	\$ 120.00
13	REAR END PANEL TOP GARNISH CLIP SET	1	\$ 52.00	\$ 52.00
14	REAR DOOR WIPER PLATE blade -	1	\$ 100.00	\$ 100.00
15	REVERSE SENSOR	1	\$ 250.00	\$ 250.00
16	REAR FLOOR WOODEN SHELVES	1	\$ 980.00	\$ 980.00
17	REVERSE CAMERA	1	\$ 380.00	\$ 380.00
NETT TOTAL				\$ 3,233.00

30 net
X n n
net - 80.
30 net
X n n
30 net
net -
net -
80 net
300 net
40 net
X n n
10 net
30 net
200 net
200 net
X n n

3613
\$1,140.00

LABOURR CHARGE DETAILS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PENEL BEATING FOR CUTING ,KUOCKING ,DISMANTLE ,REFIT AND REPLACEMENT OF PARTS.	\$ 1,800.00		800
2	SPRAY PAINTING TO AFFECTED AREA.	\$ 1,500.00		800
3	TO APPLY TUFF COATING.	\$ 250.00		40.
4	DISMANTLE AND REPLACEMENT REVERSE SENSOR ,REVERSE CAMERA,DOOR GLASS HEATER WIREHARNNESS PERFORM WIRING CHECK.	\$ 280.00		30.
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR.	\$ 350.00		50.
6	TRANFER REAR DOOR MECHANISM LH AND RH.	\$ 160.00		100
7	DISMANTLE AND REPLACEMENT REAR WOODEN SHELVES	\$ 250.00		100
8	INSTALL COMPANY STICKER	\$ 200.00		100.
9	INSTALL REAR DOORS GLASS FILM	\$ 180.00		X
10	DISMANTLE AND REPLACEMENT REAR DOOR GLASS	\$ 180.00		160
TOTAL		\$ 5,150.00		

TOTAL PARTS COST	: \$	13,745.18
TOTAL LABOUR COST	: \$	5,150.00
TOTAL REPAIR COST	: \$	18,895.18

\$ 2080.00

APPROVED DETAILS

NO. OF WORKING DAYS
 RE-SURVEY
 LUMP SUM OR PART BY PART
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 EMAIL & FAX NUMBER

19225.18

Tanjah 97495744

26/9/18 @ 1520

*Resurvey After repair
 sur @ 14hanto van
 6 days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

parts \$ 7,731.09
+ S/N \$ 1,140.00
+ Labour \$ 2,080.00

\$ 10,951.09
- 20%

\$ 8,760.87
= L/S: \$ 8,750.00

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 24 September 2018 2:08 PM
To: Michael Wong; assignments@lkkauto.com; Nivitha (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: Requesting for pre-repair inspection Our Ref: 18/18/18/VC05/020932 TBA (YN9146J) Your Ref: GBG730R

Without Prejudice

Dear Michael

Thank you for your reply to appoint a Single Joint Expert. Please let us have the workshop's details and location.

Dear Catherine/Nivitha

Please arrange Mohammed Taufikh to attend to the TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

2:27pm @ 24/9/18
VNI
Mr. Michael
arrange on 26/9/18
estimate provided.

From: Michael Wong [mailto:michael@huayu.sg]
Sent: Monday, 24 September, 2018 1:05 PM
To: ONG LI LI
Subject: Re: Requesting for pre-repair inspection Our Ref: TBA (YN9146J) Your Ref: GBG730R

Dear Lonpac,

I would like to pick the third person on the list, Mohammad Taufikh.

No.	Name	Please tick <input checked="" type="checkbox"/>
1	Kalvin Ang	<input type="checkbox"/>
2	Xing Guo Qiang	<input type="checkbox"/>
3	Mohamad Taufikh	<input checked="" type="checkbox"/>

4

Bryan Ang

5

Adrian Ling

6

Mohammed Rasul

7

Marcus Chua

8

Kenneth Kong

9

Muhammad Nazril Bin Abdullah

10

Sathya Sai Kathirrasen

Please drop me a call at +65 9090 0095.Thank you.

Regards,
Michael Wong

On 24 Sep 2018, at 11:02 AM, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly withQ your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input checked="" type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	ok
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: Michael Wong [<mailto:michael@huayu.sg>]
Sent: Friday, September 21, 2018 4:04 PM
To: CHEW BENG KEE
Subject: Requesting for pre-repair surgery

We're a 3rd party claim company named Sinai Automotive Pte. Ltd.

Below the attached sent are the GIA report of a car accident today.

Please send a list of surveyors available to us so that we could select the surveyor to conduct surgery.

Yours sincerely,
Anson

Mei Kwan (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 28 September, 2018 2:51 PM
To: Mei Kwan (LKKAuto)
Cc: MT_Claim_SG; Poh Kin (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: RE: Requesting for pre-repair inspection Our Ref: 18/18/18/VC05/020932 TBA (YN9146J) Your Ref: GBG730R
Attachments: YN9146J 210918.PDF
Categories: HMK

Hi Mei Kwan

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 28 September, 2018 8:16 AM
To: ONG LI LI
Cc: MT_Claim_SG; Poh Kin (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: RE: Requesting for pre-repair inspection Our Ref: 18/18/18/VC05/020932 TBA (YN9146J) Your Ref: GBG730R

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/18/18/VC05/020932
LKK REF: CC4/LPC18017503/T1fa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: GBG 730R

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- TP GIA report

Kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Dear Lonpac,

I would like to pick the third person on the list, Mohammad Taufikh.

No.	Name	Please tick \surd
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	<input checked="" type="checkbox"/>

Please drop me a call at +65 9090 0095.Thank you.

Regards,
Michael Wong

On 24 Sep 2018, at 11:02 AM, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with Q your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	ok
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: Michael Wong [<mailto:michael@huayu.sg>]
Sent: Friday, September 21, 2018 4:04 PM

Poh Kin (LKKAuto)

From: Michael Wong <michael@huayu.sg>
Sent: Thursday, 24 January 2019 1:34 PM
To: Poh Kin (LKKAuto)
Subject: Re: RTA involving vehicle nos. YN 9146J and GBG 730R on 21/09/2018

OK! accept your offer,Thanks

发自我的 iPhone

在 2019年1月21日, 下午2:22, Poh Kin (LKKAuto) <pohkin@lkkauto.com> 写道:

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/LPC18017503/T1fa3
Your Ref: GBG 730R

Dear Michael,

We refer to the above matter.

Thank you for your patient waiting.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:-

1. Cost of Repair (w/GST)	S\$ 8,750.00
2. Loss of Rental (\$100.00 x 6 days)	S\$ 600.00 (subject to invoice)
	S\$ 9,350.00

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Monday, 21 January 2019 2:23 PM
To: 'michael@huayu.sg'
Subject: RTA involving vehicle nos. YN 9146J and GBG 730R on 21/09/2018
Attachments: RE: Finalization of repair cost of Vehicle no. GBG730R, DOA: 21/09/2018

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/LPC18017503/T1fa3
Your Ref: GBG 730R

Dear Michael,

We refer to the above matter.

Thank you for your patient waiting.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:-

1. Cost of Repair (w/GST)	S\$ 8,750.00
2. Loss of Rental (\$100.00 x 6 days)	S\$ 600.00 (subject to invoice)
	S\$ 9,350.00

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 28 December 2018 10:05 AM
To: 'michael@huayu.sg'; Taufikh (LKKAuto)
Subject: RE: Finalization of repair cost of Vehicle no. GBG730R, DOA: 21/09/2018
Attachments: TP estimate- Marked.pdf

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/LPC18017503/T1fa3
Your Ref: GBG 730R

Dear Michael,

We refer to the above matter.

Apologies for late reply.

For COR, our surveyor had recommended amount at L/S \$8,750.00 (before GST) with 6 repair days.

Please note that: All finalisation is subject to our Principal insurer's approval.

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

We need original copy LOD.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

-----Original Message-----

From: Taufikh (LKKAuto)

Sent: Friday, 28 December 2018 9:23 AM

To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Subject: FW: Finalization of repair cost of Vehicle no. GBG730R

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 4 October 2018 9:08 AM
To: 'michael@huayu.sg'
Cc: Admin A
Subject: RE: Our Ref: 18/18/18/VC05/020932 FW: Completion of repair works

WITHOUT PREJUDICE

Our Ref: CC4/LPC18017503/T1fa3
Your Ref: GBG 730R

Dear Michael,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YN 9146J AND GBG 730R ON 21/09/2018

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

-----Original Message-----

From: ONG LI LI [mailto:llong@lonpac.com]

Sent: Thursday, 4 October 2018 8:50 AM

To: michael@huayu.sg; Poh Kin (LKKAuto) <pohkin@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: Our Ref: 18/18/18/VC05/020932 FW: Completion of repair works

Without Prejudice

Dear Michael

Please liaise with LKK Auto Consultants Pte Ltd for quantum and liability.

Dear Poh Kin/Mei Kwan

For your handling, please reply to workshop

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: Michael Wong [mailto:michael@huayu.sg]

Sent: Thursday, 4 October, 2018 3:07 AM

To: ONG LI LI

Subject: Completion of repair works

Dear Miss Li Li,

Bellow attached are the photos with regards to the completion of repair of vehicle GBG730R.

Please take a look. If need be, please contact me at +65 9090 0095.

Poh Kin (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 21 January 2019 12:09 PM
To: Poh Kin (LKKAuto)
Cc: MT_Claim_SG; Admin A
Subject: RE: <URGENT>SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YN 9146J (OI) AND GBG 730R (TP) ON 21-09-2018; LKK ref : CC4/LPC18017503/T1fa3; Lonpac ref: 18/18/18/VC05/020932

Categories: clear

Dear Poh Kin

Please proceed.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]
Sent: Monday, 14 January, 2019 6:14 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A
Subject: <URGENT>SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YN 9146J (OI) AND GBG 730R (TP) ON 21-09-2018; LKK ref : CC4/LPC18017503/T1fa3; Lonpac ref: 18/18/18/VC05/020932
Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/LPC18017503/T1fa3
Your Ref: 18/18/18/VC05/020932

Dear Ms Ong Li Li,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YN 9146J (OI) AND GBG 730R (TP) ALONG AYE ON 21/09/2018

We refer to the above matter.

Liability: The accident occurred when our insured collided into the rear of third party vehicle. Liability is down against our Insured.

Summary to offer to third party repairer, Sinai Automotive Pte Ltd is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 19,275.18	\$ 8,750.00

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Monday, 14 January 2019 6:14 PM
To: 'ONG LI LI'
Cc: MT_Claim_SG; Admin A
Subject: <URGENT> SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YN 9146J (OI) AND GBG 730R (TP) ON 21-09-2018; LKK ref : CC4/LPC18017503/T1fa3; Lonpac ref: 18/18/18/VC05/020932
Attachments: LKK Adjustment Report.pdf; LKK Inspection report.pdf; LKK RE-SURVEY PHOTO.pdf; LKK RESURVEY PHOTO-AFTER REPAIR.pdf; LKK SURVEY PHOTO.pdf; TP LOD_GBG 730R.pdf
Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/LPC18017503/T1fa3
Your Ref: 18/18/18/VC05/020932

Dear Ms Ong Li Li,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YN 9146J (OI) AND GBG 730R (TP) ALONG AYE ON 21/09/2018

We refer to the above matter.

Liability: The accident occurred when our insured collided into the rear of third party vehicle. Liability is down against our Insured.

Summary to offer to third party repairer, Sinai Automotive Pte Ltd is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 19,275.18	\$ 8,750.00
2. Loss of Rental (pending invoice)	\$ 1,080.00 (\$180.00 x 6 days)	\$ 720.00 (\$120.00 x 6 days)
Total	\$ 20,355.18	\$ 9,470.00

****06 days recommendation for repair**

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.

SINAI AUTOMOTIVE PTE. LTD

ROC No.:201830476Z

1 SOON LEE STREET #04-44

PIONEER CENTRE, SINGAPORE (627605)

Tel: 6262 4438 Fax:6484 1111

1. Personal Data Collection Statement

Sinai Automotive Pte Ltd recognizes its obligations under the Personal Data Protection Act 2012 (PDPA) which includes the collection, use and disclosure of personal data for the purpose for which an individual has given consent to.

The personal data collected by **SA** includes all personal data given in this form, or in any documents provided, or to be provided to us by you or from other sources, for the purpose of working with the insurance company to file for an accident claim or to request for your current insurance certificate/policy or to provide you a quotation (new/renewal) on the insurance premium or to work on any insurance matters that is related to the initial assignment or to provide to lawyers in the event of litigation/personal injury claims or to make an application for any type of loans from any financial institution.

2. Purpose of Collection

We may collect and use the personal data for :

- a. Carry out identity checks
- b. Carry out No-claim Discount (NCD) and claims verification
- c. Communicate on purposes relating to the any application/claim
- d. Determine and/or verify your credit worthiness for the financial and insurance products you apply for
- e. Provide advice for the product recommendation base on your financial needs analysis
- f. Provide on-going services and respond to your inquiries/instructions
- g. Make or obtain payments
- h. Investigate and settle claims
- i. Recover any debt owed to us
- j. Detect and prevent fraud, unlawful or improper activities
- k. Conduct research and statistical analysis
- l. Coach employees and monitor for quality assurance
- m. Apply/Obtain quotation for insurance for new application/renewal by our partner(s) /agent(s)
- n. Allow our partner(s) and/or agent(s) to contact and use your personal data on our marketing/promotional materials relating to our product or other insurance products or services via telephone calls, text messages, faxes, mails or emails.

Xu JIANYUAN

Name :

Date : 210918

FIRETECH SERVICES PTE LTD
50 Bukit Batok Street 23
#07-03/04 Midview Building
Singapore 659578
Tel: 6267 9595 Fax: 6267 9559

SINAI AUTOMOTIVE PTE.LTD.

ROC NO:201830476Z

1 SOON LEE STREET #04-44/45
PIONEER CENTRE, SINGAPORE [627605]
Tel: 62624438 Fax:69289896

Satisfaction and Discharge Voucher

Dear Sir/Mdm,

I/We FIRETECH SERVICES PTE LTD hereby acknowledge, having received repair done to my/our vehicle no. G8673OR from **SINAI Automotive Automotive Pte.Ltd.**, which has been repaired to my/our satisfaction and acceptance.



I/ We shall fully discharge SINAI Automotive Pte Ltd in respect of the damage caused to the said vehicle in an accident that occurred thereto or about the 21/09/2018 at Jurong port road towards Jilun Ahmad Ibrahim.



I/ We agreed the payment of SGD \$ 3750.00 pay to SINAI Automotive Pte Ltd for such repairs is in full discharge of my/our claim on the corporation under the policy number 50091273335-01, reference claim number G8673OR, in respect of the damages caused to the said vehicle in an accident that occurred on the 21st day of the September 20 18.

Name: Xu JIANYUAN

NRIC no.: 58071852E

Signature: [Handwritten Signature]

Company stamp:



FIRETECH SERVICES PTE LTD
50 Bukit Bakok Street 23
#07-03/04 Midview Building
Singapore 659578
Tel: 6267 9595 Fax: 6267 9559

SINAI AUTOMOTIVE PTE. LTD

ROC No.:201830476Z

1 SOON LEE STREET #04-44

PIONEER CENTRE, SINGAPORE (627605)

Tel: 6262 4438 Fax:6484 1111

To:

Dear Sir/Madam

Accident involving _____ and _____ on _____

At/along _____

I/We, _____, am the registered
owner of the motor vehicle no. _____.

Please note that I have assigned all compensation monies due to me/us in the above said accident to
Sinai Automotive Pte Ltd

I/We, hereby authorized you to release all compensation monies pertaining to the above-mentioned
accident to **Sinai Automotive Pte Ltd** and forward your settlement cheque to **Sinai Automotive**
Pte Ltd whom I have authorized to collect the said compensation/monies.

FIRETECH SERVICES PTE LTD
50 Bukit Batok Street 23
#07-03/04 Midview Building
Singapore 659578
Tel: 6267 9595 Fax: 6267 9559



Signature of Claimant

Witness



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18017503/T1fa3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 14-02-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 9146J	Veh. Inspected	GBG 730R
Policy No.	Z18VC05000577	Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020932	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	24/09/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKYBAM20Z0140629	Colour	SILVER
Odometer	37317	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70R14	DUNLOP	6 mm
L/H Front Tyre	175/70R14	DUNLOP	6 mm
R/H Rear Tyre	175/70R14	DUNLOP	6 mm
L/H Rear Tyre	175/70R14	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/09/2018	Inspection Date	26/09/2018
Survey held at	SINAI AUTOMOTIVE PTE LTD 1 SOON LEE STREET #04-45 PIONEER CENTRE SINGAPORE 627605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 730R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR LH	BENT	1,415.00	1,415.00
1	REAR DOOR RH	BENT	1,225.00	1,225.00
1	REAR DOOR "LOGO"	NECESSARY	89.00	89.00
1	REAR DOOR "NISSAN NV200"	NECESSARY	78.00	78.00
1	REAR DOOR GLASS DEFROSTER WIREHARNES	CUT	281.00	281.00
1	REAR DOOR GLASS LH	CRACKED	720.00	720.00
1	REAR DOOR GLASS RH	CUT	410.00	410.00
1	REAR DOOR GARNISH LH	CUT	189.00	189.00
2	REAR DOOR GLASS FILM @ \$208.00	NECESSARY	416.00	416.00
2	REAR NUMBER PLATE LAMP @ \$98.00	NOT NECESSARY	196.00	-
1	REAR DOOR INNER TRIM LH	NOT NECESSARY	381.00	-
1	REAR DOOR WIPER MOTOR	BENT	518.00	518.00
1	REAR DOOR WIPER ARM	CUT	140.00	140.00
1	REAR DOOR WIPER ARM COVER	CUT	60.00	60.00
2	REAR DOOR HINGE @ \$120.00	NOT NECESSARY	240.00	-
1	REAR DOOR CHECKER LH	NOT NECESSARY	189.70	-
1	REAR DOOR WEATHERSTRIP (INNER)	CUT	221.00	221.00
1	REAR DOOR WEATHERSTRIP (CENTER)	CUT	163.00	163.00
2	REAR DOOR LOWER LOCK @ \$99.90	NOT NECESSARY	199.80	-
2	REAR DOOR TOP LOCK @ \$128.00	N/S NOT NECESSARY / O/S BENT	256.00	128.00
1	REAR BUMPER	DEFORMED	480.80	480.80
2	REAR BUMPER REFLECTOR @ \$41.60	N/S NOT NECESSARY / O/S CUT	83.20	41.60
2	REAR BUMPER SIDE RETAINER @ \$35.20	NECESSARY	70.40	70.40
1	REAR BUMPER SPONGE	DEFORMED	160.00	160.00
1	REAR TOWING HOOK	DENTED	154.00	154.00
1	REAR TOWING HOOK COVER	CUT	54.00	54.00
2	TAIL LAMP @ \$630.00	N/S CUT / O/S NOT NECESSARY	1,260.00	630.00

Report Ref No. CC4/LPC18017503/T1fa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL (OUTER)	BENT	652.00	652.00
1	REAR END PANEL (INNER)	TO REPAIR SEE LABOUR	610.00	-
1	REAR FLOOR PANEL TOP MAT	TORN	594.00	120.00
1	REAR END PANEL TOP GARNISH	DEFORMED	174.30	174.30
	LESS 10% DISCOUNT		-1,168.02	-859.01
			10,512.18	7,731.09
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00
1	SET TAILLAMP CLIP (SN)	NOT NECESSARY	40.00	-
2	REAR DOOR SEALANT @ \$80.00 (SN)	NECESSARY	160.00	80.00
1	SET REAR DOOR INNER TRIM CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR NUMBER PLATE LAMP GARNISH CLIP (SN)	NOT NECESSARY	26.00	-
2	REAR DOOR GLASS SEALANT @ \$80.00 (SN)	NECESSARY	160.00	80.00
1	REAR DOOR "70KM" STICKER (SN)	NECESSARY	30.00	30.00
1	REAR DOOR "PAX" STICKER (SN)	NECESSARY	30.00	30.00
2	REAR DOOR GLASS INNER SEAL @ \$60.00 (SN)	NECESSARY	120.00	80.00
1	SET REAR DOOR COMPANY LOGO (SN)	NECESSARY	920.00	300.00
1	REAR END PANEL (OUTER) SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR END PANEL (INNER) SEALANT (SN)	NOT NECESSARY	120.00	-
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	52.00	10.00
1	REAR DOOR WIPER BLADE (SN)	CUT	100.00	30.00
1	REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	REAR FLOOR WOODEN SHELVES (SN)	CRACKED	980.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	380.00	-
			3,613.00	1,140.00
	LABOUR			
	PANEL BEATING FOR CUTTING, KNOCKING, DISMANTLE, REFIT AND REPLACEMENT OF PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL (INNER).		1,800.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,500.00	800.00
	TO APPLY TUFF COATING.		250.00	40.00

Report Ref No. CC4/LPC18017503/T1fa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DISMANTLE AND REPLACEMENT REVERSE SENSOR, REVERSE CAMERA, DOOR GLASS, HEATER WIREHARNNESS PERFORM WIRING CHECK.		280.00	30.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.		350.00	50.00
	TRANSFER REAR DOOR MECHANISM LH AND RH.		160.00	100.00
	DISMANTLE AND REPLACEMENT REAR WOODEN SHELVES.		250.00	100.00
	INSTALL COMPANY STICKER.		200.00	100.00
	INSTALL REAR DOORS GLASS FILM.	NOT NECESSARY	180.00	-
	DISMANTLE AND REPLACEMENT REAR DOOR GLASS.		180.00	160.00
			5,150.00	2,180.00
GRAND TOTAL			19,275.18	11,051.09

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,750.00
---	--	--	-----------------

Report Ref No. CC4/LPC18017503/T1fa3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.