

# SINAI AUTOMOTIVE PTE.LTD.

ROC NO:201830476Z

1 SOON LEE STREET #04-44/45

PIONEER CENTRE, SINGAPORE [627605]

Tel: 62624438 Fax:69289896

TO INSURANCE CO	: LONPAC INSURANCE BHD	DATE	21-Sep-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	TP CLAIMS
ESTIMATE REPORT	:		
<b>OWNER'S PARTICULAR</b>		<b>VEHICLE DETAILS</b>	
NAME	: FIRETECH SERVICES PTE LTD	VEHICLE NO	: GBG730R
ADDRESS	: 50 BUKIT BATOK STREET 23 #07-03 MIDVIEW BUILDING S(659578)	MODEL	: NISSAN NV200
TEL. NO.	:	CHASSIS NO	: VSKYBAM20Z0140629
OWNER'S INSURANCE	: NTUC Income	REGISTRATION DATE	: 27/5/2017
POLICY NO.	: 5091278335-01	MARKET VALUE	: \$54,800
ACCIDENT DETAILS	:	COE REBATE AMOUNT	: \$26,561
DATE/TIME	: 21/9/2018 / 8:05AM	LIMIT REPAIR	: \$28,239

## QUOTATION SUMMARY

### CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR DOOR LH	1	\$ 1,415.00	\$ 1,415.00	bt
2	REAR DOOR RH	1	\$ 1,225.00	\$ 1,225.00	bt
3	REAR DOOR "LOGO"	1	\$ 89.00	\$ 89.00	nei
4	REAR DOOR "NISSAN NV200"	1	\$ 78.00	\$ 78.00	nei
5	REAR DOOR GLASS DEFROSTER WIREHARNES	1	\$ 281.00	\$ 281.00	cut
6	REAR DOOR GLASS LH	1	\$ 720.00	\$ 720.00	cut
7	REAR DOOR GLASS RH	1	\$ 410.00	\$ 410.00	cut
8	REAR DOOR GARNISH LH	1	\$ 189.00	\$ 189.00	cut
9	REAR DOOR GLASS FILM	2	\$ 208.00	\$ 416.00	nei
10	REAR NUMBER PLATE LAMP	2	\$ 98.00	\$ 196.00	X
11	REAR DOOR INNER TRIM LH	1	\$ 381.00	\$ 381.00	X
12	REAR DOOR WIPER MOTOR	1	\$ 518.00	\$ 518.00	X
13	REAR DOOR WIPER ARM	1	\$ 140.00	\$ 140.00	cut
14	REAR DOOR WIPER ARM COVER	1	\$ 60.00	\$ 60.00	lat
15	REAR DOOR HINGE	2	\$ 120.00	\$ 240.00	X
16	REAR DOOR CHECKER LH	1	\$ 189.70	\$ 189.70	X
17	REAR DOOR WEATHERSTRIP (INNER)	1	\$ 221.00	\$ 221.00	cut
18	REAR DOOR WEATHERSTRIP (CENTER)	1	\$ 163.00	\$ 163.00	cut
19	REAR DOOR LOWER LOCK	2	\$ 99.90	\$ 199.80	X
20	REAR DOOR TOP LOCK	2	\$ 128.00	\$ 256.00	LH-X, RH-b,
22	REAR BUMPER	1	\$ 480.80	\$ 480.80	de
23	REAR BUMPER REFLECTOR	2	\$ 41.60	\$ 83.20	LH-X, RH.
24	REAR BUMPER SIDE RETAINER	2	\$ 35.20	\$ 70.40	nei
25	REAR BUMPER SPONGE	1	\$ 160.00	\$ 160.00	de

27	REAR TOWING HOOK	1	\$ 154.00	\$ 154.00	dd
27	REAR TOWING HOOK COVER	1	\$ 54.00	\$ 54.00	art
29	TAIL LAMP	2	\$ 630.00	\$ 1,260.00	24-ut, R4)
30	REAR END PANEL (OUTER)	1	\$ 652.00	\$ 652.00	bt
31	REAR END PANEL (INNER)	1	\$ 610.00	\$ 610.00	Rx
32	REAR FLOOR PANEL TOP MAT	1	\$ 594.00	\$ 120 594.00	*tn
33	REAR END PANEL TOP GARNISH	1	\$ 174.30	\$ 174.30	de
TOTAL PRICE				\$ 11,680.20	
LESS 10%				\$ 1,168.02	
SUB TOTAL PRICE				\$ 10,512.18	

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP SET	1	\$ 65.00	\$ 65.00	30 one
2	TAILLAMP CLIP SET	1	\$ 40.00	\$ 40.00	X
3	REAR DOOR SEALANT	2	\$ 80.00	\$ 160.00	nr - 80.
4	REAR DOOR INNER TRIM CLIP SET	1	\$ 60.00	\$ 60.00	30 one
5	REAR NUMBER PLATE LAMP GARNISH CLIP SET	1	\$ 26.00	\$ 26.00	X
6	REAR DOOR GLASS SEALANT	2	\$ 80.00	\$ 160.00	80 one
7	REAR DOOR "70KM" STICKER	1	\$ 30.00	\$ 30.00	nr
8	REAR DOOR "Pax" STICKER	1	\$ 30.00	\$ 30.00	nr
9	REAR DOOR GLASS INNER SEAL	2	\$ 60.00	\$ 120.00	80 one
10	REAR DOOR COMPANY LOGO (SET)	1	\$ 920.00	\$ 920.00	300 one
11	REAR END PANEL (OUTER) SEALANT	1	\$ 120.00	\$ 120.00	40 one
12	REAR END PANEL (INNER) SEALANT	1	\$ 120.00	\$ 120.00	X
13	REAR END PANEL TOP GARNISH CLIP SET	1	\$ 52.00	\$ 52.00	10 one
14	REAR DOOR WIPER PLATE blade -	1	\$ 100.00	\$ 100.00	30 one
15	REVERSE SENSOR	1	\$ 250.00	\$ 250.00	200 one
16	REAR FLOOR WOODEN SHELVES	1	\$ 980.00	\$ 980.00	200 one
17	REVERSE CAMERA	1	\$ 380.00	\$ 380.00	X
NETT TOTAL				\$ 3,233.00	

**LABOURR CHARGE DETAILS**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PENEL BEATING FOR CUTING ,KUOCKING ,DISMANTLE ,REFIT AND REPLACEMENT OF PARTS.	\$ 1,800.00		800
2	SPRAY PAINTING TO AFFECTED AREA.	\$ 1,500.00		800
3	TO APPLY TUFF COATING.	\$ 250.00		40.
4	DISMANTLE AND REPLACEMENT REVERSE SENSOR ,REVERSE CAMERA,DOOR GLASS HEATER WIREHARNNESS PERFORM WIRING CHECK.	\$ 280.00		30.
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR.	\$ 350.00		50.
6	TRANFER REAR DOOR MECHANISM LH AND RH.	\$ 160.00		100
7	DISMANTLE AND REPLACEMENT REAR WOODEN SHELVES	\$ 250.00		100
8	INSTALL COMPANY STICKER	\$ 200.00		100.
9	INSTALL REAR DOORS GLASS FILM	\$ 180.00		
10	DISMANTLE AND REPLACEMENT REAR DOOR GLASS	\$ 180.00		160
<b>TOTAL</b>		<b>\$ 5,150.00</b>		

TOTAL PARTS COST	:	\$	13,745.18
TOTAL LABOUR COST	:	\$	5,150.00
TOTAL REPAIR COST	:	\$	18,895.18

**APPROVED DETAILS**

NO. OF WORKING DAYS :  
 RE-SURVEY :  
 LUMP SUM OR PART BY PART :  
 DATE & TIME OF SURVEY :  
 SURVEYED BY :  
 CONTACT NUMBER :  
 EMAIL & FAX NUMBER :

Tanjah 97495744  
 'wp'  
 26/9/18 @ 1520.  
 Resurvey After repair  
 sur e (kanto) on  
 6 days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: