

INS. CASE OWNER:

CC 3 / ASM 180 17 508 , KKA352

LKK:

IDAC:

77091

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FCL



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 16/09/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Admitted) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

Loss of Use (LOU):

SS

Loss of Income (LOI):

SS

LOR only

LOU only

LOR + LOU

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS

Global Sum SS: 5800.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Not Paid/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

GIA

ASS. REC. BY:

REF:

AA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 8836R

Yr Regn:

08, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kiax Latitude c.c.

1995

Colour:

n. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1 ABL 15/AUG 273342

Gen. Cond: Goody Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Giti

215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

16/9/18

D.O.I.

25/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/9 File pass to Catherine
11pm @ 4950h

(Rec'd 37344.61/8872)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9836R*Not Authorised
11 Aug 2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9836R

VF1ABL15AUC273342

RENAULT

LATITUDE

17.9.2018

AXA**PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

- | | | | |
|----|---------------|----------|---|
| \$ | <i>Buclem</i> | 1,108.46 | ✓ |
| \$ | <i>SL</i> | 768.84 | X |
| \$ | <i>SL</i> | 113.47 | X |
| \$ | <i>SL</i> | 135.97 | ✓ |
| \$ | <i>SL</i> | 44.99 | X |
| \$ | <i>SL</i> | 43.61 | X |
| \$ | <i>SL</i> | 135.97 | X |
| \$ | <i>SL</i> | 44.99 | X |
| \$ | <i>SL</i> | 43.61 | X |
| \$ | <i>SL</i> | 777.52 | X |
| \$ | <i>SL</i> | 225.95 | X |
| \$ | <i>SL</i> | 225.95 | X |
| \$ | <i>SL</i> | 2,872.68 | } |
| \$ | <i>SL</i> | 470.06 | |
| \$ | <i>SL</i> | 323.05 | |
| \$ | <i>SL</i> | 493.35 | |
| \$ | <i>SL</i> | 493.35 | |
| \$ | <i>SL</i> | 225.36 | |
| \$ | <i>SL</i> | 225.36 | |
| \$ | <i>SL</i> | 276.08 | |
| \$ | <i>SL</i> | 276.08 | |
| \$ | <i>SL</i> | 367.84 | |
| \$ | <i>SL</i> | 367.84 | |
| \$ | <i>SL</i> | 586.45 | |
| \$ | <i>SL</i> | 168.13 | |
| \$ | <i>SL</i> | 202.67 | |
| \$ | <i>SL</i> | 74.40 | |
| \$ | <i>SL</i> | 50.52 | |
| \$ | <i>SL</i> | 221.81 | |

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9836R

30	1 DOOR PANEL REAR RH	\$	R	2,844.66	X
30	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	X
30	1 FENDER PANEL REAR RH	\$	R	3,299.13	✓
31	1 WHEELARCH REAR RH	\$	Sm	543.47	X
32	1 TAILLAMP RH	\$	CM	552.55	✓
33	1 TAILLAMP PANEL RH	\$	R	986.70	} X
34	1 TAILLAMP LH	\$	Sm	552.55	
35	1 TAILLAMP PANEL LH	\$	R	986.70	
36	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
37	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm	404.56	
38	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
39	1 SPARE WHEEL PANEL TRIM	\$	Sm	612.21	
40	1 EXHAUST REAR	\$	R	7,489.05	} X
41	1 EXHAUST CAP REAR	\$	R	230.49	

TOTAL	\$	34,199.54
10%	\$	3,419.95
	\$	30,779.59

Special Nett

1	1SET PARKING AID	\$	Sm	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	} X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	
10	1 EXHAUST MOUNTING REAR	\$	Sm	17.82	
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	} X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9836R

19	1 TAILLAMP CLIP RH	\$	<i>na</i> 5.00	—
20	1 TAILLAMP CLIP LH	\$	<i>na</i> 5.00	X
21	2 REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00	<i>4000</i>
22	1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00	—
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	<i>3000</i>
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i> 385.00	X
25	1 SPARE TYRE	\$	<i>sn</i> 330.00	X

TOTAL \$ 2,225.02**TOTAL PARTS \$ 33,004.61****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,750.00	<i>4401</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,200.00	<i>6001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9836R

To supply and re-do rear luggage floor panel insulation padding.

\$ *nn* 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ 380.00 *100%*

To transfer of rear windscreen fittings and conduct water seepage test.

\$ 170.00 *120%*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

TOTAL \$ 9,290.00 *4670*

Over All Total \$ 42,294.61

42674.60

(LUMP SUM)

Repair Days

15 days

4 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHB9836R

Vehicle to be Exported: Yes

Intended Deregistration Date: 25 Sep 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2013

Engine No.: M9R8839C000390

Chassis No.: VF1ABL15AUC273342

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 20 Aug 2013

First Registration Date: 20 Aug 2013

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Aug 2021

PARF Rebate Amount: \$8,748.00

Intended COE Rebate Details

COE Expiry Date: 19 Aug 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$54,952.00

COE Rebate Amount: \$19,923.00

Total Rebate Amount: \$28,671.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Sep 2018

OK

Hsiao Tong (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 28 August 2019 2:56 PM
To: Poh Kin (LKKAUTO)
Subject: TCS REF: AAD1809-240--Accident involving SLS9756B (AXA) & SHB9836R on 16.09.18
Attachments: AAD1809-240 - VEH REPAIR IN WORKSHOP.pdf

WITHOUT PREJUDICE

Dear Poh Kin

Refer to our tele-conversation.

Please see the attachment for the correct timing of vehicle repair in our workshop.

The correct timing should be 16/09/18 to 28/09/18.

Original hard copy will pass to Kenneth's to bring back your office.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



<TP - Mandate IA> - S8M00VPY [ACCIDENT INVOLVING SLS 9756B(OI) / SHB 9836R (TP) / OTHERS ON 16/09/2018]

Type

🔔 Question

Message

Liability: 100%. Insured driver swerved to right lane, hit by a lorry(XD7130G), the impact caused him to hit onto third party who was on his left. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$5,837.79(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 31-Aug-19

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/8/2019

Survey Details:

Date of loss	16-Sep-18
Date of appointment	25-Sep-18
Date of survey	25-Sep-18
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SHB 9836R
Make and Model	RENAULT LATITUDE 2.0L DCI - 1995cc
Date of registration	20-Aug-13
Excess	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	\$ 42,294.61
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 4,860.50
Check items (estimate)	\$ -
Labour	\$ 1,350.00
Total	\$ 6,210.50
Lump Sum(if applicable)	\$ 4,950.00

Number of days for repair	<u>4 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/GST)	\$	5,296.50	
Loss of use		NIL	no. of days
Loss of rental	\$	333.84	(4days x\$83.46)
Loss of income	\$	200.00	(4days x \$50.00)
LTA search fees	\$	7.45	
Others		NIL	
Proposed Total	\$	5,837.79	

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 2 September 2019 1:28 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 72091, vehicle number SHB9836R

1/9/19 8:50 PM *** pls proceed - NG Stacey

-----Original Message-----

From: stacey.ng@axa.com.sg <stacey.ng@axa.com.sg>
Sent: Sunday, 1 September, 2019 8:51 PM
To: admin-d@lkkauto.com
Subject: New message for service request 72091, vehicle number SHB9836R

AXA Insurance has sent you a message for claim number S8M00VPY.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Tuesday, 10 September 2019 7:48 PM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'
Cc: 'claims'
Subject: RE: TCS REF: AAD1809-240--Accident involving SLS9756B (AXA) & SHB9836R on 16.09.18 //LKK REF: CC3/ASM18017508/Kpa3

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Friday, 6 September 2019 8:32 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: RE: TCS REF: AAD1809-240--Accident involving SLS9756B (AXA) & SHB9836R on 16.09.18 //LKK REF: CC3/ASM18017508/Kpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of **\$5,800.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Wednesday, 28 August 2019 2:56 PM

To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Subject: TCS REF: AAD1809-240--Accident involving SLS9756B (AXA) & SHB9836R on 16.09.18

WITHOUT PREJUDICE

Dear Poh Kin

Refer to our tele-conversation.

Please see the attachment for the correct timing of vehicle repair in our workshop.

The correct timing should be 16/09/18 to 28/09/18.

Original hard copy will pass to Kenneth's to bring back your office.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1809-240

Your Ref : SLS9756B

Date : 21. February 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHB9836R AND SLS9756B ON 16/09/18 05:15 PM ALONG UPPER BUKIT TIMAH ROAD TOWARDS CLEMENTI ROAD

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	5,296.50
2.	Loss of Rental for <u>4</u> days @ \$ <u>83.46</u> per day	\$	333.84
3.	Loss of Income for <u>4</u> days @ \$ <u>50</u> per day	\$	200.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	5,837.83

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver
 Certificate of Insurance
 Original final repair bill

Rental rate and mileage records
 Authorization To Act
 LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM18017508/Kpa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 01-10-2019



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 9756B	Veh. Inspected	SHB 9836R
Policy No.	VCX/P2005541	Coverage (\$)	0.00
Claim No.	S8M00VPY	Excess (\$)	0.00
Assign From		Assign Date	25/09/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273342	Colour	METALLIC WHITE / RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	6 mm
L/H Front Tyre	215/60 R16	GITI	6 mm
R/H Rear Tyre	215/60 R16	FALKEN	7 mm
L/H Rear Tyre	215/60 R16	FALKEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/09/2018	Inspection Date	25/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9836R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED / CRACKED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	DISTORTED	135.97	135.97
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR (CONSISTENT)	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR (CONSISTENT)	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER (CONSISTENT)	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT' (CONSISTENT)	NOT NECESSARY	225.36	-
1	BOOT BADGE (CONSISTENT)	NOT NECESSARY	225.36	-
1	BOOT STRUT LH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT STRUT RH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM (CONSISTENT)	SERVICEABLE	586.45	-
1	BOOT SWITCH (CONSISTENT)	SERVICEABLE	168.13	-
1	BOOT LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CC3/ASM18017508/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP (CONSISTENT)	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG (CONSISTENT)	SERVICEABLE	221.81	-
1	DOOR PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH (CONSISTENT)	BENT	3,299.13	3,299.13
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	TAILLAMP RH (CONSISTENT)	CRACKED	552.55	552.55
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM (CONSISTENT)	SERVICEABLE	612.21	-
1	EXHAUST REAR (CONSISTENT)	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR (CONSISTENT)	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,419.95	-509.61
			30,779.58	4,586.50
SPECIAL NETT ITEMS				
1	SET PARKING AID (SN) (CONSISTENT)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-

Report Ref No. CC3/ASM18017508/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN) (CONSISTENT)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN) (CONSISTENT)	NECESSARY	5.00	5.00
1	TAILLAMP CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NECESSARY	100.00	30.00
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
			2,225.02	274.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,750.00	440.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, DOOR PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		3,200.00	600.00

Report Ref No. CC3/ASM18017508/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGAGGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	100.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			9,670.00	1,350.00
GRAND TOTAL			42,674.60	6,210.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,950.00

Report Ref No. CC3/ASM18017508/Kpa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.