

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9836R

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Not Auth oriz
*11 Aug 849501***SHB 9836R**

VF1ABL15AUC273342

RENAULT

LATITUDE

17.9.2018

AXA**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Buclem</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>SL</i> 768.84 X
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 ✓
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SL</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>SL</i> 777.52 X
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>SL</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>SL</i> 225.95 X
13	1 BOOT REAR	\$	<i>SL</i> 2,872.68 }
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06 }
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05 }
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35 }
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35 }
18	1 BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36 }
19	1 BOOT BADGE	\$	<i>SL</i> 225.36 }
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08 }
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08 }
22	1 BOOT HINGE LH	\$	<i>SL</i> 367.84 }
23	1 BOOT HINGE RH	\$	<i>SL</i> 367.84 }
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45 }
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13 }
26	1 BOOT LOCK	\$	<i>SL</i> 202.67 }
27	1 BOOT LOCK CATCH	\$	<i>SL</i> 74.40 }
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52 }
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81 }

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9836R

30	1 DOOR PANEL REAR RH	\$	R	2,844.66	X
30	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	X
30	1 FENDER PANEL REAR RH	\$	R	3,299.13	✓
31	1 WHEELARCH REAR RH	\$	Sm	543.47	X
32	1 TAILLAMP RH	\$	CM	552.55	✓
33	1 TAILLAMP PANEL RH	\$	R	986.70	} X
34	1 TAILLAMP LH	\$	Sm	552.55	
35	1 TAILLAMP PANEL LH	\$	R	986.70	
36	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
37	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm	404.56	
38	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
39	1 SPARE WHEEL PANEL TRIM	\$	Sm	612.21	} X
40	1 EXHAUST REAR	\$	R	7,489.05	
41	1 EXHAUST CAP REAR	\$	R	230.49	

TOTAL	\$	34,199.54
10%	\$	3,419.95
	\$	30,779.59

Special Nett

1	1SET PARKING AID	\$	Sm	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	} X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	
10	1 EXHAUST MOUNTING REAR	\$	Sm	17.82	
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	} X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9836R

19	1 TAILLAMP CLIP RH	\$	na	5.00	—
20	1 TAILLAMP CLIP LH	\$	na	5.00	X
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	80.00
22	1 WINDSCREEN MOULDING	\$	na	100.00	—
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	30.00
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	X
25	1 SPARE TYRE	\$	sn	330.00	X

TOTAL \$ 2,225.02**TOTAL PARTS \$ 33,004.61****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,750.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,200.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9836R

To supply and re-do rear luggage floor panel insulation padding.

\$ *nn* 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ 380.00 *100%*

To transfer of rear windscreen fittings and conduct water seepage test.

\$ 170.00 *120%*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

TOTAL \$ 9,290.00

Over All Total \$ 42,294.61

(LUMP SUM)

Repair Days

15 days

& day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: