

INS. CASE OWNER:

CC3, Asm 180 17509, PHA34

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Pre-assign / CCU / FTE

Registered in Merimen:



Insured Vehicle No.:

SDV 8886 U

Claim No.:

Sgm 00000000

Name of Insured:

Ang Geok Lan Landy

Policy No.:

GA056815/1

Insured Tel No.:

HP:

Make / Model:

M-BENZ 180

Excess Sec II :SS

D.O.A.:

21/09/18 (sat)

Place of Accident:

Junct. of Telok Blangah Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lim Chin Tong

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

96818866

(V/L: YES / NO)

Insured Liability: %

Final? Yes / No

SHE 5316 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans. Cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: P-MOAT ONLY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

26/9

Sent By:

Hm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

3/9/19

Confirm with:

Jasmine

Email:

Call:

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 9(a).

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

14124.00

(OI TURNING TO ENTER INTO M/ROAD)

Loss of Rental (LOR):

S\$

1191.84 (12 days) x 99.32

Loss of Use (LOU):

S\$

600.00 (\$50 x 12 days)

Loss of Income (LOI):

S\$

600.00 (\$50 x 12 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

S\$

7.45

Medical:

S\$

Disbursement:

S\$

Legal Cost:

S\$

(e.g. Tow/ Independent)

Total:

S\$

15923.29 Global Sum S\$: 159W.W

1) Claim status: No Claim/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$

159W.W

Name 1:

Trans-Cab Auto Services Pte Ltd

Guarantee

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY:

REF:

A41

-Kennerh

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S14C 5316X Yr Regn: 03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Peugeot c.c. 1895Colour: M. White / Red AC: Insured / Std / NI / NASp. Reading: 541820 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL15AUC 276838Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil S/Rim / STD A/Rim orTyre Size: King Long 215/60R16R: GitiBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 22/9/18

Survey held at

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 25/9/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Old body & N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/9 File pass to Carhenn

US\$ 13200 credit 350764 7371

LAF 42m w/hs.

10 + 2 sum + 1 PRS = 13

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees:

Others:

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5316X**AAD1809-225***Not Authorized*
61 Pmg &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5316X

VF1ABL15AUC276838

RENAULT

LATITUDE

22.9.2018

AXA

PART		LIST	
1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT LH	\$	151.41
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER RETAINER FRT RH	\$	150.77
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	FENDER PANEL FRT LH	\$	783.83
1	WHEELARCH FRT LH	\$	278.84
1	FENDER BRACKET LOWER LH	\$	15.79
1	FENDER INSULATOR LH	\$	130.84
1	DOOR PANEL FRT RH	\$	2,844.66
1	DOOR HINGE UPPER RH	\$	261.28
1	DOOR HINGE LOWER RH	\$	300.55
1	DOOR CHECK FRT RH	\$	194.77
1	DOOR LOCK FRT RH	\$	908.75
1	DOOR CATCH FRT RH	\$	131.23
1	DOOR HANDLE OUTER FRT LH RH	\$	477.76
1	DOOR HANDLE COVER FRT LH	\$	13.22
1	DOOR HANDLE MODULE FRT LH	\$	133.60
1	DOOR REGULATOR FRT LH	\$	505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97
1	DOOR PANEL REAR RH	\$	2,844.66
1	DOOR GUIDE REAR RH	\$	176.82

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5316X**LKK Auto Consult** for Repairs only

the Repairer of the following:

- To resurvey before/after repair
- To display damaged parts and repair
- Parts prices are subject to confirmation
- Third party survey is on a "best and final" basis
- No illegal modifications allowed
- Supplemental claim will be considered and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

AAD1809-225

1	DOOR HINGE UPPER <i>LH RH</i>	\$	<i>R</i>	274.50
1	DOOR HINGE LOWER LH	\$	<i>R</i>	300.55
1	DOOR CHECK REAR LH	\$	<i>R</i>	203.06
1	DOOR LOCK REAR LH	\$	<i>R</i>	908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i>	126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i>	35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i>	7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i>	13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i>	133.60
1	DOOR REGULATOR REAR LH	\$	<i>Sn</i>	1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Sn</i>	893.75
1	DOOR REGULATOR NUT REAR LH	\$	<i>Sn</i>	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i>	6.31
1	DOOR FINISHER REAR LH	\$	<i>Sn</i>	423.10
1	DOOR MOULDING REAR LH	\$	<i>Sn</i>	176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>Sn</i>	5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>Sn</i>	6.91
1	DOOR CASING REAR LH	\$	<i>Sn</i>	1,509.06
1	DOOR WATER SHIELD REAR LH	\$	<i>Sn</i>	30.39
1	DOOR CASING CLIP	\$	<i>Sn</i>	12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Sn</i>	48.74
1	DOOR FINISHER INNER REAR LH	\$	<i>Sn</i>	323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i>	46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i>	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i>	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i>	20.33
1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i>	210.96
1	DOOR BLIND REAR LH	\$	<i>Sn</i>	741.80
1	DOOR WHEATHESTRIIP REAR LH	\$	<i>Sn</i>	410.66
1	DOOR SEAL REAR LH	\$	<i>Sn</i>	162.02
1	DOOR GLASS RUNNER SEAL REAR LH	\$	<i>Sn</i>	229.31
1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>Sn</i>	334.69
1	DOOR WAIST SEAL INNER REAR LH	\$	<i>Sn</i>	115.64
1	FENDER PANEL REAR <i>LH RH</i>	\$	<i>R</i>	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i>	671.45
1	WHEELARCH REAR LH	\$	<i>Sn</i>	543.47
1	DOOR MIRROR ASSY LH	\$	<i>Sn</i>	1,483.40
1	ROCKER PANEL INNER GARNISH LH	\$	<i>Sn</i>	466.51

X

✓

X

X

X

X

Trans-cab Auto Services Pte Ltd

AAD1809-225

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5316X

1	ROCKER PANEL INNER LH	\$	n 1,024.79	X
1	ROCKER PANEL CENTER LH	\$	As 990.25	✓
1	BUMPER COVER REAR	\$	As 1,108.46	✓
1	BUMPER LOWER REAR	\$	As 768.84	✓
1	BUMPER BRACKET CTR REAR	\$	Sn 113.47	X
1	BUMEP R BRACKET SIDE LH REAR	\$	Sn 135.97	X
1	BUMEP R RETAINER LH REAR	\$	Sn 44.99	X
1	AIR CLEANER BOX	\$	Sn 464.20	X
1	AIR CLEANER HOSE	\$	Sn 175.85	X
1	LOWER ARM LH L70Y	\$	nm 685.76	X
1	KUNCKLE ARM LH L70Y	\$	nm 846.98	X
1	ABSORBER FRT LH L70Y	\$	nm 360.54	X

\$	37,458.44
----	-----------

10% \$	3,745.84
--------	----------

\$	33,712.60
----	-----------

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na 30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na 80.00	60na
1	FRONT DOOR STICKER 'Chassis'	\$	na 50.00	15na
1	REAR DOOR STICKER '6555 3333'	\$	na 80.00	60na
1	DOOR CHECK BOLT	\$	Sn 22.69	} X
1	DOOR GUIDE SCREW	\$	Sn 10.85	
1	DOOR HINGE BOLT	\$	Sn 10.85	
1	DOOR HINGE NUT RH	\$	Sn 14.60	
1	DOOR CHECK BOLT	\$	Sn 22.69	
1	DOOR CHECK NUT	\$	Sn 3.75	
1	DOOR LOCK SCREW L70Y	\$	Sn 6.12	
1	DOOR CATCH SCREW L70Y	\$	Sn 10.06	
1SET	RADIATOR GRILLE FRAME CLIP	\$	na 52.00	
1SET	BUMPER CLIP FRT	\$	na 66.00	
1	BUMPER BRACKET CLIP FRT LH	\$	na 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na 10.50	

Trans-cab Auto Services Pte Ltd

AAD1809-225

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5316X

1	BUMPER BRACKET CLIP FRT RH	\$	na 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	na 10.50 X
1	TOW COVER FRT	\$	Sm 14.50 X
1SET	RADAIOR GRILLE SCREW	\$	na 16.00 X
1SET	BUMPER GRILLE LOWER CLIP	\$	na 69.00 X
1	FRONT LEFT TYRE	\$	54330.00 X
1	FRONT LEFT TYRE RIM	\$	By 380.00 ✓

TOTAL	\$	1,434.63
--------------	-----------	-----------------

TOTAL PARTS	\$	33,781.60
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00 1400
Putty and spray painting of the affected portion.	\$	5,000.00 1760
To rust-proofing of the affected areas.	\$	170.00 120
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 100
To check steering geometry and computer wheel alignment	\$	220.00 60
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na 380.00 X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	na 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 40
To Check Electrical Lighting Concerned.	\$	170.00 30

Trans-cab Auto Services Pte Ltd

AAD1809-225

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5316X

To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	601
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X

TOTAL	\$	14,770.00
--------------	-----------	------------------

Over All Total	\$	48,551.60
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~20 DAYS~~

10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5316X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000976
Chassis No.:	VF1ABL15AUC276838
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00 ✓
Original Registration Date:	21 Mar 2014
First Registration Date:	21 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00 ✓

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	20 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00 ✓
COE Rebate Amount:	\$25,571.00
Total Rebate Amount:	\$34,944.00 ✓

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Sep 2018

OK

TP Veh	SHC5316X
Date of Reg	21.03.2014
DOA	22.09.2018
COE Expiry Date	20.03.2022

\$

(I) Estimated Book Value

Unit Cost	39,000.00
Import Duty	3,999.60
Registration Fee	140.00
PQP Paid	58,745.00
ARF Paid	12,498.00
Estimated Per Taxi Purchase Price	114,382.60
Estimated Per Taxi Purchase Price	114,382.60
Less 60% of ARF Paid	7,498.80
Estimated Full Lifespan Depreciation	106,883.80
Estimated Full Lifespan Depreciation	106,883.80
Times Balance Life (42/96 months)	46,761.66
	46,761.66
Add 60% of ARF Paid	7,498.80
Estimated Book Value	54,260.46

(II) Adjusted LTA Rebate

PARF Rebate	
PQP Paid	
Times Balance Life (69/96 months)	
Adjusted COE Rebate	
PARF Rebate	
Add Adjusted COE Rebate	
Adjusted LTA Rebate	34,944.00

(Summary) Estimated Nett Value

Estimated Book Value	54,260.46
Less Adjusted LTA Rebate	34,944.00
Estimated Net Value	19,316.46

Hsiao Tong (LKKAUTO)

From: claims <claims@transcab.com.sg>
Sent: Tuesday, 13 August 2019 8:53 AM
To: Hsiao Tong (LKKAUTO)
Cc: jasminetan@transcab.com.sg; 'Ng Wai Yin'; claims@transcab.com.sg
Subject: RE: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHC5316X(DOA: 22/09/2018). - AAD1809-225 //LKK REF: CC3/ASM18017509/Kpa3
Attachments: IMG_4875.JPG; IMG_4877.JPG; IMG_4878.JPG; IMG_4880.JPG

Without Prejudice

Dear Hsiao Tong

Attached after repair photo for your perusal.

Thank You
Best Regards,
Calvin Er
Finance Department
TEL: 6603 1265 Ext.307

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 10 August, 2019 2:49 PM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Subject: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHC5316X(DOA: 22/09/2018). - AAD1809-225 //LKK REF: CC3/ASM18017509/Kpa3

Your ref: **AAD1809-225 (SHC5316X)**
Our ref: CC3/ASM18017509/Kpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We are seeking mandate approval from AXA.

Kindly advise if there is any after repair/ after paint photos for SHC5316X(DOA: 22/09/2018). If so, kindly let us have a copy of the photos.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com



<TP - Mandate IA> - S8M00WMP [ACCIDENT INVOLVING SDV 8886U(OI) & SHC 5316X(TP) ON 22/09/2018]

Type

🔗 Question

Message

Liability: 100%. Insured driver made right turn and collided with third party who was driving straight on the opposite direction. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$16,072.61(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 10 Aug 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 10/8/2019

Survey Details:

Date of loss	22-Sep-18
Date of appointment	25-Sep-18
Date of survey	25-Sep-18
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SHC 5316X
Make and Model	RENAULT LATITUDE 2.0L DCI - 1995cc
Date of registration	21-Mar-14
Excess	
Market Value/ Book Value	\$ 54,260.46 (est)
Part Rebate	\$ 34,944.00 (est)
Nett Loss	\$ 19,316.46 (est)

Repair details:

Initial Estimate	\$ 48,551.60
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 12,862.53
Check items (estimate)	NIL
Labour	\$ 3,630.00
Total	\$ 16,492.53
Lump Sum(if applicable)	\$ 13,200.00

Number of days for repair	10 days
---------------------------	---------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID made right turn and collided with third party who was driving straight on the opposite direction.

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 14,124.00	
Loss of use	NIL	no. of days
Loss of rental	\$ 1,291.16	(13days x \$99.32)
Loss of income	\$ 650.00	(13days x \$50.00)
LTA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 16,072.61	

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 13 August 2019 6:42 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 72112, vehicle number SHC5316X

13/8/19 5:36 PM *** Message Pls proceed with your proposed mandate. - KHOR Saw Theng

-----Original Message-----

From: sawtheng.khor@axa.com.sg [mailto:sawtheng.khor@axa.com.sg]
Sent: Tuesday, 13 August, 2019 5:36 PM
To: admin-d@lkkauto.com
Subject: New message for service request 72112, vehicle number SHC5316X

AXA Insurance has sent you a message for claim number S8M00WMP.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Wednesday, 28 August 2019 2:00 PM
To: Hsiao Tong (LKKAUTO); 'claims'
Cc: 'Ng Wai Yin'
Subject: RE: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHC5316X(DOA: 22/09/2018). - AAD1809-225 //LKK REF: CC3/ASM18017509/Kpa3

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Friday, 16 August 2019 4:10 PM
To: claims <claims@transcab.com.sg>
Cc: jasminetan@transcab.com.sg; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>
Subject: RE: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHC5316X(DOA: 22/09/2018). - AAD1809-225 //LKK REF: CC3/ASM18017509/Kpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of **\$15,900.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims <claims@transcab.com.sg>

Sent: Tuesday, 13 August 2019 8:53 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: jasminetan@transcab.com.sg; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg

Subject: RE: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHC5316X(DOA: 22/09/2018). - AAD1809-225 //LKK REF: CC3/ASM18017509/Kpa3

Without Prejudice

Dear Hsiao Tong

Attached after repair photo for your perusal.

Thank You
Best Regards,
Calvin Er
Finance Department
TEL: 6603 1265 Ext.307

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Saturday, 10 August, 2019 2:49 PM

To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg

Subject: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHC5316X(DOA: 22/09/2018). - AAD1809-225 //LKK REF: CC3/ASM18017509/Kpa3

Your ref: **AAD1809-225 (SHC5316X)**
Our ref: CC3/ASM18017509/Kpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We are seeking mandate approval from AXA.

Kindly advise if there is any after repair/ after paint photos for SHC5316X(DOA: 22/09/2018). If so, kindly let us have a copy of the photos.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1809-225

Your Ref : SDV8886U

Date : 24.January 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHC5316X AND SDV8886U ON 22/09/18 07:05 PM ALONG Bukit Chermin Road

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	14,124.00
2.	Loss of Rental for <u>14</u> days @ \$ <u>99.32</u> per day	\$	1,390.48
3.	Loss of Income for <u>14</u> days @ \$ <u>50</u> per day	\$	700.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	16,221.97

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 2 May 2019 1:09 PM
To: LANDY.PANCAKE@GMAIL.COM
Subject: ACCIDENT INVOLVING SDV8886U AND SHC5316X ALONG JCT OF TELOK BLANGAH RD TWDS BT. CHERMIN RD ON 22/09/2018

Dear Ms. **ONG GEOK LAN LANDY**,

OUR REF : CC3/ASM18017509/Kha3
YOUR REF : SDV8886U (DRIVER: LIM CHIN TONG)
ACCIDENT INVOLVING SDV8886U AND SHC5316X ALONG JCT OF TELOK BLANGAH RD TWDS BT. CHERMIN RD ON 22/09/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s **TRANS-CAB AUTO SERVICES PTE LTD**, acting on behalf of the owner of SHC5316X against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third Party vehicle SHC5316X. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to khanchna@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorization Letter for the Driver to drive the vehicle
- Driver's driving license or foreign driving license
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at khanchna@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act


We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHC5316X and SDV8886U along Bukit Chermin Road on 22/09/18 07:05 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 24 (day) of January 2019

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager



4901809-225

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SDV8886U	(Insd veh)	Model: RENAULT LATITUDE-2.0 L (A)
	SHC5316X	(TP veh)	
Date of Accident/ Time:	22/09/2018		

Repair Estimate	: \$	53,411.39	
Final Repair Cost	: \$		
Loss of Use	: \$		days at \$ per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$	15,900.00	

Payee Name : TRANS-CAB AUTO SERVICES PTE LTD.

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: <u>9 (A)</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative: NG WA YIN Workshop stamp: 
 Date: 05 SEP 2019
 Signature of Witness / Workshop stamp (if applicable): Wine Tay
 Name of Witness: Wine Tay
 Date: 05 SEP 2019

Signature of AXA's surveyor/representative: KSC
 Name of AXA's surveyor/representative: 6/9/19
 Date: 6/9/19

Trans-Cab Auto Services Pte Ltd

* No. 2 Ang Mo Kio Street 63. Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AXA INSURANCE PTE LTD 8 SHENTON WAY, #27-01 AXA TOWER 068811 SINGAPORE ATTENTION:	INVOICE NO. : INV1812-494 DATE : 31. December 2018 REFERENCE NO : AAD1809-225 TERMS : DUE DATE : 31. December 2018 PAGE : 1
--	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHC5316X;DOA 22.09.18(LUMP SUM-18)	1	14,124.00	14,124.00

Total SGD Excl. GST : 13,200.00

7% GST : 924.00

**** FOURTEEN THOUSAND ONE HUNDRED TWENTY FOUR SGD ONLY ****

Total SGD Incl. GST : 14,124.00

1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"

2) Please quote our Invoice Number during payment.

3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.

4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.

THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

24 January, 2019

To Whom It May Concern

Dear Sir / Madam,

Accident on 22/09/18 07:05 PM at Bukit Chermin Road

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHC5316X. The taxi was hired to MOHD KEMARUDIN BIN WAHID a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$99.32 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan

General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K


22-09-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.
Accident No.	AAD1809-225	Accident Date 22-09-2018
9/22/2018 19:05	10/5/2018 17:30	SHCS316X

Yours Faithfully,

Trans-Cab Services Pte Ltd**Jasmine Tan****General Manager**

[> Back to OneMotoring](#)**Vehicle Insurance Particulars Result**

Vehicle No.	Incident Date/Time	Insurance Company Name
SMC3477T	22 Sep 2018 / 15:38:00	LIBERTY INS P L
SDV8886U	22 Sep 2018 / 19:05:00	AXA INSURANCE PTE LTD
SKZ2476E	22 Sep 2018 / 03:15:00	AXA INSURANCE PTE LTD
SLG9154B	24 Sep 2018 / 13:20:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Print](#)[OK](#)[Save as PDF](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM18017509/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY NG

Date : 04-10-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDV 8886U	Veh. Inspected	SHC 5316X
Policy No.	GA056815/1	Coverage (\$)	0.00
Claim No.	S8M00WMP	Excess (\$)	0.00
Assign From		Assign Date	25/09/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC276838	Colour	METALLIC WHITE/RED
Odometer	541820	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	LING LONG	7 mm
L/H Front Tyre	215/60 R16	LING LONG	7 mm
R/H Rear Tyre	215/60 R16	GITI	7 mm
L/H Rear Tyre	215/60 R16	GITI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/09/2018	Inspection Date	25/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5316X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT (CONSISTENT)	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER SPOILER FRT (CONSISTENT)	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT (CONSISTENT)	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH (CONSISTENT)	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT (CONSISTENT)	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT (CONSISTENT)	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT (CONSISTENT)	TO REPAIR SEE LABOUR	914.08	-
1	FENDER PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	15.79	-
1	FENDER UNSULATOR LH (CONSISTENT)	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER RH (CONSISTENT)	BENT	261.28	261.28
1	DOOR HINGE LOWER RH (CONSISTENT)	BENT	300.55	300.55
1	DOOR CHECK FRT RH (CONSISTENT)	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH (CONSISTENT)	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT RH (CONSISTENT)	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH (CONSISTENT)	DISTORTED	505.19	505.19
1	DOOR REGULATOR MOTOR FRT RH (CONSISTENT)	JAMMED	796.46	796.46
1	DOOR REGULATOR GUIDE FRT RH (CONSISTENT)	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH (CONSISTENT)	BENT	2,844.66	2,844.66

Report Ref No. CC3/ASM18017509/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR GUIDE REAR RH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	203.06	-
1	DOOR LOCK REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR LH (CONSISTENT)	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH (CONSISTENT)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH (CONSISTENT)	SERVICEABLE	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH (CONSISTENT)	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR LH (CONSISTENT)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	NOT NECESSARY	6.91	-
1	DOOR CASING REAR LH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH (CONSISTENT)	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-

Report Ref No. CC3/ASM18017509/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR GRAB HANDLE REAR LH (CONSISTENT)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUBBER SEAL REAR LH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR LH (CONSISTENT)	SERVICEABLE	115.64	-
1	FENDER PANEL REAR RH (CONSISTENT)	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR (CONSISTENT)	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	DOOR MIRROR ASSY LH (CONSISTENT)	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH LH (CONSISTENT)	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER LH (CONSISTENT)	BENT	990.25	990.25
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	AIR CLEANER BOX (CONSISTENT)	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE (CONSISTENT)	SERVICEABLE	175.85	-
1	LOWER ARM LH L70Y (CONSISTENT)	NOT NECESSARY	685.76	-
1	KNUCKLE ARM LH L70Y (CONSISTENT)	NOT NECESSARY	846.98	-
1	ABSORBER FRT LH L70Y (CONSISTENT)	NOT NECESSARY	360.54	-
1	BUMPER RETAINER FRT RH (CONSISTENT)	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
	LESS 10% DISCOUNT		-3,745.84	-1,371.95
			33,712.58	12,347.53
	SPECIAL NETT ITEMS			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT(SN) (CONSISTENT)	NOT NECESSARY	20.00	-

Report Ref No. CC3/ASM18017509/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CHASSIS' (SN) (CONSISTENT)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER '6555 3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN) (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT RH (SN) (CONSISTENT)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT)	SERVICEABLE	10.06	-
1	SET RADIATOR GRILLE FRAME CLIP (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN) (CONSISTENT)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN) (CONSISTENT)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN) (CONSISTENT)	NOT NECESSARY	69.00	-
1	FRONT LEFT TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	FRONT LEFT TYRE RIM (SN) (CONSISTENT)	BENT	380.00	380.00
			1,434.61	515.00

Report Ref No. CC3/ASM18017509/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT,BUMPER BEAM FRT,FENDER PANEL FRT LH,FENDER BRACKET LOWER LH,DOOR LOCK FRT RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER LH,DOOR CHECK REAR LH,DOOR LOCK REAR LH,DOOR FINISHER BRACKET INNER REAR LH AND ROCKER PANEL INNER LH.		6,000.00	1,400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,000.00	1,760.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.		170.00	40.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-

Report Ref No. CC3/ASM18017509/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			14,770.00	3,630.00
GRAND TOTAL			49,917.19	16,492.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,200.00

Report Ref No: CC3/ASM18017509/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SBM00WNP

Reference

CC3/ASM18017509/Kpa3a2

Loss Date

22 September 2018

Report Date

24 Sep 2018 12:00:00 AM

Request Date

30 July 2019

Due Date

Vendor Name

L&K AUTO CONSULTANTS PTE LTD (TPP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

5HCS316X

Make

TPVD RENAULT

Model

LATITUDE-2.0 L (A)

Service Address

...

Primary Contact/Insured

ONG GEOK LAN LANDY

16 ANG MO KIO CENTRAL 3, #12-25 GRANDEUR

8, 567748, Singapore

96818886

LANDY.PANCAKE@GMAIL.COM

Claim Handler

KHOR Saw Theng

6568804754

sawtheng.khor@axa.com.sg

Actions

Next Step

Wait for: Approve Invoice

Auto Invoice is

Additional Instructions

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	L&K AUTO CONSULTANTS PTE LTD (TPP)	10 October 2019

NAME RENTAL RECEIPT.pdf	TYPE / Claim Documents	SUB-TYPE Others	AUTHORISED CONSULTANTS PTE LTD (TP)	DATE 10 October 2019
RENTAL_MILEAGE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2019
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2019
LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2019
LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2019
LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
PARF_COE_REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2019
LTA.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2019
Rental Rate & Mileage.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2019
TP Mandate (A dtd 100819).pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2019
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED
 TP_ESTIMATE_-_MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2019
 SOYBBRAJ INSID GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	26 September 2018
 TP PRI FROM WORKSHOP WITH ESTIMATE.jpg	Letters and Correspondence	Workshop	DHAKAL Raghav	26 September 2018
 SHCS316X TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	26 September 2018