

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7886J**AAD1809-216***Not Notified*
64 Sept 8 9201

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7886J

KL1LA69RJBB106321

CHEVROLET

EPICA 2.0

23.9.2018

III**PART****LIST**

1	1	Headlamp RH	\$	SH	816.00
2	1	Headlamp RH inner panel	\$	N	611.16
3	1	Front Fender RH	\$	N	837.60
4	1	Front Fender Liner RH	\$	SH	47.00
5	1	Front Fender Inner Wheel House Panel RH	\$	N	1,437.00
6	1	Front Shock Absorber Assy RH	\$	SH	216.17
7	1	Front Shock Absorber Top Mounting RH	\$	SH	48.32
8	1	Front Lower Arm RH	\$	SH	283.00
9	1	Front Knuckle Arm RH	\$	SH	230.00
10	1	Front Hub Unit	\$	SH	376.00
11	1	Front Disc Brake RH	\$	SH	157.55
12	1	Front Strut Bar Bracket RH	\$	N	235.01
13	1	Front Stabilizer Bar	\$	SH	234.00
14	1	Front Stabilizer Bar Link RH	\$	SH	51.79
15	1	Front Stabilizer Bar Bracket RH	\$	N	105.75
16	1	Front Stabilizer Bar Bush RH	\$	SH	66.00
17	1	Front Beam A - Impact RH	\$	SH	214.00
18	1	Horn Unit (Low Tone)	\$	SH	53.46
19	1	Horn Unit (High Tone)	\$	SH	53.46
20	1	Front Support Panel Assy	\$	N	1,222.32
21	1	Front brace panel	\$	N	134.37
22	1	Windscreen Washer Tank (Reservoir A-W/Shield)	\$	SH	62.00
23	1	Windscreen Washer Tank Motor (Pump Wswa)	\$	SH	51.00
24	1	TANK, WIPER HOSE	\$	SH	21.00
25	1	Radiator Assembly (Radiator A	\$	SH	618.00
26	1	Bonnet Panel	\$	N	1,250.00
27	1	Front Fender RH	\$	N	837.60

X

Trans-cab Auto Services Pte Ltd

AAD1809-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7886J

28	1	Front Fender Liner RH	\$	Su	47.00
29	1	Fender Insulation RH	\$	Su	39.00
30	1	Front Fender Inner Wheel House Panel RH	\$	N	1,437.00
31	1	Front Door RH	\$	N	1,133.00
32	1	Front Door Glass Guide RH Chrome Moulding	\$	Su	60.00
33	1	Front Door Outer Moulding	\$	Su	220.00
34	1	Front Door Outer Handle	\$	Su	125.00
35	1	Front Door Handle Support	\$	Su	3.00
36	1	Front Door outer handle inner seal	\$	Su	89.15
37	1	Front Door outer key lock	\$	Su	25.00
38	1	Front Door Hinge Upper	\$	N	65.00
39	1	Front Door Hinge Lower	\$	N	65.00
40	1	Front Door inner lock	\$	N	586.00
41	1	Front Door Inner Lock Latch RH	\$	N	206.00
42	1	Front Door Check / Arrestor	\$	N	67.50
43	1	Front Door Weatherstrip RH	\$	Su	138.79
44	1	Front Door glass channel weatherstrip	\$	Su	160.00
45	1	Front Door inner trim board	\$	Su	455.69
46	1	Front Door window glass	\$	Su	456.12
47	1	Front Door Power Window Motor (Master) RH	\$	Su	284.97
48	1	Front Door power window motor switch	\$	Su	145.00
49	1	Front Door Window Regulator Gear RH	\$	Su	84.58
50	1	Front Door Outer Pillar Panel RH	\$	N	715.00
51	1	Front Door Pillar Inner Panel RH	\$	N	850.00
52	1	Front Door Center Pillar Panel RH	\$	N	698.15
53	1	Front Side View Mirror Assy RH	\$	Su	1,191.00
54	1	Front Side Rocker Panel Garnish RH	\$	Su	236.40
55	1	Front Side Rocker Panel Outer RH	\$	N	600.00
56	1	Front Side Rocker Panel Inner RH	\$	N	519.30

TOTAL	\$	20,972.21
10%	\$	2,097.22
	\$	18,874.99

Specical Nett

1 Set Front Bumper Fastener Clip

\$

~~ 24.00 X

Trans-cab Auto Services Pte Ltd

AAD1809-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7886J

1 Set Front licence plate with holder	\$	192.00	}	X
1 Set Radiator Grille clip	\$	35.00		
1 Set Front Fender Liner clip	\$	30.00		
1 Front Fender RR Bracket RH	\$	7.10		
1 Rear Wheel Rim Hub Cap RH	\$	166.30		
1 Front right tyre	\$	220.00	}	
1 Front Tyre Rim RH	\$	350.00		
1 Front right door sticker 'Trans-cab'	\$	80.00		
1 Rear right door sticker '6555-3333'	\$	80.00		

TOTAL \$ **1,184.40****TOTAL PARTS** \$ **20,059.39****LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	600
Putty and spray painting of the affected portion.	\$	4,000.00	200
Towing Fees.	\$	120.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To rust-proofing of the affected areas.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD1809-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7886J

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
TOTAL	\$	10,460.00
Over All Total	\$	30,519.39

Repair Days (Lump Sum)

~~15~~ days*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: