

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5460L**AAD1804-228***Not Authored
L/Lm @ 3000/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5460L

VF1ABL15AUC280946

RENAULT

LATITUDE

24.8.2018

AIG**PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

\$	<i>Rev</i> 1,108.46	<i>✓</i>
\$	<i>Not Lm</i> 768.84	<i>✓</i>
\$	<i>Sm</i> 113.47	<i>X</i>
\$	<i>Sm</i> 135.97	<i>X</i>
\$	<i>Sm</i> 44.99	
\$	<i>Sm</i> 43.61	
\$	<i>Sm</i> 135.97	
\$	<i>Sm</i> 44.99	
\$	<i>Sm</i> 43.61	
\$	<i>R</i> 777.52	
\$	<i>R</i> 225.95	
\$	<i>R</i> 225.95	
\$	<i>R</i> 2,872.68	
\$	<i>Sm</i> 470.06	<i>X</i>
\$	<i>Sm</i> 323.05	
\$	<i>Sm</i> 493.35	
\$	<i>Sm</i> 493.35	
\$	<i>Rev</i> 225.36	
\$	<i>Rev</i> 225.36	
\$	<i>Sm</i> 276.08	
\$	<i>Sm</i> 276.08	
\$	<i>R</i> 367.84	
\$	<i>R</i> 367.84	
\$	<i>Sm</i> 586.45	<i>X</i>
\$	<i>Sm</i> 168.13	
\$	<i>R</i> 202.67	
\$	<i>R</i> 74.40	
\$	<i>Sm</i> 50.52	<i>X</i>
\$	<i>Sm</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1804-228

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5460L

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
31	1 WHEELARCH REAR LH	\$	Sn	543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	X
33	1 FENDER PANEL REAR RH	\$	R	3,299.13	X
34	1 WHEELARCH REAR RH	\$	Sn	543.47	X
35	1 TAILLAMP RH	\$	Sn	552.55	X
36	1 TAILLAMP PANEL RH	\$	R	986.70	X
37	1 TAILLAMP LH	\$	ngm	552.55	✓
38	1 TAILLAMP PANEL LH	\$	R	986.70	} X
39	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
42	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
43	1 EXHAUST REAR	\$	R	7,489.05	
44	1 EXHAUST CAP REAR	\$	Sn	230.49	
45	1 CHASSIS PANEL REAR RH	\$	Sn	3,766.43	
46	1 KUCKLE ARM REAR RH L70Y	\$	Sn	736.67	
47	1 BRAKE DISC REAR L70Y	\$	Sn	525.91	
48	1 WHEEL HUB NUT L70Y	\$	Sn	51.11	
49	1 WHEEL HUB CAP L70Y	\$	Sn	57.82	
50	1 ABS SENSOR REAR RH L70Y	\$	Sn	255.75	
51	1 REAR AXLE L70Y	\$	Sn	4,167.03	
52	1 AXLE ARM RH L70Y	\$	Sn	117.22	
53	1 LOWER ARM REAR RH L70Y	\$	Sn	905.99	
54	1 ABSORBER REAR	\$	Sn	389.75	
55	1 STABILIZER BAR REAR RH	\$	Sn	604.65	
56	1 BRAKE CALIPER REAR RH	\$	Sn X	1,300.67	
57	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09	
58	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	
TOTAL		\$		56,525.01	
10%		\$		5,652.50	
		\$		50,872.51	

Specical Nett

1	1SET PARKING AID	\$	Sn	700.00	X
2	1SET REAR BUMPER CLIP	\$	nc	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	nc	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nc	10.00	X

Trans-cab Auto Services Pte Ltd

AAD1804-228

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5460L

5 1SET BUMPR RETAINER RH CLIP RR	\$	nn	20.00	X
6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7 1SET BUMPR RETAINER CLIP LH RR	\$	nn	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
11 1SET BOOT FINISHER CLIP	\$	nn	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	nn	30.00	—
13 1 BOOT STICKER "6555-3333"	\$	nn	30.00	—
14 1 BOOT INNER TRIM CLIP	\$	nn	45.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19 1 TAILLAMP CLIP RH	\$	nn	5.00	X
20 1 TAILLAMP CLIP LH	\$	nn	5.00	✓
21 2 REAR WINDSCREEN SELANT	\$	nn	80.00	} X
22 1 WINDSCREEN MOULDING	\$	nn	100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	
25 1 SPARE TYRE	\$	nn	330.00	
26 1 RIGHT REAR TYRE	\$	nn	330.00	
27 1 RIGHT REAR TYRE RIM	\$	nn	380.00	

TOTAL \$ 2,935.02**TOTAL PARTS \$ 53,807.53****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	4001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1804-228

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5460L

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 12,540.00

Over All Total \$ 66,347.53

(LUMP SUM)

Repair Days

20 DAYS
2 1/2 days