

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

26-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6248 C

1 pc	n/s head lamp	\$	1,028.00
1 pc	Bonnet grille <i>x repair</i>	\$	385.00
1 pc	Front bumper	\$	531.00
1 pc	Front bumper emblem @ \$44.00	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00 <i>nb - o/s</i>	\$	32.00
1 pc	Front bumper n/s upper bracket @ \$16.00	\$	16.00
1 pc	Front bumper n/s support bracket @ \$16.00	\$	16.00
1 pc	Front bumper n/s protector @ \$51.00 <i>x</i>	\$	51.00
1 pc	Front bumper n/s fog lamp cover @ \$66.00 <i>x</i>	\$	66.00
1 pc	Front n/s wheel cover @ \$116.00 <i>x repair</i>	\$	116.00
1 pc	Front n/s fender @ \$384.00	\$	384.00
1 pc	Front n/s fender inner shield @ \$120.00	\$	120.00
	<i>Front Support Panel</i>	\$	2,789.00
	Less 10%	\$	278.90
		\$	2,510.10

S/NETT

1 set	Front bumper clips	\$	48.00
1 pc	Front n/s fender sticker <i>x</i>	\$	30.00
1 set	Front n/s fender inner shield clips	\$	28.00
1 set	N/s door stickers	\$	100.00
1 pc	Front n/s headlamp lower clip @ \$6.00	\$	6.00
1 pc	Front n/s headlamp side clip @ \$3.00	\$	3.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged parts for resurvey
- Parts price to be based on "original" basis
- Third party survey to be on "original" basis
- No illegal repair and replacement
- Survey and repair to be done by the insurance company

Acknowledged by: *Kalvin LKK*
Signature: *Kalvin LKK*
Date: *26/9/18*

Sundry	<i>26/9/18 1000 hrs</i>	\$	50.00 <i>20</i>
Towing Fee	<i>5 Days</i>	\$	50.00
To check for wiring and focus front n/s head lamp	<i>45</i>	\$	40.00 <i>20</i>
To check front n/s wheel alignment	<i>APR Repair photo</i>	\$	80.00 <i>x</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>x</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bonnet, support panel, front n/s wheel housing, front n/s door, etc		\$	1,200.00 <i>600</i>
To putty and spray painting on bonnet, front bumper, front n/s wheel housing, front n/s fender, front n/s door		\$	1,000.00 <i>900</i>
To apply rustproofing on the repaired and replaced panels.		\$	120.00 <i>50</i>
		\$	5,445.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

CASH SALE/WORK ORDER No:Y 9039



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717
TEL : 6743 1987 (3 LINES) FAX : 6743 0013
Reg No: 200415052W

Date, 25/9/18

寶號

Messrs: Premier

車號

Vehicle No: SHC 6248 C

車型

Model No: Optima

由

From: Old Tampines Rd

到

To: Changi South

其他

Remark: Omega-L1

時間

Time: 08:04-08:50-09:35

AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by: [Signature]

收貨人

Received by: [Signature]