

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

21/09/2018 18:31

JOB-NO: 50110967

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7570P

TRANS: AUTO

CHASSIS: KMHET41VMAA796048

MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDi

ENGINE: D4EA9781826

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,900.00	0.00	1,900.00		Y	_____
2 R&R SPARE TYRE BOARD/ CARPET/ TRIM	1.00	120.00	0.00	120.00		Y	_____
3 R&R REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	_____
4 R&R BOOTLID COMPENENTS	1.00	130.00	0.00	130.00		Y	_____
5 ALIGNMENT BOOTLID	1.00	180.00	0.00	180.00		Y	_____
6 MOUNT WORKBENCH	1.00	300.00	0.00	300.00		Y	_____
7 TO ALIGNMENT CHASSIS	1.00	350.00	0.00	350.00		Y	_____
8 R&R REAR PASSENGER SEAT & SEAT BELT & ROOF LINING	1.00	250.00	0.00	250.00		Y	_____
9 R&R REAR WINDSCREEN GLASS	1.00	100.00	0.00	100.00		Y	_____
10 RUST PROOFING	1.00	150.00	0.00	150.00		Y	_____
11 SUNDRIES	1.00	80.00	0.00	80.00		Y	_____
12 TO RESETTING AND RECODING TAIL LAMP & BOOTLID LAMP & DIAGNOSTIC (CLEAR FAULT CODE) & TO CHECK & REPAIR WIRING SYSTEM	1.00	150.00	0.00	150.00		Y	_____
13 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	_____
14 RESPRAY BOOTLID	1.00	250.00	0.00	250.00		Y	_____
15 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	_____
16 RESPRAY TAIL LAMP INNER PANEL RH	1.00	150.00	0.00	150.00		Y	_____
17 RESPRAY REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	_____
18 RESPRAY REAR FENDER RH	1.00	250.00	0.00	250.00		Y	_____
19 RESPRAY REAR FENDER LH	1.00	250.00	0.00	250.00		Y	_____
20 TOWING	1.00	120.00	0.00	120.00		Y	_____
TOTAL:		5,350.00	0.00	5,350.00			_____

MATERIALS

1 REAR BUMPER	1.00	523.93	104.79	419.14	L	Y	_____
2 REAR BUMPER PROTECTOR LH	1.00	102.96	20.59	82.37	L	Y	_____
3 REAR BUMPER PROTECTOR RH	1.00	102.96	20.59	82.37	L	Y	_____
4 REAR BUMPER LWR EXT	1.00	40.70	8.14	32.56	L	Y	_____
5 REAR BUMPER REINFORCEMENT	1.00	426.30	85.26	341.04	L	Y	_____
6 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	79.75	15.95	63.80	L	Y	_____
7 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	79.75	15.95	63.80	L	Y	_____
8 REAR BUMPER REINFORCEMENT SPONGE	1.00	101.55	20.31	81.24	L	Y	_____
9 REAR END PANEL	1.00	323.29	64.66	258.63	L	Y	_____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
10 REAR END PANEL TOP GANISH	1.00	42.02	8.40	33.62	L	Y	
11 SPARE TYRE BOARD	1.00	162.14	32.43	129.71	L	Y	
12 BOOTLID	1.00	1,139.11	227.82	911.29	L	Y	
13 BOOTLID HINGE LH	1.00	140.80	28.16	112.64	L	Y	
14 BOOTLID HINGE RH	1.00	140.80	28.16	112.64	L	Y	
15 BOOTLID DAMPER LH	1.00	104.50	20.90	83.60	L	Y	
16 BOOTLID DAMPER RH	1.00	104.50	20.90	83.60	L	Y	
17 BOOTLID EMBLEM-LOGO	1.00	33.65	6.73	26.92	L	Y	
18 BOOTLID EMBLEM-HYUNDAI	1.00	40.11	8.02	32.09	L	Y	
19 BOOTLID EMBLEM-SONATA	1.00	40.92	8.18	32.74	L	Y	
20 BOOTLID EMBLEM-CRDI	1.00	26.30	5.26	21.04	L	Y	
21 BOOTLID LAMP LH	1.00	203.50	40.70	162.80	L	Y	
22 BOOTLID LAMP RH	1.00	203.50	40.70	162.80	L	Y	
23 BOOTLID PLATE LAMP LH	1.00	49.50	9.90	39.60	L	Y	
24 BOOTLID PLATE LAMP RH	1.00	49.50	9.90	39.60	L	Y	
25 BOOTLID LOCK	1.00	109.45	21.89	87.56	L	Y	
26 BOOTLID LOCK CATCH	1.00	108.90	21.78	87.12	L	Y	
27 BOOTLID INSULATOR	1.00	155.10	31.02	124.08	L	Y	
28 BOOTLID RUBBER BEADING	1.00	91.30	18.26	73.04	L	Y	
29 TAIL LAMP RH	1.00	336.50	67.30	269.20	L	Y	
30 TAIL LAMP LH	1.00	336.50	67.30	269.20	L	Y	
31 TAIL LAMP INNER PANEL RH	1.00	267.30	53.46	213.84	L	Y	
32 REAR FENDER RH	1.00	1,598.30	319.66	1,278.64	L	Y	
33 REAR BUMPER RETAINER LH	1.00	42.68	8.54	34.14	L	Y	
34 REAR BUMPER RETAINER RH	1.00	42.68	8.54	34.14	L	Y	
35 REAR FENDER INNER TRIM LH	1.00	191.62	38.32	153.30	L	Y	
36 REAR FENDER INNER TRIM RH	1.00	191.62	38.32	153.30	L	Y	
37 REAR FENDER AIR VENT RH	1.00	55.60	11.12	44.48	L	Y	
38 REAR MUD-FLAP LH	1.00	41.55	8.31	33.24	L	Y	
39 REAR MUD-FLAP RH	1.00	41.55	8.31	33.24	L	Y	
40 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	
41 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	0.00	230.00	S	Y	
42 REAR BUMPER ADS STICKER	1.00	130.00	0.00	130.00	S	Y	
43 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	
44 BOOTLID INSULATOR CLIPS (1 SET)	1.00	35.00	0.00	35.00	S	Y	
45 BOOTLID STICKER-CAB BOOKING 65521111	1.00	80.00	0.00	80.00	S	Y	
46 BOOTLID STICKER-CITYCAB	1.00	80.00	0.00	80.00	S	Y	
47 BOOTLID ADS STICKER	1.00	150.00	0.00	150.00	S	Y	
48 REAR NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	
49 TAIL LAMP INNER PANEL SEALANT RH	1.00	50.00	0.00	50.00	S	Y	
50 REAR FENDER SEALANT RH	1.00	50.00	0.00	50.00	S	Y	
51 REAR FENDER ADS STICKER RH	1.00	180.00	0.00	180.00	S	Y	
52 REAR FENDER ADS STICKER LH	1.00	180.00	0.00	180.00	S	Y	
53 REPAIR REAR FENDER LH	1.00	0.00	0.00	0.00	S	Y	
54 REAR FENDER INNER TRIM CLIP SET	1.00	35.00	0.00	35.00	S	Y	
55 REAR WINDSCREEN GLASS SEALANT	1.00	50.00	0.00	50.00	S	Y	
TOTAL:		9,247.69	,574.53	7,673.16			
TOTAL PARTS & LABOUR :		14,597.69	1,574.53	13,023.16			

EXCESS/LOADING:S\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Paul
Hp 90010068

Paul
25/09/18 @ 1200hrs

Vehicle to be recommended
uneconomical to repair

[illegible]