

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 859Z**AAD1809-213**

Not Authorised
Resony B4 paint
83730.19

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 859Z
VF1ABL15AUC283210
RENAULT
LATITUDE
21.9.2018
AXA

	PART		LIST
1	DOOR PANEL REAR RH	\$	<i>Ad/warp R</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>R</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sn</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>Sn</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>Sn</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>R</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>R</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sn</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>nn</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>nn</i> 6.91
1	DOOR CASING REAR RH	\$	<i>Sn</i> 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	<i>Sn</i> 30.39
1	DOOR CASING CLIP	\$	<i>nn</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Sn</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>Sn</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>R</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>R</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>R</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>R</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>Sn</i> 210.96
1	DOOR BLIND REAR RH	\$	<i>R</i> 741.80

Trans-cab Auto Services Pte Ltd

AAD1809-213

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 859Z

1	DOOR WHEATHESTRIP REAR RH	\$	410.66	} X
1	DOOR SEAL REAR RH	\$	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	115.64	
1	FENDER PANEL REAR RH	\$	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	671.45	
1	WHEELARCH REAR RH	\$	543.47	
1	DOOR MIRROR ASSY RH	\$	1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	466.51	
1	ROCKER PANEL INNER RH	\$	1,024.79	}
1	ROCKER PANEL CENTER RH	\$	990.25	

\$	20,401.70
----	-----------

10% \$	2,040.17
--------	----------

\$	18,361.53
----	-----------

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	300.00	} X
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR GUIDE SCREW	\$	10.85	
1	DOOR HINGE BOLT	\$	10.85	
1	DOOR HINGE NUT RH	\$	14.60	
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR CHECK NUT	\$	3.75	
1	DOOR LOCK SCREW L70Y	\$	6.12	
1	DOOR CATCH SCREW L70Y	\$	10.06	

TOTAL \$	401.63
----------	--------

TOTAL PARTS \$	18,763.16
----------------	-----------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00
----	----------

Trans-cab Auto Services Pte Ltd

AAD1809-213

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 859Z

Putty and spray painting of the affected portion.	\$	4,200.00	66d
To rust-proofing of the affected areas.	\$	170.00	3d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2d
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To dismantle advertisement sticker	\$	nn 170.00	X
Towing Fees.	\$	nn 120.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X

TOTAL \$ 11,620.00**Over All Total \$ 30,383.16****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party supply of parts is not allowed
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PART-BY-PART (REPAIR DAY)**15 DAYS**

2 1/2 days