

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 163Y**AAD1809-214***Not Authorized*
*L1 Sup &*Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :**SHD 163Y**

VF1ABL15AUC281558

RENAULT

LATITUDE

22.9.2018

AXA

PART		LIST	
1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT LH	\$	151.41
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER RETAINER FRT RH	\$	150.77
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	FENDER PANEL FRT LH	\$	783.83
1	WHEELARCH FRT LH	\$	278.84
1	FENDER BRACKET LOWER LH	\$	15.79
1	FENDER INSULATOR LH	\$	130.84
1	DOOR PANEL FRT LH	\$	2,844.66
1	DOOR HINGE UPPER LH	\$	261.28
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK FRT LH	\$	194.77
1	DOOR LOCK FRT LH	\$	908.75
1	DOOR CATCH FRT LH	\$	131.23
1	DOOR HANDLE OUTER FRT LH	\$	477.76
1	DOOR HANDLE COVER FRT LH	\$	13.22
1	DOOR HANDLE MODULE FRT LH	\$	133.60
1	DOOR REGULATOR FRT LH	\$	505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97
1	DOOR PANEL REAR LH	\$	2,844.66
1	DOOR GUIDE REAR LH	\$	176.82

Trans-cab Auto Services Pte Ltd**AAD1809-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 163Y

1	DOOR HINGE UPPER LH	\$	274.50
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK REAR LH	\$	203.06
1	DOOR LOCK REAR LH	\$	908.75
1	DOOR HANDLE OUTER REAR LH	\$	126.49
1	DOOR HANDLE CAP REAR LH	\$	35.52
1	DOOR HANDLE SEAL REAR LH	\$	7.89
1	DOOR HANDLE COVER REAR LH	\$	13.22
1	DOOR HANDLE MODULE REAR LH	\$	133.60
1	DOOR REGULATOR REAR LH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75
1	DOOR REGULATOR NUT REAR LH	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH	\$	423.10
1	DOOR MOULDING REAR LH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH	\$	1,509.06
1	DOOR WATER SHIELD REAR LH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR GRAB HANDLE REAR LH	\$	210.96
1	DOOR BLIND REAR LH	\$	741.80
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66
1	DOOR SEAL REAR LH	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64
1	FENDER PANEL REAR LH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR LH	\$	543.47
1	DOOR MIRROR ASSY LH	\$	1,483.40
1	ROCKER PANEL INNER GARNISH LH	\$	466.51

Trans-cab Auto Services Pte Ltd

AAD1809-214

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 163Y

1	ROCKER PANEL INNER LH	\$	<i>Sn</i> 1,024.79	}	X
1	ROCKER PANEL CENTER LH	\$	<i>Sn</i> 990.25		
1	BUMPER COVER REAR	\$	<i>Sn</i> 1,108.46		
1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84		
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47		
1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97		
1	BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99		
1	AIR CLEANER BOX	\$	<i>Sn</i> 464.20		
1	AIR CLEANER HOSE	\$	<i>Sn</i> 175.85	}	?
1	LOWER ARM LH L70Y	\$	<i>Sn</i> 685.76		
1	KUNCKLE ARM LH L70Y	\$	<i>Sn</i> 846.98		
1	ABSORBER FRT LH L70Y	\$	360.54		?

\$	37,458.44
10% \$	3,745.84
\$	33,712.60

Specical Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	60sn
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	15sn
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	60sn
1	DOOR CHECK BOLT	\$	sn	22.69	} X
1	DOOR GUIDE SCREW	\$	sn	10.85	
1	DOOR HINGE BOLT	\$	sn	10.85	
1	DOOR HINGE NUT RH	\$	sn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	}
1SET	BUMPER CLIP FRT	\$	nn	66.00	
1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	

Trans-cab Auto Services Pte Ltd

AAD1809-214

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 163Y

1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	X
1	TOW COVER FRT	\$	nn	14.50	X
1SET	RADAITOR GRILLE SCREW	\$	nn	16.00	X
1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1	FRONT LEFT TYRE	\$	nn	330.00	90%nn
1	FRONT LEFT TYRE RIM	\$	nn	380.00	✓

TOTAL \$ 1,434.63**TOTAL PARTS \$ 33,781.60****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6000.00	6000
Putty and spray painting of the affected portion.	\$	5,000.00	13200
To rust-proofing of the affected areas.	\$	170.00	900
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	600
To check steering geometry and computer wheel alignment	\$	220.00	600
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn	380.00 X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn	380.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	200
To Check Electrical Lighting Concerned.	\$	170.00	200

Trans-cab Auto Services Pte Ltd**AAD1809-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 163Y

To transfer of front fender fittings, attachment and perform water seepage test.

\$ *nr* 380.00 *X*

To transfer of front door fittings, attachment and perform water seepage test.

\$ 380.00 *601*

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ 380.00 *601*

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *nr* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nr* 380.00 *X***TOTAL \$ 14,770.00****Over All Total \$ 48,551.60****PART-BY-PART (REPAIR DAY)***20 DAYS**5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: