



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2005048  
INV Date 20/07/2020  
Reference CC4/EQI18017539/R1es3n2  
Code EQI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SLA 8283A  
Insured Veh. PC 8889U  
Claim No. DM18HO02072/JT  
Policy No. DMBPHQ17-000077  
Accident Date 07/08/2018  
Inspection Date 02/10/2018

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQI18017539/R1es3n2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 20-07-2020	
			Code : EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	PC 8889U	<b>Veh. Inspected</b>	SLA 8283A
	<b>Policy No.</b>	DMBPHQ17-000077	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	DM18HO02072/JT	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	JANET	<b>Assign Date</b>	25/09/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	NISSAN SYLPHY 1.6	<b>c.c</b>	1598
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	MNTBBAB17Z0026638	<b>Colour</b>	GREY
	<b>Odometer</b>	51466	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/60 R16	BRIDGESTONE	6 mm
	<b>L/H Front Tyre</b>	195/60 R16	BRIDGESTONE	6 mm
	<b>R/H Rear Tyre</b>	195/60 R16	BRIDGESTONE	6 mm
	<b>L/H Rear Tyre</b>	195/60 R16	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	07/08/2018	<b>Inspection Date</b>	02/10/2018
	<b>Survey held at</b>	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 8283A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LAMP ASSY -RH (N)	CRACKED	489.00	489.00
1	HOOD (N)	BENT	867.20	867.20
1	EMBLEM RAD GRIL (N)	NECESSARY	59.70	59.70
1	RAD GRILLE (N)	CRACKED	716.70	716.70
10	CLIP @\$1.20 (N)	NECESSARY	12.00	12.00
1	FACE -FR BUMPER (N)	DEFORMED	487.40	487.40
1	BRKT LIC (N) (ADDITIONAL)	NECESSARY	136.60	136.60
	LESS 20% DISCOUNT		-553.72	-553.72
			2,214.88	2,214.88
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRT LICENCE PLATE (SN)	BENT	60.00	60.00
			60.00	60.00
	<b><u>LABOUR</u></b>			
	S/PAINT FRONT BONNET ,FRT BUMPER COVER ,HDLAMP PNL RH FRT FENDER RH & LH . (ADDITIONAL)		1,250.00	1,250.00
	RENEW FRT HEADLAMP RH .(ADDITIONAL)		48.00	48.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		120.00	80.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA X2 PANEL (FRT PANEL & HOOD).		200.00	100.00
	REPAIR FRONT FENDER RH ,HEADLAMP PANEL RH RENEW FRONT BONNET & FRONT BUMPER COVER.		975.00	780.00
	S/PAINT FRONT BONNET ,FRT BUMPER COVER,HEADLAMP PANEL RH & FRT FENDER RH .	NOT NECESSARY	1,250.00	-
			-	-
			-	-
			-	-
			3,843.00	2,258.00
	<b>GRAND TOTAL</b>		<b>6,117.88</b>	<b>4,532.88</b>

Report Ref No. CC4/EQI18017539/R1es3n2



RECOMMENDED COST OF REPAIRS			4,532.88
-----------------------------	--	--	----------

Report Ref No. CC4/EQI18017539/R1es3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 8283A

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 8283A

RE-INSPECTION







## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

