

709

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0352/2018
DATE : 17-AUG-2018

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR HO JEE THAU
ADDRESS : BLK 707 WOODLANDS DRIVE 40
#11-64
S(730707)
TELEPHONE NO : 93858564/91877759

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-PC8889U
VEHICLE NO : SLA8283A
MODEL CODE : BDTARCZB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16983933B
CHASSIS NO : MNTBBAB17E0026638
MILEAGE : 1 KM
DATE IN : 17/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 07/08/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / ~~CAR NOT AT WORKSHOP~~

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

31/08/2018

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA8283A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S
			CHARGES	RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00 80	
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA X2 PANEL (FRT PANEL & HOOD)	200.00 100	
4	ZZ/001	REPAIR FRONT FENDER RH, HEADLAMP PANEL RH RENEW FRONT BONNET & FRONT BUMPER COVER	975.00 780	
5	ZZ/002	S/PAINT FRONT BONNET, FRT BUMPER COVER, HEADLAMP PANEL RH & FRT FENDER RH	1250.00 750	1,250
TOTAL LABOUR CHARGES			2545.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA8283A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 FRT LICENCE PLATE	FLP			60.00 <i>FA</i> / /
2 LAMP ASSY-RH	26010-3SB1C	489.00	<i>? CRD</i> / /	
3 HOOD	F510M-3SBMA	867.20	<i>FA</i> / /	
4 EMBLEM RAD GRIL	62890-1KA0A	59.70	<i>per</i> / /	
5 RAD GRILLE	62312-3SB0A	716.70	<i>CRD</i> / /	
6 CLIP(10X1.2)	01553-10501	12.00	<i>per</i> / /	
7 FACE-FR BUMPER	62022-3ST1H	487.40	<i>DE</i> / /	
SUB TOTAL		2632.00	0.00	60.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		526.40	0.00	0.00
GRAND TOTAL		2105.60	0.00	60.00
OVERALL TOTAL		2165.60		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA8283A

TOTAL LABOUR CHARGES	2545.00
TOTAL SPARE PARTS CHARGES	2165.60
GRAND TOTAL	4710.60 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME
SURVEYED DATE
AUTHORIZED DATE
EXCESS CLAUSE
LIABILITY
REMARKS

Rasul - Hp 90010068
02/10/18 @ 1720

0.00
0.00

4 days + 1 day = 5 days

Resurvey b4 part

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0352/2018
DATE : 17-AUG-2018

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR HO JEE THAU
ADDRESS : BLK 707 WOODLANDS DRIVE 40
#11-64
S(730707)
TELEPHONE NO : 93858564/91877759

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-PC8889U
VEHICLE NO : SLA8283A
MODEL CODE : BDTARCZB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16983933B
CHASSIS NO : MNTBBAB17Z0026638
MILEAGE : 1 KM
DATE IN : 17/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 07/08/2018

DS => Rasu 1

ZHR

(5 Days)

La = \$60 x 5
= \$300

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA8283A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S
			CHARGES	RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	80.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA X2 PANEL (FRT PANEL & HOOD)	200.00	100.00
4	ZZ/001	REPAIR FRONT FENDER RH, HEADLAMP PANEL RH RENEW FRONT BONNET & FRONT BUMPER COVER	975.00	780.00
5	ZZ/002	S/PAINT FRONT BONNET, FRT BUMPER COVER, HDLAMP PNL RH FRT FENDER RH & LH (SUPPLEMENTARY LABOUR)	1250.00	1250.00 (S)
6	ZZ/003	RENEW FRT HEADLAMP RH (SUPPLEMENTARY LABOUR)	48.00	48.00 (S)
TOTAL LABOUR CHARGES			2593.00	2258.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA8283A

DAMAGED PARTS & PRICES				
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 BRKT LIC(SUPPLEMENTARY ITEM) <i>mc ✓</i>	96210-3ST0A	136.60	(S)	OK
2 FRT LICENCE PLATE	FLP			60.00 OK
3 LAMP ASSY-RH (SUPPLEMENTARY ITEM)	26010-3SB1C	489.00		OK
4 HOOD	F510M-3SBMA	867.20		OK
5 EMBLEM RAD GRIL	62890-1KA0A	59.70		OK
6 RAD GRILLE	62312-3SB0A	716.70		OK
7 CLIP(10X1.2)	01553-10501	12.00		OK
8 FACE-FR BUMPER	62022-3ST1H	487.40		OK
SUB TOTAL		2768.60	0.00	60.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		553.72	0.00	0.00
GRAND TOTAL		2214.88	0.00	60.00
OVERALL TOTAL		2274.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLA8283A

NETT ITEM	2768.60
LESS 20.00%)	-553.72
NETT AMOUNT	2214.88
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	60.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	60.00
TOTAL LABOUR CHARGES	2258.00
TOTAL SPARE PARTS CHARGES	2274.88
TOTAL CHARGES	4532.88
ADD 7 % GST	317.30
GRAND TOTAL	4850.18