

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/ZHR/0352/2018  
DATE : 17-AUG-2018

EQ INSURANCE COMPANY LIMITED  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX S(069110)  
TEL : 62239433  
FAX : 62234190  
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR HO JEE THAU  
ADDRESS : BLK 707 WOODLANDS DRIVE 40  
#11-64  
S(730707)  
TELEPHONE NO : 93858564/91877759

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-PC8889U  
VEHICLE NO : SLA8283A  
MODEL CODE : BDTARCZB17EWA----A  
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)  
ENGINE NO : HR16983933B  
CHASSIS NO : MNTBBAB17Z0026638  
MILEAGE : 1 KM  
DATE IN : 17/08/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : MUHAMMAD ZUHRI  
ACCIDENT DATE : 07/08/2018

**DIRECT SETTLEMENT**

**OWNER CLAIMING LOSS OF USE / RENTAL**

**CAR AT WORKSHOP / ~~CAR NOT AT WORKSHOP~~**

**KINDLY REVERT TO ME ASAP**

31/08/2018

**EMAIL : [zuhri@tanchong.com](mailto:zuhri@tanchong.com)**

**OFFICE : 67038916 FAX : 64697472**

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA8283A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	80
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA X2 PANEL (FRT PANEL & HOOD)	200.00	100
4	ZZ/001	REPAIR FRONT FENDER RH, HEADLAMP PANEL RH RENEW FRONT BONNET & FRONT BUMPER COVER	975.00	780
5	ZZ/002	S/PAINT FRONT BONNET, FRT BUMPER COVER, HEADLAMP PANEL RH & FRT FENDER RH	1250.00	750
TOTAL LABOUR CHARGES			2545.00	

## TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA8283A

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 FRT LICENCE PLATE	FLP			60.00 <i>OK</i>
2 LAMP ASSY-RH	26010-3SB1C	489.00	?	
3 HOOD	F510M-3SBMA	867.20	<i>OK</i>	
4 EMBLEM RAD GRIL	62890-1KA0A	59.70	<i>OK</i>	
5 RAD GRILLE	62312-3SB0A	716.70	<i>OK</i>	
6 CLIP(10X1.2)	01553-10501	12.00	<i>OK</i>	
7 FACE-FR BUMPER	62022-3ST1H	487.40	<i>OK</i>	
SUB TOTAL		2632.00	0.00	60.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		526.40	0.00	0.00
GRAND TOTAL		2105.60	0.00	60.00
OVERALL TOTAL		2165.60		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA8283A

TOTAL LABOUR CHARGES	2545.00
TOTAL SPARE PARTS CHARGES	2165.60
GRAND TOTAL	4710.60 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	: Rasul - Hp 90011068
SURVEYED DATE	: 02/10/18 @ 1720
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00 4 days
LIABILITY	: 0.00
REMARKS	:

Resurvey b4 part

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: