

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5389K**AAD1809-233***Not Authorised*
61 Rm @ 41006

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5389K

VF1ABL15AUC280057

RENAULT

LATITUDE

24.9.2018

AIG

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	<i>Sm</i> 151.41 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 207.21 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
13	1	TOW COVER FRT	\$	<i>Sm</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>Not</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75 X
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sm</i> 615.90 X
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	HEADLAMP LH	\$	<i>Sm</i> 1,184.43 X
20	1	HEADLAMP RH	\$	<i>mg ch</i> 1,184.43 ✓
21	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
22	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
23	1	BONNET	\$	<i>R</i> 1,941.63 X
24	1	BONNET INSULATOR	\$	<i>Sm</i> 405.73 X
25	1	BONNET STRUT LH	\$	<i>Sm</i> 88.61 X
26	1	BONNET STRUT RH	\$	<i>Sm</i> 88.61 X
27	1	BONNET HINGE LH	\$	<i>R</i> 348.31 X
28	1	BONNET HINGE RH	\$	<i>R</i> 348.31 X

Trans-cab Auto Services Pte Ltd

AAD1809-233

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5389K

29	1	BONNET CABLE COVER	\$	SL 161.03 X
30	1	BONNET SEAL OUTER	\$	SL 92.36 X
31	1	BONNET SEAL INNER	\$	SL 157.28 X
32	1	FENDER PANEL FRT LH	\$	R 783.83 X
33	1	FENDER PANEL FRT RH	\$	R 783.83 X

TOTAL	\$	16,347.81
10%	\$	1,634.78
	\$	14,713.03

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	nn 52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	nn 66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn 12.00
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn 10.50
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn 12.00
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn 10.50
7	1	TOW COVER FRT	\$	SL 14.50
8	1SET	RADAIOR GRILLE SCREW	\$	nn 16.00
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn 69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00
11	2	FRAME FULL SUPPORT PANEL NUT	\$	SL 20.00
12	2	FRAME FULL SUPPORT PANEL STUD	\$	SL 30.00
21	1	Windscreen moulding	\$	nn 100.00
22	1SET	Front licence plate with holder	\$	nd 80.00 45nn

TOTAL	\$	562.50
TOTAL PARTS	\$	15,275.53

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,450.00 40d

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1809-233

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5389K

Putty and spray painting of the affected portion.	\$	4401 2,200.00
To rust-proofing of the affected areas.	\$	nn 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	5 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	5 380.00 X
To replace, refix and top up coolant for radiator	\$	5 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	5 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	5 170.00 X

TOTAL \$ 7,790.00**Over All Total \$ 23,065.53****(LUMP SUM) Repair Days****7 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by LKK Auto Consultants
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: