

ANG



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLW 9352 L

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>6,903.96</u>
	Plus/Less 25%	\$	<u>1,725.99</u>
	<b>Total of Cost / List</b>	\$	<u><u>5,177.97</u></u>
	(b) Nett Price Items		_____
	Less		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items		_____
<b>Total Parts Cost</b>		\$	<u><u>5,177.97</u></u>
<b>Labour</b>		\$	<u><u>3,070.00</u></u>
<b>Total</b>		\$	<u><u>8,247.97</u></u>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Emo Qiang - 82880282

Company : LKK

Survey conducted on : 27/9/18 at \_\_\_\_\_

Part by part.  
before part photos.

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 6 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SLQ 9352 L  
 Make & Model : TOYOTA PRIUS  
 Chassis No : ZVW508031139

Submit By : Carmen Lim  
 Year Manufacture : 2016  
 Engine No. : \_\_\_\_\_

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH rear door / BT	1	\$1,181.75	?	
2	RH rear door hinge top X	1	\$78.34		
3	RH rear door hinge bottom X	1	\$78.34		
4	RH rear door lock X	1	\$411.70		
5	RH rear door checker X	1	\$156.79		
6	RH rear door weatherstrip ?	1	\$178.40		
7	RHR door glass outer moulding X	1	\$111.61		
8	RHR power window motor X	1	\$511.69		
9	RHR power window regulator X	1	\$177.64		
10	RH side skirt / cut	1	\$721.50	?	
11	RH side skirt clip / NB <sup>L</sup>	10	\$50.00		
12	RH rear fender / BUL	1	\$881.60	?	
13	RH rear fender undershield ?	1	\$92.30		
14	RH rear fender undershield clip / MCL	10	\$30.00		
15	RH rear rim / cut	1	\$1,555.10	?	
16	Rear bumper / cut	1	\$497.50		
17	Rear bumper clip / MCL	10	\$40.00		
18	Rear bumper lower garnish RH X Repair	1	\$149.70		
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : SLQ 9352 L Submit By : Carmen Lim  
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RHR FENDER,RHR DOOR,RHF DOOR) RH SIDE SKIRT , REAR BUMPER)	\$1,200.00	800.
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RHR FENDER,RHR DOOR,RHF DOOR) RH SIDE SKIRT , REAR BUMPER)	\$1,200.00	1000
3	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
4	To remove & refit inner seat & upholstery to assist work load.	\$250.00	60
5	To check wiring	\$50.00	30
6	To tuff coat	\$100.00	60
7	To remove & refit reverse sensor to assit work load	\$120.00	40

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.