

AIG



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemp.com.sg

Repair Estimates

SLM 8964 E

Parts	(a) Cost / List Price Items	\$	<u>2,075.50</u>
	Plus/Less 25%	\$	<u>518.88</u>
	Total of Cost / List	\$	<u><u>1,556.63</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items	\$	<u>200.00</u>
Total Parts Cost		\$	<u><u>1,756.63</u></u>
Labour		\$	<u><u>1,620.00</u></u>
Total		\$	<u><u>3,376.63</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Eric G. P.

Company : UKIC

Survey conducted on : 02/10/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

*part by net.
before paint photos*



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLM 8964 E
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU203555433

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor x NN	1	\$200.00	S.N	
2	Rear bumper / ec	1	\$497.50		
3	Rear bumper clip / ec	10	\$40.00		
4	Rear bumper side retainer LH x JMN	1	\$112.70		
5	Rear bumper side retainer RH x JMN	1	\$112.70		
6	Rear bumper reinforcement ?	1	\$398.90		
7	Rear bumper lower garnish centre / ec	1	\$582.60		
8	Rear bumper lower garnish LH x JMN	1	\$149.70		
9	Rear bumper lower garnish RH x JMN	1	\$149.70		
10	Rear bumper tow cover x	1	\$31.70		
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

