

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5630M**AAD1809-234***Not Authorized
1/10/18*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5630M

VF1ABL15AUC280315

RENAULT

LATITUDE

24.9.2018

AXA**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Price</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	394.68 ?
4	1	BUMPER RETAINER FRT LH	\$	<i>Dir</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	914.08 ?
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>RM</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>SL</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>mgcm</i> 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
22	1	HEADLAMP RH	\$	<i>SL</i> 1,184.43 X
22	1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
22	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1	BONNET	\$	<i>R</i> 1,941.63 ✓

Trans-cab Auto Services Pte Ltd**AAD1809-234**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5630M

27	1	BONNET INSULATOR	\$	Su	405.73
28	1	BONNET STRUT LH	\$	Su	88.61
29	1	BONNET STRUT RH	\$	Su	88.61
30	1	BONNET HINGE LH	\$	N	348.31
31	1	BONNET HINGE RH	\$	N	348.31
32	1	BONNET LOCK	\$	N	305.48
33	1	BONNET CABLE	\$	Su	119.19
34	1	BONNET CABLE COVER	\$	Su	161.03
35	1	BONNET SEAL OUTER	\$	Su	92.36
36	1	BONNET SEAL INNER	\$	Su	157.28
37	1	FENDER PANEL FRT LH	\$	N	783.83
38	1	FENDER PANEL FRT RH	\$	N	783.83
39	1	WHEELARCH FRT LH	\$	Su	278.84
40	1	WHEELARCH FRT RH	\$	Su	278.84
41	1	FENDER BRACKET LOWER LH	\$	Su	15.79
42	1	FENDER BRACKET LOWER RH	\$	Su	15.79
43	1	FENDER INSULATOR LH	\$	Su	130.84
44	1	FENDER INSULATOR RH	\$	Su	130.84
45	1	WIPER RESERVOIR	\$	Su	348.25
46	1	WIPER RESERVOIR NECK	\$	Su	136.11
47	1	WIPER RESERVOIR MOTOR	\$	Su	270.06
48	1	AIR CLEANER LOWER	\$	Su	271.26
49	1	AIR CLEANER HOSE	\$	Su	76.14
55	1	ENGINE TOP COVER 2.0	\$	Su	555.12
56	1	ENGINE OIL SUMP	\$	Su	484.67
58	1	BASE BATTERY TRAY	\$	Su	363.40
59	1	AIR CLEANER BOX	\$	Su	464.20
60	1	TURBO DUCT	\$	Su	1,027.80
61	1	A/C HEATER VALVE	\$	Su	484.50
63	1	SUBFRAME OUTER FRT	\$	Su	2,652.45
64	1	SUBFRAME BRACKET OUTER LH	\$	Su	92.36
65	1	SUBFRAME BRACKET OUTER RH	\$	Su	92.36
66	1	ENGINE UNDERTRAY	\$	Su	564.98
67	1	A/C CONDENSER	\$	Su	2,020.37
68	1	A/C CONDENSER GARNISH LH UPPER	\$	Su	39.67
69	1	A/C CONDENSER GARNISH RH UPPER	\$	Su	39.67
70	1	A/C CONDENSER GARNISH LH	\$	Su	58.81
71	1	A/C CONDENSER GARNISH RH	\$	Su	59.60

Trans-cab Auto Services Pte Ltd

AAD1809-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5630M

72	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Su	208.39
73	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Su	658.72
74	1	A/C PIPE COMPRESSOR	\$	Su	334.29
75	1	A/C PIPE	\$	Su	658.72
76	1	A/C COMRPESSOR	\$	Su	2,684.61
77	1	AIR COOLER	\$	Su	792.60
78	1	AIR INTERCOOLER HOSE (LONG)	\$	Su	1,014.13
79	1	AIR INTERCOOLER HOSE (Short)	\$	Su	375.14
80	1	TRANSMISSION COOLER	\$	Su	1,219.30
81	1	TRANSMISSION COOLER PAD	\$	Su	17.96
82	1	RADIATOR	\$	Su	1,202.20
83	2	RADIATOR STUD UPPER	\$	↗	14.41
84	2	RADIATOR BUSH UPPER	\$	↗	50.12
85	2	RADIATOR MTG LOWER	\$	Su	55.85
86	1	RADAITOR FAN COWLING	\$	Su	820.54
87	1	RADIATOR FAN MOTOR LH	\$	Su	967.36
88	1	RADIATOR FAN MOTOR RH	\$	Su	1,479.46
89	1	RADIATOR TANK	\$	Su	324.62
90	1	RADIATOR HOSE UPPER	\$	Su	240.56
91	1	RADIATOR HOSE LOWER	\$	Su	491.18
92	1	RADIATOR TANK HOSE	\$	Su	61.18
93	1	AUTO COMPUTER	\$	Su	5,032.17
94	1	INJECTION COMPUTER	\$	Su	4,706.30
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	Su	5,154.52
96	1	STEERING PUMP ELECTRIC	\$	Su	2,306.90
97	1	STEERING PINION RACK	\$	Su	4,413.11

TOTAL	\$	65,397.93
10%	\$	6,539.79
	\$	58,858.13

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	Su	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	Su	66.00	✓

Trans-cab Auto Services Pte Ltd

AAD1809-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5630M

3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
7	1	TOW COVER FRT	\$	nn	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	nn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
21	1	Windscreen moulding	\$	nn	100.00	} 45nn
22	1SET	Front licence plate with holder	\$	B	80.00	

TOTAL	\$	562.50
TOTAL PARTS	\$	59,420.63

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 500

Towing Fees.

\$ 120.00 30

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 440

To rust-proofing of the affected areas.

\$ 170.00 30

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

Trans-cab Auto Services Pte Ltd**AAD1809-234**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5630M

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>2cl</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i>	380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>↵</i>	380.00	<i>X</i>
To lift-up engine with gear box and refit.	\$	<i>↵</i>	440.00	<i>X</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>↵</i>	440.00	<i>X</i>
To remove and refit air bag system and reset.	\$	<i><</i>	480.00	<i>X</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>↵</i>	380.00	<i>X</i>
To vacuum, replace, refix and recharge air condenser	\$		380.00	<i>10cl</i>
To replace, refix and top up coolant for radiator	\$		170.00	<i>5cl</i>
To vacuum, replace, refix and recharge Air Intercooler	\$		170.00	<i>5cl</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i>	170.00	<i>X</i>
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i>	170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1809-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5630M

TOTAL	\$	17,170.00
--------------	-----------	------------------

Over All Total	\$	76,590.63
-----------------------	-----------	------------------

Repair Days (LUMP SUM)~~20 DAYS~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: