



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower, Singapore 068811 Attn: Motor Claims Contact No 63387288	Cust No/Name	/Mr Teh Yik Chuan
	Reg No/Reg Date	SLW7478X / 21/05/2015
	Date In/Mileage	24/09/2018/ 0
	Chassis No	KNAFX411MF5358306
	Engine No	G4FGEH752070
	Make/Model	KIA/FORTE K3 1.6 A EX W/ LED & D.B
	Colour/Trim	K3R / WK

Account No	Terms	Date/Time Printed	GSE	Operator	WIP No
F000008	Credit	24/09/2018/ 18:41	DS	218 / MarsLer	10611

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 REVERSE SENSOR SET				280.00 ✓
M SUNDRY C & C LOGO				50.00 X
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				602 80.00
S MIPNT88088 DIAGNOSTIC / SCANNING				250.00 ✓
S MIPNT88088 TO REPLACE REAR BUMPER, REINFORCEMENT, ETC -TO REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				1200 1800.00 ✓
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				840 1680.00 ✓
M KS 86611 A7 000 COVER - REAR BUMPER	1.00	768.00	0.00	768.00 ✓
P KS 86695 A7 000 COVER - REAR BUMPER,	1.00	234.00	0.00	234.00 ✓
M KS 92405 A7 000 LH REAR REFLECTOR RE	1.00	114.00	0.00	114.00 ✓
P KS 0G032 50 037A CLIP - BUMPER	10.00	2.00	0.00	20.00 ✓
M KS 86631 A7 000 BEAM-RR BUMPER	1.00	365.00	0.00	365.00 ✓
M KS 86636 A7 000 BRACKET - REAR BEAM	2.00	5.00	0.00	10.00 ✓
M KS 86635 A7 000 BRACKET - REAR BEAM	1.00	5.00	0.00	5.00 ✓
M KS 86633 A7 000 BRACKET-RR RAIL UPR	1.00	4.00	0.00	4.00 ✓
M KS 86634 A7 000 BRACKET-RR RAIL UPR	1.00	4.00	0.00	4.00 ✓
M KS 86641 A7 000 LH STAY - REAR BUMPER	1.00	75.00	0.00	75.00 ✓
M KS 86642 A7 000 RH STAY - REAR BUMPER	1.00	75.00	0.00	75.00 ✓
M KS 86613 A7 000 LH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00 ✓
M KS 86614 A7 000 RH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00 ✓
P KS 86310 A7 050 KIA LOGO	1.00	37.00	0.00	37.00 ✓
P WFFORTE FORTE EMBLEM	1.00	40.00	0.00	40.00 ✓
P WFEMBLEMK3 EMBLEM K3	1.00	15.00	0.00	15.00 ✓
Z NOTES ACCIDENT ON 23/09/2018 ALONG YISHUN AVE 1 (NEAR YISHUN DAM)				

Estimate

Confirm & accepted by

Repair days 4

LKK Auto Causal Agency
Attn: Catherine

R - 1045
? - 732
L - 2630

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower, Singapore 068811 Attn: Motor Claims Contact No 63387288	Cust No/Name	/Mr Teh Yik Chuan
	Reg No/Reg Date	SLW7478X / 21/05/2015
	Date In/Mileage	24/09/2018/ 0
	Chassis No	KNAFX411MF5358306
	Engine No	G4FGEH752070
	Make/Model	KIA/FORTE K3 1.6 A EX W/ LED & D.B
	Colour/Trim	K3R / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000008	Credit	24/09/2018/ 18:41	DS	218 / MarsLer	10611

Description of Goods//Services	Qty	Unit Price	Disc%	Amount
OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SKT5774G TP INS : AXA				
Estimate				

Confirm & accepted by Authorized signatory and company stamp	Parts	1,832.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	4,090.00
	Others (Lub, etc)	0.00
	Sundry	50.00
	Total (w/o GST)	5,972.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.