

ASS. REC. BY:

REF: CS/FCI18017604/Grd312 Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

27/9/18 2:47pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 914 Y

Insured:

SH 8176G

at Workshop m/s

Trans - Cab

Tel:

6287 6666

of

No. 2 AMK St. 63

Policy No:

Claim No:

D18007078MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

2:49pm 27/9/18

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 914Y - CC3/AIG/7023033/Kf93

D.O.A: 28/11/

SH 8176G - CC3/AIG/10000431/Cwjg1

D.O.A: 8/01/2010

14/11/18

Rerert 1A via email.

15/11/18

Confirmed with Wai Yin \$1,320.00 @ 3 days (Red: \$31,388.21, 95%.)

SYNOPSIS

REF:

C3878K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt.: Consistent? : Yes or No

GiA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 15 NOV 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 1320.00

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photo

) Others

TOTAL

22x15: 330

170 + 330

50

19

569



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007078MFSH

Date: 14 November 2018

Our Ref: CS/FCI18017604/Grd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 914Y

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02/10/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>32,708.21</u>
Revised Estimate Amount	: S\$ <u>1,320.00</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the o/s body.



Yours faithfully

XING GUO QIANG
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-09-2018	Our Ref No. D18007078MFSH
Accident Date	25-09-2018	Claim Type. Third Party
Insured Vehicle	SH8176G	Third Party Vehicle. SHD914Y
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244541)



PRI Documents



Close



PRI Header Details

Claim No	D18007078MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS CA
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: CANDY.KONG@TRASCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8176G	TP Vehicle No	SHD914Y
PRI Recieved Date	27-09-2018 03:54:53 PM	Surveyor Appointed Date	27-09-2018 02:45:56 PM	Surveyor Accept Date	27-09-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-09-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, November 14, 2018 3:46 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18007078MFSH/1
Attachments: SHD 914Y.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SHD 914Y.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, September 27, 2018 2:57 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007078MFSH/1

Dear Sir / madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 27 September, 2018 2:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007078MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Janice Lee (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, November 15, 2018 10:46 AM
To: Janice Lee (LKKAUTO)
Cc: 'Candy Kong'; Guo Qiang (LKKAUTO)
Subject: FW: SHD 914Y FCI -- AAD1809-248
Attachments: image001.wmz; SHD 914Y EST.pdf

Hi Janice

We confirmed COR amount \$1,320.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Wednesday, 14 November, 2018 3:35 PM
To: candy.kong@transcab.com.sg
Cc: Ng Wai Yin <waiyin.ng@transcab.com.sg>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: SHD 914Y FCI

Dear Candy,

Kindly confirm P/P \$1,320.00 @ 3 DAYS.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD914Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003156
Chassis No.:	VF1ABL15AUC283249
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	29 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$42,672.00
COE Rebate Amount:	\$32,048.00
Total Rebate Amount:	\$47,046.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Sep 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD914Y
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003156
Chassis No.:	VF1ABL15AUC283249
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	29 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$42,672.00
COE Rebate Amount:	\$31,944.00
Total Rebate Amount:	\$46,942.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Oct 2018

OK

Trans-cab Auto Services Pte Ltd**AAD1809-248**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 914Y

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 914Y

VF1ABL15AUC283249

RENAULT

LATITUDE

25.9.2018

FCIL

PART		LIST	
1	DOOR PANEL REAR RH <i>X Repair</i>	\$	2,844.66
1	DOOR GUIDE REAR RH <i>X</i>	\$	176.82
1	DOOR HINGE UPPER RH <i>X</i>	\$	274.50
1	DOOR HINGE LOWER RH <i>X</i>	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y <i>X</i>	\$	203.06
1	DOOR LOCK REAR RH <i>X</i>	\$	908.75
1	DOOR HANDLE OUTER REAR RH <i>X</i>	\$	126.49
1	DOOR HANDLE CAP REAR RH <i>X</i>	\$	35.52
1	DOOR HANDLE SEAL REAR RH <i>X</i>	<i>NN</i> \$	7.89
1	DOOR HANDLE COVER REAR RH <i>X</i>	\$	13.22
1	DOOR HANDLE MODULE REAR RH <i>X</i>	\$	133.60
1	DOOR REGULATOR REAR RH <i>X</i>	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR RH <i>X</i>	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y <i>X</i>	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y <i>X</i>	\$	6.31
1	DOOR FINISHER REAR RH <i>X</i>	\$	423.10
1	DOOR MOULDING REAR RH <i>X</i>	\$	176.82
1	DOOR MOULDING CLIP L70Y <i>X</i>	\$	5.92
1	DOOR MOULDING SCREW L70Y <i>X</i>	\$	6.91
1	DOOR CASING REAR RH <i>X</i>	\$	1,509.06
1	DOOR WATER SHIELD REAR RH <i>X</i>	\$	30.39
1	DOOR CASING CLIP <i>X</i>	\$	12.63
1	DOOR CASING LIGHT L70Y <i>X</i>	\$	48.74
1	DOOR FINISHER INNER REAR RH <i>X</i>	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR RH <i>X</i>	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR RH <i>X</i>	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH <i>X</i>	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH <i>X</i>	\$	20.33
1	DOOR GRAB HANDLE REAR RH <i>X</i>	\$	210.96

Trans-cab Auto Services Pte Ltd**AAD1809-248**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 914Y

1	DOOR BLIND REAR RH	X		\$	741.80
1	DOOR WHEATHESTRIIP REAR RH	X		\$	410.66
1	DOOR SEAL REAR RH	X		\$	162.02
1	DOOR GLASS RUNNER SEAL REAR RH	X		\$	229.31
1	DOOR WAIST SEAL OUTER REAR RH	X		\$	334.69
1	DOOR WAIST SEAL INNER REAR RH	X		\$	115.64
1	FENDER PANEL REAR RH	X	Repair	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	X		\$	671.45
1	WHEELARCH REAR RH	X		\$	543.47
1	DOOR MIRROR ASSY RH	X		\$	1,483.40
1	ROCKER PANEL INNER GARNISH RH	X		\$	466.51
1	ROCKER PANEL INNER RH	X		\$	1,024.79
1	ROCKER PANEL CENTER RH	X		\$	990.25
1	BUMPER COVER REAR	X	Repair	\$	1,108.46
1	BUMPER LOWER REAR	X		\$	768.84
1	BUMPER BRACKET CTR REAR	X		\$	113.47
1	BUMEP R BRACKET SIDE RH REAR	X		\$	135.97
1	BUMEP R RETAINER RH REAR	X		\$	44.99

\$	22,573.43
----	------------------

10% \$	2,257.34
--------	-----------------

\$	20,316.08
----	------------------

Special Nett

2	FRAME FULL SUPPORT PANEL NUT	X		\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	X		\$	30.00
1 SET	WHEELARCH CLIP FRT LH	X		\$	30.50
1	REAR DOOR STICKER '6555-3333'			\$	80.00
1	DOOR CHECK BOLT	X		\$	22.69
1	DOOR GUIDE SCREW	X		\$	10.85
1	DOOR HINGE BOLT	X		\$	10.85
1	DOOR HINGE NUT RH	X		\$	14.60
1	DOOR CHECK BOLT	X		\$	22.69
1	DOOR CHECK NUT	X		\$	3.75
1	DOOR LOCK SCREW L70Y	X		\$	6.12
1	DOOR CATCH SCREW L70Y	X		\$	10.06
1	RIGHT REAR TYRE RIM			\$	380.00

Trans-cab Auto Services Pte Ltd

AAD1809-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 914Y

1	RIGHT REAR TYRE	X	NN	\$	300.00
---	-----------------	---	----	----	--------

TOTAL	\$	942.13
-------	----	--------

TOTAL PARTS	\$	21,258.21
-------------	----	-----------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	200	4,500.00
----	-----	----------

Putty and spray painting of the affected portion.

\$	600	4,200.00
----	-----	----------

To rust-proofing of the affected areas.

\$	NN	X	170.00
----	----	---	--------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	NN	X	380.00
----	----	---	--------

To check steering geometry and computer wheel alignment

\$	60	220.00
----	----	--------

To transfer of tire, rim and on wheel balancing.

\$	X	170.00
----	---	--------

To Check Electrical Lighting Concerned.

\$	X	170.00
----	---	--------

To transfer of front fender fittings, attachment and perform water seepage test.

\$	NN	X	380.00
----	----	---	--------

To transfer of front door fittings, attachment and perform water seepage test.

\$	X	380.00
----	---	--------

Towing Fees.

\$	X	120.00
----	---	--------

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$	X	380.00
----	---	--------

AAD1809-248

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 914Y

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair. \$ *NNX* 380.00

TOTAL \$ 11,450.00

Over All Total \$ 32,708.21

LUMP SUM (PART-BY-PART)

15 DAYS

2 Days.

part by part.

After repair photos.

Guo Q: ang - 8288082

02/10/18.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017604/Grd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-11-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8176G	Veh. Inspected	SHD 914Y
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18007078MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	27/09/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC283249	Colour	RED
Odometer	190879	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	5 mm
L/H Front Tyre	215/60 R16	FALKEN	5 mm
R/H Rear Tyre	215/60 R16	FALKEN	5 mm
L/H Rear Tyre	215/60 R16	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/09/2018	Inspection Date	02/10/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 914Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	NOT NECESSARY	176.82	-
1	DOOR HINGE UPPER RH	NOT NECESSARY	274.50	-
1	DOOR HINGE LOWER RH	NOT NECESSARY	300.55	-
2	DOOR CHECK REAR LH/RH L70Y	NOT NECESSARY	203.06	-
1	DOOR LOCK REAR RH	NOT NECESSARY	908.75	-
1	DOOR HANDLE OUTER REAR RH	NOT NECESSARY	126.49	-
1	DOOR HANDLE CAP REAR RH	NOT NECESSARY	35.52	-
1	DOOR HANDLE SEAL REAR RH	NOT NECESSARY	7.89	-
1	DOOR HANDLE COVER REAR RH	NOT NECESSARY	13.22	-
1	DOOR HANDLE MODULE REAR RH	NOT NECESSARY	133.60	-
1	DOOR REGULATOR REAR RH	NOT NECESSARY	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH	NOT NECESSARY	893.75	-
1	DOOR REGULATOR NUT REAR L70Y	NOT NECESSARY	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	NOT NECESSARY	6.31	-
1	DOOR FINISHER REAR RH	NOT NECESSARY	423.10	-
1	DOOR MOULDING REAR RH	NOT NECESSARY	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	NOT NECESSARY	6.91	-
1	DOOR CASING REAR RH	NOT NECESSARY	1,509.06	-
1	DOOR WATER SHIELD REAR RH	NOT NECESSARY	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	NOT NECESSARY	48.74	-
1	DOOR FINISHER INNER REAR RH	NOT NECESSARY	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH	NOT NECESSARY	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH	NOT NECESSARY	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	NOT NECESSARY	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	NOT NECESSARY	20.33	-
1	DOOR GRAB HANDLE REAR RH	NOT NECESSARY	210.96	-
1	DOOR BLIND REAR RH	NOT NECESSARY	741.80	-

Report Ref No. CS/FCI18017604/Grd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR WEATHERSTRIP REAR RH	NOT NECESSARY	410.66	-
1	DOOR SEAL REAR RH	NOT NECESSARY	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH	NOT NECESSARY	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH	NOT NECESSARY	334.69	-
1	DOOR WAIST SEAL INNER REAR RH	NOT NECESSARY	115.64	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	NOT NECESSARY	671.45	-
1	WHEELARCH REAR RH	NOT NECESSARY	543.47	-
1	DOOR MIRROR ASSY RH	NOT NECESSARY	1,483.40	-
1	ROCKER PANEL INNER GARNISH RH	NOT NECESSARY	466.51	-
1	ROCKER PANEL INNER RH	NOT NECESSARY	1,024.79	-
1	ROCKER PANEL CENTER RH	NOT NECESSARY	990.25	-
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
1	BUMPER LOWER REAR	NOT NECESSARY	768.84	-
1	BUMPER BRACKET CTR REAR	NOT NECESSARY	113.47	-
1	BUMPER BRACKET SIDE RH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER RH REAR	NOT NECESSARY	44.99	-
	LESS 10% DISCOUNT		-2,257.33	-
			20,316.10	-
	SPECIAL NETT ITEMS			
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	REAR DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	80.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-

Report Ref No. CS/FCI18017604/Grd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
1	RIGHT REAR TYRE RIM (SN)	CUT	380.00	380.00
1	RIGHT REAR TYRE (SN)	NOT NECESSARY	300.00	-
			942.11	460.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL REAR RH,FENDER PANEL REAR RH AND BUMPER COVER REAR.		4,500.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	-		-	-
	-		-	-
	-		-	-
			11,450.00	860.00
	GRAND TOTAL		32,708.21	1,320.00

Report Ref No. CS/FCI18017604/Grd3n2



RECOMMENDED COST OF REPAIRS			1,320.00
-----------------------------	--	--	----------

Report Ref No. CS/FCI18017604/Grd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.