

ASS. REC. BY:

REF: CS/FCI 18017611 / Rlv d3 ⁿ² Special Instruction:Surveyor
CWS

Rasul

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 27/9/18 @ 2:40pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ 8978G

Insured:

8HA 2096K

at Workshop m/s

Hup Hup Workshop

Tel: 6265 5270

of

27A Jurong Post Rd # 01-29

Policy No:

Claim No:

D18006896MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/09/18

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

28/9/18 @ naming

Date/Time:

3:13pm @ 27/9/18

Person Contacted:

Ms. Wong

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GZ 8978G - CS/MSG/1015463/Kun DOA: 9/3/2010
	8HA 2096K - CS/FCI/18007775/6 DOA: 22/4/18
02/10/18	@ 10:41 a.m. revised PA to Karen Tan via email.
11/11/18	@ 11:54am L2 \$5000 confirmed with ms Wong (Red 5000.51, 5110 mv: \$19K (EST) LTA: \$12,869 HV: \$631

WITNESS
Inspector

Rasul

REF: FCI

41436

COG APRA: 2021/11/18

ASSIGNMENT

From: Date: 28/9/18

Estimated Cost

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GZ 89786
at Workshop n/s: Hup Hup Motor
of: 27A - Jurong Port Rd # 01-29

Insured

Policy No

Claims No

Sum Insured

Excess


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 19K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GZ 89786 Yr Regn: 2006 / 86P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI FB 70A BORDERS 2838

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 492453 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FB 70ABA00743

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size: F: 185R14C

R: 165R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Concord*

Front R/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 16/09/18

Survey held at: Hup Hup

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Rasul,

pls check parts prices & see my remarks

RECEIVED 21 NOV 2018

[Signature]
3/10

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS (\$)

Photos

Others

TOTAL

1)

Date/Time, File Return to?

2) 11/11 - typist

Report Format: CWS

Lump Sum / I.B.F: (\$ 5000)

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

170

50

50

70

340



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006896MFSH

Date: 02 October 2018

Our Ref: CS/FCI18017611/R1vd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GZ 8978G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/09/2018 at the premises of M/s Hup Hup Workshop Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 10,202.51</u>
Revised Estimate Amount	: <u>S\$ 6,828.54</u>
"Check" Items Amount	: <u>S\$ 208.42</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 7 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-09-2018	Our Ref No. D18006896MFSH
Accident Date	16-09-2018	Claim Type. Third Party
Insured Vehicle	SHA2096K	Third Party Vehicle. GZ8978G
Survey Location	27-A JURONG PORT ROAD #01-29	
Contact Person.	WONG (MS)	
Contact No.	62655270/ 62613407	Fax No. 62618456
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUP HUP WORKSHOP PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244315)



PRI Documents



Close



PRI Header Details

Claim No	D18006896MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & HUP HUP
Workshop Name	HUP HUP WORKSHOP PTE LTD (Contact Person : WONG (MS))	Survey Location & Contact Details	27-A JURONG PORT ROAD #01-29 Mobile: 62613407 , Phone: 62655270 , Fax: 62618450 EmailId: HUPWSHOP@HOTMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA2096K	TP Vehicle No	GZ8978G
PRI Recieved Date	26-09-2018 02:53:14 PM	Surveyor Appointed Date	27-09-2018 02:40:01 PM	Surveyor Accept Date	27-09-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-09-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 2 October 2018 10:41 AM
To: KARENTAN@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18006896MFSH/1
Attachments: GZ 8978G - Preli Advise.pdf

Dear Karen,

Enclosed herewith preliminary advice of GZ 8978G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler (ON BEHALF VERON)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 27 September 2018 3:35 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006896MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 28/09/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 27 September 2018 2:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006896MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 19 November 2018 8:37 AM
To: SUR; 'hupwshop@hotmail.com'
Subject: RE: GZ 8978G-DOA: 16/9/2018 (FCIL TP)

Dear Ms Wong,

WITHOUT PREJUDICE

Close at Lump Sum \$5000/-

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 15 November 2018 2:44 PM
To: SUR <sur@lkkauto.com>; 'hupwshop@hotmail.com' <hupwshop@hotmail.com>
Subject: RE: GZ 8978G-DOA: 16/9/2018 (FCIL TP)

Dear Ms Wong,

WITHOUT PREJUDICE

Offer Lump Sum \$5100/- @ 7 working days.

Kindly confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 7 November 2018 2:18 PM
To: SUR <sur@lkkauto.com>; 'hupwshop@hotmail.com' <hupwshop@hotmail.com>
Subject: RE: GZ 8978G-DOA: 16/9/2018 (FCIL TP)

Dear Ms Wong,

WITHOUT PREJUDICE

Re-offer Lump Sum \$4600 @ 7 working days.

Kindly confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Monday, 5 November 2018 5:17 PM

To: SUR <sur@lkkauto.com>; 'hupwshop@hotmail.com' <hupwshop@hotmail.com>

Subject: GZ 8978G-DOA: 16/9/2018 (FCIL TP)

Dear Ms Wong,

WITHOUT PREJUDICE

Offer Lump Sum \$4250/- @ 7 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66SS0020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH18120800 Vehicle Registration No: GZ8978G
Name(as shown in NRIC) : MUTHUSAMY SATHISH NRIC/FIN/Passport No : G2345992U
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No. : 86191267
Email Address : PAPGONDOLA@SAFEWELLACCESS.COM
Date of Accident : 16/09/2018 Time of Accident : 19:30
Place of Accident : CLEMENCEAU AVE
Insurance Company: ERGO INSURANCE PTE. LTD.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Add in witness

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: Boey Loke
NRIC/FIN No.:
Date: 19 Sep 2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 4143G

Vehicle Details

Vehicle No.: GZ8978G
Vehicle to be Exported: No
Intended Deregistration Date: 19 Nov 2018
Vehicle Make: MITSUBISHI
Vehicle Model: FB70ABOSRDEB
Primary Colour: White
Manufacturing Year: 2006
Engine No.: 4M40HD1146
Chassis No.: FB70ABA00743
Maximum Power Output: -
Open Market Value: \$18,184.00
Original Registration Date: 27 Sep 2006
First Registration Date: 27 Sep 2006
Transfer Count: 4
Actual ARF Paid: \$910.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2021
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$23,127.00
COE Rebate Amount: \$12,869.00
Total Rebate Amount: \$12,869.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 19 Nov 2018

OK

19,000
12,869

6,131

QUOTATION

合合車廠私人有限公司

HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101

TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456

Business Regn. / GST Regn. No. 19-8004325-G

Date: 25/09/2018

M/s MS FIRST CAPITAL INSURANCE LIMITED

VEHICLE NO. GZ 8978G

MAKE Mit. Fuso Lorry
FB 70

Our Ref: HHW/TP 2397/2018

Your Ref:

- 1 pc Front bumper
- 1 pc Front bumper bracket
- 1 pc LH corner panel
- 1 pc LH headlamp
- 1 pc LH signal lamp
- 1 pc LH marker lamp
- 1 pc LH door
- 1 pc LH door hinges - bottom
- 1 pc LH door hinge - top
- 1 pc LH step garnish
- 1 pc LH headlamp lower rubber
- 1 pc LH scuff plate
- 1 pc LH door pillar
- 1 pc Front windscreen glass rubber

1 pc L T A sticker

Dismantle and fix front windscreen glass.

Dismantle and reassembler dashboard panel.

Labour charge to knock, repair, straighten both side door pillar, windscreen glass pillar, LH wheel arch panel, LH floorboard panel, dismantle, align, adjust and replace parts. To cut, weld replace LH door rear pillar.

Spray paint on front bumper, LH corner panel, LH door-inside/outside, LH wheel arch panel, LH w/screen glass pillar, LH door rear pillar.

Redo company logo and company lettering.

Rasul
Ap 90010068

7 days

4/5

28/09/18 @ 1220

Rey after repair

25%

Less 20%

870	MIT	821.47
X44	7	119.42 X
71		564.37
672.51	CM	768.05
	MIS	227.65
	MIS	159.75
1866.12	MIT	2071.50
115	71	162.54
	SVC	X 162.54
291.40	CRB	539.35
	MIS	21.00
	CRB	141.10
	repair	1533.25
	117	X 423.65
		7715.64
		-1543.13
		6172.51
	net	30.00SN
	117	X 200.00
	1770	X 450.00
	250	200
	1100	1800.00
	1000	1300.00
	180	250.00SN
		10202.51

N.B.: Estimate does not include 7% GST



QUOTATION

合合車廠私人有限公司 HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101

TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456

Business Regn. / GST Regn. No. 19-8004325-G

Date: 25/09/2018

M/s MS FIRST CAPITAL INSURANCE LIMITED

VEHICLE NO. GZ 8978G

MAKE Mit. Fuso Lorry
FB 70

Our Ref: HHW/TP 2397/2018

Your Ref: "

- | | |
|------|-------------------------------|
| 1 pc | Front bumper |
| 1 pc | Front bumper bracket |
| 1 pc | LH corner panel |
| 1 pc | LH headlamp |
| 1 pc | LH signal lamp |
| 1 pc | LH marker lamp |
| 1 pc | LH door |
| 1 pc | LH door hinges - bottom |
| 1 pc | LH door hinge - top |
| 1 pc | LH step garnish |
| 1 pc | LH headlamp lower rubber |
| 1 pc | LH scuff plate |
| 1 pc | LH door pillar |
| 1 pc | Front windscreen glass rubber |

1 pc L T A sticker

Dismantle and fix front windscreen glass.

Dismantle and reassembler dashboard panel.

Labour charge to knock, repair, straighten both side door pillar, windscreen glass pillar, LH wheel arch panel, LH floorboard panel, dismantle, align, adjust and replace parts. To cut, weld replace LH door rear pillar.

Spray paint on front bumper, LH corner panel, LH door-inside/outside, LH wheel arch panel, LH w/screen glass pillar, LH door rear pillar.

Redo company logo and company lettering.

Rasul
Ap 90010068
7 days
4/5
28/09/18 @ 1220
Rasy after
repair
3/10/18
Less 20% 25%

711	821.47
X	119.42
X	564.37
CM	768.05
MS	227.65
MS	159.75
711	2071.50
711	162.54
X	162.54
CM	539.35
MS	21.00
	141.10
repair	1533.25
X	423.65
	7715.64
	-1543.13
	6172.51
new	30.00SN
X	200.00
1710	450.00
250	200
1100	1800.00
1000	1300.00
180	250.00SN
	10202.51

N.B.: Estimate does not include 7% GST





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017611/R1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2096K	Veh. Inspected	GZ 8978G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18006896MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	27/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FB70ABOSRDEB	c.c	2835	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	FB70ABA00743	Colour	WHITE	
Odometer	492453	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14C	CONDOR	7 mm	
L/H Front Tyre	185 R14C	CONDOR	7 mm	
R/H Rear Tyre	165 R15 (D)	CONDOR	5/5 mm	
L/H Rear Tyre	165 R15 (D)	CONDOR	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/09/2018	Inspection Date	28/09/2018	
Survey held at	HUP HUP WORKSHOP PTE LTD 27-A JURONG PORT ROAD #01-29 SINGAPORE 619101			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 8978G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT	821.47	810.00
1	FRONT BUMPER BRACKET	NOT NECESSARY	119.42	-
1	LH CORNER PANEL	BENT	564.37	564.37
1	LH HEADLAMP	CRACKED	768.05	672.51
1	LG SIGNAL LAMP	MISSING	227.65	227.65
1	LH MARKER LAMP	MISSING	159.75	159.75
1	LH DOOR	BENT	2,071.50	1,881.12
1	LH DOOR HINGES-BOTTOM	BENT	162.54	115.00
1	LH DOOR HINGE-TOP	SERVICEABLE	162.54	-
1	LH STEP GARNISH	CRACKED	539.35	291.40
1	LH HEADLAMP LOWER RUBBER	MISSING	21.00	21.00
1	LH SCUFF PLATE	CRACKED	141.10	141.10
1	LH DOOR PILLAR	TO REPAIR SEE LABOUR	1,533.25	-
1	FRONT WINDSCREEN GLASS RUBBER	NOT NECESSARY	423.65	-
	LESS 20% DISCOUNT		-1,543.13	-
	LESS 25% DISCOUNT		-	-1,220.98
			6,172.51	3,662.92
SPECIAL NETT ITEMS				
1	LTA STICKER (SN)	NECESSARY	30.00	30.00
1	REDO COMPANY LOGO AND COMPANY LETTERING (SN)		250.00	180.00
			280.00	210.00
LABOUR				
	DISMANTLE AND FIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	200.00	-
	DISMANTLE AND REASSEMBLER DASHBOARD PANEL.		450.00	250.00
	LABOUR CHARGE TO KNOCK,REPAIR,STRAIGHTEN BOTH SIDE DOOR PILLAR,WINDSCREEN GLASS PILLAR,LH WHEEL ARCH PANEL,LH FLOORBOARD PANEL,DISMANTLE,ALIGN,ADJUST AND REPLACE PARTS TO CUT,WELD REPLACE LH DOOR REAR PILLAR.INCLUSIVE OF THE REPAIR OF LH DOOR PILLAR.		1,800.00	1,100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT ON FRONT BUMPER, LH CORNER PANEL, LH DOOR-INSIDE/OUTSIDE, LH WHEEL ARCH PANEL, LH W/SCREEN GLASS PILLAR, LH DOOR REAR PILLAR.		1,300.00	1,000.00
			3,750.00	2,350.00
GRAND TOTAL			10,202.51	6,222.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/FCI18017611/R1vd3n2

MARKET VALUE: \$19,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,869.00=NETT VALUE: \$6,131.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.